

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC3/MSG18013151/Utpn2

MS 16/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX181D

at Workshop m/s ft.

of _____

Insured: SCG298K

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

G/A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA59648

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

have G.A. have Estimate of performance.

23/7- Report via Email.

RECEIVED 14 AUG 2018

7/8/18 1/5 + 3000 confirmed with Alan.
(Red: 12350.52; 8070)

Date/Time, File Pass to?

☐ : Preli. Report

11/4/18 Typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

10

210

Report Format: TP

Lump Sum / I.B.I. (\$ 3000/-)

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 23 July 2018 8:54 AM
To: 'Monica Chung'; 'rashitha.shahuthuman@income.com.sg'
Cc: SUR; Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 13/7/2018, SKX 181D (TP VEHICLE), SCG298K (OI VEHICLE)
Attachments: skx 181d gia.pdf

Dear Monica/Rashitha,

Please be informed that we had inspected the vehicle SKX 181D at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 41788.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8638E

Vehicle Details

Vehicle No.: SKX181D

Vehicle to be Exported: No

Intended De-registration Date: 19 Jul 2018

Vehicle Make: B.M.W.

Vehicle Model: 216D GRAN TOURER LED NAV 7 SEATER

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 36869390B37C15A

Chassis No.: WBA2E32010P836820

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$30,508.00

Original Registration Date: 23 Nov 2015

First Registration Date: 23 Nov 2015

Transfer Count: 0

Actual ARF Paid: \$24,712.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Nov 2025

PARF Rebate Amount: \$18,534.00

Intended COE Rebate Details

COE Expiry Date: 22 Nov 2025

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$60,689.00

COE Rebate Amount: \$41,114.00

Total Rebate Amount: \$59,648.00

The information contained herein is correct as at 19 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 14/07/2018 10:30 |
| Date Of Accident | 13/07/2018 16:10 |
| Exact Location Of Accident | AMK ST11 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKX181D |
| Insured/Policyholder | |
| Name Of Registered Owner | TAN WEE LENG GELYN |
| NRIC No | S6938638E |
| Email Address | GELYNTAN@HOTMAIL.COM |
| Mobile Phone No | (LOCAL) +65-96955125 |
| Alternative Phone No | OFFICE-96955125 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | BMW |
| Model | 216 |
| Exact Purpose for which vehicle was being used at time of accident | NORMAL USAGE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | P1689992 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | TAN WEE LENG GELYN |
| NRIC No | S6938638E |
| Date Of Birth | 11/11/1969 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 04/04/1989 |
| Driving Experience | 29 YEARS AND 3 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-96955125 |
| Fax Number | |
| Contact Number | OFFICE-96955125 |
| Email Address | GELYNTAN@HOTMAIL.COM |

Address 491 YIO CHU KANG RD #03-06
 Postcode 787078
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : RAE-AN LECK SZE RUI
 GENDER: : FEMALE
 Passenger 2 NAME: : KAE LA LECK SZE HAN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name KEBUN BARU NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 111 ANG MO KIO AVENUE 4 , POSTCODE: 560111 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4589999 - FAX NO: 64574454
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

Details of Witness 1

Name KUMAR
 Phone Number 84488603
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCG298K
 Vehicle Make/Model/Colour TOYOTA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TAN PECK KEE

NRIC/Passport Number

S0013577A

Contact Number

92379933

Address

17 NERAM CRESCENT

Postcode

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach Police Report Statement
Upon conversation on 14 Jul 2018, 3rd party
decided to claim under insurance.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 14/7/2018
NRIC/FIN No.: 0101044



**SINGAPORE
POLICE FORCE**



F/20180713/2136

1 of 2

POLICE REPORT (NP299)

Report No. F/20180713/2136

Police Station Of Origin
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

| | | |
|--|--|-------------------------|
| Date/Time Report Made 13/07/2018 17:44 | Vide Report No. | Station Diary No. 16 |
| Name Of Informant TAN WEE LENG GELYN | Address 491 YIO CHU KANG ROAD #03-06 SINGAPORE 787078 | |
| ID Type / ID No. NRIC NO / S6938638E | Contact No. Home/Office | Mobile 96955125 |
| Nationality SINGAPORE CITIZEN | Email Address | |
| Occupation Real estate agent | Sex Female | Age 48 |
| Institution/School Name | Date of Birth 11/11/1969 | Race Chinese |
| Date/Time Of Incident 13/07/2018 16:10 - 13/07/2018 16:10 | Location Of Incident ANG MO KIO STREET 11 SINGAPORE | |

Brief details.

On 13/07/2018 at about 1610hrs, upon approaching the zebra crossing along Ang Mo Kio Street 11, I saw there was an Indian man wanted to cross the road. Thus, I slowed down and stop my car bearing registration no: SKX181D at the zebra crossing. While my car was in a stationary position, subsequently, there was a loud bang came from rear. I then realized that there was another car bearing registration no: SCG298K had hit onto the rear side of my car. The Indian man was shocked and he had run after he heard the sound of the collision. I managed to stop the Indian man and he had given his name. His name is Kumar, contact no: 84488603. He is willing to be my witness. I also managed to obtain the particulars of the other driver by the name of Tan Peck Kee, S0013577A, residing at No.17, Neram Crescent,

Signature Of Officer Recording The Report:

F / Staff Sgt SHAHRUL SOPHIAN BIN JUMAAT

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
13/07/2018 17:44

Officer In-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Staff Sgt SHAHRIL RASHIDI BIN SADLI
Contact No.: 64849999

Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



F/20180713/2136

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20180713/2136

contact no: 92379933. At this point of time, I was told that she would bear the damages of my car. I will keep liaising with her to settle on this matter.

Signature Of Officer Recording The Report:

F / Staff Sgt SHAHRUL SOPHIAN BIN JUMAAT

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Staff Sgt SHAHRIL RASHIDI BIN SADLI
Contact No.: 64849999

Authentication Stamp

Signature Of Informant:

Date/Time:
13/07/2018 17:44

Classification Of Case:

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

Not Approved
2/18
19/17/18
2/5 #3000/2
3 day

VEHICLE NO:SKX 181D

| QTY | PARTICULAR | |
|-------|-----------------------------------|-----------------------|
| 1 PCS | TAILGATE | |
| 1 PCS | TAILGATE REAR LOGO | |
| 1 PCS | TAILGATE WEATHERSTRIP | |
| 1 PCS | REAR BUMPER | 966.25 |
| 1 PCS | REAR BUMPER CHROME MOULDING | 105.65 |
| 2 PCS | REAR BUMPER REFLECTORS @\$66.00 | 35.00 |
| 2 PCS | REAR BUMPER PDC SENSORS @ | 380.65 x 2 = 761.30 |
| 1 PCS | REAR BUMPER REINFORCEMENT | 423.80 |
| 2 PCS | REAR BUMER SIDE HOLDERS @\$125.00 | |
| 1 SET | REAR BUMPER CLIPS | |
| 1 PCS | REAR BUMPER UNDER COVER | |
| 1 PCS | REAR BUMPER LOWER SKIRTING | |
| 1 PCS | REAR BUMPER INNER RETAINER TOP | 195.35 |
| 1 PCS | REAR BUMPER INNER LOCK SENSOR | 181.20 |
| 1 PCS | REAR END PANEL | |
| 1 PCS | REAR EXHAUST MUFFLER | |
| 2 PCS | TAILLAMPS @\$750.00 | 152 |
| | | |
| | | 11 \$1,645.32 X |
| | | 11 \$86.30 X |
| | | 11 \$266.40 X |
| | | To. n \$1,817.30 ✓ |
| | | cm \$488.20 ✓ |
| | | M. s. cm \$132.00 1pc |
| | | Shed \$1,140.00 2 pcs |
| | | Bed \$899.20 ✓ |
| | | 11 \$250.00 X |
| | | ner \$50.00 ✓ |
| | | 11 \$311.20 X |
| | | ns \$420.00 X |
| | | cm \$283.50 ✓ |
| | | Shed \$266.60 ✓ |
| | | 11 \$1,019.20 X |
| | | 11 \$1,885.30 X |
| | | 11 \$1,500.00 X |
| | | \$12,460.52 |

LABOUR CHRAGES:

| | |
|--|----------------|
| TO CHECK WIRING | \$80.00 30 |
| TO DISMENTLE & REPLACING PDC SENSOR | \$100.00 60 |
| TO DISMENTLE & REFIX REAR WINDSCREEN | 11 \$150.00 X |
| TO DISMENTLE & REFIX REAR EXHAUST | 11 \$150.00 X |
| TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY | \$150.00 80 |
| TO SPRAY RUST PROOFING | 11 \$100.00 X |
| LABOUR FOR PANEL BEATING & REPLACING PARTS | \$880.00 500 |
| TO PUTTY & SPRAY PAINTING | \$1,280.00 500 |
| TOTAL | \$15,350.52 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 2718.55
52
258262
375262

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18013151/UTBN2

Date: 15/08/2018

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | A28696025QMX |
| Claimant Vehicle No : | SKX181D | Insured Vehicle No : | SCG298K |
| Date of Loss: | 13/07/2018 | Nature of Claim: | TP |
| | | Claim No: | 564500 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SKX181D | Engine No: | 36869390B37C15A |
| Make & Model: | BMW 216I, 1.5 (A) | Chassis No: | WBA2E32010P836820 |
| Reg. Date: | 23/11/2015 (Man. Year: 2015) | Odometer: | 49925 km |
| Colour: | White | | |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|------------------|
| Front Tyre Size: | 205/55R17 | Rear Tyre Size: | 205/55R17 |
| Front Left Side: | Goodyear 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|-----------------|------------------|--------------|
| Parts | 12,460.52 | 2,582.62 | 9,877.90 | 79.27 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,890.00 | 1,170.00 | 1,720.00 | 59.52 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 15,350.52 | 3,752.62 | 11,597.90 | 75.55 |
| Approved Total (Overridden) (\$\$) | | 3,000.00 | | |
| (\$\$) | 15,350.52 | 3,000.00 | 12,350.52 | 80.46 |
| + GST 7.00/7.00% (\$\$) | 1,074.54 | 210.00 | 864.54 | 80.46 |
| Nett Amount (\$\$) | 16,425.06 | 3,210.00 | 13,215.06 | 80.46 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 23/07/2018 | |
| Date Inspected: | 19/07/2018 Inspected At: | Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|---|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 15 Aug 2018) | |
| Parts: M1-MPV | BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0) | |
| Labour: Repairer's | (Price-denominated Standard List) | |
| Print Code: (Unsubmitted, no print-code for SKX181D) | | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|---------------|------------|------------|
| 1 | 1 | | *TAILGATE | Not Necessary | 1,645.32 F | *- FL |
| 2 | 1 | | *TAILGATE REAR LOGO | Not Necessary | 86.30 F | *- FL |
| 3 | 1 | | *TAILGATE WEATHERSTRIP | Not Necessary | 266.40 F | *- FL |
| 4 | 1 | | *REAR BUMPER | Torn | 1,817.30 F | *966.25 FL |
| 5 | 1 | | *REAR BUMPER CHROME MOULDING | Cracked | 488.20 F | *105.65 FL |
| 6 | 1 | | *REAR BUMPER REFLECTORS | N/s Cracked | 132.00 F | *35.00 FL |
| 7 | 1 | | *REAR BUMPER PDC SENSORS | Shorted | 1,140.00 F | *761.30 FL |
| | | | (2 Pcs) | | | |
| 8 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 899.20 F | *423.80 FL |
| 9 | 2 | | *REAR BUMPER SIDE HOLDERS | Not Necessary | 250.00 F | *- FL |
| 10 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 50.00 F | *50.00 FL |
| 11 | 1 | | *REAR BUMPER UNDER COVER | Not Necessary | 311.20 F | *- FL |
| 12 | 1 | | *REAR BUMPER LOWER SKIRTING | No such part | 420.00 F | *- FL |
| 13 | 1 | | *REAR BUMPER INNER RETAINER TOP | Cracked | 283.50 F | *195.35 FL |
| 14 | 1 | | *REAR BUMPER INNER LOCK SENSOR | Shorted | 266.60 F | *181.20 FL |
| 15 | 1 | | *REAR END PANEL | Repair | 1,019.20 F | *- FL |
| 16 | 1 | | *REAR EXHAUST MUFFLER | Not Necessary | 1,885.30 F | *- FL |
| 17 | 2 | | *TAILLAMPS | Not Necessary | 1,500.00 F | *- FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 12,460.52 | 2,718.55 |
| - List Item Discount on L Items 0.00/5.00% (\$\$) | 0.00 | 135.93 |
| Total Parts (\$\$) | 12,460.52 | 2,582.62 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|--|----------|------------|----------|
| Labour Items | | | | |
| 1 | TO CHECK WIRING | New | 80.00 | 30.00 |
| 2 | TO DISMENTLE & REPLACING PDC SENSOR | New | 100.00 | 60.00 |
| 3 | TO DISMENTLE & REFIX REAR WINDSCREEN | New | 150.00 | - |
| 4 | TO DISMENTLE & REFIX REAR EXHAUST | New | 150.00 | - |
| 5 | TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY | New | 150.00 | 80.00 |
| 6 | TO SPRAY RUST PROOFING | New | 100.00 | - |
| 7 | LABOUR FOR PANEL BEATING & REPLACING PARTS | New | 880.00 | 500.00 |
| 8 | TO PUTTY & SPRAY PAINTING | New | 1,280.00 | 500.00 |
| Gross Labour Cost (\$\$) | | | 2,890.00 | 1,170.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >