

INSURANCE

INS. CASE OWNER:

val
MRB

CC 4/AXA1801

3156, R. 08/1/18

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

14/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SIM 72571

Name of Insured:

TAN ANN ANN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

12/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MARCUS MO SHIM EWAN

Driver Tel No.:

(VAL YES / NO)

Claim No.:

88MOD081 58511

Policy No.:

UPA/PLANCON

Make / Model:

TOYOTA

Place of Accident:

BET TIMAH RU NEAR
KAMPUNG JAYA RD.

OI GIA REPORT (YES / NO)

TP GIA REPORT (YES / NO)

Insured Liability:

Final? Yes / No

517 4027c



INSRS:
WSP:
Tel:
Liability:
RMKS:

world
auto



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

20/1/18
18h10

517 4027c

517 4027c

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

EMAIL 12.9.18

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PBR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

29.8.18 + 3.08pm

CALLER DID CONFIRMED ACCIDENT. DID (CHANGED LANE AND HIT
TOYOTA. INFORM TO CLAIM. ADVISED TO SETTLE AND MOVE
ABOUT NCD ISSUE.

EMAIL WSP LIABILITY CLAIM.

RECEIVED 02 JAN 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 15.9.18

Confirm with: Sopha

Confirm by: WEP

Repair Cost:

44

SS1,450.00

(3 days) Reduction:

45

%

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 14.12.18

Confirm with: Sopha

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 15

If NO or B 28, Ass. Lia

Repair Cost:

nil

SS1,551.50

OID (CHANGED LANE HIT TP

Loss of Rental (LOR):

SS -

(1 days)

Loss of Use (LOU):

SS 180.00

(S 60 x 3 days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☐

LOU only ☒

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS -

(e.g. Tow/ Independent)

2) Report Format: TP

Legal Cost

SS -

3) Survey fee: 330

Total:

SS 1,733.50

Global Sum SS:

FINAL PAYMENT

Date/Time: 14.12.18

Confirm with: Sopha

Email ☒ Call ☐

Payee 1:

SS1,733.50

Name 1:

WORLD AUTO RE ID

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

CONFIRMED

ASSIGNMENTFrom: _____ Date: 19/7/18

Estimated Cost: _____

On: ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLJ 4027Cat Workshop m/s World Autoof No. 1 Krunji Loop

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bail. or Market Value: 80K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 4027C Yr Regn: 2016 / DMCType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel 1.5X c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 132879 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru31214803Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 3 mmD.O.A. 12/07/18 D.O.I. 20/07/18Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>4:50 - 1:45:00 (8:00 - 3:04:20 68:11)</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18013156/eb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 19-07-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 7257U	Veh. Inspected	SLJ 4027C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/07/2018	Inspection Date		
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000234

Date : 18/07/2018
 Vehicle Num. : SLJ 4027C (LCR) 2016 DEC
 Make/Model : HONDA VEZEL HYBRID Rn 31214003
 Chassis/Eng# :
 Accident Date : 12/07/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- LIST ITEMS :
- 1 REAR BUMPER
 - 1 REAR SIDE BUMPER - RH
 - 1 REAR BUMPER TAIL LAMP RH
 - 1 REAR WHEEL ARCH MOULDING - RH
 - 1 REAR COMPARTMENT BOX
 - 1 REAR BUMPER RETAINER RH
 - 1 REAR FENDER INNER TRIM BOARD RH

800 900.00 DE
 195 250.00 DE
 700.00 X SU
 218 250.00 DE
 280.00 X
 89.00
 345.00 X } SU

List Total S\$:
 20.00% Discount S\$:

2,814.00
 562.80
 2,251.20

- SPECIAL NETT ITEMS :
- 1 REAR BUMPER CLIP
 - 1 REAR TAILLAMP CLIPS
 - 1 REAR WHEEL ARCH MOULDING CLIPS
 - 1 REVERSE SENSOR
 - 1 REAR FENDER INNER TRIM BOARD CLIPS

40.00 DE
 40.00 X SU
 20 40.00 DE
 280.00 X } SU
 40.00 X

Special Nett Total S\$:

440.00

LABOUR :
 LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER
 REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
 PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

850.00 3000.00

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

1,000.00 400

Labour Total S\$:

1,850.00

E. & O.E.

Total S\$: 4,541.20

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resue
 Hp 90010068
 3 days
 4/5
 20/07/18 @ 1500
 Run after repair

Aclur

Celine Fong (LKKAuto)

From: tgttan@worldauto.com.sg
Sent: Friday, 12 October 2018 4:06 PM
To: Celine Fong (LKKAuto)
Subject: RE: OUTSTANDING CASES - Rasul - SLJ 4027C

Hi Celine

Finalised COR \$1450 (LUMP SUM) and 3 days of repairs.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

From: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Sent: Friday, 12 October 2018 11:07 AM
To: tgttan@worldauto.com.sg
Subject: RE: OUTSTANDING CASES - Rasul - SLJ 4027C

Dear Sophia,

Lump sum \$1,450.00, 3 days

Please check.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tgttan@worldauto.com.sg <tgttan@worldauto.com.sg>
Sent: Tuesday, 11 September 2018 5:56 PM
To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Subject: FW: OUTSTANDING CASES - Rasul

Hi Celine

Can assist these files for Rasul

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
143 Cecil Street #01-01 GB Building
069542

Attention : Motor Claim Department
Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000234

Date : 18/07/2018
Vehicle Num. : SLJ 4027C (LCR)
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 12/07/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|---------------------------------|--|--------|
| 1. | 1 | REAR BUMPER | | 900.00 |
| 2. | 1 | REAR SIDE BUMPER - RH | | 250.00 |
| 3. | 1 | REAR BUMPER TAIL LAMP RH | | 700.00 |
| 4. | 1 | REAR WHEEL ARCH MOULDING - RH | | 250.00 |
| 5. | 1 | REAR COMPARTMENT BOX | | 280.00 |
| 6. | 1 | REAR BUMPER RETAINER RH | | 89.00 |
| 7. | 1 | REAR FENDER INNER TRIM BOARD RH | | 345.00 |

List Total S\$:

20.00% Discount S\$:

900.00 ~~DE~~
250.00 ~~DE~~
700.00 X
250.00 ~~DE~~
280.00 X
89.00 ?
345.00 X

2,814.00

562.80

2,251.20

- | | | | | |
|----|---|------------------------------------|--|--------|
| 1. | 1 | REAR BUMPER CLIP | | 40.00 |
| 2. | 1 | REAR TAILLAMP CLIPS | | 40.00 |
| 3. | 1 | REAR WHEEL ARCH MOULDING CLIPS | | 40.00 |
| 4. | 1 | REVERSE SENSOR | | 280.00 |
| 5. | 1 | REAR FENDER INNER TRIM BOARD CLIPS | | 40.00 |

Special Nett Total S\$:

440.00

LABOUR :

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER
REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

850.00 ~~3000~~

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

1,000.00 ~~400~~

Labour Total S\$:

1,850.00

E. & O.E.

Total S\$: 4,541.20

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:
• To survey before/after spray painting
• To display damaged part(s) during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

~~Rene~~
Hp 90010068
3 days
4/5
20/07/18 @ 1500
Rene after repair



MANDATE REQUEST FOR S8M00OHR

File

Type

 Question

Message

Liability: Insured changed lane and hit third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$1,551.50 (w/GST) Loss of Use: \$180.00 (3days x \$60) LTA : \$2.00 Total: \$1,733.50 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (23/11/2018)

Reply



Re:MANDATE REQUEST FOR S8M00OHR

Type

🔗 Question

Message

Hi Pls proceed as per IA, thanks-VO

Reply



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

07/11/2018

Your Ref :

Our Ref : TP/2125/2018

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER

SINGAPORE 06811

Attn : Motor Claim Dept – Third Party

Dear Sirs,

ACCIDENT INVOLVING VEH.NO. SLJ4027C / SLM7257U ON 12/07/2018

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF PL)

Enclosed herewith are the following documents for your information and necessary actions only :-

a) Our Final Repair Bill

Please assist in our claims of :

Final Bill	\$	1450.00	(already finalised)
GST 7%	\$	101.50	
Search Fee	\$	2.00	
Loss of Use (\$60x 3 days)	\$	180.00	

Amount	\$	<u>1733.50</u>
--------	----	----------------

Kindly let us have your reply and payment as soon as possible.

Thank you for your kind attention and much appreciated assistance.

Yours faithfully,

A handwritten signature in black ink, appearing to be a stylized 'J' or 'L' followed by a flourish.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 12 September 2018 3:02 PM
To: ANNANN.TAN09@GMAIL.COM
Cc: MARCUSHO@GMAIL.COM
Subject: ACCIDENT INVOLVING SLM 7257U AND SLJ 4027C ALONG BUKIT TIMAH ROAD NEAR KAMPONG JAVA ROAD ON 12/07/2018

12 SEPT 2018

TAN ANN ANN

Dear Sir/ Mdm

OUR REF : CC4/ASM18013156/R1eb3
YOUR REF : SLM 7257U
ACCIDENT INVOLVING SLM 7257U AND SLJ 4027C ALONG BUKIT TIMAH ROAD NEAR KAMPONG JAVA ROAD ON 12/07/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s WORLD AUTO PTE LTD acting on behalf of the owner of SLJ 4027C against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had hit the Third Party vehicle SLJ 4027C. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORISATION

In the matter of the following accident:-

DATE OF ACCIDENT : 12-07-2018

CLIENT'S VEHICLE NO : SLJ4027C

PLACE OF ACCIDENT : BUKIT TIMAH ROAD

THIRD PARTY VEHICLE NO : SLM7257U

I/We, LCRF PTE LTD

ADDRESS: 29 PAYA LEBAR ROAD, PAYA LEBAR OFFICE CENTRE

UEN/NRIC/FIN NO : 201624597K

Tel. (O) _____ (H) _____ (MOBILE) _____

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us in respect of the above matter up to the final conclusion of the said matter.

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us for the purpose of negotiating and enter into settlement with the tortfeasor, their insurers or solicitors appointed by the tortfeasor/insurers without the need to commence action.

I/We hereby authorize World Auto Pte Ltd to receive on my/our behalf all settlement sums and disbursements including loss of use/rental to pay to yourselves all costs you may at any time receive in connection with the above mention matter.

DATED THIS 13TH DAY OF JULY YEAR 2018



Name: LCRF PTE LTD
UEN No: 201624597K



redefining / insurance

(LLKK)

CLAIM REF : S8M00OHR
INSURED : TAN ANN ANN

DISCHARGE VOUCHER

We/I [LCRF PTE LTD, NRIC NO. 201624597K] hereby agree to accept the sum of dollars [ONE THOUSAND SEVEN HUNDRED THIRTY THREE AND CENTS FIFTY ONLY.] [S\$1,733.50] paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SLM 7257U] as a result of an accident along [BUKIT TIMAH ROAD] on [12/07/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SUJ 4027C].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SLM 7257U] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SLM 7257U].

Dated this 10 day of December 2018

Claimant's Signature : _____

NRIC no./ Company Stamp : _____

Occupation/ Business : _____

Address : _____

Telephone No. : _____

Witness's Name : baseline Foong

Witness's Signature : [Signature]

Witness's NRIC No. : S200104F



WORLD AUTO PTE LTD
47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
S'PORE 577200
Tel No. : 64513933 Fax No. : 64557576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #24-01 AXA TOWER
S'PORE 068811

Attention : Motor Claim Department
Contact : 68804888 Fax No. : 68804838

Tax Invoice : F188902

Date : 05/11/2018
Vehicle Num. : SLJ 4027C
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 12/07/2018
Claim No. : TP/2125/2018
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LUMP SUM REPAIR		1,450.00
		Labour Total S\$:		1,450.00

Total S\$: 1,450.00
GST 7% S\$: 101.50
Amount Due S\$: 1,551.50
=====


WORLD AUTO PTE LTD

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-107640
Date of Request: 13/07/2018

Your Ref No: Online Purchase

World Auto Pte Ltd
47 Jln Pemimpin
#01-02/03 Halcyon 2
Singapore 577200

Dear Sir/Madam,

Enquiry Date: 13/07/2018
Enquiry By: Wong Yin Cheng
Vehicle No.: SLM7257U
Accident Date: 12/07/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLM7257U	AXA Insurance Pte Ltd	06/04/2017-05/04/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-107640
Date of Request: 13/07/2018

Your Ref No: Online Purchase

World Auto Pte Ltd
47 Jln Pemimpin
#01-02/03 Halcyon 2
Singapore 577200

Dear Sir/Madam,

Enquiry Date 13/07/2018
Enquiry By Wong Yin Cheng
Vehicle No. SLM7257U
Accident Date 12/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLM 7257U (Insd veh)	Model:	HONDA VEZEL 1.5X
	SLJ 4027C (TP veh)		
Date of Accident:	12/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,859.08
Final Repair Cost	:	\$	1,551.50
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	3days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	1,733.50

Is Third Party Workshop GIA Registered?		<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____100____(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	WORLD AUTO PTE LTD	:	\$ 1,733.50

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

03/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18013156/R1eb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Date : 03-01-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 7257U	Veh. Inspected	SLJ 4027C	
Policy No.	VPA/P1924021	Coverage (\$)	0.00	
Claim No.	S8M00OHR	Excess (\$)	0.00	
Assign From		Assign Date	19/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL 1.5X	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU31214803	Colour	BLUE	
Odometer	132879	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	5 mm	
L/H Front Tyre	215/60 R16	DUNLOP	5 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	5 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/07/2018	Inspection Date	20/07/2018	
Survey held at	1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 4027C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEFORMED	900.00	800.00
1	REAR SIDE BUMPER -RH (CONSISTENT)	DEFORMED	250.00	195.00
1	REAR BUMPER TAIL LAMP RH (CONSISTENT)	SERVICEABLE	700.00	-
1	REAR WHEEL ARCH MOULDING -RH (CONSISTENT)	DEFORMED	250.00	218.00
1	REAR COMPARTMENT BOX (CONSISTENT)	SERVICEABLE	280.00	-
1	REAR BUMPER RETAINER RH (CONSISTENT)	SERVICEABLE	89.00	-
1	REAR FENDER INNER TRIM BOARD RH (CONSISTENT)	SERVICEABLE	345.00	-
	LESS 20% DISCOUNT		-562.80	-242.60
			2,251.20	970.40
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR TAILLAMP CLIPS (SN) (CONSISTENT)	SERVICEABLE	40.00	-
1	REAR WHEEL ARCH MOULDING CLIPS (SN) (CONSISTENT)	NECESSARY	40.00	20.00
1	REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	280.00	-
1	REAR FENDER INNER TRIM BOARD CLIPS (SN) (CONSISTENT)	SERVICEABLE	40.00	-
			440.00	60.00
LABOUR				
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER REPAIRS INCLUDING PANEL BEAT ,CUT/WELD ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		850.00	400.00
	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		1,000.00	400.00
			-	-
			-	-
			-	-
			1,850.00	800.00
GRAND TOTAL			4,541.20	1,830.40

Report Ref No. CC4/ASM18013156/R1eb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00
---	--	--	----------

Report Ref No. CC4/ASM18013156/R1eb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.















No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	5840001-IR	
Reference	CC4/ASM18013156/R1-4302 	
Loss Date	12 July 2018	
Request Date	18 July 2018	
Due Date		
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)	
Type of Loss	Third Party Vehicle Damage	
Services	Pending verification - Direct Settlement	
Actions	<div>Next Step</div> <div>Wait for Approve Invoice</div> <div>Next Step</div>	
Vehicle Information	<div>Incident Vehicle Registration #</div> <div>SLH027C</div> <div>Make</div> <div>TPVD HONDA</div> <div>Model</div> <div>VEZEL-1.5 HYBRID (A)</div> <div>Service Address</div> <div>...</div>	
Primary Contact/Insured	<div>TAN ANN ANN</div> <div>21 TAN KIM CHENG ROAD, #12-21, 266621, Singapore</div> <div>91713703</div>	
Claim Handler	<div>OH Vale</div> <div>6568804897</div> <div>vale.oh@axa.com.sg</div>	

Additional instructions

Document Type	Document SubType	NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
<div> <div> <div></div> <div>Upload Documents</div> </div> </div>	<div> <div></div> <div></div> </div>		Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TPP)	9 January 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 LKKdischarge.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	9 January 2019
 LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	23 November 2018
 Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	23 November 2018
 LIA H&B CDE Rebate Details.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	23 November 2018
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	23 July 2018
 SLJ4027C TP GIA REPORT PDF	Reports & Statement	GIA Report	KATAN BHOSALE Phagati	18 July 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
■ SLM7257U INSD GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	18 July 2018
■ EMAIL RECEIVED FROM WORKSHOP.mig	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	18 July 2018
■ P1934021_GI_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	HO Winnie	14 July 2018