COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE'NO: SHD 3007X

MAKE

18/7/2018 12:59 CHMV

\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	AMOUNT 458.60 322.30 552.60 112.70 143.40 22.00 30.70 94.80 148.40 1,885.50 471.38 1,414.13
\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	322.30 552.60 112.70 143.40 22.00 30.70 94.80 148.40 1,885.50 471.38
\$ \$ \$ \$ \$ \$ \$ \$	552.60 112.70 143.40 22.00 30.70 94.80 148.40 1,885.50 471.38
\$ \$ \$ \$ \$ \$ \$	112.70 143.40 22.00 30.70 94.80 148.40 1,885.50 471.38
\$ \$ \$ \$ \$ \$	143.40 22.00 30.70 94.80 148.40 1,885.50 471.38
\$ \$ \$ \$	22.00 30.70 94.80 148.40 1,885.50 471.38
\$ \$ \$	30.70 94.80 148.40 1,885.50 471.38
\$ \$ \$	94.80 148.40 1,885.50 471.38
\$ \$ \$	1,885.50 471.38
\$	1,885.50 471.38
\$	471.38
	471.38
•	135.70
\$	50.00
	185.70
-	100.70
	280
\$	350.00
	20 6 250.00
1	× 50.00
	120.00
*	3 120.00
\$	770.00
,	
\$	2,369.83
/ey	
dice" basis	3
red <u>and</u> ce Compan	ıy
if	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.