

22/03/2001

ASS. REC. BY:

REF: CS/MSG18013168/

Krd32

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

Meinmen

Monica chung

of

MSIG

Date/Time:

19/7/18 @ 4:24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 9527Y

Insured:

GX 384

at Workshop m/s

Lim Yew Boo Spray paint

Tel:

6454 5011

of

Blk 10, Sin Ming Ind. Est # 01-10

9685 2332

Policy No:

28766247 MKC

Claim No:

564821

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

4:43pm @ 19/7/18

Person Contacted:

serene

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLN 9527Y - X	7/8/18 - VNI (scene)
	GX 384 - X	10/8/18 - VNI
2/7/18 -	vehicle not in	17/8/18 - She say will update me on 20/8/18
27/7/18 -	vehicle still not in called serene.	17/8/18 - vehicle still not in yet (she call back & up)
30/07/18 -	vehicle not in yet (scene)	08/11/18 - Pervert 1A thru meinmen
3/8/18 -	vehicle still not in yet (scene)	

ASS. REC. BY:

REF: *MSGL*

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Lim Yew Boo
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLN 95274 Yr Regn: 03, 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mazda 6 c.c. 1998
 Colour: M. Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 32292 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM8GL1071140707340
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rlm / STD A/Rlm or _____
 Tyre Size: F: 225/55R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 03 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 17/7/18 D.O.I. 28/8/18
 Survey held at _____
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>29/8</u>	<u>File pass to Catherine</u>
	<u>B1829.12 + supp</u>
	<u>(confirm with Serene \$1,445.12 @ 3 days (Red: \$1873.46, 56%))</u>

RECEIVED 09 NOV 2018

Date/Time, File Pass to? : Prell. Report
 1) typist : Final Report
 Date/Time, File Return to? _____
 2) _____
 Report Format: TP
 Lump Sum / I.B.I: (\$) 1445.12
 Days Of Repair: 3
 Resurvey No. of Trlp: (
 Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech Invs (\$))
 : Weekend (\$))
 Survey Fee: 150
 Transportation: _____ \$ + RS. _____ \$
 Photos _____
 Others 10
 TOTAL .160

[Signature]
9/11/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18013168/Krd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 19-07-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 38H	Veh. Inspected	SLN 9527Y
Policy No.	28766247MKC	Coverage (\$)	0.00
Claim No.	564821	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	19/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/07/2018	Inspection Date	28/08/2018
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 08 Nov 2018

Preliminary Advice

Insured Vehicle No	: GX38H	Accident Date	: 17/07/2018
TP Vehicle No	: SLN9527Y	Assignment Date	: 19/07/2018
Make	: MAZDA 6	Est. Duration of Repair	: 3.00
Date of Inspection	: 28/08/2018		
Inspection At	: LIM YEW BOO SPRAY PAINT CO (HQ) BLK 10 SIN MING INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,318.58
Revised Amount	:S\$	1,445.12
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,445.12
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2018		19 Jul 2018 16:24 <input type="button" value="Assign"/>				New Assignment <input type="button" value="Cancel Case"/>

Main	Reference	Claim Details	Documents	<input type="button" value="Show All"/>
------	-----------	---------------	-----------	---

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	Chian Chen Photographic Trading, Co. Reg. No.: 33253500B	
Main Claimant:	LEE ENG HOCK, ID: S1515366J	
Vehicle Reg. No.:	SLN9527Y	Date of Loss: 17/07/2018 18:00 - :59 [13 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 564821	Policy/Cover Note No.: 28766247MKC (TP, Fire & Theft) Coverage: 03/07/2017 - 02/01/2019
Vehicle Reg. No. (Insured):	GX38H	Policy No. (Claimant):
		Excess:
Repairer:	Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10, 575645 Sin Ming - Tel: 96852332	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/07/2018]	
Adj Asg. Remarks:	SJE Agree Please appoint Kenneth Kong from LKK and contact Serene LIM @ 64545011. Liability not clear	

ASSOCIATED MAIL RECEIVED	<input type="button" value="View All"/>	<input type="button" value="Compose Case Mail"/>
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>		<input type="button" value="View All"/>	<input type="button" value="Search Tasks"/>	<input type="button" value="Create New Task"/>	<input type="button" value="Complete"/>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, November 09, 2018 9:58 AM
To: Serene LIM; SUR
Cc: Kenneth Kong (LKKAuto)
Subject: RE: SLN9527Y MAZDA 6

Dear Serene,

Confirm \$1,445.12 @ 3 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Serene LIM [mailto:serene@autocare.com.sg]
Sent: Thursday, November 08, 2018 3:40 PM
To: SUR <sur@lkkauto.com>
Cc: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Subject: SLN9527Y MAZDA 6

Hi Janice

We spoke.

Attached supplementary for rivets necessary on frt nose panel – pls let Kenneth know

Regards
Serene@LYB

From: [Kenneth Kong \(LKKAuto\)](mailto:Kenneth Kong (LKKAuto))
Sent: Monday, November 05, 2018 9:55 AM
To: Serene LIM
Subject: RE: SLN9527Y MAZDA 6

Hi Serene, Mazda less 20% on parts. So total should be \$1429.12, please confirmed.

From: Serene LIM [mailto:serene@autocare.com.sg]
Sent: Friday, 21 September, 2018 11:01 AM
To: Kenneth Kong (LKKAuto)
Subject: Re: SLN9527Y MAZDA 6

Hi Kenneth

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5366J
Vehicle Details	
Vehicle No.:	SLN9527Y
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	PE20848533
Chassis No.:	JM6GL1071H0107340
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$23,067.00
Original Registration Date:	23 May 2017
First Registration Date:	23 May 2017
Transfer Count:	0
Actual ARF Paid:	\$24,294.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2027
PARF Rebate Amount:	\$18,220.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,414.00
COE Rebate Amount:	\$47,355.00
Total Rebate Amount:	\$65,575.00

The information contained herein is correct as at 05 Nov 2018

OK

for surveyor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2018 12:55
Date Of Accident	17/07/2018 18:00
Exact Location Of Accident	BLK 501 JURONG WEST ST 51 OSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN9527Y
Insured/Policyholder	
Name Of Registered Owner	LEE ENG HOCK
NRIC No	S1515366J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97326950
Alternative Phone No	OFFICE-97326950

Vehicle Particulars

Manufacturer	MAZDA
Model	6-2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	PARKED IN PARKING LOT
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099695829
Cover Note Number	

Driver

Name of Driver	LEE ENG HOCK
NRIC No	S1515366J
Date Of Birth	26/04/1954
Occupation	OUTDOOR
Date Of Driving Pass	12/09/1979
Driving Experience	38 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97326950
Fax Number	
Contact Number	OFFICE-97326950
EMail Address	NOEMAIL

Address	703 JURONG WEST STREET 71 \$07-104
Postcode	640703
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO. T/20180718/2054 ATTACHED

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR SHORIF
Phone Number	83607021
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX38H
Vehicle Make/Model/Colour	NISSAN/ VAN/ SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (ii) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
(Date & Name)



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:



**SINGAPORE
POLICE FORCE**



T/20180718/2054

1 of 3

Report No. T/20180718/2054

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/07/2018 12:09	Vide Report No.:	Station Diary No.: 86
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: LEE ENG HOCK		Address: APT BLK 703 JURONG WEST STREET 71 #07-104 SINGAPORE 640703	
ID Type / ID No.: NRIC NO / S1515366J		Contact No.: Home/Office:	Mobile: 97326950
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 64	Date of Birth: 26/04/1954	Type of Informant: Vehicle Owner
Race: Chinese		Language: English	Institution / School Name:
Occupation: Manager		Driving Licence Information: Class: 2B,2A,2,3,4	Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 17/07/2018 18:00	Type of Location: Car Park
Location: JURONG WEST STREET 51 Blk 501 OSCP				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GX38H	Van			Grey		0
SLN9527Y	Car			Blue	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/00L

MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING SINGAPORE 048581

Estimate : TP18/042

Attention : Motor Claim Department
 Contact : 62209644 Fax No. : 62257402

Date : 23/07/2018
 Vehicle Num. : SLN 9527Y
 Make/Model : MAZDA 6-2016
 Chassis/Eng# : JM6GL1071H0107340/PE20848533
 Accident Date : 17/07/2018
 Claim No. :
 Reference : LYB/SLN9527Y/MSIG/tp
 Policy No. :

*Not Authorized
 Recovery B4 paint
 81429-12*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT GRILLE BASE		114.80 <i>CM</i>
2.	2	FRONT GRILLE (BOTTOM)	137.70	275.40 <i>nn</i>
3.	1	FRONT EMBLEM		122.70 <i>mi</i>
4.	8	FRONT GRILLE SHORT CHROME	46.80	374.40 <i>nn</i>
5.	2	FRONT GRILLE LONG CHROME	75.20	150.40 <i>nl</i>
6.	1	FRONT NOSE PANEL		448.50 <i>Bul/nd</i>

List Total S\$: 1,486.20
 10.00% Discount S\$: 148.62
20%
 1,337.58

SPECIAL NETT ITEMS :				
1.	1	FRONT NO PLATE (EMBOSS) + HOLDER		55.00 <i>nd</i>
2.	2	FRONT SENSOR	283.00	566.00 <i>nd</i>

Special Nett Total S\$: 621.00

LABOUR :

TO CHECK & RECTIFY WIRING SYSTEM	15h	60.00
LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS	50h	80.00
TO RE-ALGN ON AFFECTED FRONT BUMPER, INNER PANEL, LABOUR TO REPLACE ABOVE RECOMMENDED PARTS.	250h	600.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/00L

MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 62209644 Fax No. : 62257402

Estimate : TP18/042

Date : 23/07/2018
 Vehicle Num. : SLN 9527Y
 Make/Model : MAZDA 6-2016
 Chassis/Eng# : JM6GL1071H0107340/PE20848533
 Accident Date : 17/07/2018
 Claim No. :
 Reference : LYB/SLN9527Y/MSIG/tp
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO PUTTY,PRIMER TO SPRAY ON FRONT BUMPER ASSY,NOSE PANEL, SENSOR USING 2K PAINTS.		400l 600.00
		Labour Total S\$:		1,340.00

	E. & O.E.	Total S\$:	3,298.58
			3316.58


 for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
Contact : 62209644 Fax No. : 62257402

Supplementary Estimate : SP18/042

Date : 08/11/2018
Vehicle Num. : SLN 9527Y
Make/Model : MAZDA 6-2016
Chassis/Eng# : JM6GL1071H0107340/PE20848533
Accident Date : 17/07/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	4	LIST ITEMS : RIVERT	5.00	20.00 <i>inc</i>
		List TotalS\$:		<u>20.00</u>



[Handwritten signature]

E. & O.E.

Total S\$: 20.00
=====

for LIM YEOW BOO SPRAY PAINT CO.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2018		19 Jul 2018 16:24 Edit Adj Rpt	S\$1,445.12 Edit Estimates	S\$1,445.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Chian Chen Photographic Trading, Co. Reg. No.: 33253500B								
Main Claimant:	LEE ENG HOCK, ID: S1515366J								
Vehicle Reg. No.:	SLN9527Y	Date of Loss:	17/07/2018 18:00 - :59 [13 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 564821	Policy/Cover Note No.:	28766247MKC (TP, Fire & Theft) Coverage: 03/07/2017 - 02/01/2019						
Vehicle Reg. No. (Insured):	GX38H	Policy No. (Claimant):							
		Excess:							
Repairer:	Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10, 575645 Sin Ming - Tel: 96852332								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/08/2018]								
Adj Asg. Remarks:	SJE Agree Please appoint Kenneth Kong from LKK and contact Serene LIM @ 64545011. Liability not clear								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN9527Y (564821)
[GX38H]
TP
LEE ENG HOCK
Jul 17 2018 6:00PM
[Chian Chen Photographic Trading]
Lim Yew Boo Spray Paint Co

Upload Documents		Upload Photos	Compose New Letter	View View in Browser
Assessment Reports				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	24/08/18 16:05	Accident Statement <small>From: SC - Reg. No: GX38H, Claimant: CHIAN CHEN PHOTOGRAPHIC TRADING</small>	1	Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	08/11/18 16:46	Adjuster Immediate Advice	1	Load HTM
Photos/Images				3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
2	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
3	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
4	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
5	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
6	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
7	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
8	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
9	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
10	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
11	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
12	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
13	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
14	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
15	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
16	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
17	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
18	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
19	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
20	09/11/18 10:02	General View	1	Load JPG <input checked="" type="checkbox"/>
21	09/11/18 10:07	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
22	09/11/18 10:07	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
23	09/11/18 10:07	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
24	09/11/18 10:07	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
Documentation				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	19/07/18 14:44	PRI & SJE AGREE - LKK	1	Load PDF
2	19/07/18 14:44	Third Party Accident Report	1	Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	13/11/18 16:37	Supplementary	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013168/KRD3E2

Date: 13/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 28766247MKC
Claimant Vehicle No : SLN9527Y	Insured Vehicle No : GX38H
Date of Loss: 17/07/2018	Nature of Claim: TP
	Claim No: 564821

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN9527Y	Engine No:	PE20848533
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GL1071H0107340
Reg. Date:	23/05/2017 (Man. Year: 2016)	Odometer:	32292 km
Colour:	Metallic Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,976.58	730.12	1,246.46	63.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	715.00	625.00	46.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,316.58	1,445.12	1,871.46	56.43

INSPECTION

Date of Assignment:	19/07/2018	
Date Inspected:	28/08/2018	Inspected At: Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10 Singapore 575645
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2018)
Parts: 143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN9527Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE BASE	Cracked	114.80 FL	*114.80 FL
2	2		*FRONT GRILLE (BOTTOM)	Not Necessary	275.40 FL	*- FL
3	1		*FRONT EMBLEM	Missing	122.70 FL	*122.70 FL
4	8		*FRONT GRILLE SHORT CHROME	Not Necessary	374.40 FL	*- FL
5	2		*FRONT GRILLE LONG CHROME	N/s Necessary/O/s Cracked	150.40 FL	*150.40 FL
6	1		*FRONT NOSE PANEL	Buckled/Dented	448.50 FL	*448.50 FL
7	1		*FRONT NO PLATE (EMBOSS)+HOLDER	Dented	55.00 FS	*45.00 FS
8	2		*FRONT SENSOR	Serviceable	566.00 FS	*- FS
9	4		*RIVERT	Necessary	20.00 FL	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,127.20	901.40
- List Item Discount on L Items 10.00/20.00% (S\$)	150.62	171.28
Total Parts (S\$)	1,976.58	730.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK & RECTIFY WIRING SYSTEM	New	60.00	15.00
2	LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS	New	80.00	50.00
3	TO RE-ALIGN ON AFFECTED FRONT BUMPER,INNER PANEL LABOUR TO REPLACE ABOVE RECOMMENDED PARTS	New	600.00	250.00
4	TO PUTTY,PRIMER TO SPRAY ON FRONT BUMPER ASSY,NOSE PANEL,SENSOR USING 2K PAINTS	New	600.00	400.00
Gross Labour Cost (\$\$)			1,340.00	715.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >