

Version

INS. CASE OWNER:

THE GINOW WAI

CC 4 UP / ATG1801

3207, G

LKE

IDAC

Surveyor:

XGQ

DOE

ASSIGNMENT

W/3/18

Date / Time:

14/7/18

Registered in Merimen:

20/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUF 1A760

Name of Insured:

UP

Insured Tel No.:

HP:

Excess Sec II : S\$

D.O.A.:

11/4/18

Is driver the owner?

(YES / ☒)

Nature of Accident:

If NO, Driver Name / Age: MUN KIN WFI

Driver Tel No.:

(V/L: ☒ YES / NO)

Claim No.:

8627206154

Policy No.:

944AAG050

Make / Model:

HOLDEN

Place of Accident:

WILLOW RD

OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO

Insured Liability:

% Final ? Yes / No

FBM 561AR



INSRS:

WSP:

Tel:

Liability:

RMKS:

The

Ginow

96208307

WILLOW



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

24/7/18
900

FBM 561AR - Y

SUF 1A760 - Y

OLD - U - TURNING
TP - STRAIGHT.

- MINA 561AR
- TP LOD IN BY EMAIL

19-7-19

EMAIL TO AIG FOR INSTRUCTION.

09/08/19

- SEND ACCEPTANCE EMAIL TO TP
- IN IN. ALL DOCS IN ORDER.

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call Of:

JOY 27-7-18

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup):

After call hr to OI: ☒

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

ETA / CIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Confirm by:

Email ☐ Call ☐

Confirm by:

Email ☒ Call ☐

If NO or B 28, Ass. Lia:

COLO U-TURN

12/8/19

1) Claim status: ☒ Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 320.00

4) Survey fee:

5) Survey fee:

6) Survey fee:

7) Survey fee:

8) Survey fee:

9) Survey fee:

10) Survey fee:

11) Survey fee:

12) Survey fee:

13) Survey fee:

14) Survey fee:

15) Survey fee:

16) Survey fee:

17) Survey fee:

18) Survey fee:

19) Survey fee:

20) Survey fee:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost: ☒

S\$ 3,325.00

5 days Reduction:

24

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

10/09/19

Confirm with:

10/09/19

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No. : 119

Repair Cost:

S\$ 3,325.00

Loss of Rental (LOR):

S\$

—

(days)

Loss of Use (LOU):

S\$

100.00

20 x 5

days

Loss of Income (LOI):

S\$

—

(5 x days)

LOR only ☐ LOU only ☒

LOR + LOU ☐

LOR + LO ☐

[Tick only one]

GIA/LTA Search

S\$

—

Medical:

S\$

—

Disbursement:

S\$

—

(e.g. Tow/Independent)

Legal Cost

S\$

—

Total:

S\$ 3,325.00

Global Sum S\$:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

3,325.00

Name 1:

THE GINOW MOTOR REPAIRING PTE LTD

Payee 2: (Strike if N.A.)

S\$

—

Name 2:

—

Payee 3: (Strike if N.A.)

S\$

—

Name 3:

—

(08/11/13) waf

ASS. REC. BY: Xel

REF:

AIG

ASSIGNMENT

From: _____ Date: 20/7/18

Estimated Cost: _____

ON / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBM 5619Rat Workshop m/s S. H. Cycle (Sincere motor Repairing)of 20 Shaw Rd # 01-03 Ching Shire Ind.Insured: Building

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or NoCA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFBM5619RYr Regn: 13 Dec 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Jupiter c.c. 114Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 3780 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3UE1120HJ144028Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 20/90-17R: 80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ARC

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 20-07-18Survey held at w/sDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orand

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

File \$3,225.60
(Job: \$1,019.60 / 24%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/LCR18013207/Gjb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 20-07-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 1976D	Veh. Inspected	FBM 5619R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/04/2018	Inspection Date	20/07/2018
Survey held at	THE SINCERE MOTOR REPAIRING PL 20 SHAW ROAD #01-03 CHING SHINE INDUSTRIAL BUILDING SINGAPORE 367956		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

THE SINCERE MOTOR REPAIRING PTE LTD

20 Shaw Road #01-03 Ching Shine Industrial Building Singapore 367956

Tel: 6383 2767 Fax: 6296 4548

Company Registration Certificate: 200720671G

Date : 29 June 2018

OUR REF: ACCQ1806009

S H CYCLE PTE LTD

20 SHAW ROAD #01-03

CHING SHINE INDUSTRIAL BUILDING

SINGAPORE 367956

RE : ESTIMATED COST TO REPAIR YAMAHA JUPITER

VEHICLE NO : FBM5619R

DATE OF ACCIDENT : 11 April 2018 @2000 Hrs

LOCATION: GHIM MOH ROAD

LKK Auto Consultants hence notify
Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Third party survey is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5 Days .

part by part .

before paint photos.

After ~~part~~ repair photos.

Guo Qiang - 82880282

20/7/18

S/NO	UNIT	DESCRIPTION	U/PRICE	AMOUNT
1	1	HANDLE BAR NIPPLE (LH/RH) - Cut	\$ 18.00	\$ 18.00 -
2	2	FRONT SIGNAL ASSY (LH/RH) - C&A	\$ 79.00	\$ 158.00 -
3	1	HANDLE BAR - BT	\$ 115.00	\$ 115.00 -
4	1	HANDLE BAR 'Y' BRACKET - BT	\$ 135.00	\$ 135.00 -
5	1	HANDLE BAR TOP COVER - Cut	\$ 88.00	\$ 88.00 -
6	1	HANDLE BAR FRONT COVER - Cut	\$ 65.00	\$ 65.00 -
7	1	HANDLE BAR REAR COVER - Cut	\$ 90.00	\$ 90.00 -
8	1	FRONT MUDGUARD - Cut & ee	\$ 95.00	\$ 95.00 -
9	1	METER ASSY TOP COVER - Cut	\$ 70.00	\$ 70.00 -
10	1	HEAD LAMP ASSY - SER	\$ 95.00	\$ 95.00 -
11	1	BRAKE LEVER X NM	\$ 29.00	\$ 29.00
12	1	FRONT FENDER - Cut	\$ 122.00	\$ 122.00 -
13	1	FRONT SHIELD - C&A	\$ 270.00	\$ 270.00 -
14	1	FRONT SHIELD BRACKET - BT	\$ 120.00	\$ 120.00 -
15	2	FRONT FORK ASSY - BT	\$ 320.00	\$ 640.00 -
16	1	STEERING STEM WITH BEARING - Cut & ee	\$ 195.00	\$ 195.00 -
17	1	EXHAUST HEAT SHIELD - Cut	\$ 68.00	\$ 68.00 -
18	1	MAIN PIPE COVER CENTRE COVER - SER? X NM	\$ 115.00	\$ 115.00
19	2	LOWER SIDE COVER (LH/RH) - Cut	\$ 57.00	\$ 114.00 -
20	2	LOWER SIDE COVER PANEL (LH/RH) - C&A	\$ 42.00	\$ 84.00 -
21	2	FRONT INNER LEG SHIELD (LH/RH) - Cut	\$ 55.00	\$ 110.00 -
22	1	REAR SHIELD - BR	\$ 212.00	\$ 212.00 -
				\$ 3,008.00
LESS 10 % DISCOUNT				\$ 300.80
				\$ 2,707.20
23	1	FRONT NUMBER PLATE - BT	\$ 15.00	\$ 15.00 -
24	1	FRONT NUMBER PLATE BRACKET - BT	\$ 18.00	\$ 18.00 -
25	1	FRONT 'P' PLATE - ee	\$ 15.00	\$ 15.00 -
26		TO RE-SPRAY CHARGE	\$	\$ 600.00 380 -
27		TO STRAIGHTEN CHASSIS - photo & invoice.	\$	\$ 450.00 ?X
28		TO DISMANTLE & ASSEMBLE PARTS FOR REPAIR	\$	\$ 380.00 180 -
29		TOWING VEHICLE TO WORKSHOP	\$	\$ 60.00 40 -
TOTAL AMOUNT :				\$ 4,245.20



Subject: AIG Ref: 8637220621SG003 / Your Ref: CC4/LCR18013207/Gjb3

Dear Joy,

Kindly advise status for this matter and upload survey report/photographs in Merimen.

Thank you.

Tee Chee Wah

AIG

Complex Claims Examiner

Claims Department

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1089

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	FBM5619R
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	YAMAHA
Vehicle Model :	JUPITER 115 Z1
Chassis No. :	MH3UE1120HJ144028
Propellant :	Petrol
Engine No. :	E3R5E0152257
Engine Capacity :	114 cc
Maximum Power Output :	-
Maximum Laden Weight :	223 kg
Unladen Weight :	98 kg
Year Of Manufacture :	2017
Original Registration Date :	13 Dec 2017
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
Quota Premium :	\$6,101.00
COE Expiry Date :	12 Dec 2027
Road Tax Expiry Date :	12 Dec 2018
Inspection Due Date :	12 Dec 2020
Intended Transfer Date :	23 Jul 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	
Amount Payable	

Pre repair inspection request - FBM5619R VS SLF1976D (OI) DOA 11/04/2018

From: Mithoosingh, Aashweenjeetkaur

To: admin-a@lkaauto.com; assignments@lkaauto.com

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim; Noor Mariesa; Md Ishak; Mohd Imran; Lim, Sheng Yang; Supramaniam; Darshene; Azlan; Syazairdina; Chan, Yoke Shi

Sent: 18/7/2018 3:23:08 PM

Attachments:  tmoMSB.Td

Hi,

Please refer to the enclosed request from **S. H. CYCLE PTE LTD.**

Claim no: 86372206215G003

Case Owner: CHEE WAH TEE

If you have any queries/concerns, please let us know.

Kindly assist to assign **Xing Guo Qiang** as **Single Joint Expert** as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Angeline [mailto:shcycle@singnet.com.sg]

Sent: Thursday, July 19, 2018 2:55 PM

To: Mithoosingh, Aashweenjeetkaur

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim; Noor Mariesa; Md Ishak; Mohd Imran; Lim, Sheng Yang; Supramaniam; Darshene; Azlan; Syazairdina; Chan, Yoke Shi

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF1976D AND FBM5619R ON 11/04/2018

Dear Aashween,

We agreed with your arrangement.

Please appoint **Xing Guo Qiang** from **LKK Auto Consultants Pte Ltd** to survey the vehicle in our workshop.

Regards

Angeline

From: Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>

Sent: Wednesday, 18 July 2018 4:03 PM

To: shcycle@singnet.com.sg

Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF1976D AND FBM5619R ON 11/04/2018

Without Prejudice

Your Reference: FBM5619R

Our Reference: 86372206215G003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohammad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

3:39pm @ 19/7/18
person @ Angeline
vehicle in
amerge on 20/7/18

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashwrajit Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

18 July 2018

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Dear sir,

Accident on
Location
Involving

11 April 2018 @2000 Hrs
GHIM MOH ROAD
FBM5619R AND SLF1976D

We are giving you notice of the above-mentioned accident involving our Vehicle No. FBM5619R and Vehicle No. SLF1976D insured by your company.

As the accident was caused solely by the negligence of your insured, we hold your company fully responsible for all the damages sustained by us as a result of the said accident.

We would appreciate if you could call us to arrange for the survey of the vehicle. Our vehicle is now lying at:-

M/s. The Sincere Motor Repairing Pte Ltd
20 Shaw Road #01-03
Ching Shine Industrial Building
Singapore 367956ADN
Tel: 6383 2767
Fax: 6296 4548

If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance Company.

Your kind co-operation in this respect will be very much appreciated.

Yours faithfully,


Angeline Tan



星發車行私人有限公司
S. H. CYCLE PTE LTD

Co. Reg. No.: A200000420C

20 Shaw Road #01-03 Ching Shine Industrial Building Singapore 367956
Tel: +65 6299 8782 Fax: +65 6296 4548 E-mail: shcycle@singnet.com.sg

9 September 2019

Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

Dear Sir,

Accident Involving FB M5619R AND SLF1976D
Along GHIM MOH ROAD On 11 April 2018 @2000 HRS

We are the owner of Vehicle No. F8M5619R which was involved in the above mentioned accident.

Our vehicle sustained damages as a result of the above said accident and we are now claiming against you for the following:-

1	Cost of Repair		\$ 3,225.60
2	Loss of Use	5 days x \$20	\$ 100.00
3	Survey Report Fee		\$
Total			\$ 3,325.60

Please advise whether you are now prepare to settle our claims as outlined above.

We authorize our Repairer, THE SINCERE MOTOR REPAIRING PTE LTD or their representative to negotiate /comprise settlement on our behalf. If there is a settlement, we further authorize you to pay whatever settlement sum to our repairer being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours truly,


S. H. CYCLE PTE LTD

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 27 July 2018 5:15 PM
To: Eileen Yap
Cc: Admin A; Vivian Lau (LKKAuto); Hsiao Tong (LKKAuto)
Subject: ACCIDENT INVOLVING SLF 1976D & FBM 5619R ON 11/04/2018 (20:00) ALONG HOLLAND AVE/CLOSE

27 July 2018

LCRF PTE LTD

Policy Holder

Your Ref: SLF 1976D
Our Ref: CC4/LCR18013207/Gjb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 1976D & FBM 5619R ON 11/04/2018 (20:00) ALONG HOLLAND AVE/CLOSE

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **FBM 5619R** against your insurance policy.

Based on the information on hand, we are of the opinion that we cannot be absolved from liability. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORITY

ACCIDENT INVOLVING
ALONG
ON

FBM5619R and SLF1976D

GHIM MOH ROAD

11 April 2018 @2000 Hrs

BY THE LETTER OF

AUTHORITY, WE

S. H. CYCLE PTE LTD

THE OWNER OF VEHICLE NO.

FBM5619R

Hereby irrevocably appoint M/s. **THE SINCERE MOTOR REPAIRING PTE LTD of 20 Shaw Road #01-03 Ching Shine Industrial Building Singapore 367956** and/or their representative to process the Third Party claim on my/our behalf and to do all and/or any of the followings

1. To submit , negotiate/comprise and to resolve settlements of my/our above mentioned claim
2. To collect payments (s) due in respect of any such claim (s) for the loss and damage, such payment to be made by way of cheque in favour of THE SINCERE MOTOR REPAIRING PTE LTD
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever as they deem necessary for the purpose of settling my/our said claim.

I/We hereby declare that all processing and documents done by virtue of this letter of authority on my/our behalf by my/our repairers of any person authorized by them shall be as good valid and effectual to all intends and purposes whatsoever as if the same had been done or executed by me/us in person.

I/We further confirm that the acceptance by M/s. THE SINCERE MOTOR REPAIRING PTE LTD of the settlement amount constitute the full discharge of my/our claim (s) in respect of the above accident.

Signed on 20 (day) Apr (Month) 2019 (Year)



星發車行
私人有限公司
S. H. CYCLE PTE LTD
20 SHAW ROAD #01-03
CHING SHINE INDUSTRIAL BUILDING
SINGAPORE 367956
TEL: 6299 8782 FAX: 6296 4548

Acknowledge by the Owner
(company stamp if applicable)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **THE SINCERE MOTOR REPAIRING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,225.60** (Repair Cost), **S\$100.00** (Loss of Rental/Use), **S\$ -** (Disbursement), for vehicle no. **FBM 5619R** that was damaged pursuant to the accident which occurred on **11/04/2018** (date) along **HOLLAND AVENUE** (location) involving vehicle no/s **SLF 1976D**. This is pursuant to the inspection conducted on **20/07/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **S.H. CYCLE PTE LTD** ("the third party claimant") of vehicle no. **FBM 5619R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **FBM 5619R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10th (day) of Sept (month) **2019** (year)

 XGQ
Signed by appointed surveyor


Signed by "the workshop" (with chop)

THE SINCERE MOTOR REPAIRING PTE LTD

20 Shaw Road #01-03 Ching Shine Industrial Building Singapore 367956

Tel: 6383 2767 Fax: 6296 4548

Company Registration Certificate: 200720671G

S. H. CYCLE PTE LTD
20 SHAW ROAD #01-03
SINGAPORE 367956

INVOICE NO SMR19090005

DATE 9-Sep-19

VEHICLE NO FBM5619R

S/NO	UNIT	DESCRIPTION	U/PRICE	AMOUNT
Date of Accident: 11 April 2018 @2000 Hrs				
Location: Ghim Moh Road				
Involving FBM5619R and SLP1976D				
1		HANDLE BAR NIPPLE (LH)	\$	18.00
1		HANDLE BAR	\$	115.00
1		FRONT FENDER	\$	122.00
1		HANDLE BAR TOP COVER	\$	88.00
1		HANDLE BAR FRONT COVER	\$	65.00
1		HANDLE BAR REAR COVER	\$	90.00
1		HEAD LAMP ASSY	\$	95.00
1		HANDLE BAR 'Y' BRACKET	\$	135.00
1		FRONT MUDGUARD	\$	95.00
2		FRONT SIGNAL ASSY (LH/RH)	\$ 79.00	158.00
1		METER ASSY TOP COVER	\$	70.00
1		EXHAUST HEAT SHIELD	\$	68.00
1		FRONT SHIELD	\$	270.00
1		FRONT SHIELD BRACKET	\$	120.00
2		FRONT FORK ASSY (LH/RH)	\$ 320.00	640.00
1		STEERING STEM WITH BEARING	\$	195.00
1		REAR SHIELD	\$	212.00
2		LOWER SIDE COVER (LH/RH)	\$ 57.00	114.00
2		LOWER SIDE COVER PANEL (LH/RH)	\$ 42.00	84.00
2		FRONT INNER LEG SHIELD (LH/RH)	\$ 55.00	110.00
				\$ 2,864.00
LESS 10% DISCOUNT				\$ 286.40
				\$ 2,577.60
1		FRONT 'F' PLATE	\$	15.00
1		NUMBER PLATE	\$	15.00
1		NUMBER PLATE BRACKET	\$	18.00
RESPRAY CHARGE				\$ 380.00
TO DISMANTLE AND ASSEMBLE PARTS				\$ 180.00
TOWING VEHICLE				\$ 40.00
				\$ 3,225.60

SINGAPORE DOLLARS: THREE THOUSAND TWO HUNDRED TWENTY FIVE AND CENTS SIXTY ONLY

RECEIVED GOODS IN GOOD CONDITION

CUSTOMER'S SIGNATURE & DATE

THE SINCERE MOTOR REPAIRING P L

AUTHORISED SIGNATURE



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Apr 2018 Edit Reg		19 Jul 2018 00:00 Edit Adj Rpt	\$53,225.60 Edit Estimates	\$53,225.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]		
Insured:	LCRF Pte Ltd, Co. Reg. No.: NA					
Main Claimant:	S.H. CYCLE PTE LTD, Co. Reg. No.: 20000420C					
Vehicle Reg. No.:	FBM5619R	Date of Loss:	11/04/2018 20:00 - :59 [3 Months and 29 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / 8637220621SG	Policy/Cover Note No.:	0999994813 (Comprehensive)			
Vehicle Reg. No. (Insured):	SLF1976D	Policy No. (Claimant):	SD18V00326			
		Excess:				
Repairer:	The Sincere Motor Repairing Pte Ltd (Shaw Road) 20 Shaw Road #01-03, Ching Shine Industrial Building, 367956 Seletar - Tel: 63832767					
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com					
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/07/2018]					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBM5619R (8637220621SG)
[SLF1976D]**







































TP

S.H. CYCLE PTE LTD

Apr 11 2018 8:00PM

[LCRF Pte Ltd]

The Sincere Motor Repairing Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser <input type="button" value="v"/>	
Letters/Correspondences			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/07/18 08:52	Accident Statement <small>From: SC - Reg. No: SLF1976D, Claimant: LCRF PTE LTD</small>	 Load HTM	
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
2	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
3	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
4	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
5	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
6	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
7	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
8	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
9	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
10	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
11	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
12	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
13	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
14	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
15	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
16	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
17	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
18	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
19	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
20	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
21	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
22	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
23	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
24	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
25	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
26	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
27	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
28	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
29	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
30	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
31	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
32	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
33	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
34	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
35	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	
36	19/07/19 11:32	General View	 Load JPG <input checked="" type="checkbox"/>	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
37	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	19/07/19 11:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	19/07/19 11:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	19/07/19 11:33	General View	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/07/18 14:04	EMAIL FROM AIG DD 19072018	1	Load PDF	
2	20/07/18 14:04	NOTICE & GIA REPORT	1	Load PDF	
3	23/07/18 19:37	TP ESTIMATE- MARKED	1	Load PDF	
4	27/07/18 17:16	LETTER TO LCRF	1	Load PDF	
5	13/09/19 07:44	WORKSHOP INVOICE	1	Load PDF	
6	13/09/19 07:44	AUTHORISATION TO ACT FORM	1	Load PDF	
7	13/09/19 07:44	Release Voucher	1	Load PDF	
8	13/09/19 07:44	LOD	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div></div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF1976D (Insd veh)	Model:	YAMAHA JUPITER 115 Z1
	FBM5619R (TP veh)		114CC
Date of Accident:	11/04/2018		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	4,245.20
Final Repair Cost	: \$	3,225.60
Loss of Use	: \$	100.00
Rental (if any)	: \$	0.00
LTA / GIA Search Fee	: \$	0.00
Others:	: \$	0.00
	: \$	
Final Settlement Sum	: \$	3,325.60

5.00 days at \$20.00 per day
days

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	The Sincere Motor Repairing Pte Ltd	: \$	3,325.60
2)		: \$	

JOANNE LEE KHANG MIN

13 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18013207/GHB3Q2

Date: 13/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994813

Claimant Vehicle No : FBM5619R Insured Vehicle No : SLF1976D

Date of Loss: 11/04/2018 Nature of Claim: TP Claim No: 8637220621SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM5619R**
 Make & Model: YAMAHA JUPITER 115 Z1, 114cc Engine No: E3R5E0152257
 Reg. Date: 13/12/2017 (Man. Year: 2017) Chassis No: MH3UE1120HJ144028
 Colour: Blue Odometer: 3780 km
 Engine Capacity: 114 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17
 Front Left Side: ARC 6 mm Rear Left Side: ARC 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,755.20	2,625.60	129.60	4.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	600.00	890.00	59.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,245.20	3,225.60	1,019.60	24.02
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
Nett Liability (S\$)		3,325.60		

INSPECTION

Date of Assignment: 19/07/2018

Date Inspected: 20/07/2018 Inspected At:

The Sincere Motor Repairing Pte Ltd
 (Shaw Road)
 20 Shaw Road #01-03, Ching Shine
 Industrial Building
 Singapore 367956

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HANDLE BAR NIPPLE (LH/RH)	Cut	18.00 FL	*18.00 FL
2	2		*FRONT SIGNAL ASSY (LH/RH)	Cracked	158.00 FL	*158.00 FL
3	1		*HANDLE BAR	Bent	115.00 FL	*115.00 FL
4	1		*HANDLE BAR Y BRACKET	Bent	135.00 FL	*135.00 FL
5	1		*HANDLE BAR TOP COVER	Cut	88.00 FL	*88.00 FL
6	1		*HANDLE BAR FRONT COVER	Cut	65.00 FL	*65.00 FL
7	1		*HANDLE BAR REAR COVER	Cut	90.00 FL	*90.00 FL
8	1		*FRONT MUDGUARD	Deformed	95.00 FL	*95.00 FL
9	1		*METER ASSY TOP COVER	Cut	70.00 FL	*70.00 FL
10	1		*HEAD LAMP ASSY	Scratched	95.00 FL	*95.00 FL
11	1		*BRAKE LEVER	Not Necessary	29.00 FL	*- FL
12	1		*FRONT FENDER	Cut	122.00 FL	*122.00 FL
13	1		*FRONT SHIELD	Cracked	270.00 FL	*270.00 FL
14	1		*FRONT SHIELD BRACKET	Bent	120.00 FL	*120.00 FL
15	2		*FRONT FORK ASSY	Bent	640.00 FL	*640.00 FL
16	1		*STEERING STEM WITH BEARING	Necessary	195.00 FL	*195.00 FL
17	1		*EXHAUST HEAT SHIELD	Cut	68.00 FL	*68.00 FL
18	1		*MAIN PIPE COVER CENTRE COVER	Not Necessary	115.00 FL	*- FL
19	2		*LOWER SIDE COVER (LH/RH)	Cracked	114.00 FL	*114.00 FL
20	2		*LOWER SIDE COVER PANEL (LH/RH)	Cracked	84.00 FL	*84.00 FL
21	2		*FRONT INNER LEG SHIELD (LH/RH)	Cracked	110.00 FL	*110.00 FL
22	1		*REAR SHIELD	Broken	212.00 FL	*212.00 FL
23	1		*FRONT NUMBER PLATE	Bent	15.00 FS	*15.00 FS
24	1		*FRONT NUMBER PLATE BRACKET	Bent	18.00 FS	*18.00 FS
25	1		*FRONT P PLATE	Deformed	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,056.00	2,912.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	300.80	286.40
Total Parts (\$\$)	2,755.20	2,625.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RE-SPRAY CHARGE	New	600.00	380.00
2	TO STRAIGHTEN CHASSIS	New	450.00	0.00
3	TO DISMANTLE & ASSEMBLE PARTS FOR REPAIR	New	380.00	180.00
4	TOWING VEHICLE TO WORKSHOP	New	60.00	40.00
Gross Labour Cost (S\$)			1,490.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >