

 SERVICE REQUESTSMESSAGESCLAIMS

Claim	S8M00OST
Reference	CC4/ASM18013214/R1ha3s2 
Loss Date	July 17, 2018
Request Date	July 19, 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #	SKT8926R
Make	TPVD MINI
Model	MINI COOPER F55

Service Address

''

Primary Contact/Insured

SOON HUA BEE PTE LTD
BLK 201E TAMPINES STREET 23, #04-100,
527201, Singapore
63380083

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions TP-EUOKAS VIRTUAL ACC please do not finalise repair. Kindly conduct PRI only.

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document TypeDocument SubType + Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
 LKKInvoice1[2].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	December 26, 2018		
 LKKAdjustment1a[2].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	December 26, 2018		
 LKKInspection[3].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	December 26, 2018		
 Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018		
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018		
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018		
 XE2114G INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	July 19, 2018		

English (default) ▾		LKK AUTO CONSULTANTS PTE LTD (TP) ▾		SUB-TYPE	AUTHOR	DATE UPLOADED
 SERVICE REQUESTS MESSAGES CLAIMS				GIA Report	DHAKAL Raghav	July 19, 2018
 TP EUOKAS-PRI RECEIVED FROM WORKSHOP WITH ESTIMATE.msg		Letters and Correspondence		Workshop	DHAKAL Raghav	July 19, 2018