

Haley

CC4, AXA 180 13278, KKA30

Surveyor:

Kenneth

DOI:

ASSIGNMENT

19/7/18

Date / Time:

19/7/18

Registered in Meriton:

19/7/18

Pre-Assign / CCU / FTE



Insured Vehicle No.:

SHD 2002

Name of Insured:

TRANS-CAB SERVICES P/L

Insured Tel No.:

HP:

Claim No.:

Policy No.:

VPA/PL680520

Make / Model:

R- Latitude

Excess Sec II :SS

D.O.A.:

14/7/2018

Place of Accident:

PARK RUS DR 1

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LOH cheng wanh

OI GIA REPORT: YES / NO, TP GIA REPORT: YES / NO

Driver Tel No.:

98860909 (V/L: YES / NO)

Insured Liability: %

Final? Yes / No

SL5 48206



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

25/7/18

SL5 48206 - X;

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

31/7/18 email. Vivian

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

24/7/18

Sent By:

John Wau only 1

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Kenneth

Repair Cost:

PR

S\$ 975.07

(3 days)

Reduction:

2180.01

% 56

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

6/7/19/9:00am

Confirm with:

CARMEN

Email ☐Call ☐

Final Liability:

S\$ 1845.82

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

W/AST

S\$ 1845.82

Loss of Rental (LOR):

S\$ 404.75

(5 days)

x 480.45 (W/AST)

Loss of Use (LOU):

S\$ -

(5 x days)

Loss of Income (LOI):

S\$ -

(5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/Independent)

Legal Cost

S\$ -

Total:

S\$ 2258.02

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$ 2258.02

Name 1:

Estern Performance pte ltd

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$250/-

ASS. REC. BY:

REF: TP/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B. / % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLS 48206 Yr Regn: 09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius cc 1780

Colour: M. P. White A/C: Insured / Std / NI / NA

Sp. Reading: 62542 T/Radio: Insured / Std / NI / NA

Eng/No: 3

C/No: JTDKBFU303571589

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: Westlake 195/65R15

Yoko R: Fatter

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 19/7/18

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 19/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/tp or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/7 File pass to Catherine

PR = 4175-07 with 3 repair days.

(Rpt = 4175-01 / 56%)

+ 3 repair days + 1 Sunday + 1 PRG = 5 days

Data/Time, File Pass to?

☐ : Prell. Report

1)

Data/Time, File Return to?

☐ : Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - St

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLS 4820 G

*Not Authorized
1.B.1
Resurvey B&P only*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Parts	(a) Cost / List Price Items	\$	3,180.10
	Plus/Less 25%	\$	795.03
	Total of Cost / List	\$	2,385.08
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	2,585.08
Labour		\$	1,320.00
Total		\$	3,905.08

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennerly
Company : CLK
Survey conducted on : 19/7/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 19/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLS 4820 G

TOYOTA PRIUS

JTDKB3FU303571589

Submit By :
Year Manufacture :
Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	✓
2	Rear bumper	1	\$497.50		✓
3	Rear bumper clip	10	\$40.00		✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		7 X
7	Rear bumper lower garnish centre	1	\$582.60		✓
8	Rear bumper lower garnish LH	1	\$149.70		X
9	Rear bumper lower garnish RH	1	\$149.70		X
10	Tail end panel	1	\$596.60		7 X
11	Tail end panel garnish	1	\$151.60		X
12	Tail end panel garnish clip	10	\$35.00		X
13	Boot weatherstrip	1	\$353.10		X
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829

Company Reg No. 200005485N / GST No. 20-0005485-N



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLS 4820 G** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,END PANEL)	\$400.00	300
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,END PANEL)	\$400.00	320
3	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X
4	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
5	To check wiring	\$50.00	15
6	To remove & refit reverse sensor	\$120.00	50
7	To tuff coat <i>nn</i>	\$80.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Print Received Message

This mail is associated with :

***SLS4820G (C0474103)**

[SHD200Z]

TP

GRAB RENTALS PTE LTD

Jul 14 2018 6:00AM

[TRANS-CAB SERVICES PTE LTD]

Esteem Performance Pte Ltd - Sin Ming

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 25/06/2019 09:52 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2258.02) - SLS4820G - Claim Handler: Stacey Ng

Approved:2258.02.

**ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Your Ref : SHD 200 Z
Our Ref : SLS 4820 G

Date : 01-10-18

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

RE : ACCIDENT INVOLVING SLS 4820 G & SHD 200 Z
ACCIDENT DATE 14-07-2018
ACCIDENT ALONG PASIR RIS DR 1

We are the workshop for the owner of motor vehicle no : SLS 4820 G which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured SHD 200 Z we are submitting these claims for your consideration.

1	Cost of repair	S \$	1,845.82
2	Loss of rental <u>5</u> days @ \$ <u>80.95</u> / day	S \$	404.75
3	Surveyor Fee	S \$	0.00
4	GIA report fees (S\$ 15.00 for search fee & S\$ 14.00 for each report fee)	S \$	0.00
5	LTA Fee	S \$	7.45
		S \$	2,258.02

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim

Claims Executive

Email : carmen@esteempert.com.sg

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Tuesday, 31 July, 2018 3:03 PM
To: 'claims@transcab.com.sg'
Cc: 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: ACCIDENT INVOLVING SHD 200Z & SLS 4820G ALONG PASIR RIS DR 1

31 July 2018

Transcab Taxi
Singapore

Dear Sir/Madam,

OUR REF : CC4/AXA1801328/Kwa3
YOUR REF : SHD 200Z

ACCIDENT INVOLVING SHD 200Z & SLS 4820G ALONG PASIR RIS DR 1

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Esteem Performance Pte Ltd** acting on behalf of the owner of SHD 2266X against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

We also wish to advise that there is an excess of **S\$5,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA's Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 8625 or email us at Vivianlau@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORITY

To Whom It May Concern:

ACCIDENT INVOLVING SLS 4820G & SHD200Z Along Rusir Ris
Dr. 1 On 14/07/2018 @ 06:45

I, Grab Rentals Pte Ltd Nric No. 201617200G
of 18 Sin Ming Lane #01-08 Midview City Singapore 573960
Owner of motor vehicle no. SLS 4820G do hereby appoint M/S
ESTEEM PERFORMANCE PTE LTD as my authorized representation and
_____ as my solicitors to write, to negotiate and settle my claim against
the other party/parties involved in the above mentioned accident. M/S ESTEEM
PERFORMANCE PTE LTD shall have absolute discretion to settle the matter at the best
terms.

I also confirm and instruct that any agreed settlement sum in respect of my claim be paid to
M/S ESTEEM PERFORMANCE PTE LTD and such payment will constitute a full and final
discharge of my claims.

I further authorize M/S ESTEEM PERFORMANCE PTE LTD to execute the discharge
voucher on my behalf.

Signature of Owner





AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SHD 200Z	(Insd veh)	Model: TOYOTA PRIUS
	SLS 4B20G	(TP veh)	
Date of Accident/ Time:	14/07/2018 / 06:30		

Repair Estimate	: \$	4,145.82	
Final Repair Cost	: \$	1,845.82	(W/GST)
Loss of Use	: \$		days at \$ per day
Rental (if any) (W/GST)	: \$	404.75	05 days at \$80.95 per day
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	2,258.02	
Payee Name : ESTEEM PERFORMANCE PTE LTD			
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability <u>100</u> (%)	
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____	
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp:  Signature of Witness / Workshop stamp (if applicable): 

Name of Representative: Carmen Kim

Date: 8.07.2019

Name of Witness: Serene

Date: 8.07.2019

Signature of AXA's surveyor/representative: 

Name of AXA's surveyor / Representative:

Date: 10/7/2019



ESTEEM PERFORMANCE PTE LTD

Blk 5083 Ang Mo Kio Industrial Park 2, #01-259/01-251 Singapore 569536.
 Tel : 6484 1221 Fax : 6484 7829
 385 Sin Ming Drive (Inside Vicom) Singapore 575718.
 Tel : 6753 2112 Fax : 6451 0394
 Co. Reg No. : 203005485N GST Reg No. : 20-0009489-N

M/S : AXA INSURANCE SINGAPORE PTE LTD
 8 Shenton Way
 #27-01 AXA Tower
 Singapore 068811

TEL:
 ATTN: Motor Claim Department

Your Ref No: SHD200Z
 Claim Type: Third Party
 Accident Date: 14/07/2018
 TP Veh Reg No: SHD200Z

Final No: CIV1301320
 Claim No: CER1301036
 Date: 19 Sep 2018
 Policy No: A29069766MKF
 Veh Reg No: SLS4820G
 Make/Model: TOYOTA PRIUS
 HYBRID 1.8 CVT
 Chassis No: ITDKB3FU303571589
 Engine No: 2ZRS091408
 Reg. Date:

Tax Invoice to Vehicle No :SLS4820G

Description	Quantity	List Price	PAGE:1
			Amount
		S\$	S\$
SPECIAL NETTITEMS: REFER TO KENNETH SURVEY/INSPECTION REPORT AS LUMP SUM REPAIRS (INCL. PARTS & LABOURS)	1 PC	S\$ 1,725.07	S\$ 1,725.07
Total			S\$ 1,725.07
Add GST @ 7%			120.75
Total Amount payable			S\$ 1,845.82

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED FORTY FIVE AND CENTS
 EIGHTY TWO ONLY

The above vehicle was surveyed by KENNETH on 19/07/2018

For Esteem Performance Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg
GST Registration No: 20-0005485-N CO Registration: 200005485N

M/S : FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
TEL: 6820 8888
ATTN: Motor Claim Department

Your Ref No: SHD200Z
Claim Type: Third Party
Accident Date: 14/07/2018
TP Veh Reg No: SHD200Z

Claim No: CER1301036
Final No: CIV1301320
Date: 19 Sep 2018
Policy No: A29069766MKF
Veh Reg No: SLS4820G
Make/Model: TOYOTA PRIUS
HYBRID 1.8 CVT
Chassis No: JTDKB3FU303571589
Engine No: 2ZRS091408
Reg. Date:

Tax Invoice to Vehicle No :SLS4820G

Description	Quantity	List Price	Amount
		S\$	S\$
Others			
1 COST OF REPAIR	1 PCS	1,725.07	
		1,725.07	1,725.07
Total			S\$ 1,725.07
Add GST @ 7%			120.75
Total Amount Payable			S\$ 1,845.82

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED FORTY FIVE AND CENTS EIGHTY TWO ONLY

The above vehicle was surveyed by KENNETH on 19/07/2018

For Esteem Performance Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



Our Ref: GR-ACC-2017-02

1st Nov 2017

Esteem Performance Pte Ltd
Blk 5033 Ang Mo Kio Ind Park 2
#01-259
Singapore 569536

Mailing Address

18 Sin Ming Lane,
#01-08 Midview City,
Singapore 573960
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$80.95
02	Mazda 3 1.5 (A) Sedan	\$66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,

Tay Chee Wee
Grab Rental Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018		19 Jul 2018 11:18 Edit Adj Rpt	S\$1,725.07 Edit Estimates	S\$1,725.07 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLS4820G	Date of Loss:	14/07/2018 06:00 - :59 [9 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0474103	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHD200Z	Policy No. (Claimant):	A29069766MKF						
		Excess:	S\$5,000.00						
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/07/2018]								
Driver/Custodian (Insured):	LOH CHEE WANG (68 / Male), NRIC: S0837710C, Tel: +6598860901 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (25/06/2019): Alert - Adj Mandate Approved (S\$2258.02) - SLS4820G - Claim Handler: Stacey Ng AXA_SG (19/07/2018): New TP Assignment - C0474103/P1680520 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS4820G (C0474103)
 [SHD200Z]
 TP
 GRAB RENTALS PTE LTD
 Jul 14 2018 6:00AM
 [TRANS-CAB SERVICES PTE LTD]
 Esteem Performance Pte Ltd - Sin Ming

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Documentation

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	17/07/18 08:51	SLS4820G TP GIA		Load PDF	
2	17/07/18 08:51	SHD200Z INS GIA Insured hit tp rear		Load PDF	
3	17/07/18 08:51	EMAIL		Load PDF	
4	17/07/18 08:52	EMAIL FROM WORKSHOP		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/07/18 14:11	TP ESTIMATE - MARKED		Load PDF	
2	24/07/18 14:11	LKK SURVEY PHOTO		Load PDF	
3	24/06/19 14:56	RENTAL RATES		Load PDF	
4	24/06/19 14:56	LTA SEARCH		Load PDF	
5	24/06/19 14:56	LETTER TO OI		Load PDF	
6	24/06/19 17:19	LOD AND OTHER DOCUMENTS		Load PDF	
7	15/07/19 12:27	WORKSHOP INVOICE		Load PDF	
8	15/07/19 12:27	AUTHORISATION TO ACT FORM		Load PDF	
9	15/07/19 12:27	PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18013228/KGA3Q2

Date: 15/07/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : SLS4820G

Insured Vehicle No :

SHD200Z

Date of Loss: 14/07/2018

Nature of Claim:

TP

Claim No: C0474103

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLS4820G

Make & Model:

TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No:

2ZRS091408

Reg. Date:

26/09/2017 (Man. Year: 2017)

Chassis No:

JTDKB3FU303571589

Colour:

Metallic Pearl White

Odometer:

62542 km

Engine Capacity:

1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side:

West Lake 3 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side:

West Lake 3 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,585.07	1,040.07	1,545.00	59.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	685.00	635.00	48.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,905.07	1,725.07	2,180.00	55.82
+ GST 7.00/7.00% (S\$)	273.35	120.75	152.60	55.83
Nett Amount (S\$)	4,178.42	1,845.82	2,332.60	55.82
+ Car Rental (5.0 x S\$80.95/day) (S\$)		404.75		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,258.02		

INSPECTION

Date of Assignment: 19/07/2018

Date Inspected: 19/07/2018 Inspected At:

Esteem Performance Pte Ltd - Sin Ming (HQ)

385 Sin Ming Drive

Singapore 575718

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2019)
Parts: 144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLS4820G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR (CONSISTENT)	Dented	200.00 FS	*200.00 FS
2	1		*REAR BUMPER (CONSISTENT)	Cracked	497.50 FL	*497.50 FL
3	10		*REAR BUMPER CLIP (CONSISTENT)	Necessary	40.00 FL	*40.00 FL
4	1		*REAR BUMPER SIDE RETAINER LH (CONSISTENT)	Serviceable	112.70 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH (CONSISTENT)	Serviceable	112.70 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Not Necessary	398.90 FL	*- FL
7	1		*REAR BUMPER LOWER GARNISH CENTRE (CONSISTENT)	Dented / Buckled	582.60 FL	*582.60 FL
8	1		*REAR BUMPER LOWER GARNISH LH (CONSISTENT)	Serviceable	149.70 FL	*- FL
9	1		*REAR BUMPER LOWER GARNISH RH (CONSISTENT)	Serviceable	149.70 FL	*- FL
10	1		*TAIL END PANEL (CONSISTENT)	Not Necessary	596.60 FL	*- FL
11	1		*TAIL END PANEL GARNISH (CONSISTENT)	Serviceable	151.60 FL	*- FL
12	10		*TAIL END PANEL GARNISH CLIP (CONSISTENT)	Not Necessary	35.00 FL	*- FL
13	1		*BOOT WEATHERSTRIP	Serviceable	353.10 FL	*- FL
					Sub Total (S\$)	3,380.10 1,320.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	795.03 280.03
					Total Parts (S\$)	2,585.07 1,040.07

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,END PANEL)	New	400.00	300.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER,END PANEL)	New	400.00	320.00
3	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
4	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
5	TO CHECK WIRING	New	50.00	15.00
6	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
7	TO TUFF COAT	New	80.00	0.00
Gross Labour Cost (S\$)			1,320.00	685.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >