

Surveyor: KASUL DOI: 20/02/19 Date / Time: 23/7/18

Registered in Merimen: -

Pre-assign / CCU / FTE

Insured Vehicle No. : XB7886U 'VIRTUAL' Claim No. : SPMOOP7Y

Name of Insured : Tony MAINTENANCE & GRC P/L Policy No. : -

Insured Tel No. : - HP: - Make / Model : -

Excess Sec II :SS D.O.A: 28/5/2018 Place of Accident : -

Is driver the owner? (YES ☒ NO ☐ Nature of Accident : -

If NO, Driver Name / Age : try new guy OI GIA REPORT: YES ☒ NO ☐ TP GIA REPORT: YES ☒ NO ☐

Driver Tel No. : 82623811 (VL: YES ☒ NO ☐ Insured Liability : - % Final ? Yes / No

Ym 9972 X → → → → →

 INSRS: WSP: <u>0055 Poulton</u> Tel: <u>-</u> Liability: <u>-</u> RMKS: <u>-</u>	 INSRS: WSP: <u>-</u> Tel: <u>-</u> Liability: <u>-</u> RMKS: <u>-</u>	 INSRS: WSP: <u>-</u> Tel: <u>-</u> Liability: <u>-</u> RMKS: <u>-</u>	 INSRS: WSP: <u>-</u> Tel: <u>-</u> Liability: <u>-</u> RMKS: <u>-</u>
---	---	---	---

Date/Time		STAGE	DATE / PIC
<u>27/11</u> <u>27/11/19</u>	<u>Ym 9972 X - X</u>	Non-Reporting ltr (1st)	
	<u>XB 7886 U - X</u>	Non-Reporting ltr (2nd)	
	<u>- TP LOD IN</u>	Non-Reporting ltr (Final)	
		Notification ltr (if non-pickup)	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	
		After call ltr to OI: <u>DO NOTHING</u>	
		Authorisation To Act:	
<u>18/12/19</u> <u>16/01/2020</u>	<u>- UPLOADED MANDATE IA IN OC</u>	Release Voucher:	
	<u>- AXA APPROVED MANDATE</u>	Final Repair Bill:	
	<u>- SEND 1st OFFER TO TP.</u>	Car Rental Invoice:	
	<u>- TP ACCEPTED OFFER.</u>	Towing Invoice:	
	<u>- ALL DOCS IN ORDER.</u>	LTA / GIA:	
	<u>- TO CLOSE.</u>	Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
PRELIMINARY ADVICE Date/Time: Sent By:		Post-Repair Photos:	
		Others:	

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: <u>LIS</u>	<u>\$5 2,500.00</u> (<u>4</u> days) Reduction: <u>10</u> %		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: <u>26/01/2020</u>	Confirm with: <u>CASUAL</u>	Email ☒ Call ☐
Final Liability:	% <u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>NIL</u>		If NO or B 28, Ass. Lin:
Repair Cost: <u>(w/gst)</u>	<u>\$5 2,475.00</u>		<u>(OLD HIR PROVIDED TP)</u>
Loss of Rental (LOR):	<u>\$5 -</u> (<u>-</u> days)		<u>TP VIDEO IN</u>
Loss of Use (LOU):	<u>\$5 750.00 x 5</u> (<u>5</u> days)		
Loss of Income (LOI):	<u>\$5 -</u> (<u>-</u> x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	<u>\$5 2.00</u>		
Medical:	<u>\$5 -</u>		
Disbursement:	<u>\$5 -</u> (e.g. Tow/ Independent)		
Legal Cost	<u>\$5 -</u>		
Total:	<u>\$5 3,427.00</u>	Global Sum \$5: <u>3,420.00</u>	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	<u>\$5 3,420.00</u>	Name 1: <u>COMMONWEALTH ENGINEERING PTY LTD</u>	
Payee 2: (Strike if N.A.)	<u>\$5 -</u>	Name 2: <u>-</u>	
Payee 3: (Strike if N.A.)	<u>\$5 -</u>	Name 3: <u>-</u>	

13314/14 (2)

1235E
LOG EXPIRY: 2024/P03

2009: Feb

4M9972X

Type: M Car / M Cycle / Bus / Van / *Convey* Taxi / Prime Mover /

MITSUBISHI FEB 3 PAK OSRNG 2977

YM 9972x
Comfort Delgro
45 pendon Road

Color	WHITE	APC	Injured / Std / N / NA
-------	-------	-----	------------------------

Sp. Hcnding 213605 HCode Insured / STD / NI / NA

Eng/Ho

FE83AEA1124U

Gen. Cond. Good ~~Fair~~ Poor / Burnt

Excess

Closing, ~~in order~~ Jammed / Leaked / Burnt or

Brake ~~In order~~ / Jammed / Leaked / Burnt

Modif: NIP / S/Rim / STD A/Rim of

Tyre Size	F:	7.00R16
	R:	185R14C

	N5	O5

29K

Consistent? Yes or No

Consistent? Yes or No

A	days	Result	Yes or No
---	------	--------	-----------

Q3: Eval: Yes or No

Verfahren: IN / OUT

log. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Part

The W/C / Chassis-frame / Body Structure affected due to collision

Elafin / Time	Action / Instruction
---------------	----------------------

U.S. \$2,500.00
Cred: \$2,314.84 (48%)

□: Prel. Report

☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Form

Leung, C. Y. & F. C. Yip (2002) *Journal of Applied Social Psychology*, 32, 1031–1047.

Add Fee: Site Map: \$

Report Format

Lump Sum / LBT (%)

Site map	15
----------	----

☐ [Index page](#) 13

Figure 3	Figure 4	Figure 5
----------	----------	----------

Manuscript 15

1164

Abstract

1000

ComfortDelGro Engineering Pte Ltd

Claim Reference:
Assessment number: YM9972X@PANDAN
Version: 1810
Date calculated: 02/19/2019 03:49 PM

Full Report
Registration: YM9972X
Printed: 19/02/2019 3:49 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	18.60	186.0	837.00
Total of Labour			837.00

Paint

Code	Description	SYSTEM AZT	Time Basis 10WU/h	WU	Price SGD
	R/F CORNER PANEL NEW PART PAINTING			7.0	
	RIGHT FRONT DOOR NEW PART PAINTING			14.0	
	RIGHT A-PILLAR NEW PART PAINTING			10.0	

Paint Material Per Part

Code	Description	Price SGD
0888	R/F CORNER PANEL NEW PART PAINTING	4.84
1482	RIGHT FRONT DOOR NEW PART PAINTING	30.63
2228	RIGHT A-PILLAR NEW PART PAINTING	5.24

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	45.00 SGD/h			
Time Paint			31.0	
Preparation Main Work Metal		1.70	17.0	76.50
Total	10 WU/h	4.80	48.0	216.00

Material Cost - Paint	Price SGD
New Part Painting	40.71
Material-constant Metal	18.10
Total	58.81

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0888	R/F CORNER PANEL	MK997198	Part un		200.00
1401	WINDSCREEN	MK488919	Ch		600.00
1410	WINDSCREEN SEAL	MK548235	se		180.00
1411	BONDING KIT	Z2156507	se		0.00
1482	RIGHT FRONT DOOR	MK702715	repair (50) un		850.00
1510	R/F DOOR FRAME SEAL	MX917491	X un		130.00

ComfortDelGro Engineering Pte Ltd

Claim Reference:
Assessment number: YM9972X@PANDAN
Version: 1810
Date calculated: 02/19/2019 03:49 PM

Full Report
Registration: YM9972X
Printed: 19/02/2019 3:49 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection: 2019-02-19

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW R/A-PILLAR (FRONT SCREEN AND INSTRUMENT PANEL REMOVED) INCLUDES: R + R HEADLAMP, CORNER PANEL, DOOR, FRONT SEAT, ALL ATTACHED PARTS AND TRIMS IN THE REPAIR SECTION		102.0	459.00
423121 10	R + R WINDSCREEN		25.0	112.50
424111 10)	RENEW R/DOOR BODY (DOOR REMOVED) INCLUDES: R + R ATTACHED PARTS OF THE DOOR, ALIGN + ADJUST DOOR		14.0	63.00
523112 10ZAX	R + R INSTRUMENT PANEL CPL INCLUDES: R + R COMBINATION INSTRUMENT		45.0	202.50

Vic (LKKAuto)

From: Cecilia Lee Peng Geok <cecilialee@sparkcarcare.com>
Sent: Thursday, 23 January, 2020 11:08 AM
To: Vic (LKKAuto)
Cc: Admin A
Subject: Re: CWR LOD AGAINST AXA/LKK - YM9972X / XB7886U DOA 28/5/2018 *** LKK REF: CC4/ASM18013314/R1ha3

Without Prejudice

Dear Sir/Madam

Strictly without admission of any liability and solely for quick amicable settlement, we confirm settlement at \$3420.00 for property damage only. Please note that this acceptance is purely for quick settlement and it shall not be cited or relied on as precedent in any proceeding. Please note that the contents of this document apply to vehicle damages only. It is condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

The duly completed document is enclosed for your attention. Please arrange to let us have your payment made in favor of ComfortDelGro Engineering Pte Ltd within the next seven (7) days.

Thank you.

Best Regards
Cecilia Lee
Claims Department | ComfortDelGro Engineering Pte Ltd
Off: 6214 8354 | Fax: 6214 1843



Think Before Printing

From: Vic (LKKAuto) <vicalpeh@lkkauto.com>
Sent: Thursday, 16 January 2020 9:47 AM
To: Cecilia Lee Peng Geok <cecilialee@sparkcarcare.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: RE: CWR LOD AGAINST AXA/LKK - YM9972X / XB7886U DOA 28/5/2018 *** LKK REF: CC4/ASM18013314/R1ha3

Without Prejudice

Dear Cecilia,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability, we have our principal's mandate we offer a global sum of **\$3,420.00** (all in) to settle your client's claim.

If agreeable, kindly chop and sign the attached DV and forward back a copy to us for payment processing.

Thank you.



Re:RE: Re:<MANDATE IA>

Type

🔗 Question

Message

Hi Pls proceed, tks-VO

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/12/2019

Survey Details:

Date of loss	28-May-18
Date of appointment	20-Jul-18
Date of survey	20-Feb-19
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	YM 9972X
Make and Model	MITSUBISHI FE83BEOSRDEA - 2977cc
Date of registration	24-Feb-09
Excess	
Market Value (est)	\$29,000.00
Part Rebate (est)	\$224.00
Nett Loss (est)	\$28,776.00

Repair details:

Initial Estimate	\$ 4,814.81
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,828.50
Check items (estimate)	\$ -
Labour	\$ 1,111.81
Total	\$ 2,940.31
Lump Sum(if applicable)	\$ 2,500.00

Number of days for repair	4 DAYS
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 6256356/1 FAX : (065) 62564315

Remarks:

VIRTUAL CASE. We have not authorized repairs. It was reported that Insured vehicle collided to the parked TP vehicle. TP video footage uploaded in SC. TP LOD IN.

Mandate:

Liability(TP)	100%	
Proposed Repair Cost	\$ 2,675.00	w/gst
Loss of Use	\$ 750.00	\$150 x 5 days
Loss of Rental	\$ -	no. of days
Loss of Income	\$ -	no. of days
GIA Search Fees	\$ 2.00	
Others (Medical Bills)	\$ -	
Proposed Total	\$ 3,427.00	
***TBC - To Be Confirmed		

PTE/YM9972X/20180528/OD_COR_CASH-CL
11/03/2019

M/s AXA Insurance Singapore Pte Ltd
C/o LKK Auto Consultants Pte Ltd
51 Ubi Avenue 1, #02-25
Singapore 408933
Attn: Motor Claims Department

WITHOUT PREJUDICE

Dear Sirs

ACCIDENT ON 28/05/2018 INVOLVING YM9972X & XB7886U
ALONG BACK ALLEY OF 7 WOODLANDS SECTOR 1

We are the authorised repair workshop for the owner of vehicle, YM9972X, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorised us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, XB7886U, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repairs	2,675.00
2. Car Rental	-
3. 5.0 days Loss of Use @ \$180	900.00
4. Surveyor Fee	-
5. LTA Fee	-
6. TP/GIA Fee	2.00
7. Medical	-
8. Others	-

(E&OE) 3,577.00

We enclose the following documents to support the claims: -

☒ Repair/Excess Bill	☒ Insurance Certificate
☐ Surveyor Report	☒ Power of Attorney
☐ Coloured Photographs	☐ Car Rental Bill
☒ GIA/Police Report(s)	☐ Medical Bill
☒ GIA/TP Search	☐ Witness Statement
☐ Others: _____	

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully

Cecilia Lee

CDGE Claims Department

59 Loyang Drive S(508969)

OID: 6214 8354 FAX: 6214 1843

Email: cecilialee@sparkcarcare.com



ComfortDelGro Engineering

ComfortDelGro Engineering Pte Ltd

Corporate Office

305 Braddell Road Singapore 579701

Mobile: +65 9383 6288

Fax: +65 9383 6285

www.sparkcarcare.com

Car Care Centres

Braddell

305 Braddell Road

Singapore 579701

Tel: 6383 6110

Loyang

59 Loyang Drive

Singapore 508969

Tel: 6214 8350

Pasir

40 Pasir Road

Singapore 650388

Tel: 6383 6775

Sen Ming

301 Sen Ming Drive

Singapore 675111

Tel: 6552 1400

Bungei Kadu

7 Bungei Kadu Way

Singapore 728793

Tel: 6340 7360

Ubi

320 Ubi Road 3

Singapore 408588

Tel: 6848 5721

www.SPARKcarcare.com

A member of

COMFORTDELGRO



ISO 9001
CERTIFIED

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road
Singapore 579701
Tel: 6228 6288
Fax: 6228 6299
www.cdgc.com.sg

Car Care Centres
205 Braddell Road Singapore 579701
59 Linyang Drive Singapore 509580
42 Pandan Road Singapore 609280
381 Sun Hong Drive Singapore 571717
7 Sengkang Kachid Vayu Singapore 758794
320 Ulu Road 2 Singapore 409048
301 Yixian Industrial Park 2 Singapore 798732
www.SPARKcarcare.com

Tel: 6283 8110
Tel: 6214 8300
Tel: 6238 8778
Tel: 6553 0400
Tel: 6969 7489
Tel: 6969 5721
Tel: 6757 7888



COMPANY CREDITING ENGINEERING

TAX INVOICE

GST REG. NO. M2-892181

80411714

Company SEE HO PTE LTD

7 WOODLANDS SPECTOR 1
738359

CONTACT NO: 69570633 62337083

Description : CASH JOB WITH RECOVERY AGAINST AXA INS

VEHICLE NO

YH 9972K

MAKE

MITSUBISHI

MODEL

FE83PE3RDEA

DATE OF PSE

CHASSIS CODE

FE83BEA11240

NO/DATE

91427528 22.02.2019

JOB NO

305270855

ODOMETER READING

JOB TYPE

Invoiced for Lump Sum Repair

Lump Sum Amt.	2,500.00
Subtotal	2,500.00
Add GST @ 7.000 %	175.00
Total Invoice amount	2,675.00

Issued by
Repair Type
Payment Type

DRASRX08 22.02.2019 14:06:20
CP90/52/5C

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Blk C Ext 1 Level 2
Singapore 579701

Attn: Finance Department

Kindly note that no receipt shall be issued unless requested.

OFFICE COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18013314/R1ha3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH		Date : 05-02-2020		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 7886U	Veh. Inspected	YM 9972X	
Policy No.	VFX/P2064586	Coverage (\$)	0.00	
Claim No.	S8M00P7Y	Excess (\$)	0.00	
Assign From		Assign Date	23/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi FE83BEOSRDE	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	FE83BEA11240	Colour	WHITE	
Odometer	213605	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16	CONDOR	7 mm	
L/H Front Tyre	7.00 R16	CONDOR	7 mm	
R/H Rear Tyre	185 R14C (D)	CONDOR	5/5 mm	
L/H Rear Tyre	185 R14C (D)	CONDOR	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/05/2018	Inspection Date	20/02/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 9972X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	R/F CORNER PANEL (WCP) (CONSISTENT)	NOT NECESSARY	200.00	-
1	WINDSCREEN (WCP) (CONSISTENT)	CRACKED	600.00	600.00
1	WINDSCREEN SEAL (WCP) (CONSISTENT)	NECESSARY	180.00	180.00
1	BONDING KIT (WCP) (CONSISTENT) (NPA)	NECESSARY	-	-
1	RIGHT FRONT DOOR (WCP) (CONSISTENT)	NOT NECESSARY	850.00	-
1	R/F DOOR FRAME SEAL (WCP) (CONSISTENT)	NOT NECESSARY	130.00	-
1	R/INN DOOR LOCK (WCP) (CONSISTENT)	NOT NECESSARY	240.00	-
1	R/MIRROR HEAD (WCP) (CONSISTENT)	SCRATCHED	60.00	60.00
1	R/ DOOR MIRROR ARM (WCP) (CONSISTENT)	NOT NECESSARY	210.00	-
1	RIGHT A-PILLAR (WCP) (CONSISTENT)	BENT	750.00	750.00
	COST PLUS 15%		483.00	238.50
			3,703.00	1,828.50
	<u>LABOUR</u>			
	186.0 WU X 45.00 SGD/H .		837.00	837.00
	LABOUR COST 48.00 WU X 45.00 SGD/H .		216.00	216.00
	MATERIAL COST.		58.81	58.81
			1,111.81	1,111.81
	GRAND TOTAL		4,814.81	2,940.31
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00

Report Ref No. CC4/ASM18013314/R1ha3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SBM00P7Y
Reference	CCA/A9M18013314/R11a3q2
Loss Date	28 May 2018
Report Date	20 Jul 2018 8:56:07 AM
Request Date	20 July 2018
Due Date	
Vendor Name	LUK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve Invoice

Auto Invoice

Vehicle Information	
Incident Vehicle Registration #	YM972X
Make	TPVD MITSUBISHI
Model	FEBJREOSRDEA-3.0 D B31 (A)
Service Address	
...	
Primary Contact/Insured	
TIDY MAINTENANCE & ENGINEERING PTE. LTD. 29 TUAS AVENUE B, 639244, Singapore 63380083 ABBY@VIRTUALINVEST.BIZ	
Claim Handler	
OH Vale 6568804897 vale.oh@asa.com.sg	

Additional Instructions VIRTUAL CASE NON REPORTING

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
INSRD GIA REPORT	Reports & Statement	GIA Report	Mentem	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (4).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 LKKAdjustment1a (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	PCA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	10 February 2020
 MANDATE IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
 TP LOO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
 LKK INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
 VIDEO.mp4	Evidence	Video	LKK AUTO CONSULTANTS PTE LTD (TP)	22 November 2018
 EMAIL TP PB WORKSHOP.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shethur	20 July 2018