

Any other

Karl.

REF:

Tokio CC3/TMI18013315/Gqd3n2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s:

Camfat layang.

of

Insured:

SL 53BJ

Policy No:

M1000750

Claims No:

M1803779

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SH6066D

Yr Bgn:

19 May 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai i40 C.C 1685

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

344629

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHLCB414MGU089043

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20-07-18

Survey held at

W/S

4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Final Rpt 81596, 2 days (Red B 1464.64, 48%)

RECEIVED 31 JUL 2018

Date/Time. File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

10

) \$ + RS. \$

) Photos

) Others

TOTAL

260

Report Format :

MEP-TP

Lump Sum / I.B.I. (\$

1594

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SH6066D
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	HYUNDAI
Vehicle Model :	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Chassis No. :	KMHLB41UMGU089043
Propellant :	Diesel
Engine No. :	D4FDGU622140
Engine Capacity :	1685 cc
Maximum Power Output :	100.0 kW (134 bhp)
Maximum Laden Weight :	2100 kg
Unladen Weight :	1501 kg
Year Of Manufacture :	2016
Original Registration Date :	19 May 2016
Lifespan Expiry Date :	18 May 2024
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid :	\$36,463.00
COE Expiry Date :	18 May 2024
Road Tax Expiry Date :	18 Nov 2018
PARF Eligibility Expiry Date :	18 May 2024
Inspection Due Date :	18 Nov 2018
Intended Transfer Date :	23 Jul 2018
CO2 Emission :	159.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2018 09:20
Date Of Accident	19/07/2018 21:35
Exact Location Of Accident	NEPTUNE COURT GANTRY .
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH6066D
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	CHUE WAH CHONG
NRIC No	S6998113E
Date Of Birth	14/05/1969
Occupation	OUTDOOR
Date Of Driving Pass	10/10/1989
Driving Experience	28 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98261818
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	492G 03-624 TAMPINES STREET 45
Postcode	527492
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR (TP FENCE)
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL5313J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	92409388
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR


No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHUE WAH CHONG
Approximate Age	49
Injuries Sustain	NECK,GIDDY
Injured person in which vehicle?	SH6066D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/7/2018 at about 2135 hrs, I vehicle A was driving into Neptune Court gentry. As a vehicle B was in front of me, then he reverse in vehicle and collided into the front portion. Causing the damage. No one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

CO-REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

2019/18
Jackson Hong
CSO

Reporting Centre Personnel's Signature
Name:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

20/7/18
Jackson Hong
CSO

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



1717 2136



Date/Time: 20.07.2018 10:48

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305190074

STOMER

COMFORT TRANSPORTATION PTE LTD
 7010045
 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 65508755 (U)

(R)

(P)

REGN NO:	SH 6066D	MILEAGE
MAKE:	HYUNDAI	FUEL E.....1/2.....F
MODEL:	I-40	DATE/TIME IN 20.07.2018 08:20
YR OF MANU:	19.05.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMGU089043	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 19.07.2018
 NATURE: 3P 19.07.2018

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 6066D CHIANG

Vehicle No.: SH 6066D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co. Reg. No. 199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
 CTPL

Singapore

Chiang

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/07/2018
Vehicle Reg. No.:	SH6066D	Driveable?	YES
Party At Fault:	UNKNOWN		

Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	19/05/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU622140	Chassis No:	KMHLB41UMGU089043
Odometer:	0 KM		

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	4

Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)
-------------------	--

COST OF CLAIMS	Amount
Parts	1,164.64
Miscellaneous Items	10.00
Labour	700.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,874.64
+ GST 7.00% (S\$)	131.22
Nett Amount (S\$)	2,005.86

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

3058.64

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2018)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH6066D/20/07/2018 11:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER COVER	20.00	0.00	*562.30 FL
2	1		*FRONT BUMPER SPONGE	20.00	0.00	*142.20 FL
3	1		*FRONT BUMPER REINFORCEMENT	20.00	0.00	*526.10 FL
4	2		*FRONT BUMPER BRACKET TOP LH/RH	20.00	0.00	*44.80 FL
5	2		*FRONT BUMPER RETAINER MOUNTING	20.00	0.00	*180.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

1,455.80

- List Item Discount on L Items (S\$)

291.16

Total Parts (S\$)

1,164.64

ComfortDelGro Engineering Pte Ltd/SH6066D/20/07/2018 11:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Front Grille / BR. 1480

reg: 1184

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	450.00
2	SPRAY PAINTING	New	250.00
Gross Labour Cost (S\$)			700.00

ComfortDelGro Engineering Pte Ltd/SH6066D/20/07/2018 11:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2 Days.

part by part.

before paint photos.

Guo Qiang - 82880282

20/7/18 4:30pm

[Signature]
25/7/18

1584.

LKY Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 23.07.2018
Time: 15:27:41
Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305190074
REGN NO : SH 6066D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 19.05.2016
DATE/TIME IN : 20.07.2018 08:20
ACCIDENT DATE : 19.07.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2164-G I40V3 GRILLE ASSY-RADIATO 1 1,480.00 20.00 1,184.00

SUB-TOTAL : 1,184.00

JOB NATURE

0000 L MERIMEN FEE 10.00

0001 L PANEL BEATING 200.00

0002 23-502 SPRAYPAINT ON AFFECTED AREA 200.00

SUB-TOTAL : 410.00

TOTAL : 1,594.00

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305190074
Date : 23/07/18

FINALIZATION FORM

To : LKK
Attn : GUO QXIANG
Vehicle Reg No. : SH 6066D

Fax :

19/07/2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: TOKIO SLL5313J
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,184.00
 - (b) Labour Charges \$410.00
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost \$1,594.00


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : Guo Qiang
Date : 26/7/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18013315/GQD3N2

Date: 01/08/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI000250
Claimant Vehicle No :	SH6066D	Insured Vehicle No :	SLL5313J
Date of Loss:	19/07/2018	Nature of Claim:	TP
		Claim No:	M1803779

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6066D	Engine No:	D4FDGU622140
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU089043
Reg. Date:	19/05/2016 (Man. Year: 2016)	Odometer:	344629 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,344.80	0.00	1,344.80	100.00
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	700.00	400.00	300.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,054.80	410.00	1,644.80	80.05
+ GST 7.00/7.00% (S\$)	143.84	28.70	115.14	80.05
Nett Amount (S\$)	2,198.64	438.70	1,759.94	80.05

INSPECTION

Date of Assignment:	30/07/2018	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/07/2018	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH6066D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	562.30 FL	*- FL
2	1		*FRONT BUMPER SPONGE	Not Necessary	142.20 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	526.10 FL	*- FL
4	2		*FRONT BUMPER BRACKET TOP LH/RH	Not Necessary	89.60 FL	*- FL
5	2		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	360.80 FL	*- FL
Sub Total (\$\$)						1,681.00 0.00
- List Item Discount on L Items 20.00/20.00% (\$\$)						336.20 0.00
Total Parts (\$\$)						1,344.80 0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	450.00	200.00
2	SPRAY PAINTING	New	250.00	200.00
Gross Labour Cost (S\$)			700.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT (SUPPLEMENTARY #1)

Our File No: CC3/TMI18013315/GQD3N2

Date: 01/08/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI000250
Claimant Vehicle No :	SH6066D	Insured Vehicle No :	SLL5313J
Date of Loss:	19/07/2018	Nature of Claim:	TP
		Claim No:	M1803779

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6066D	Engine No:	D4FDGU622140
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU089043
Reg. Date:	19/05/2016 (Man. Year: 2016)	Odometer:	344629 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,184.00	1,184.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,184.00	1,184.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	82.88	82.88	0.00	0.00
Nett Amount (S\$)	1,266.88	1,266.88	0.00	0.00
+ Previous Recommendations (S\$)		0.00		
Nett Liability (S\$)		1,266.88		

INSPECTION

Date of Assignment:	30/07/2018	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/07/2018	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH6066D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE RAD	Broken	1,480.00 FL	*1,480.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,480.00	1,480.00
- List Item Discount on L Items 20.00/20.00% (S\$)					296.00	296.00
Total Parts (S\$)					1,184.00	1,184.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >