



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:ERNEST			Ref: CC4/ASM18013331/Dea3q2 Date: 29/03/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	CB 7302L	Veh. Inspected	SLK 6855K	
Policy No.	CN858098	Coverage (\$)	0.00	
Claim No.	S8M00PFA	Excess (\$)	0.00	
Assign From		Assign Date	23/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	CITROEN DS5	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF7KF9HD8DS516335	Colour	WHITE	
Odometer	64838 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	CONTINENTAL	5 mm	
L/H Front Tyre	225/50 R17	CONTINENTAL	5 mm	
R/H Rear Tyre	225/50 R17	CONTINENTAL	5 mm	
L/H Rear Tyre	225/50 R17	CONTINENTAL	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/07/2018	Inspection Date	26/07/2018	
Survey held at	BODYFIX NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06 AMK AUTOPOINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	