

REP: CS/LPC18013348/Uvd357  
 S. REC. BY: Marius  
 ASSIGNMENT (Office)  
 From (Person): Gerald Poh of LPC Date/Time: 23/07/18 @ 8:37pm  
 Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

① OT/TP/WS/TP RES/OD RES/EVA/INV/MV/CS  
 To Inspect Vehicle No: SKW 5258P Insured: \_\_\_\_\_  
 at Workshop n/s: Koon Heng Motor Tel: 6748 7348  
 of 1 Kaki Blk Ave 6 #02-14 Autobay  
 Policy No: Z17VP05015665 Claim No: 17/18/18/VPO5/020771  
 Sum Insured: \_\_\_\_\_ Excess: \$1,500.00  
 Make of Veh: \_\_\_\_\_ D.O.A. 19/07/2018  
 (Client's Record)

CA / (REV) / REP. / REV 24 HRS  
 Date/Time: 11:41am @ 23/7/18 Person Contacted: Mr. Tan H.O.D. Endorsement: \_\_\_\_\_  
 Vehicle: ① IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 5258P - CC4/LPC17018544/T1hb3n2 DOA: 22/21/17
24/7-	Revert via merimen (check if towing is payable)
24/7-	check with workshop towing is from accident scene to workshop Koon Heng.
24/7@4.42pm	Inform by Gerald that towing charge LPC with bare ask workshop spreaded bill to Insurance with original invoice. prove.

(08/11/13) Wef

ASS. REG. BY: Merimen

REF:

LTC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 5258Pat Workshop m/s Koon hy

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 1500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 886

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 70 151 % 3 Val.: Yes or NoCA / (REV) / REP. / 24 HRS LTA 60103

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKW 5258P Yr Regn: 10 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or LAMake: Subaru Outback c.c. 2498Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 47845 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 3F2B591KC2F6013584Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or OKBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/60R18

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 19/7/18 D.O.I. 23/7/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 Part 2

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/7/18 Rece approved from Chew Beng Kee via merimen25/7/18 @ 1034am Informal Mr Tan c/A on IBI ex \$1500, Towing to separate bill to insurance with original invoice prove.30/7/18 4/5 & 5520 confirmed with insurance. (Red 6215.55, 531)

RECEIVED 31 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 31/7 - typistReport Format: merimenLump Sum / I.B.I.: (\$ 5550/2)Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS, \$:

Photos:

Others:

TOTAL

$1 \times 15 = 15$   
 $15 + 170 = 185$   
 $185 \times 20\% = 37$   
 $37 + 185 = 222$

222
50
50 + 50
109
1
(481) + 10




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS/LPC18013348/Uvd3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 23-07-2018	
			Code : LPC2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.			Veh. Inspected	SKW 5258P
Policy No.	Z17VP05015665		Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020771		Excess (\$)	1,500.00
Assign From	MERIMEN (GERALD POH)		Assign Date	23/07/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	19/07/2018		Inspection Date	23/07/2018
Survey held at	KOON HENG MOTOR BLK 1 KAKI BUKIT AVE 6 #02-14 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018 <a href="#">Sendback Est</a>	20 Jul 2018 17:52 <b>S\$10,072.75</b>	23 Jul 2018 08:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

Insured:	NG CHEE KEONG, ID: S7527649D			
Vehicle Reg. No.:	SKW5258P	Date of Loss:	19/07/2018 00:00 - :59 [32 Months and 19 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 17/18/18/VP05/020771	Policy/Cover Note No.:	Z17VP05015665 (Comprehensive) Coverage: 31/10/2017 - 30/10/2018	
		Excess:	S\$1,500.00	
Repairer:	Koon Heng Motor (-) 1 Kaki Bukit Ave 6, #02-14, Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6748 7348			
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/08/2018]			
Adj Asg. Remarks:	SURVEY & REVERT			

[View All](#)   [Compose Case Mail](#)

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

### ALL ASSOCIATED TASKS

<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

## View Received Message

This mail is associated with :

**SKW5258P (17/18/18/VP05/020771)**

OD

Jul 19 2018 12:00AM

[NG CHEE KEONG]

Koon Heng Motor

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** Lonpac Insurance Bhd (HQ) (LONPAC\_HQ), sent on 24/07/2018 18:03 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$5743.30) - SKW5258P - Claim Handler: Gerald Poh

Approved:5743.30.

### DOCUMENTS SUMMARY

There are no documents.

**Veron Chen (LKKAUTO)**

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 25 July 2018 9:18 AM  
**To:** SUR  
**Subject:** FW: ACCIDENT INVOLVING FBM3338P & SKW5258P ON 19.7.2018  
**Attachments:** 23072018170623.pdf

CS/LPC18013348/Uvd3

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [mailto:[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)]  
**Sent:** Wednesday, 25 July, 2018 9:00 AM  
**To:** admin-d@lkkauto.com  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** FW: ACCIDENT INVOLVING FBM3338P & SKW5258P ON 19.7.2018

Dear Catherine,

Your advice dated 24 July 2018 refers.

You may proceed to authorize repair as adjusted.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** GERALD POH WEE BIN  
**Sent:** Monday, 23 July, 2018 5:12 PM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** 'mt\_claim@lonpac.com'; 'lihui@completevms.com.sg'  
**Subject:** ACCIDENT INVOLVING FBM3338P & SKW5258P ON 19.7.2018

Our Ref : 17/18/18/VP05/020771

Dear Catherine,

Please see attached and proceed to conduct a pre-repair survey.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Gerald Poh

Date: 24 Jul 2018

**Preliminary Advice**

Vehicle No	: SKW5258P	Accident Date	: 19/07/2018
Make	: SUBARU OUTBACK	Policy No.	: Z17VP05015665
Assignment Date	: 23/07/2018	Excess	: S\$1,500.00
Date of Inspection	: 23/07/2018	Est. Duration of Repair	: 5.00
Inspection At	: KOON HENG MOTOR (-) 1 KAKI BUKIT AVE 6, #02-14, AUTOBAY@KAKI BUKIT SINGAPORE 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	10,072.75
Revised Amount	:S\$	4,285.20
Check Items (Estimated)	:S\$	1,458.10
Total	:S\$	5,743.30
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	60,087.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,913.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Kindly advise if the towing charge is payable.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/07/2018 14:10
Date Of Accident	19/07/2018 10:15
Exact Location Of Accident	UPPER JURONG ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW5258P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG CHEE KEONG
NRIC No	S7527649D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94230324
Alternative Phone No	OFFICE-94230324

### Vehicle Particulars

Manufacturer	SUBARU
Model	OUTBACK-2.5 I-S CVT AWD SR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	Z17VP05015665
Cover Note Number	

### Driver

Name of Driver	NG CHEE KEONG
NRIC No	S7527649D
Date Of Birth	17/09/1975
Occupation	INDOOR
Date Of Driving Pass	31/07/1995
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94230324
Fax Number	
Contact Number	OFFICE-94230324
Email Address	NOEMAIL

Address	BLK 816 JELICOE ROAD # 18 -06 SINGAPORE 200816
Postcode	200816
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	FBM33389 (MOTORCYCLE)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ROCHOR N.P.C. 11 KAMPONG KAPOR ROAD, SINGAPORE 208678
Police Station Address	<b>ROAD:</b> 11 KAMPONG KAPOR ROAD , <b>POSTCODE:</b> 208678 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 19 JULY 2018 AT ABOUT 2215HRS , I WAS DRIVING OUT MY CAR FROM JURONG CAMP AND WANTED TO TURN RIGHT, INTO UPPER JURONG ROAD TOWARDS PIE . WHEN I WAS MOVING OUT A LANE AFTER THE STOP LINE, ONE WHITE MOTORBIKE, COMING FROM UPPER JURONG ROAD TOWARDS BOON LAY WAY, COLLIDED INTO MY VEHICLE RIGHT SIDE NEAR TO THE DRIVER'S FRONT RIGHT SIDE DOOR. AFTER ACCIDENT I GOT OUT OF MY CAR AND RENDERED ASSISTANCE TO THE SAID MOTORCYCLIST. DUE TO THE ACCIDENT, THE FRONT RIGHT DRIVER'S DOOR OF MY CAR IS SERIOUSLY DAMAGED . I AM HEREBY LODGING THIS REPORT FOR MY PERSONAL REFERENCE AND NECESSARY FOLLOW UP ACTION BY TRAFFIC POLICE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM3338P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	WONG HENG CHEONG
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name

WONG HENG CHEONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please follow police report

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature

Date & Time: 20/7/18

G5AP/NC Sketch Plan Form V9

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20/7/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20180720/2007

1 of 4

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

Report No. T/20180720/2007

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/07/2018 01:31	Vide Report No.: J/20180719/0204	Station Diary No.: 10
--	-------------------------------------	--------------------------

### Informant's Particulars

Name of Informant: NG CHEE KEONG			Address: APT BLK 816 JELlicOE ROAD #18-06 SINGAPORE 200816		
ID Type / ID No.: NRIC NO / S7527649D			Contact No.: Home/Office: Mobile: 94230324		
Nationality: SINGAPORE CITIZEN			Email: garyngck@gmail.com		
Sex: Male	Age: 42	Date of Birth: 17/09/1975	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: COMPANY MANAGER			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

### General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 19/07/2018 22:15	Type of Location: T-Junction
Location: Along Road 1 UPPER JURONG ROAD  100 Upper Jurong Rd Jurong Camp 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM3338P	Motorcycle	HONDA		White	Slightly Damaged	0
SKW5258P	Car	SUBARU	OUTBACK 2.5I-S CVT AWD SR	Grey	Seriously Damaged	0

### Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------





**SINGAPORE  
POLICE FORCE**



T/20180720/2007

2 of 4

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

Report No. T/20180720/2007

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKW5258P	LONPAC INSURANCE BHD.	Z17VP05015665	31/10/2017	30/10/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	WONG HENG CHEONG		ID No.	S7968015Z
Related Vehicle	FBM3338P (Motorcycle)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	Slight
Driver				
Name	NG CHEE KEONG		ID No.	S7527649D
Related Vehicle	SKW5258P (Car)		Contact No.	94230324
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On 19 July 2018 at about 2215hrs, I was driving out my car from Jurong Camp and wanted to turn right, into Upper Jurong Rd towards PIE.

When I was moving out a lane after the stop line, one white motorbike, coming from Upper Jurong Rd towards Boon Lay Way, collided into my vehicle right side near to the driver's front right side door.

After the accident, I got out of my car and rendered assistance to the said motorcyclist.

Due to the accident, the front right driver's door of my car is seriously damaged.

I am hereby lodging this report for my personal reference and necessary follow up action by Traffic Police.



**SINGAPORE  
POLICE FORCE**



T/20180720/2007

4 of 4

Report No. T/20180720/2007

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapor Road SINGAPORE  
208678  
Tel No: 1800-2949999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

Staff Sgt TAUFIQ BIN JUPRI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 3 RASHIDAH BINTE AZMAN

Contact No.: 65476216

Authentication Stamp

NP168

Singapore Police Force

Signature Of Informant:

Date/Time:

20/07/2018 01:31

Classification Of Case:



> Back to OneMotoring <

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

7649D

### Vehicle Details

Vehicle No.:

SKW5258P

Vehicle to be Exported:

No

Intended De-registration Date:

24 Jul 2018

Vehicle Make:

SUBARU

Vehicle Model:

OUTBACK 2.5I-S CVT AWD SR

Primary Colour:

Grey

Manufacturing Year:

2015

Engine No.:

FB25Y045175

Chassis No.:

JF2BS9KC2FG013584

Maximum Power Output:

129.0 kW (172 bhp)

Open Market Value:

\$21,496.00

Original Registration Date:

31 Oct 2015

First Registration Date:

31 Oct 2015

Transfer Count:

0

Actual ARF Paid:

\$22,095.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

30 Oct 2025

PARF Rebate Amount:

\$16,571.00

### Intended COE Rebate Details

COE Expiry Date:

30 Oct 2025

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$59,889.00

COE Rebate Amount:

\$43,516.00

**Total Rebate Amount:**

**\$60,087.00**

The information contained herein is correct as at 24 Jul 2018

OK

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 7649D

### Vehicle Details

Vehicle No.: SKW5258P  
Vehicle to be Exported: Yes  
Intended De-registration Date: 23 Jul 2018  
Vehicle Make: SUBARU  
Vehicle Model: OUTBACK 2.5I-S CVT AWD SR  
Primary Colour: Grey  
Manufacturing Year: 2015  
Engine No.: FB25Y045175  
Chassis No.: JF2BS9KC2FG013584  
Maximum Power Output: 129.0 kW (172 bhp)  
Open Market Value: \$21,496.00  
Original Registration Date: 31 Oct 2015  
First Registration Date: 31 Oct 2015  
Transfer Count: 0  
Actual ARF Paid: \$22,095.00 11047

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 30 Oct 2025  
PARF Rebate Amount: \$16,571.00


### Intended COE Rebate Details

COE Expiry Date: 30 Oct 2025  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$59,889.00  
COE Rebate Amount: \$43,532.00  
**Total Rebate Amount: \$60,103.00**

The information contained herein is correct as at 23 Jul 2018


OK

WORTH \$16,000  
Cash & Prizes  
EACH WEEK



Snap a shot of yourself and a car you love!  
Simply tag @SGCARMART #SGCMLOVECARs  
to participate! Find out more >

1st - 31st  
July 2018



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Aitis 1.6A



\$2500 Downpayment Monthly  
From \$588 Onwards. Lowest  
3.68%P.A@GV Cars Financing  
GV Credit Pte Ltd StarAd



click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

Subaru Outback

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Subaru Outback		Any	Any	2015	Any	Any	Any	Available
	Subaru Legacy Outback 2.5i-S		\$92,800	\$11,190 /yr	18-Nov-2015	2,498 cc	45,922 km	SUV	Available
1 Owner Only! Fully Agent Maintained In Beautiful Condition! Rare And Sought After Wagon! Muscular Look And Powerful Engine For A Great Ride. Minimum Down Payment With Bank Or In House Loan Available....									
Posted: 17-Jul-2018 Tags: 2015 Subaru Legacy, Subaru Legacy, Subaru, Legacy, Used Subaru									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Subaru Outback, Subaru Outback Singapore, used Subaru Outback Singapore, used Subaru Outback, used vehicles Singapore or even buy used Subaru Outback Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement  
©2004-2018 sgCarMart. All rights reserved.

Compare

**LONPAC INSURANCE BHD** (S98FC5635C)

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555.

Tel: (65) 6250 7388 Fax: (65) 6296 3767 Website: www.lonpac.com.sg

GST Reg No.: FB-0085635-C

MX1

**CERTIFICATE OF INSURANCE**

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE.  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE).  
ROAD TRANSPORT ACT 1987 (MALAYSIA).  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

Certificate No. : Z17VP05015665

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

SUBARU OUTBACK 2.5  
- SKW5258P

2. Name of Policy Holder

NG CHEE KEONG (HUANG ZHIQIANG)

3. Effective Date of the Commencement of Insurance  
for the purpose of the Act

31/10/2017

4. Date of Expiry of the Insurance

30/10/2018

5. Persons or Classes of Persons entitled to drive

(A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/HER PERMISSION  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so  
permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT  
COVER USE FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS  
(OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE  
MOTOR TRADE.

Excess : S\$ 1,500.00 (SECTION 1) INSURED / NAMED DRIVERS  
S\$ 3,500.00 (SECTION 1) UNNAMED DRIVERS  
S\$ 3,000.00 (SECTION 1) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG AND/OR INEXPERIENCED DRIVERS  
S\$ 100.00 WINDSCREEN EXCESS


LONPAC'S AUTHORISED WORKSHOPS

Condition : ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS

\* Limitations rendered Inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and  
Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor  
Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner : MAYBANK

  
CHIEF EXECUTIVE  
(Singapore Branch)User ID: MRMLP0014  
Date Issued: 17/10/2017

# KOON HENG MOTOR

(Reg. No: 24840700K)

BLK 1 KAKI BUKIT AVE 6 #02-14 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883

TEL: 67487348 FAX: 67432524

email: koonhengmotor@gmail.com

M/S **Lonpac Insurance Bhd**  
300 Beach Road #17-04/07  
The Concourse  
Singapore 199555  
Tel : 6250 7388  
Fax : 6296 2706

Estimation No : 19072018 / 5258

Type : OD

Date : 20/7/2018

A/C No : SKW5258P

## Re: ESTIMATION ON REPAIR COST TO VEHICLE NO: SKW5258P

Make/ Model : Subaru Outback2.5I-S CVT AWD  
Chassis No : JF2BS9KC2FG013584

Accident Date : 19/07/2018

Page 1/2

### PARTS REQUIRED

	Description	Qty	U/Price (S\$)	Amount (S\$)
1	Front Door Side Mirror Lower Cover	1	32.00	32.00
2	Front RH Door	1	500.00	500.00
3	Front RH Door Side Hinges	2	48.00	96.00
4	Front RH Door Stepper <del>Checker</del>	1	45.00	45.00
5	Front RH Door Wheel Rubber <del>front RH door rubber</del>	1	70.00	70.00
6	Front RH Door Lower Garnish <del>Rock panel garnish</del>	1	230.00	230.00
7	Front RH Door Moulding	1	168.00	168.00
8	Front RH Door Piler <del>Pillar</del>	1	300.00	300.00
9	Front RH Fender	1	280.00	280.00
10	Front RH Fender Dust Cover	1	80.00	80.00
11	Front RH Fender Dust Cover Clips	10	2.00	20.00
12	Front RH Fender Top Side Moulding	1	25.00	25.00
13	Front Bonnet	1	660.00	660.00
14	Front Bonnet Hinges	2	30.00	60.00
15	Front Bonnet Trim Cover Clips	10	3.00	30.00
16	Front RH Tyre Rim	1	576.00	576.00
17	Front RH Tyre Shock Absorber	1	245.00	245.00
18	Front RH Knuckle Arm	1	195.00	195.00
19	Front RH Knuckle Arm Bearing	1	145.00	145.00
20	Front RH Tyre Lower Arm	1	220.00	220.00
21	Front RH Tyre Drive Shaft	1	320.00	320.00
22	Front <del>Tyre FP Mounting</del> <del>Shock absorber mounting</del>	1	62.00	62.00
23	Anti Roll Bar <del>linkage RH</del>	1	26.00	26.00
				4,385.00
Add 15% On Parts				657.75
TOTAL SPARE PARTS				5,042.75

2729  
P-4179  
157  
4805.85  
6981.88  
5500

# KOON HENG MOTOR

(Reg. No: 24840700K)

BLK 1 KAKI BUKIT AVE 6 #02-14 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883

TEL: 67487348 FAX: 67432524

email: koonhengmotor@gmail.com

M/S

**Lonpac Insurance Bhd**

300 Beach Road #17-04/07

The Concourse

Singapore 199555

Tel : 6250 7388

Fax : 6296 2706

Estimation No : 19072018 / 5258

Type : OD

Date : 20/7/2018

A/C No : SKW5258P

**Re: ESTIMATION ON REPAIR COST TO VEHICLE NO: SKW5258P**

Make/ Model : Subaru Outback2.5I-S CVT AWD

Accident Date : 19/07/2018

Chassis No : JF2BS9KC2FG013584

Page 2/2

Balance B/F Of Spare Parts

5,042.75

## LABOUR CHARGES

- |    |   |
|----|---|
| 24 | TO KNOCK/REPAIR/WELDING OF DAMAGED PARTS, CHANGING OF ACCIDENT PART |
| 25 | TO SPRAY PAINT FOR AFFECTED AREAS                                   |
| 26 | TO WIRING   |
| 27 | TOWING FEES   |
| 28 | TO UNDER CARRIAGE   |
| 29 | SEAT CUSHION  |
| 30 | WHEEL ALIGNMENT   |
| 31 | TYRE 225/60R18  |

1,800.00

1,800.00

100.00

200.00

500.00

200.00

150.00

280.00

5,030.00

GRAND TOTAL AMOUNT (PARTS & LABOUR)

10,072.75

11,765.55

Insured parties hence notify the following:

- Before or after spray painting
- Before or after damaged part(s) during resurvey
- Repairs are subject to confirmation
- Survey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Any supplementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

not allowed  
2 hrs  
Take photo before painting  
5 days  
EXCESS \$1500  
Tel: 62563561  
1/5 \$5550.2

# KOON HENG MOTOR

(Reg. No: 24840700K)

BLK 1 KAKI BUKIT AVE 6 #02-14 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883

TEL: 67487348 FAX: 67432524

email: koonhengmotor@gmail.com

M/S **Lonpac Insurance Berhad**  
300 Beach Road #17-04/07  
The Concourse  
Singapore 199555  
Tel : 6250 7388  
Fax : 6296 2706

Estimation No : 19072018 / 5258

Type : OD

Date : 20/7/2018

A/C No : SKW5258P

## Re: ESTIMATION ON REPAIR COST TO VEHICLE NO: SKW5258P

Make/ Model : Subaru Outback 2.5I-S CVT AWD

Accident Date : 19/07/2018

Chassis No : JF2BS9KC2FG013584

### PARTS REQUIRED

	Description	Qty	U/Price (S\$)	Amount (S\$)
1	RH Head Lamp	1	1,450.00	1,450.00
2	RH Bumper Side Retainer	1	22.00	22.00
			TOTAL	1,472.00
			Add 15% ON Parts	220.80
			TOTAL SPARE PARTS	1,692.80

Cash Sale / Work Order

No: 13440

**LEE SHENG TOWING SERVICE**

1 Kaki Bukit Ave 6 #01 -60  
Singapore 417883

H/P: 9777 7373



**24 Hours Towing Services**

Date: 2/18

宝号 Messrs: Koon Heng Motor  
车号 Vehicle No: 54252587 车型 Model No: SUBARU 4WD

由 From: 100/500000 到 To: 2/9

时间(天/夜) Time (day/night): 1.2 towing & King Kong  
其他 Others: 100 150

CASH \$: 150

CHEQUE:

注意: 本公司对所拖之车辆, 在运行中如有任何损失或破坏, 一概由车主自行负责。  
NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misadventures to the towed vehicle.

150/500000

经手人  
Authorised by:

收货人  
Received by:



**Koon Heng Motor**

REG. NO. 24840700K



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018 <a href="#">Sendback Est</a>	20 Jul 2018 17:52 <b>S\$10,072.75</b>	23 Jul 2018 08:37 <a href="#">Edit Adj Rpt</a>	<b>S\$5,550.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	25 Jul 2018 17:53	25 Jul 2018 17:55 <b>S\$1,667.50</b>	25 Jul 2018 17:55			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>NG CHEE KEONG</b> , ID: S7527649D		
Vehicle Reg. No.:	<b>SKW5258P</b>	Date of Loss:	19/07/2018 00:00 - :59 [32 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>OD / 17/18/18/VP05/020771</b>	Policy/Cover Note No.:	Z17VP05015665 (Comprehensive) Coverage: 31/10/2017 - 30/10/2018
		Excess:	S\$1,500.00
Repairer:	<b>Koon Heng Motor (-)</b> 1 Kaki Bukit Ave 6, #02-14, Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6748 7348		
Handling Insurer:	<b>Lonpac Insurance Bhd (HQ)</b> - Tel: +65 62507388 ... [Handled by <b>Gerald Poh</b> - 6250 7388 ext 240]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 01/08/2018]		
Driver/Custodian:	NG CHEE KEONG (), NRIC: S7527649D		
Adj Asg. Remarks:	SURVEY & REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- LONPAC\_HQ (24/07/2018): Alert - Adj Mandate Approved (S\$5743.30) - SKW5258P - Claim Handler: Gerald Poh

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



## Claim Documents

SKW5258P (17/18/18/VP05/020771)






OD  
Jul 19 2018 12:00AM  
[NG CHEE KEONG]  
Koon Heng Motor

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

### Assessment Reports
















































1 per page ▼ ☒

No	Finalized On	Koon Heng Motor (-)	Thumbnail	Print
1	20/07/18 17:52	Repairer Estimates	 Load HTM	<input type="checkbox"/>
2	25/07/18 17:55	Repairer Estimates Suppl. #1	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 16:15	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
2	24/07/18 16:22	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
3	24/07/18 16:24	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>

### Photos/Images

3 per page ▼ ☒

No	Finalized On	Koon Heng Motor (-)	Thumbnail	Print
1	20/07/18 17:58	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	20/07/18 17:58	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	20/07/18 17:58	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	20/07/18 17:58	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	20/07/18 17:58	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	20/07/18 17:58	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	20/07/18 17:58	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	20/07/18 17:58	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/18 19:06	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	23/07/18 19:06	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	23/07/18 19:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports				<input checked="" type="checkbox"/>
No	Finalized On	Koon Heng Motor (-)	Thumbnail	Print
21	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
58	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
59	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
60	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
61	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
62	23/07/18 19:06	General View	 Load JPG	<input checked="" type="checkbox"/>
63	26/07/18 09:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/07/18 09:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/07/18 09:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/07/18 09:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/07/18 09:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/07/18 09:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				
No	Finalized On	Koon Heng Motor (-)	Thumbnail	Print
69	26/07/18 09:13	Reinspection Photo		Load JPG
70	26/07/18 09:13	Reinspection Photo		Load JPG
71	26/07/18 09:13	Reinspection Photo		Load JPG
72	26/07/18 09:13	Reinspection Photo		Load JPG
73	26/07/18 09:13	Reinspection Photo		Load JPG
74	26/07/18 09:13	Reinspection Photo		Load JPG
75	26/07/18 09:13	Reinspection Photo		Load JPG
76	26/07/18 09:13	Reinspection Photo		Load JPG
77	26/07/18 09:13	Reinspection Photo		Load JPG
78	26/07/18 09:13	Reinspection Photo		Load JPG
79	26/07/18 09:13	Reinspection Photo		Load JPG
80	26/07/18 09:13	Reinspection Photo		Load JPG
81	26/07/18 09:13	Reinspection Photo		Load JPG
82	26/07/18 09:13	Reinspection Photo		Load JPG
83	26/07/18 09:13	Reinspection Photo		Load JPG
84	26/07/18 09:13	Reinspection Photo		Load JPG
85	26/07/18 09:13	Reinspection Photo		Load JPG
86	26/07/18 09:13	Reinspection Photo		Load JPG
87	26/07/18 09:13	Reinspection Photo		Load JPG
88	26/07/18 09:13	Reinspection Photo		Load JPG
89	26/07/18 09:13	Reinspection Photo		Load JPG
90	26/07/18 09:13	Reinspection Photo		Load JPG
91	26/07/18 09:13	Reinspection Photo		Load JPG
92	26/07/18 09:13	Reinspection Photo		Load JPG
93	26/07/18 09:13	Reinspection Photo		Load JPG
94	26/07/18 09:13	Reinspection Photo		Load JPG
95	26/07/18 09:13	Reinspection Photo		Load JPG
96	26/07/18 09:13	Reinspection Photo		Load JPG
97	26/07/18 09:13	Reinspection Photo		Load JPG
98	26/07/18 09:13	Reinspection Photo		Load JPG
99	26/07/18 09:13	Reinspection Photo		Load JPG
Documentation			1 per page	
No	Finalized On	Koon Heng Motor (-)	Thumbnail	Print
1	20/07/18 17:57	Reports		Load TIF
2	20/07/18 17:57	Reports		Load TIF
3	20/07/18 17:57	Reports		Load TIF
4	20/07/18 17:57	Reports		Load TIF
5	20/07/18 17:57	Reports		Load TIF
6	20/07/18 18:00	Police Report		Load TIF
7	20/07/18 18:00	Police Report		Load TIF
8	20/07/18 18:00	Police Report		Load TIF
9	20/07/18 18:00	Police Report		Load TIF
10	20/07/18 18:00	Police Report		Load TIF
11	20/07/18 18:00	Copy of Insured's IC		Load TIF
12	20/07/18 18:00	Copy of Claimant's Identity Card		Load TIF
13	20/07/18 18:00	Insured's Driving License		Load TIF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 16:16	ESTIMATE		Load PDF
2	31/07/18 09:32	SUPPLEMENTARY		Load PDF

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse  
Singapore 199555

Our File No: CS/LPC18013348/UVD3S2  
Date: 03/08/2018

## REFERENCE

Insured/Claimant: NG CHEE KEONG Policy No: Z17VP05015665  
Date of Loss: 19/07/2018 Nature of Claim: OD Claim No: 17/18/18/VP05/020771

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKW5258P**  
Make & Model: SUBARU OUTBACK, 2.5 I-S CVT AWD SR (A) Engine No: FB25Y045175  
Reg. Date: 31/10/2015 (Man. Year: 2015) Chassis No: JF2BS9KC2FG013584  
Colour: Grey Odometer: 47845 km  
Engine Capacity: 2498 cc  
Market Value/New Car Price: S\$88,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/60R18 Rear Tyre Size: 225/60R18  
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm  
Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,710.25	4,805.85	1,904.40	28.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,030.00	2,180.00	2,850.00	56.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,740.25</b>	<b>6,985.85</b>	<b>4,754.40</b>	<b>40.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,550.00</b>		
<b>- Excess (S\$)</b>	0.00	1,500.00	-1,500.00	
<b>Nett Amount (S\$)</b>	<b>11,740.25</b>	<b>4,050.00</b>	<b>7,690.25</b>	<b>65.50</b>

## INSPECTION

Date of Assignment: 23/07/2018  
Date Inspected: 23/07/2018 Inspected At: Koon Heng Motor  
1 Kaki Bukit Ave 6, #02-14, Autobay@Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 03 Aug 2018)	
<b>Parts:</b>	N/A	SUBARU OUTBACK 2.5 I-S CVT AWD SR (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW5258P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Door Side Mirror Lower Cover (WCP)	Missing	32.00 F	*32.00 F
2	1		*Front RH Door (WCP)	Badly Dented	500.00 F	*500.00 F
3	1		*Front RH Door Side Hinges @ 2 pcs x \$ 48 (WCP)	Lower Bent	96.00 F	*48.00 F
4	1		*Front RH Door Stopper (WCP)		45.00 F	-
5	1		*Front RH Door Wheel Rubber (WCP)		70.00 F	-
6	1		*Front RH Door Lower Garnish (WCP)		230.00 F	-
7	1		*Front RH Door Moulding (WCP)	Not Necessary	168.00 F	*- F
8	1		*Front RH Door Piller (WCP)		300.00 F	-
9	1		*Front RH Door Piller		-	-
10	1		*Front RH Fender (WCP)	Distorted	280.00 F	*280.00 F
11	1		*Front RH Fender Dust Cover (WCP)	Torn	80.00 F	*80.00 F
12	10		*Front RH Fender Dust Cover Clips @ 10 pcs x \$ 2 (WCP)	Necessary	20.00 F	*20.00 F
13	1		*Front RH Fender Top Side Moulding (WCP)	Not Necessary	25.00 F	*- F
14	1		*Front Bonnet (WCP)	Repair	660.00 F	*- F
15	2		*Front Bonnet Hinges @ 2 pcs x \$ 30 (WCP)	Not Necessary	60.00 F	*- F
16	10		*Front Bonnet Trim Cover Clips @ 10 pcs x \$ 3 (WCP)	Not Necessary	30.00 F	*- F
17	1		*Front RH Tyre Rim (WCP)	Dented / Bent	576.00 F	*576.00 F
18	1		*Front RH Tyre Shock Absorber (WCP)	Bent	245.00 F	*245.00 F
19	1		*Front RH Knuckle Arm (WCP)	Bent	195.00 F	*195.00 F
20	1		*Front RH Knuckle Arm Bearing (WCP)	Necessary	145.00 F	*145.00 F
21	1		*Front RH Tyre Lower Arm (WCP)	Bent	220.00 F	*220.00 F
22	1		*Front RH Tyre Drive Shaft (WCP)	Not Necessary	320.00 F	*- F
23	1		*Front Tyre FP Mounting (WCP)		62.00 F	-
24	1		*Anti Roll Bar RH (WCP)		26.00 F	-
25	1		*Add 15% On Parts		657.75 F	*351.15 F
26	1		*Front RH Door Checker (WCP)	Not Necessary	-	*- F

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*Front RH Door Rubber (WCP)	Necessary	-	*80.50 F
28	1		*Rocker Panel Garnish (WCP)	Distorted	-	*264.50 F
29	1		*Front RH Door Pillar (WCP)	Not Necessary	-	*- F
30	1		*Front Shock Absorber Mounting (WCP)	Twisted	-	*71.30 F
31	1		*Anti Roll Bar Linkage RH (WCP)	Bent	-	*29.90 F
32	1		*RH BUMPER SIDE RETAINER (WCP)	Not Necessary	-	*- F
<b>Supplementary #1</b>						
33	1		*RH HEAD LAMP (WCP)	Cracked	1,450.00 F	*1,450.00 F
34	1		*ADD 15% ON PART		217.50 F	*217.50 F
F=Franchise part.						
					<b>Total Parts (S\$)</b>	<b>6,710.25      4,805.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To Knock/Repair/Welding of damaged Parts,Changing Of Accident Parts	New	1,800.00	900.00
2	To Spray Painting For Affected Areas	New	1,800.00	900.00
3	To Wiring	New	100.00	20.00
4	Towing Fees	New	200.00	150.00
5	To Under Carriage	New	500.00	150.00
6	Seat Cushion	New	200.00	0.00
7	Wheel Alignment	New	150.00	60.00
8	Tyre 225/60r18 (SERVICEABLE) (SN)	New	280.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,030.00</b>	<b>2,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >