

ASS. REC. BY:

REF:

03/AG18013350/Gvd3 n2

Special Instruction:

Surveyor
Mithoo Singh

GUO Qiang

ASSIGNMENT (Office)

From (Person):

Mithoo Singh

of

ALG

Date/Time: 23/7/18 @ 11:54am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 9998M

Insured:

SLN 3044M

at Workshop m/s

King's Auto

Tel:

6457 8629

of 31k 176, Sin Ming Drive # 02-10

Policy No:

2100508503

Claim No:

83285163485G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/07/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:30pm @ 23/7/18

Person Contacted:

Annie

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLF 9998M - X
	SLN 3044M - X
31/7/18	@ 2:28pm Alex said est. not ready
21/8/18	@ 4:19pm Alex said still pending parts prices from supplier

Est. Repairs:

20 days

Res.: Yes or No

D.O.A.

D.O.I.

Lump Sum:

20 %

3 Val.: Yes or No

Survey held at

w/s

2:30pm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/7	Estimate given later.
19/11	LS \$6250 hwd: 21 with Alex. (Red 4960.12, 4490)

RECEIVED 19 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

6

1)

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

19/11 - typst

Add Fee:

☐

Site Insp (\$)

) \$ + RS. SI

250
20☐

Interview (\$)

) Photos

Report Format:

Mithoo

☐

Tech. Invs (\$)

) Others

Lump Sum / I.B.I. (\$)

6250/2

☐

Weekend (\$)

)

TOTAL

270