


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF272E
Ref. No : TAX/07/18/2070
Reg. Date : 10/10/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : NG KIAN HUA
Type of Accident : HEAD TO REAR
Date / Time of Accident : 15/07/2018 08:00:00 AM
Accident Reported Date / Time : 16/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097058
Special Instruction to ARC, if any :
SLT9178P
Prepared Date : 16/07/2018 04:44:10 PM



Sathya Sen
18/7/2018

2 days

- Part by Part repair
- Question mark item photo
- Photo before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603572557

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 338.00

0.00

Total Spray Painting Charges : 558.00

0.00

Total Material Charges : 1,325.39

1,325.39

Other Charges : 576.88

0.00

TOTAL : 2,798.27**0.00****Lum Sum Total : 0.00****0.00**

No. of Repair Days : 4.00

~~0.00~~ 2 days

Prepared / Adjusted By :

Arc / Surveyor Sign Off Date : 17/07/2018 06:40:39 AM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/07/2018 10:37:43 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	576.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY ✓ <i>CRK</i>	1	423.90	25.00	317.92	Replace	Replace	No
			PIXEL STICKER ✓ <i>NEC</i>	2	60.00	0.00	120.00	Replace	Replace	No
			SENSOR REVERSE ?	1	180.00	0.00	180.00	Replace	Replace	No
52462470 30			PAD, RR BUMPER, RH & LH, 1 X	2	3.80	25.00	5.70	Replace	Replace	No
52462470 20			PAD, RR BUMPER, RH & LH, 2 X	2	3.80	25.00	5.70	Replace	Replace	No
52462470 10			PAD, RR BUMPER, RH & LH, 3 X	2	3.80	25.00	5.70	Replace	Replace	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH X	2	11.00	25.00	16.50	Replace	Replace	No
52453470 10			GUARD, RR BUMPER LOWER ? ✓ <i>action</i>	1	558.30	25.00	418.72	Replace	Replace	No
52169470 20			COVER, GUARD RR BUMPER LOWER ✓ <i>cut</i>	1	14.80	25.00	11.10	Replace	Replace	No
52461470 10			PAD, RR BUMPER, CTR ?	3	2.20	25.00	4.95	Replace	Replace	No
52023470 30			REAR BUMPER REINFORCEMENT ?	1	318.80	25.00	239.10	Replace	Replace	No
TOTAL MATERIALS								1,325.40	1,325.39	
TOTAL MATERIALS(Discounted)								1,325.39	1,325.39	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									