

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

2/ 08/TP180/13387/Utbn2

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB9131Y

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLB9131Y Yr Regn: 4, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: KIA Forte K3 c.c. 1591

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 40260 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAF2411MG.5570946

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45ZR17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIN / SUMI /

TOYO / YOKO or

Front: 7 mm Rear: 7 mm

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 14/7/18 D.O.I. 23/7/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Ninc S. lly ASX.

4/5 &amp; 20/12 (Red. 36321 64%)

RECEIVED 31 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format : TP

Lump Sum / I.B.I. (\$) 20501

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

140
50
50
32
80
352

Ref. No : <u>CS7TP18013387/446</u>	Res. Date: <u>25/7/18</u>	Date Received:
Veh. No : <u>SLB91317</u>	SP: _____	WKSP: <u>Ben</u>
C/No : _____		
<b>Action/Instruction:</b>		
1.File	2.Submit Photo?	YES / NO
3.Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation	b) Days of repair
others:		
Final Re-inspection or Progress Photos		Inspected By:

MSG18090324 / SMC Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 13/07/2018 12:18  
SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 13/07/2018 12:18  
Date Of Accident 12/07/2018 18:45  
Exact Location Of Accident JALAN TOA PAYOH (PIE)  
Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SLB9131T  
**Insured/Policyholder**  
Name Of Registered Owner SEAH LIEU CHIN PAMELA  
NRIC No S8429651A  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-93633397  
Alternative Phone No OFFICE-93633397  
**Vehicle Particulars**  
Manufacturer KIA  
Model FORTE K3  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR  
**Insurance Company**  
Name of Insurance Company AXA INSURANCE PTE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number GA185008  
Cover Note Number  
**Driver**  
Name of Driver SEAH CHYE YONG  
NRIC No S0157596A  
Date Of Birth 04/06/1952  
Occupation INDOOR  
Date Of Driving Pass 23/04/1976  
Driving Experience 42 YEARS AND 2 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-96622171  
Fax Number  
Contact Number  
Email Address NOEMAIL

Address 31 ELIAS ROAD #12-22  
 Postcode 519934  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured PARENT  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

### General Information of the Accident

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3  
 Passenger 1  
 NAME: : WONG LENA  
 GENDER: : FEMALE  
 Passenger 2  
 NAME: : SHANE TAN  
 GENDER: : MALE

### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

I WAS DRIVING ALONG JALAN TOA PAYOH (PIE) ON 12/07/2018 AT ABOUT 6.45PM. TRAFFIC VOLUME WAS MODERATE. I WAS DRIVING ON THE SECOND LANE. I SAW TWO BIKES ON MY RIGHT SIDE IN BETWEEN LANE 1 AND LANE 2. SUDDENLY, I HEARD A BANG ON THE RIGHT SIDE OF MY CAR. I STOPPED MY CAR IN FRONT, I ALIGHTED FROM MY CAR AND I SAW THE BIKE AND THE RIDER LYING ON THE ROAD. IMMEDIATELY, I RAN OVER TO ASSIST HIM. THE RIDER TOLD ME THAT HE TRIED TO AVOID A CAR ON HIS RIGHT SIDE. HIS BIKE SWERVED AND SKIDDED THUS HIT THE RIGHT SIDE OF MY CAR. WE EXCHANGE OUR PARTICULARS.

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBM9335H  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category MOTORCYCLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or Court orders.

  
 Policyholder's Signature

Date &amp; Time: 13/7/18, 10:40AM

  
 Driver's Signature

(if driver is not the policyholder)

Date &amp; Time: 13/7/18, 10:40AM


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Jalan Taci Payoh (PIE) on 12/7/18 at about 645pm. Traffic volume was moderate. I was driving on the second lane. I saw two bikes on my right side in between lane 1 and lane 2. Suddenly I heard a bang on the right side of my car. I stopped my car in front. I alighted from my car and I saw the bike, <sup>and the rider</sup> lying on the road. Immediately I ran over to assist him. The rider told me that he tried to avoid a car on his right side. His bike swerved and skidded thus hit the right side of my car. We exchanged our particulars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
Policyholder's Signature  
Date & Time: 13/7/18, 1052 AM

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 13/7/18, 1052 AM

13/7/18 11.10 AM  
Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9651A
<b>Vehicle Details</b>	
Vehicle No.:	SLB9131T
Vehicle to be Exported:	No
Intended De-registration Date:	24 Jul 2018
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A SX
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	G4FGFH608516
Chassis No.:	KNAFZ411MG5570946
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$16,306.00
Original Registration Date:	27 Apr 2016
First Registration Date:	27 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$16,306.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2026
PARF Rebate Amount:	\$12,229.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$36,683.00
<b>Total Rebate Amount:</b>	<b>\$48,912.00</b>

The information contained herein is correct as at 24 Jul 2018

OK





# BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
(Unit C) #01-28-53/55 Singapore 417883  
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
Website: www.bluwel.com.sg Email: bluwei2088@yahoo.com.sg  
Co. Reg. No.: 200704951N  
GST Reg. No.: 200704951N

SLB91317

Front door o/s	Body	1277.00	
Front door inner rubber o/s	A1	121.00	X
1 set Front door frame black sticker o/s	1ea	68.00	
Front door glass regulator o/s	A1	266.00	X
Front door glass regulator motor o/s	shld	362.00	
Front door inner trim board o/s	A1	654.00	X
Recliner panel o/s	2	1354.00	X
	102	4102.00	
To check wiring		50.00	20
To spray rust proofing		60.00	50
To Dismantle & refix seat cushions, garnish		120.00	80
labour for panel beating & replacing parts		600.00	400
To putty & spray painting		800.00	500
		TOTAL \$5732.00	

not attached  
2hr  
2/5/2020  
4hr.

1707

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18013387/Utbn2

BLK 1 KAKI BUKIT AVE 6  
#01-28/51/53/55(MAIN OFFICE)SINGAPORE  
417883

Date : 01-08-2018



ON BEHALF OF SEAH LIEU CHIN PAMELA

Code : TP149

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLB 9131T
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	23/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3 (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNAFZ411MG5570946	Colour	BLACK
Odometer	40260	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 ZR17	PIRELLI	7 mm
L/H Front Tyre	215/45 ZR17	PIRELLI	7 mm
R/H Rear Tyre	215/45 ZR17	PIRELLI	7 mm
L/H Rear Tyre	215/45 ZR17	PIRELLI	7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	12/07/2018	Inspection Date	23/07/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 9131T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR O/S	BADLY DENTED	1,277.00	1,277.00
1	FRONT DOOR INNER RUBBER O/S	NOT NECESSARY	121.00	-
1	SET FRONT DOOR FRAME BLACK STICKER O/S	NECESSARY	68.00	68.00
1	FRONT DOOR GLASS REGULATOR O/S	NOT NECESSARY	266.00	-
1	FRONT DOOR GLASS REGULATOR MOTOR O/S	SHORTED	362.00	362.00
1	FRONT DOOR INNER TRIM BOARD O/S	NOT NECESSARY	654.00	-
1	ROCKER PANEL O/S	TO REPAIR SEE LABOUR	1,354.00	-
	LESS 10% DISCOUNT		-	-170.70
			4,102.00	1,536.30
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		60.00	50.00
	TO DISMANTLE & REFIX SEAT,CUSHION,GARNISH.		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF ROCKER PANEL O/S.		600.00	400.00
	TO PUTTY & SPRAY PAINTING.		800.00	500.00
			1,630.00	1,050.00
<b>GRAND TOTAL</b>			<b>5,732.00</b>	<b>2,586.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,050.00</b>

Report Ref No. CS/TP18013387/Utbn2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.