

(08/11/13) wef

ASS. REC. BY: MORCUS

REF:

TR/ CS/TP18013388/49602

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP/WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SFT82Lat Workshop m/s Sum

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 45

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 27A 38084

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFT82L Yr Regn: 7110Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Audi A6 c.c. 2773Colour: Black A/C: Insured / Std / NI / NASp. Reading: 212288 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ4FIAN054196

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/7/18 D.O.I. 24/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2yr repair4/5 @ 6050(Red @ 9133.10, 60%)

RECEIVED 31 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report1) 30/7/18☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 6050

5x15=75

170+75
50
50
65
80
490

Ref. No : <u>CS/TP/8013388/1096 n2</u>	Res. Date: <u>25/7/18</u>	Date Received:
Veh. No : <u>SF182L</u>	SP:	WKSP: <u>22/</u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	
3. Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection or Progress Photos		Inspected By: <u>[Signature]</u>

MSME18001328 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 16/07/2018 13:05
SUBMITTED BY: CHIAI PAI YING

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available at the centre.

ACCIDENT STATEMENT

Date Of Report 16/07/2018 13:05
Date Of Accident 14/07/2018 02:35
Exact Location Of Accident TEBING LANE (CARPARK)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFT82L
Insured/Policyholder
Name Of Registered Owner CHAN GEOK CHYE
NRIC No S1125297D
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98199299
Alternative Phone No OFFICE-98199299
Vehicle Particulars
Manufacturer AUDI
Model A5
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number GA141144
Cover Note Number
Driver
Name of Driver ISAAC CHAN YANG ZHI
NRIC No S9416708F
Date Of Birth 06/05/1994
Occupation INDOOR
Date Of Driving Pass 22/11/2012
Driving Experience 5 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98199299
Fax Number
Contact Number
Email Address NOEMAIL

Address 82 BEDOK TERRACE
 Postcode 469241
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY CAR A WAS PARKED IN A VIP LOT. A SECURITY GUARD CAME AND INFORM ME THAT CAR B WHILE DOING A REVERSING HIT THE FRONT OF MY CAR A.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKT314J
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver JUNNAYDY TEO JUN HONG
 NRIC/Passport Number S9520295J
 Contact Number 97507591
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature

Date & Time: 16/11/18 04:57 PM


 Driver's Signature

(If driver is not the policyholder)

Date & Time: 16/11/18 04:57 PM


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car (A) was parked in a VIP lot. A security guard came to inform me that car B while doing reversing, hit the front of my car (A).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 16/11/18, 10:45 am

Driver's Signature
(if driver is not the policyholder)
Date & Time: 16/11/18, 10:45 am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GUARMC SketchPlanForm_v3

2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5297D
Vehicle Details	
Vehicle No.:	SFT82L
Vehicle to be Exported:	Yes
Intended De-registration Date:	24 Jul 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.8 FSI QUATTRO
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	CCE022205
Chassis No.:	WAUZZZ4F1AN054196
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$50,050.00
Original Registration Date:	30 Jul 2010
First Registration Date:	30 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$50,050.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2020
PARF Rebate Amount:	\$30,030.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jul 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$41,000.00
COE Rebate Amount:	\$8,054.00
Total Rebate Amount:	\$38,084.00

The information contained herein is correct as at 24 Jul 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!**How much is my car worth?**

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Estima 2.4A



\$5800 Downpayment Monthly
From \$938 Onwards. Lowest
3.68% P.A. @ Gv Cars Financing
GV Credit Pte Ltd [StarAd](#)

ABWIN




Browse by Category ▼

Sort by

3 vehicles

Audi A6

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	Audi A6		Any	Any	2010	Any	
	Audi A6	Audi A6 2.0A TFSI MU	\$45,088	\$10,860 /yr	31-Aug-2010	1,984 cc	
Great Short Term Drive! Drive With Peace Of Mind! Problem Free Unit With Warranty! Luxurious And Powerful For The C Affordable As Japanese Saloons! Yet More Classy! Own T...							
Cars 88 Pte Ltd							
Posted: 19-Jul-2018 Tags: 2010 Audi A6, Audi A6, Audi, A6, Used Audi							
	Audi A6	Audi A6 2.0A TFSI MU	\$44,800	\$10,460 /yr	20-Sep-2010	1,984 cc	11
Excellent Condition, No Repairs Needed. Accident Free, Bank Loan In House Loan Available. 3 Months Warranty From O...							
Posted: 16-Jul-2018 Tags: 2010 Audi A6, Audi A6, Audi, A6, Used Audi							
	Audi A6	Audi A6 2.8A FSI MU	\$55,000	\$15,580 /yr	08-Jul-2010	2,773 cc	
Very Well Maintained And Groomed. Immaculate Condition. Wear And Tears All Done With Receipts. 100% Accident Free Of Mind! Trade In And High Loans Available. Call/SMS Now T...							
Monster Motors Pte Ltd							
Posted: 29-May-2018 Tags: 2010 Audi A6, Audi A6, Audi, A6, Used Audi							

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
------	-------	-------	--------------	----------	---------	---------

For old advertisements, view [Expired ads](#)



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

SFT82L

	Front bumper	20/02	1842.45	✓
2pc	Front bumper side retainers @45.00	new	90.00	✓
	Front bumper reinforcement	Surf	641.50	✓
	Front bumper towing cover	1	30.00	✓
2pc	Front bumper chrome mouldings @181.00	new	362.00	✓
	Front bumper fog lamp grille o/s	to. n	93.90	✓
	Front bumper sensor o/s	sub	185.00	✓
	headlamp o/s	one	2436.25	✓
	Front grille	one	649.00	✓
	Front licence plate garnish	to. n	152.50	✓
	Front support panel	1	875.50	✓
	Bumper	1	3991.00	✓
	Front fender o/s	1	1082.00	✓
	Front licence plate with holder	one	42.00	✓
			12473.10	
			6499.6	

To check wiring	50.00	- 20
To spray rust proofing	11 50.00	✓
To dismantle & replacing front bumper sensor	80.00	- 50
To refill air con gas	11 150.00	✓
labour for panel beating & replacing parts	880.00	- 600
To putty & spray painting	1500.00	- 750
	TOTAL @ 15183.10	

LKK Auto Consultants hence notify the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7589.81
 6071



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18013388/Uqbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 01-08-2018



ON BEHALF OF CHAN GEOK CHYE

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SFT 82L
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	24/07/2018

2. Vehicle Particulars & Condition

Make & Model	AUDI A6 (A)	c.c	2773
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WAUZZZ4F1AN054196	Colour	BLACK
Odometer	212286	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	6 mm
L/H Front Tyre	245/40 R18	PIRELLI	6 mm
R/H Rear Tyre	245/40 R18	PIRELLI	6 mm
L/H Rear Tyre	245/40 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/07/2018	Inspection Date	24/07/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFT 82L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED / DEFORMED	1,842.45	1,842.45
2	FRONT BUMPER SIDE RETAINERS @\$45.00	NECESSARY	90.00	90.00
1	FRONT BUMPER REINFORCEMENT	BENT	641.50	641.50
1	FRONT BUMPER TOWING COVER	TO REPAIR SEE LABOUR	30.00	-
2	FRONT BUMPER CHROME MOULDINGS @\$181.00	NECESSARY	362.00	362.00
1	FRONT BUMPER FOG LAMP GRILLE O/S	TORN	93.90	93.90
1	FRONT BUMPER SENSOR O/S	SHORTED	185.00	185.00
1	HEADLAMP O/S	CRACKED	2,436.25	2,436.25
1	FRONT GRILLE	CRACKED	649.00	649.00
1	FRONT LICENCE PLATE GARNISH	TORN	152.50	152.50
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	875.50	-
1	BONNET	TO REPAIR SEE LABOUR	3,991.00	-
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	1,082.00	-
1	FRONT LICENCE PLATE W/HOLDER	CRACKED	42.00	42.00
	LESS 5% DISCOUNT		-	-324.73
			12,473.10	6,169.87
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO DISMANTLE & REPLACING FRONT BUMPER SENSOR.		80.00	50.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	150.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER TOWING COVER,FRONT SUPPORT PANEL,BONNET AND FRONT FENDER O/S.		880.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	750.00
			2,710.00	1,420.00
GRAND TOTAL			15,183.10	7,589.87
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,050.00

Report Ref No. CS/TP18013388/Uqbn2



Report Ref No. CS/TP18013388/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.