MG SOLUTION PIE LTD

23 Kaki Bukit Ave 4 (South Wing) #02-03B Vicom Inspection Centre, Singapore 415933

10 10-0		Rehnia.
1.4 1.4 2		360 10-
	43 (373	43 1373 Fext 69

Date : 33/X/4 Co. Reg. No.: 201427944N . # Velhele in 5 TRP 97)

TO : ECICS LIMITED

By Fax & Email

10 : 6337 (779 500 : 6337 (779

Email: Claims Gecics. Com'sg

Atin: Motor Claims Department

Dear Sir,

Re: Accident involving motor vehicle Nos. JRP 9779 and Sta 2767 yalong at Tuas Checkpoint towards malaysix on 21/7/18

As a result of the accident, our client's / customer's vehicle has been damaged. Before our client / we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a Pre- Repair Survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client / we shall proceed to repair the vehicle without further reference to you.

Thank you.

Yours MIGHTINK.

OF MIGHTINK.


MS. HENGYCKE HOVE

MS. HENG YOKE HONG HP: 9188 6931 FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed Surveyor: __ (Name & Signature)

Date & Time of inspection: _





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865

1 of 3 Report No. T/20180723/2048


TelNo: 65470000

REPORT	OFA	TRAFFIC	ACCIDENT
--------	-----	---------	----------

Date/Time Report Made: 23/07/2018 12:23		Made:	Vide Report No.:	Station Diary No.:	
Informant	's Partic	ulars			
Name of It	SIONG		Address: 442B FAJAR RD #12-30 SIN	GAPORE 672442	
ID Type / I FIN NO / C		Р	Contact No.: Home/Office:		
Nationality: SINGAPORE CITIZEN		ΕN	Email:	Mobile: 92335165	
Sex: Male	Age: 30	Date of Birth: 23/05/1988	Type of Informant:		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: CONSTRUCTION			Driving Licence Information: Class:	Date of Expiry:	

General Inford	mation of the Acciden				
Type of A∝cident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident:	Type of Location:	
Location: Along Road 1 TUAS WEST		1100	21/07/2018 18:00		
TUAS CHECK Weather:	POINT	T			
troctioi.		Road Surface:	R	oad Speed Limit:	
Traffic Flow:		Traffic Control:			
			l l r	Traffic Volume:	
Type of Collision	on:				
			Ar an No	nyone conveyed by nbulance; o	

Vehicle No. Type	Involved Make	Model			
JRP9779		1410uel	COIOF	Condition	No of Passenger
	\				0
SKA2767Y					
ļ	ļ				0





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000


2 of 3 Report No. T/20180723/2048

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION

I WAS AT TUAS CHECKPOINT HEADING TOWARDS MALAYSIA. I WAS TRAVELLING ON THE DRIVEWAY AFTER HAVING MY PASSPORT CLEARED. I WAS DRIVING WHEN SUDDENLY A SINGAPORE CAR(SKA2767Y) CAME OUT FROM ANOTHER COUNTER AND COLLIDED INTO THE LEFT SIDE OF MY CAR. MY CAR IS A MALAYSIAN CAR.





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20180723/2048

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
MUHAMMAD SYUKRI BIN ABU BAKAR	
Signature Of Interpreter: Not applicable	Date/Time: 23/07/2018 12:23
Officer In Charge Of Case: TP/ AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case: SINGAPORE POLICE FORCE
Authentication Stamp	Signature: