

ASSIGNMENT

From: _____ Date: 18/07/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMB 5893S

at Workshop m/s: SMRT

of: Woodlands

Insured: YN 7812X

Policy No: 5076879890-02 01.01.2018

Claims No: MT/1008100-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: before 2pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMB 5893S Yr Regn: NOV 2015

Type: M.Car / M.Cycle (Bus) / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MAN C.C. 10518

Colour: Multicolour A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: 50342170624215

C/No: WMAA 9522867003046

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275 / 70 R22-5

R: 275 / 70 R22-5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fireenza

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/7/2018 D.O.I. 18/7/2018

Survey held at SMRT

Des. of Damages (P) / Rear (O/S) / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction
	SMB 5893S - NS/INC 18013449/3449
	YN 7812X - X
	(\$ 5,253.91 Red - 50%)
	RECEIVED 21 AUG 2018

Date/Time, File Pass to? 01/08/18

1) Typist

Date/Time, File Return to? _____

2) _____

Report Format :

Lump Sum / I.B.I. (\$) 5,150/- L/S

Days Of Repair: 2

Resurvey No. of Trip: /

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

Survey Fee: 160

Transportation: S + RS. SI

Photos

Others

TOTAL 160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013449/Vsb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 24-07-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7842X	Veh. Inspected	SMB 5893S
Policy No.	5076879890-02	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/07/2018	Inspection Date	18/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	13/07/2018 18:05						
Vehicle No.(For Motor)	YN7842X								
Search									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5076879890-02	HUP HENG POULTRY INDUSTRIES PTE LTD	199004442Z	GFT	Comprehensive	YN7842X	YN7842X	01/01/2018	
Continue									

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1008100-001	SMRT BUSES LTD	SMB 5893S	YN 7842X	13/7/2018	\$ 10,403.91	\$ 5,150.00
2	MT/1006439-002	COMFORT TRANSPORTATION PTE LTD	SHC 8823D	SJM 9957T	8/8/2018	\$ 2,433.30	\$ 1,100.00
3	MT/1006711-002	COMFORT TRANSPORTATION PTE LTD	SH 2201G	GBH 1995G	8/8/2018	\$ 3,592.00	\$ 700.00
4	MT/1006359-002	CITYCAB PTE LTD	SHC 239T	FW 822C	7/8/2018	\$ 3,097.20	\$ 2,000.00

Claim received from LKK Auto

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SMB5893S		
Vehicle Type :	H20 - Public Transport Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	OmniBus (SMRT - ARF-exempted)		
Vehicle Make :	MAN		
Vehicle Model :	A95		
Chassis No. :	WMAA95ZZ8G7003046		
Propellant :	Diesel		
Engine No. :	50342170624215		
Engine Capacity :	10518 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	23100 kg		
Unladen Weight :	14880 kg		
Year Of Manufacture :	2015		
Original Registration Date :	11 Nov 2015		
Lifespan Expiry Date :	10 Nov 2032		
Road Tax Expiry Date :	10 Nov 2018		
Inspection Due Date :	10 Nov 2018		
Intended Transfer Date :	23 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 20 August 2018 1:29 PM
To: 'Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)'; 'Sathya Sai (LKK Auto)'; 'SUR'; 'Admin A'
Cc: 'Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC)'; 'AutoSvs-ARC (Bus)'; 'Bryan Ang (LKKAuto)'
Subject: RE: Finalisation - SMB5893S (BUS/07/18/1013) - IDAC

Dear Catherine,

Confirm final fig \$5,150/- @ 2 working days under lump sum repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) [mailto:catherineleesc@smrt.com.sg]
Sent: Wednesday, 8 August 2018 12:04 PM
To: Sathya Sai (LKK Auto) <SathyaSai@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; AutoSvs-ARC (Bus) <AutoSvs-ARCBus@smrt.com.sg>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Subject: Finalisation - SMB5893S (BUS/07/18/1013) - IDAC

Hi Sathya,

Attached herewith our copy and your marked copy of the bus repair estimate for the case.
Our finalised amount is \$5,150/- @ 2 working days under lump sum repair.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



Moving People, Enhancing Lives

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2018 09:11
Date Of Accident	13/07/2018 07:50
Exact Location Of Accident	LENTOR AVENUE AFT (BS: 59019 - AFT SG SELETAR BRID
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB5893S
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MAN
Model	BUS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	DII027592MFBP
Cover Note Number	

Driver

Name of Driver	KOH YAU CHEE
Passport No/FIN	G2752616R
Date Of Birth	20/12/1982
Occupation	OUTDOOR
Date Of Driving Pass	07/03/2016
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "personal information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: BALQISH NRIC/FIN No.: SB 34 0325Z
--	---	--

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB5893S
 Ref. No : BUS/07/18/1013
 Reg. Date : 01/01/1900
 Vehicle Type : DOUBLE DECK
 Make : A95MAN
 Model : MAN A95
 Name of Driver : Koh Yau Chee
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 13/07/2018 07:50:00 AM
 Accident Reported Date / Time : 17/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : LKK
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 Right view mirror damaged
 TP: YN7842X (NTUC) - LKK
 Prepared Date : 18/07/2018 10:28:16 AM



LKK Auto Consultancy - to be notified
 the Repairer of the
 • To resurvey before a repair is completed
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Must Prejudice" basis
 • No illegal implications, as allowed
 • Supplemental's item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sathya Sai
 13/7/2018

- Part by Part
 - Photo before paint

Priority
 26/7/2018

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	0.00 1060
Total Labour	1,325.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses



Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

7242.40

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB5893S
Ref. No : BUS/07/18/1013
Reg. Date : 11/11/2015
Vehicle Type : DOUBLE DECK
Make : A95MAN
Model : MAN A95
Name of Driver : Koh Yau Chee
Type of Accident : SIDE SWIPE
Date / Time of Accident : 13/07/2018 07:50:00 AM
Accident Reported Date / Time : 17/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097089
Special Instruction to ARC,if any :
Righr view mirror damaged
TP: YN7842X (NTUC) - LKK
Prepared Date : 18/07/2018 10:28:16 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WMAA95ZZ8G7003046


Mileage : 0

Work Shop :

Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,325.00	1,060.00
Total Spray Painting Charges	: 0.00	0.00
Total Material Charges	: 4,277.73	4,277.73
Other Charges	: 0.00	-200.00
TOTAL	: 5,602.73	5,137.73
Lump Sum Total	: 5,600.00	5,150.00
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	: Sunny Tan Ah Leong	Sathya
Arc / Surveyor Sign Off Date	: 18/07/2018 11:57:48 AM	18/07/2018 03:20:20 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/07/2018 11:57:48 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	1,060.00
Total Labour	1,325.00	1,060.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	0.00	-200.00
Total Other Costs	0.00	-200.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
4001M01-ACCE467	RIGHT	6010161	FRONT VIEW MIRROR RH	1	1,244.90	10.00	1,120.41	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	10	37.00	0.00	370.00	Replace	Replace	No
		4006315	ACTIVATOR	1	80.00	0.00	80.00	Replace	Replace	No
	COMMON	4006313	PRIMER	1	80.00	0.00	80.00	Replace	Replace	No
		6000917	IU BRACKET	0	35.00	0.00	0.00	Replace	Not given	No
G20.05.01.03			SCREEN LOWER (A95)	1	4,107.50	10.00	3,696.75	Replace	Replace	No
TOTAL MATERIALS							5,347.16	5,347.16		
TOTAL MATERIALS(Discounted)							4,277.73	4,277.73		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013449/Nsbe2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 04-09-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 7842X	Veh. Inspected	SMB 5893S
Policy No.	5076879890-02	Coverage (\$)	0.00
Claim No.	MT/1008100-001	Excess (\$)	0.00
Assign From		Assign Date	18/07/2018
2. Vehicle Particulars & Condition			
Make & Model	MAN A95	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMAA95ZZ8G7003046	Colour	MULTI COLOUR
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/07/2018	Inspection Date	18/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 5893S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT VIEW MIRROR RH	BROKEN	1,244.90	1,244.90
1	SCREEN LOWER (A95)	CRACKED	4,107.50	4,107.50
	LESS 10% DISCOUNT		-	-535.24
			5,352.40	4,817.16
SPECIAL NETT ITEMS				
10	SEALANT SIKAFLEX @\$37.00 (SN)	NECESSARY	370.00	370.00
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
1	PRIMER (SN)	NECESSARY	80.00	80.00
1	IU BRACKET (SN)	NOT NECESSARY	35.00	-
			565.00	530.00
LABOUR				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		1,325.00	1,060.00
			1,325.00	1,060.00
GRAND TOTAL			7,242.40	6,407.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,150.00

Report Ref No. NS/INC18013449/Nsbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SKETCH PLAN

④ 536859ms

Bus (A) _____ LENTOR AVENUE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO REPORT

DECLARATION

/We declare the foregoing particulars are true in every respect.

Policyholder's Signat
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FIN No.: S8340325Z



Address	6 ANG MO KIO ST 62
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	10

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY BUS WAS TRAVELLING STRAIGHT ALONG LENTOR AVENUE AFTER EXITING BUS STOP 59019 (AFT SG SELETAR BRIDGE). A LORRY (YN7842X) HAD OVERTOOK MY BUS FROM BEHIND ON THE RIGHT AND CUT INTO MY PATH HENCE THE LEFT REAR PORTION OF THE SAID LORRY COLLIDED ONTO THE RIGHT VIEW MIRROR OF MY BUS. NO INJURY REPORTED. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7842X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WANG XIAOYANG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	