

REF:


NS/INC 18013462 / Nrbaz

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **SJG 1130 X**
 Policy No: **509737275** **10012018-09012019**
 Claims No: **MT/1011180-001**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No **SHB 1807 C** Yr Regn: **Feb / 2015**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /
 Truck / Trailer or _____
 Make: **Toyota Prius** C.C. **1798**
 Colour **Maroon** A/C: Insured / Std / NI / NA
 Sp. Reading **400086** T/Radio Insured / Std / NI / NA
 Eng/No: **2ZR6308247**
 C/No: **JTDKN36U205758530**
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **195/65 R15**
 R: **195/65 R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Falken (Frt) Achilles (Rear)**

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 18/7/2018	D.O.A. 18/7/2018

Survey held at **SMRT**Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB 1807C - CC3 / LCR 8005591 / Spb3 DA: 160818 TAX/07/18/2079
	SJG 1130 X - X
	11/9/18pm Confirmed, 12 @ 1150f and 3 days with Poh Guan. (Red 1980.38, 63%) NTue
	RECEIVED 12 SEP 2018
	- SJG 1130 X

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: **3**Resurvey No. of Trip: **2**

Survey Fee:

Date/Time File Return to?

3)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Transportation

) \$ - RS \$

) Photos

) Others

Report Format: **TP**Lump Sum / I.B.I: (\$ **1150f**)

TOTAL

160

TP Claims against NTUC Income: Follow-Through Survey

Date : 12/09/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1003231-002	SMRT TAXIS PTE LTD	SHC 4304L	SLP 5483E	16/07/2018	7:40	\$ 2,615.80	\$ 1,150.00
2	MT/1003062-002	SMRT TAXIS PTE LTD	SMB 1647M	YN 5332P	16/07/2018	7:05	\$ 10,579.30	\$ 5,700.00
3	MT/1011180-001	SMRT TAXIS PTE LTD	SHB 1807C	SIG 1130X	18/07/2018	9:15	\$ 3,130.38	\$ 1,150.00
4	MT/1004097-003	SMRT TAXIS PTE LTD	SHD 6234L	GBA 177U	22/07/2018	22:05	\$ 12,277.40	\$ 4,735.09
5	MT/1003320-002	SMRT TAXIS PTE LTD	SHC 4544K	SDT 3015K	16/07/2018	0:50	\$ 8,587.11	\$ 3,650.00

Claim received from LKK



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013462/Vrb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 24-07-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJG 1130X	Veh. Inspected	SHB 1807C
Policy No.	5097327275	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	18/07/2018	Inspection Date	18/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Tuesday, 11 September 2018 4:59 PM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'
Subject: RE: SHB1807C

Dear Poh Suan,

Confirmed Lump Sum \$1,150.00 and 3 days.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Sunday, 5 August 2018 11:10 AM
To: Sathya Sai (LKK Auto) <SathyaSai@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; 'Ms Lee (Lee Sheng Auto)' <ekchen_lee@leeshengauto.com.sg>; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ngsiuching@smrt.com.sg>
Subject: SHB1807C

Hi Sathya,

Attached herewith the repair estimate of SHB 1807C having Case No: TAX/07/18/2079.

There is no change to the approved amount of \$1,150 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Ms Lee,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Sunday, 5 August 2018 10:40 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

Jānīce Lee (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Sunday, August 05, 2018 11:10 AM
To: Sathya Sai (LKK Auto)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Subject: SHB1807C
Attachments: img-805103948-0001.pdf

Hi Sathya,

Attached herewith the repair estimate of SHB 1807C having Case No: TAX/07/18/2079.

There is no change to the approved amount of \$1,150 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Ms Lee,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Sunday, 5 August 2018 10:40 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="18/07/2018 18:05"/>						
Vehicle No.(For Motor)	<input type="text" value="SJG1130X"/>								
<input type="button" value="Search"/>									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5097327275	ADEN GARAGE PTE LTD	201608223D	GPC	Third Party	SJG1130X	SJG1130X	10/01/2018	09/01/2019
<input type="button" value="Continue"/>									

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SHB1807C
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Scheme:	Taxi (Company)
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Chassis No.:	JTDKN36U205758530
Propellant:	Petrol-Electric
Engine No.:	2ZR6308247
Motor No.:	3JM6308247
Engine Capacity:	1798 cc
Power Rating:	60.0 kW
Maximum Power Output:	100.0 kW (134 bhp)
Maximum Laden Weight:	1805 kg
Unladen Weight:	1370 kg
Year Of Manufacture:	2015
Original Registration Date:	11 Feb 2015
Lifespan Expiry Date:	10 Feb 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid:	\$52,904.00
COE Expiry Date:	10 Feb 2023
Road Tax Expiry Date:	10 Feb 2019
PARF Eligibility Expiry Date:	10 Feb 2023
Inspection Due Date:	10 Feb 2019
Intended Transfer Date:	23 Jul 2018
CO2 Emission:	92.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$30,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OKPrint

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB1807C
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6308247
Chassis No.:	JTDKN36U205758530
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	11 Feb 2015
First Registration Date:	11 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Feb 2023
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	10 Feb 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,904.00
COE Rebate Amount:	\$29,208.00
Total Rebate Amount:	\$35,274.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2018 10:59
Date Of Accident	18/07/2018 09:15
Exact Location Of Accident	JALAN BUKIT MERAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1807C
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	OW LEONG SAN
NRIC No	S1708326J
Date Of Birth	15/02/1965
Occupation	OUTDOOR
Date Of Driving Pass	19/08/1993
Driving Experience	24 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	847
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
NAME:	: NGUYEN THI DIEP QUYNH
GENDER:	: FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG JALAN BUKIT MERAH WITH A PASSENGER ON BOARD DUE TO RED TRAFFIC LIGHT JUNCTION AHEAD. A MOMENT LATER, SUDDENLY THE VEHICLE SJG1130X FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG1130X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMMAD SIDIK BIN SULAIMAN
NRIC/Passport Number	S8304773I
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage


No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 18/7/18
@ 11am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1807C
 Ref. No : TAX/07/18/2079
 Reg. Date : 11/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : OW LEONG SAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 18/07/2018 09:18:00 AM
 Accident Reported Date / Time : 18/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097083
 Special Instruction to ARC, if any :
 SJG1130X
 Prepared Date : 18/07/2018 11:18:55 AM



Sathya Sai
 18/7/2018

[Signature]
 25/7/18

2 days

- Lump Sum Repair

- ? item photo

- Photo after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U205758530

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges : 507.00

0.00

Total Spray Painting Charges : 558.00

0.00

Total Material Charges : 934.02

953.09

Other Charges : 576.88

0.00

TOTAL : **2,575.90** 3130.38

0.00

Lum Sum Total : **2,600.00**

0.00

No. of Repair Days : 4.00

0.00

Prepared / Adjusted By :

2 days

Arc / Surveyor Sign Off Date : 18/07/2018 01:46:52 PM

01/01/1900 12:00:00 AM

M

Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/07/2018 01:39:04 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	507.00	0.00 200 /
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200 /
TO RESPRAY BUMPER BEAM	180.00	0.00 ? +
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓ 296.88 net
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60 /
TO REPLACE SUNDRY PARTS	100.00	0.00 20 /
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	576.88	0.00

3120.78

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR <i>R</i>	1	458.60	25.00	343.95	Replace	Replace	No
			PIXEL STICKER <i>✓ NEC</i>	2	60.00	0.00	120.00 <i>✓</i>	Replace	Replace	No
			SENSOR REVERSE <i>? DM</i>	1	180.00	0.00	180.00 <i>✓</i>	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR <i>✓ Defect</i>	1	228.90	25.00	171.67 <i>✓</i>	Replace	Replace	No
52161-16010			BUMPER CLIPS <i>✓ NEC</i>	10	1.61	25.00	12.07 <i>✓</i>	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR <i>? DT</i>	1	205.70	25.00	154.25 <i>(S) ✓</i>	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH <i>?</i>	1	139.60	25.00	104.70 <i>X ✓</i>	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH <i>?</i>	1	139.60	25.00	104.70 <i>X ✓</i>	Replace	Replace	No
TOTAL MATERIALS								1,191.38	1,191.36	
TOTAL MATERIALS(Discounted)								934.02	953.09	

Added Spare Parts / Material Usage After Surveyor Signed off

3130.38

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/07/18/2079	Date of Collection	1 / 1
Vehicle No	SHB 1807 C	Date of Request	19/07/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	2 / 1

S/N	Part Number	Part Description	Quantity	Unit Price
		REVERSE SENSOR	1pc	✓ DMG
		REAR BUMPER REPAIRMENT	1pc	✓ DT

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

Satya Sen

22/7/2018

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

20-7-18/08:38

ADV 20-7-18/12:38

20-7-18/16:38

SMRT Accident Vehicle Repair Estimates

18-7-18/16:38

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1807C
 Ref. No : TAX/07/18/2079
 Reg. Date : 11/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : OW LEONG SAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 18/07/2018 09:18:00 AM
 Accident Reported Date / Time : 18/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sathya
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097083
 Special Instruction to ARC, if any :
 SJG1130X NTAC 45
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR Sathya Sai (LKK) & Email : sathyasai@lkkauto.com HP: 98072012
 LUMP SUM REPAIR
 Prepared Date : 18/07/2018 11:18:55 AM



13:30 23-7-18
 Recording Camera ☐ ☒
 Radio Antenna ☐ ☒
 1st witness [Signature] Date 18-7-18
 2nd witness [Signature] Date 23-7-18

reflect 400087 reverse sensor not effective 14:10 pass

1 1 3
 4 2 4 1

Supplementary

to Refer to the Supplementary for list 4001491=

LEE SPRING AUTO PTE LTD

Vehicle Return Date: 23-7-18
 Vehicle Return Time: AM 12:50

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205758530

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	200.00
Total Spray Painting Charges	: 558.00	200.00
Total Material Charges	: 542.34	638.01
Other Charges	: 576.88	111.99
TOTAL	: 2,184.22	1,150.00
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 4.00	3.00
Prepared / Adjusted By	:	SATHYA (LKK)
Arc / Surveyor Sing Off Date	: 18/07/2018 01:46:52 PM	18/07/2018 04:38:02 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/07/2018 01:39:04 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	507.00	200.00
Total Labour	507.00	200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
Total Spray Painting & Panel Beating	558.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-264.89
Total Other Costs	576.88	111.99

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>/</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>S</i>	No <i>/</i> <i>DM</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No <i>/</i>
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No <i>/</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Replace <i>S</i>	No <i>/</i> <i>DT</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>
TOTAL MATERIALS							847.43	638.02		
TOTAL MATERIALS(Discounted)							542.34	638.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

638.01
+ 200.00
+ 576.88

1414.89

- 202

1131.91

US \$1150/-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013462/Nrbe2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 02-10-2018	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJG 1130X	Veh. Inspected	SHB 1807C
Policy No.	5097327275	Coverage (\$)	0.00
Claim No.	MT/1011180-001	Excess (\$)	0.00
Assign From		Assign Date	18/07/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDKN36U205758530	Colour	MAROON
Odometer	400086	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	ACHILLES	6 mm
L/H Rear Tyre	195/65 R15	ACHILLES	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/07/2018	Inspection Date	18/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1807C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.28
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	ARM SUB-ASSY. RR BUMPER LH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY. RR BUMPER RH	SERVICEABLE	139.60	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
			1,785.38	934.90
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER REAR.		507.00	200.00
	SPRAY PAINT.		558.00	200.00
	TO TEST AND REFIX REVERSE SENSOR.		120.00	60.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,345.00	480.00
GRAND TOTAL			3,130.38	1,414.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,150.00

Report Ref No. NS/INC18013462/Nrbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)**BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.