

ASS. REC. BY

REF

CS/AGI#8013467/KSD3ⁿ²

of Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Albert Hong

of

AGI

Date/Time

24/7/18 @ 4:03pm

Estimated Cost:

Bill to:

OD (D) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIL 2565S

Insured:

FBF 9499E

at Workshop m/s:

T & T Auto Service

Tel:

9145 9776

of

Blk 160, Sin Ming Drive #08-14

Policy No:

Claim No:

C20001805

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/07/2018

CA / REV / REP. / REV 24 HRS

up

Date/Time

5:22pm @ 24/7/18

Person Contacted:

Vincent

H.O.D. Endorsement:

Vehicle (D) IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SIL 2565S - X
	FBF 9499E - X

ASS. REC. BY:

REF: AG21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ T&T

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STL 25655 Yr Regn: 17, 08Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Armen c.c. 1898Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 405828 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GJI 1305971Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Radar

Front

R/Bal. 9 mm

Rear

R/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 23/7/18D.O.A. 24/7/18

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/7 File pass to Catherine, est not ready
L12m 8 240d email

(\$7,077.36 Red - 75%)

RECEIVED 27 JUL 2018

Date/Time, File Pass to?

27/7/18

1) Typist

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS \$

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 2,400.00 2/5)

TOTAL

250

Nivitha (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Tuesday, 24 July 2018 4:03 PM
To: assignments
Cc: SUR
Subject: Appoint LKK to conduct TP survey, Our Ref: C20001805

Hi Team,

Please accept survey assignment and liaise with TP workshop.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg



Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: T & T Auto Services Pte Ltd <tntautoservices@gmail.com>
Sent: Tuesday, 24 July, 2018 1:53 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: Accident Involving FBF9499E / SJL2565S on 23/07/2018

Dear Albert,

We refer to the above matter.

Kindly arrange pre-repair inspection of vehicle no: SJL2565S at our premises:

T & T Auto Services Pte Ltd
Blk 160 Sin Ming Drive
#08-14 Sin Ming AutoCity
S(575722)

Please assign LKK Auto Consultants Pte Ltd to conduct the survey.

Thank you.

Best Regards.

Vincent Tan
T & T Auto Services Pte Ltd
Tel: 6266 6876 Fax: 6266 6861
Hp: 9145 9776

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 2317L

Vehicle Details

Vehicle No.: SJL25655

Vehicle to be Exported: Yes

Intended De-registration Date: 24 Jul 2018

Vehicle Make: HONDA

Vehicle Model: AIRWAVE 1.5M A

Primary Colour: Black

Manufacturing Year: 2008

Engine No.: L15A5207283

Chassis No.: GJ11305971

Maximum Power Output: 81.0 kW (108 bhp)

Open Market Value: \$15,583.00

Original Registration Date: 20 Nov 2008

First Registration Date: 20 Nov 2008

Transfer Count: 1

Actual ARF Paid: \$15,583.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Nov 2018

PARF Rebate Amount: \$7,791.00

Intended COE Rebate Details

COE Expiry Date: 19 Nov 2018

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$10,455.00

COE Rebate Amount: \$336.00

Total Rebate Amount: \$8,127.00

The information contained herein is correct as at 24 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/07/2018 15:58
Date Of Accident	23/07/2018 22:15
Exact Location Of Accident	NICOLL HIGHWAY TOWARDS GUILLEMARD ROAD L/P 60F
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL2565S
Insured/Policyholder	
Name Of Registered Owner	STARS RENTAL & LEASING
Co Reg No	53312317L
Email Address	STARSRENTLEASE@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-81583155
Vehicle Particulars	
Manufacturer	HONDA
Model	AIRWAVE-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093348634-01
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD ISKANDAR BIN ABDULLAH
NRIC No	S7924171G
Date Of Birth	31/07/1979
Occupation	OUTDOOR
Date Of Driving Pass	06/11/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81583155
Fax Number	
Contact Number	
EMail Address	ISNAQISZAIRA@GMAIL.COM

Address BLK 307 BUKIT BATOK ST 31 #04-119
SINGAPORE
Postcode 650307
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : NA
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBF9499E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

NA(MOTORCYCLIST)

Approximate Age

Injuries Sustain

REFER POLICE REPORT

Injured person in which vehicle?

F8F9499E

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180724/2005

1 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20180724/2005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/07/2018 00:48	Vide Report No.: E/20180723/0195	Station Diary No.: 5
--	-------------------------------------	-------------------------

Informant's Particulars

Name of Informant: MUHAMMAD ISKANDAR BIN ABDULLAH			Address: APT BLK 307 BUKIT BATOK STREET 31 #04-119 SINGAPORE 650307	
ID Type / ID No.: NRIC NO / S7924171G			Contact No.: Home/Office: Mobile: 81583155	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 38	Date of Birth: 31/07/1979	Type of Informant: Driver	
Race: Javanese			Language: English	Institution / School Name:
Occupation: Driving instructor/tester			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/07/2018 22:15	Type of Location: Straight Road
Location: NICOLL HIGHWAY Towards Guillemard Road, Lamppost 60F Lamp Post Number: 60F	Weather: Clear	Road Surface: Dry	Road Speed Limit:	Traffic Volume: Heavy
Traffic Flow: One Way	Type of Collision: Moving Vehicle Against - Parked Vehicle	Traffic Control: Not Controlled	Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF9499E	Motorcycle				Seriously Damaged	0
SJL2565S	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20180724/2005

2 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20180724/2005

CONTINUATION OF REPORT

Driver			
Name	MUHAMMAD ISKANDAR BIN ABDULLAH	ID No.	S7924171G
Related Vehicle	NIL	Contact No.	81583155
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 23/07/2018 at about 2215hrs, I was driving my black Honda Airwave vehicle bearing the registration number SJL2565S along Nicoll Highway on the third lane towards Guillemard Road when I spotted a black motorbike bearing the registration number FBF9499E entering the highway through a slip road from Java Road at high speed and I slowed down to let his motorbike stabilize before turning into my lane behind me. I then gradually came to a stop as the traffic was congested. I then felt something colliding into the back of my vehicle after a few seconds. I went down to check and saw that a motorcyclist was half unconscious and lying on his side. I tried to ask him if he was ok but he was unable to answer me. There was a lot of blood on his face which was on the floor as well. He was subsequently conveyed to the hospital through the ambulance. I am unsure of where he was conveyed to. I am currently suffering from some backache and might be going to a hospital to make a check. I was driving Grab and sending my female passenger to Bukit Batok. The female passenger did not sustain any injuries. I am not sure how the motorcyclist collided onto my vehicle but I felt that he might have banged his face into my vehicle's spoiler as it had partially came out. My vehicle sustained a big dent at the bumper and car boot door. I am unsure how much the total damages will cost me. The motorbike suffered serious damages at the front as well. I have no camera in my vehicle. The Traffic Police was at scene and advised me to lodge a police report.



SINGAPORE
POLICE FORCE



T/20180724/2005

3 of 3

Police Station Of Origin:

Bukit Batok N.P.C

21 Bukit Batok East Avenue 4 SINGAPORE

659840

Tel No: 1800-6659999

Report No. T/20180724/2005

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 NG CHOR MUI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt LEE GUANG HUI

Contact No.: 65476138

SN 114

Authentication Stamp

NP168



Signature :

Singapore Police Force

Signature Of Informant:

Date/Time:

24/07/2018 00:48

Classification Of Case:

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

STARS RENTAL & LEASING
50 SERANGOON NORTH AVE 4
#02-19 FIRST CENTRE
SINGAPORE 555856

Not Notarized
11/2/2300
Money After Pay

ESTIMATE

DATE : 25/07/2018
VEHICLE NO : SJL 2565 S
MAKE/MODEL : Honda Airwave
ACC DATE : 23/07/2018

PARTICULAR *5 days* AMOUNT S\$

LIST ITEMS:				
1	1	TAILGATE	<i>Bt</i>	1,650.80 ✓
2	1	TAILGATE INNER LOCK	<i>R</i>	365.20 x
3	1	TAILGATE WEATHERSTRIP	<i>Sn</i>	285.40 x
4	1	TAILGATE OUTER MOULDING	<i>od/wor</i>	452.80 ✓
5	1	TAILGATE OUTER GARNISH	<i>CWA / way</i>	670.20 ✓
6	1	TAILGATE TOP SPOILER	<i>ng-M</i>	465.80 ✓
7	1	TAILGATE LOGO	<i>nu</i>	83.10 ✓
8	4	TAILGATE WINDSCREEN MOULDING	<i>nu</i>	135.10 ✓
9	1	TAILGATE WIPER MOTOR	<i>Sn</i>	395.80 x
10	1	TAILGATE WIPER ARM	<i>Sn</i>	195.20 x
11	1	TAILGATE WIPER ARM COVER	<i>Sn</i>	56.10 x
12	1	REAR BUMPER	<i>Bu</i>	1,320.80 ✓
13	2	REAR BUMPER SIDE RETAINER	<i>Sn</i>	171.00 x
14	1	REAR BUMPER BEAM	<i>Bt</i>	195.20 ✓
15	1	REAR END PANEL	<i>R</i>	595.80 x
16	1	REAR END PANEL TOP GARNISH	<i>Sn</i>	358.40 x
				7,396.70
Less Discount:			20%	1,479.34
				5,917.36

SPECIAL NETT ITEMS:	
1	1 REAR NUMBER PLATE
2	1 TAILGATE WINDSCREEN SEALANT
3	10 REAR BUMPER CLIP
4	2 REAR END PANEL TOP GARNISH CLIP
5	1 REAR REVERSE SENSOR

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

<i>nd</i>	50.00	<i>45sn</i>
<i>na</i>	50.00	<i>40sn</i>
<i>na</i>	50.00	✓
<i>na</i>	10.00	x
<i>Sn</i>	350.00	x
		510.00

LABOUR CHARGES:	
1	TO CHECK WIRING
2	TO TUFF KOTE
3	TO REMOVE/REFIX REAR WINDSCREEN
4	TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
5	TO TRANSFER TO TAILGATE
6	TO REMOVE/REFIX REVERSE SENSOR
7	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
8	TO SPRAY PAINTING ON AFFECTED AREA

Acknowledged by Repairer
Signature:
Date:

	50.00	<i>20l</i>
	250.00	<i>30l</i>
	150.00	<i>120l</i>
	150.00	<i>60l</i>
	150.00	<i>60l</i>
	100.00	<i>50l</i>
	1,200.00	<i>600l</i>
	1,000.00	<i>800l</i>
		3,050.00

GRAND TOTAL: 9,477.36





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18013467/Ksd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 28-07-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBF 9499E	Veh. Inspected	SJL 2565S
Policy No.		Coverage (\$)	0.00
Claim No.	C20001805	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	24/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA AIRWAVE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GJ11305971	Colour	METALLIC BLACK
Odometer	405828	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	RADAR	9 mm
L/H Front Tyre	195/60 R15	RADAR	9 mm
R/H Rear Tyre	195/60 R15	RADAR	9 mm
L/H Rear Tyre	195/60 R15	RADAR	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/07/2018	Inspection Date	24/07/2018
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 25655

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BENT	1,650.80	1,650.80
1	TAILGATE INNER LOCK	TO REPAIR SEE LABOUR	365.20	-
1	TAILGATE WEATHERSTRIP	SERVICEABLE	285.40	-
1	TAILGATE OUTER MOULDING	DENTED / WARPED	452.80	452.80
1	TAILGATE OUTER GARNISH	CRACKED / WARPED	670.20	670.20
1	TAILGATE TOP SPOILER	MTG CRACKED	465.80	465.80
1	TAILGATE LOGO	NECESSARY	83.10	83.10
4	TAILGATE WINDSCREEN MOULDING	NECESSARY	135.10	135.10
1	TAILGATE WIPER MOTOR	SERVICEABLE	395.80	-
1	TAILGATE WIPER ARM	SERVICEABLE	195.20	-
1	TAILGATE WIPER ARM COVER	SERVICEABLE	56.10	-
1	REAR BUMPER	BUCKLED	1,320.80	1,320.80
2	REAR BUMPER SIDE RETAINER @\$85.50	SERVICEABLE	171.00	-
1	REAR BUMPER BEAM	BENT	195.20	195.20
1	REAR END PANEL	TO REPAIR SEE LABOUR	595.80	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	358.40	-
	LESS 20% DISCOUNT		-1,479.34	-994.76
			5,917.36	3,979.04
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	DENTED	50.00	45.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
10	REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
2	REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	10.00	-
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	350.00	-
			510.00	135.00
<u>LABOUR</u>				
	TO CHECK WIRING .		50.00	20.00
	TO TUFF KOTE.		250.00	30.00
	TO REMOVE/REFIX REAR WINDSCREEN.		150.00	120.00
	TO REMOVE/REFIX UPHOLSTERY ,CUSHION SEAT & ROOF LINING.		150.00	60.00

Report Ref No. CS/AGI18013467/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER TO TAILGATE .		150.00	60.00
	TO REMOVE/REFIX REVERSE SENSOR .		100.00	50.00
	TO PANEL BEATING ,REMOVING & REPLACING OF NEW PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE INNER LOCK AND REAR END PANEL .		1,200.00	600.00
	TO SPRAY PAINTING ON AFFECTED AREA.		1,000.00	800.00
			3,050.00	1,740.00
GRAND TOTAL			9,477.36	5,854.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/AGI18013467/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.