

Winnetho

CC 4, ASM 180

13472, T1ha39

59311

Surveyor:

WTH

DOI:

ASSIGNMENT

23/7/18

Date / Time:

23/7/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 8034L

Name of Insured:

Lim Yean Sung

Insured Tel No.:

HP:

Excess Sec II : S\$

D.O.A.:

23/7/2018

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Liew Swee Lee

Driver Tel No.:

96526250

(V/L-YES/NO)

Claim No.:

S8moop H2

Policy No.:

VPALP2049332

Make / Model:

T. wish

Place of Accident:

Srt 2 BKE

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLC 6626



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kee Luan Hwa



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

23/7

SLC 6626 - X; SLW 8034L - X

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

26/7

Sent By:

Jin (Jing)

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

R/P

S\$ 5,602.56

( 7 days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

22/02/19

Confirm with:

ADRIANE

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

LONG KATE ENDED TO

Repair Cost:

S\$

5,602.56

Loss of Rental (LOR):

S\$

—

( days)

Loss of Use (LOU):

S\$

540.00

(S 60 x 9 days)

Loss of Income (LOI):

S\$

—

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

—

Disbursement:

S\$

—

(e.g. Tow/Independent)

Legal Cost:

S\$

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4350.00

Total:

S\$

6,144.56

Global Sum S\$:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6,144.56

Name 1:

LEE KUAN HWA

MOTOR SERVICES

Payee 2: (Strike if N.A.)

S\$

—

Name 2:

—

Payee 3: (Strike if N.A.)

S\$

—

Name 3:

—

(08/11/13) wef

ASS. REC. BY: Tanfer

REF:

AXA

## ASSIGNMENT

From: \_\_\_\_\_ Date: 5/7/2018 Veh No: SLC6629 Yr Regn: 2016 April  
 Estimated Cost: \_\_\_\_\_ Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or  
 To Inspect Vehicle No: \_\_\_\_\_ Make: Mazda 2 c.c. 1496  
 at Workshop m/s \_\_\_\_\_ Colour: Red A/C: Insured / Std / NI / NA  
 of \_\_\_\_\_ Sp. Reading: 60288 T/Radio: Insured / Std / NI / NA  
 Insured: \_\_\_\_\_ Eng/No: \_\_\_\_\_  
 Policy No: \_\_\_\_\_ C/No: MM6DL259A9W190 866  
 Claims No: \_\_\_\_\_ Gen. Cond: Good / Fair / Poor / Burnt  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_ Steering: Inorder / Jammed / Leaked / Burnt or  
 (Client's Record) a... Brake: Inorder / Jammed / Leaked / Burnt or  
 Make of Veh: \_\_\_\_\_ Modi: Nil / S/Rim / STD A/Rim or  
 (Policy Condition) Tyre Size: F: 185/65R15  
 Remark: The veh had commenced its R: h...  
 repair at the time of inspection.  
 Bal. or Market Value: q 62K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 7 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 1up  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI  
 TOYO / YOKO or  
 Front 6 mm Rear 6 mm  
 R/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 25/7/18  
 Survey held at Lee Kuan Yew Sy Hwa  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Email w/s \$562.56, 7 days to Advise.
	(CRD: \$3,314.84/82%)
	LU: \$62,000.00
	LU: \$

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

Photos

☐ : Tech. Invs (\$ \_\_\_\_\_)

Others

☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

&gt; Back to OneMotoring

## Enquire Transfer Fee

## Vehicle Details

Vehicle No.: SLC662G  
 Vehicle Type: P10 - Passenger Motor Car  
 Vehicle Attachment 1: No Attachment  
 Vehicle Scheme: Normal  
 Vehicle Make: MAZDA  
 Vehicle Model: MAZDA2 SEDAN 1.5L SP.6EAT  
 Chassis No.: MM6DL2SAAGW190866  
 Propellant: Petrol  
 Engine No.: P52034651B  
 Engine Capacity: 1496 cc  
 Maximum Power Output: 85.0 kW ( 113 bhp)  
 Maximum Laden Weight: 1538 kg  
 Unladen Weight: 1079 kg  
 Year Of Manufacture: 2016  
 Original Registration Date: 29 Apr 2016  
 Lifespan Expiry Date: -  
 COE Category: E - Open Category  
 Quota Premium: \$47,510.00  
 COE Expiry Date: 28 Apr 2026  
 Road Tax Expiry Date: 28 Oct 2018  
 PARF Eligibility Expiry Date: 28 Apr 2026  
 Inspection Due Date: 28 Apr 2019  
 Intended Transfer Date: 23 Jul 2018  
 CO2 Emission: 121.00 (g/km)  
 CEV/VES Rebate Utilised: \$5,000.00  
 Amount: -  
 CO Emission: -  
 HC Emission: -  
 NOx Emission: -  
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.  
 Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	25.00	-	25.00

Transfer Fee:

Total Amount Payable:

You may print this page for reference.

OK

Print

# LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719  
Workshop: 24, Sungei Kadut Street 4 Singapore 729050  
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712  
Business Reg. No: 36463500B

M/s: **AXA INSURANCE SINGAPORE PTE LTD**  
8 SHENTON WAY #27-10  
Singapore 068811

Date : 24.07.2018

Motor Claim Dept

Vehicle number : **SLC 662 G**  
Make/Model : **MAZDA, MAZDA 2 SEDAN 1.5L SP.6EAT**  
Date of accident : **23.07.2018**  
Claim Type : **TP Claim**

Accident involving SLC 662 G & SLW 8034 L along (SLE) Highway on 23.07.2018.

Re: Estimate

1.	1 pc	Rear bumper	\$	909.00	de -
2.	2 pcs	Rear bumper bracket	\$	44.80	rel -
3.	2 pcs	Rear bumper side retainer LH,RH	\$	43.40	rel
4.	2 pcs	Rear bumper reflexor LH,RH	\$	50.40 108.80	LH - can - , RH - Xnn
5.	1 set	Rear reverse sensor	(S/Nett) \$	200.00	re -
6.	1 pc	Rear end panel	\$	624.00	bt -
7.	1 pc	Rear boot weathershield	\$	107.00	twi -
8.	1 pc	Rear end garnish	\$	57.00	de -
9.	2 pcs	Rear end side garnish LH,RH	\$	346.00	Xnn
10.	1 pc	Rear lock	\$	181.00	bt -
11.	2 pcs	Rear tail lamp	\$	752.00	can
12.	1 pc	Rear boot	\$	820.60	bt -
13.	1 pc	Rear boot inner trim	\$	288.00	Xnn
14.	2 pcs	Rear boot lamp LH,RH	\$	198 396.00	LH - Xnn RH - can
15.	1 pc	Rear Mazda 2 emblem	\$	55.10	re -
16.	1 pc	Rear Mazda 2 logo	\$	55.60	re -
17.	1 pc	Rear skyactiv technology emblem	\$	64.30	re -
18.	1 set	Rear number plate & casing	(S/Nett) \$	45.00	Xnn

李光華 摩托燒焊

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

# LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719  
Workshop: 24, Sungei Kadut Street 4 Singapore 729050  
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712  
Business Reg. No: 36463500B

M/s: **AXA INSURANCE SINGAPORE PTE LTD**  
8 SHENTON WAY #27-10  
Singapore 068811

Date : 24.07.2018

Motor Claim Dept

Vehicle number : **SLC 662 G**  
Make/Model : **MAZDA, MAZDA 2 SEDAN 1.5L SP.6EAT**  
Date of accident : **23.07.2018**  
Claim Type : **TP Claim**

Accident involving SLC 662 G & SLW 8034 L along (SLE) Highway on 23.07.2018 .

Re: Estimate

19.	2 pcs	Rear boot bracket	\$	236.00	✓
20.	15 pcs	Rear clips	\$	67.50	✓
21.	1 pc	Rear fender LH	\$	944.30	✓
				-----	
				\$	6,337.40
				4265.70. 20% - 3412.56 SN - 200 3612.56	
				-----	
				\$	80.00
				\$	100.00
				\$	1,200.00
				\$	1,200.00
				-----	
				\$	8,917.40
				-----	
				\$	1990

Yours Faithfully,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

李光華 廖煒燒 輝  
LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL 6269 9192 FAX 6269 2239 H/P 9631 1712

Temple 97495749  
"wp"  
25/7/18 @ 1800  
Resurvey before part  
7 days.  
surveillance  
Parts - 3612.56  
Labour - 1990  
\$5602.56 #



## <IA UPLOADED> S8M00PHZ ACCIDENT INVOLVING VEHICLES SLW 8034L(OI) AND SLC 662G(TP) ON 23/07/2018

Type

🔗 Question

Message

Hi Vic, pls offer @ \$8000 to \$8100 (global). Tks

Reply

## LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719  
Workshop: 24, Sungei Kadut Street 4 Singapore 729050  
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712  
Email: kuanhwa@singnet.com.sg  
Business Reg. No: 36463500B

**AXA Insurance Singapore Pte Ltd**  
8 SHENTON WAY #27-10  
SINGAPORE 068811.

Date : 20.12.2018

Motor Claim Dept

Attn to:  
Your Ref:

### Third Party Direct Settlement

Re: Accident involving SLC 662 G & SLW 8034 L along (SLE)Highway on 23.07.2018

We refer to the above accident which is due to the fault of your insured SLW 8034 L,  
we are now claiming against you/your insured for our client's losses as follow:

1	Cost of Repair	\$	5,602.56
2	Rental Fee	\$	540.00
3	GIA Search Fee	\$	2.00
			-----
Total:		\$	6,144.56
			-----

Enclosed are the Repair bill and supporting documents.  
We look forward to your reply.

Thank you very much.

Yours faithfully,

李光華 廖曉曉 譚

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

25 SEPTEMBER 2018

LIM YEOW SUNG  
21 CANBERRA DRIVE  
#09-44  
SINGAPORE 768076

By Post & By Email

Dear Sir/Madam,

OUR REF : CC4/ASM18013472/T1ha3  
YOUR REF : SLW 8034L  
ACCIDENT INVOLVING SLW 8034L AND SLC 662G ALONG SLE TOWARDS BKE ON  
23.07.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s LEE KUAN HWA MOTOR SERVICE, acting on behalf of the owner of SLC 662G against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SLC 662G. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)

[Lim.christine31@gmail.com](mailto:Lim.christine31@gmail.com)  
(Email)

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Tuesday, 25 September, 2018 2:32 PM  
**To:** Lim.christine31@gmail.com  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** YOUR REF: SLW 8034L\_ACCIDENT INVOLVING SLW 8034L AND SLC 662G ALONG SLE TOWARDS BKE ON 23.07.2018



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

25 SEPTEMBER 2018

LIM YEOW SUNG  
21 CANBERRA DRIVE  
#09-44  
SINGAPORE 768076

By Post & By Email

Dear Sir/Madam,

OUR REF : CC4/ASM18013472/T1ha3

YOUR REF : SLW 8034L

ACCIDENT INVOLVING SLW 8034L AND SLC 662G ALONG SLE TOWARDS BKE ON 23.07.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s LEE KUAN HWA MOTOR SERVICE, acting on behalf of the owner of SLC 662G against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SLC 662G. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 7 days from the date of this letter if not provided at AXA's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

LETTER OF AUTHORITY

To: AXA INSURANCE PTE LTD

Dear Sirs

ACCIDENT INVOLVING VEHICLE NO. SLC 662 G AND SLW 8034 L  
AT LOCATION: (SLE) Highway  
ON ACCIDENT DATE 23.07.2018.

I / We had gave you instructions to repair my / our vehicle no. SLC 662 G which was damaged in the in the above accident.

In consideration that you have agreed to permit me / us to take delivery of my / our vehicle without any payment of the repair cost, I / We hereby authorize you and/or your solicitors as my/our representative to write, negotiate and settle the accident claim on my/our behalf against any party involved in the above mentioned accident.

I / We hereby undertake to co-operate with you and render you all the assistance (including having my/our vehicle re-inspected and being a witness at trial) that may be necessary for you to recover the cost of repairs and the loss of use to my/our vehicle. I / We further undertake to keep you informed at all times of any communication received from any party involved in the above mentioned accident.

In the event of my claim against any party involved in the abovementioned accident being unsuccessful for any reason whatsoever, I / We shall bear the repair / excess cost payable to **Lee Kuan Hwa Motor Service** either by cash / cheque or claim against my/our insurance policy.

I / We hereby authorize the payment of my/our claim to be made payable to my/our representative **Lee Kuan Hwa Motor Service** accordingly.

Yours faithfully,

Signature: 

Name :

Tok Wei DE

NRIC No:

S8612967A



redefining / insurance

CLAIM REF : S8M00PHZ  
INSURED : LIM YEOW SUNG

DISCHARGE VOUCHER

We/I, TOH WEI DE, NRIC NO. S8612967A hereby agree to accept the sum of dollars SIX THOUSAND ONE HUNDRED FORTY FOUR AND CENTS FIFTY SIX ONLY (S\$6,144.56) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SLW 8034L as a result of an accident along SLE TOWARDS BKE on 23/07/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLC 662G.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SLW 8034L in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SLW 8034L.

Dated this 22 day of Feb 2019.

Claimant's Signature



NRIC no./ Company Stamp

S8612967 A

Occupation/ Business

\_\_\_\_\_

Address

BLK 121 Pending Road #04-158 (S) 670121

Telephone No.

\_\_\_\_\_

Witness's Name

 李光華 廖曉輝

Witness's Signature

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 6269 9192 FAX: 6269 2239 HP: 9631 1712

Witness's NRIC No.

\_\_\_\_\_

## LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719  
Workshop: 24, Sungei Kadut Street 4 Singapore 729050  
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712  
Business Reg. No: 36463500B

M/s: **TOH WEI DE(ZHUO WEIDE)**  
**APT BLK 121 PENDING RD**  
**#04-158**  
**SINGAPORE 670121**

Date : 20.12.2018

Vehicle number : **SLC 662 G**  
Make/Model : **MAZDA , MAZDA2 SEDAN 1.5L**  
Date of accident : **23.07.2018**  
Claim Type : **TP CLAIM**

### Final repair bill

To contract part-by-part repair cost \$ 5,602.56

李光華摩托修理

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-112421

Date of Request: 23/07/2018

Your Ref No: Online Purchase

Lee Kuan Hwa Motor Service  
24 Sungei Kadut Street 4  
Singapore 729050

Dear Sir/Madam,

Enquiry Date 23/07/2018  
Enquiry By ADELIN LEE SU FANG  
TP Vehicle No. SLW8034L  
Accident Date 23/07/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLW8034L	AXA Insurance Pte Ltd	02/03/2018-01/03/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-112421

Date of Request: 23/07/2018

Your Ref No: Online Purchase

Lee Kuan Hwa Motor Service  
24 Sungei Kadut Street 4  
Singapore 729050

Dear Sir/Madam,

Enquiry Date 23/07/2018

Enquiry By ADELINE LEE SU FANG

TP Vehicle No. SLW8034L

Accident Date 23/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW 8034L (Insd veh)	Model:	MAZDA 2
	SLC 662G (TP veh)		
Date of Accident:	23/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	8,917.40
Final Repair Cost	:	\$	5,602.56
Loss of Use	:	\$	540.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	6,144.56

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability <u>100</u> (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	LEE KUAN HWA MOTOR SERVICE	:	\$ 6,144.56

JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

26/02/2019  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18013472/T1ha3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 26-02-2019



ATTN: WINNIE HO

Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 8034L	Veh. Inspected	SLC 662G
Policy No.	VPA/P2049332	Coverage (\$)	0.00
Claim No.	S8M00PHZ	Excess (\$)	0.00
Assign From		Assign Date	23/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	MAZDA 2	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MM6DL2SAAGW190866	Colour	RED
Odometer	60288	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	SUMITOMO	6 mm
L/H Front Tyre	185/65 R15	SUMITOMO	6 mm
R/H Rear Tyre	185/65 R15	SUMITOMO	6 mm
L/H Rear Tyre	185/65 R15	SUMITOMO	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	23/07/2018	Inspection Date	25/07/2018
Survey held at	LEE KUAN HWA MOTOR SERVICE 24 SUNGEI KADUT ST. 4 SINGAPORE 729050		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 662G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	909.00	909.00
2	REAR BUMPER BRACKET (CONSISTENT)	NECESSARY	44.80	44.80
2	REAR BUMPER SIDE RETAINER LH,RH (CONSISTENT)	NECESSARY	43.40	43.40
2	REAR BUMPER REFLECTOR LH,RH (CONSISTENT)	N/S CRACKED / O/S NOT NECESSARY	100.80	50.40
1	REAR END PANEL (CONSISTENT)	BENT	624.00	624.00
1	REAR BOOT WEATHERSHIELD (CONSISTENT)	TWISTED	107.00	107.00
1	REAR END GARNISH (CONSISTENT)	DEFORMED	57.00	57.00
2	REAR END SIDE GARNISH LH,RH (CONSISTENT)	NOT NECESSARY	346.00	-
1	REAR LOCK (CONSISTENT)	BENT	181.00	181.00
2	REAR TAIL LAMP (CONSISTENT)	CRACKED	752.00	752.00
1	REAR BOOT (CONSISTENT)	BENT	820.60	820.60
1	REAR BOOT INNER TRIM (CONSISTENT)	NOT NECESSARY	288.00	-
2	REAR BOOT LAMP LH ,RH (CONSISTENT)	N/S NOT NECESSARY / O/S CRACKED	396.00	198.00
1	REAR MAZDA 2 EMBLEM (CONSISTENT)	NECESSARY	55.10	55.10
1	REAR MAZDA 2 LOGO (CONSISTENT)	NECESSARY	55.60	55.60
1	REAR SKYACTIV TECHNOLOGY EMBLEM (CONSISTENT)	NECESSARY	64.30	64.30
2	REAR BOOT BRACKET (CONSISTENT)	BENT	236.00	236.00
15	REAR CLIPS (CONSISTENT)	NECESSARY	67.50	67.50
1	REAR FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	944.30	-
	LESS 20% DISCOUNT		-	-853.14
			6,092.40	3,412.56
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	200.00	200.00
1	SET REAR NUMBER PLATE & CASING (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
			245.00	200.00
<b>LABOUR</b>				
	TO TOWING SERVICES.		80.00	60.00

Report Ref No. CC4/ASM18013472/T1ha3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WIRING SERVICES .		100.00	30.00
	TO REPLACE & REPAIR LOWER CHARGE.INCLUSIVE OF THE REPAIR OF REAR FENDER LH .		1,200.00	900.00
	TO PUTTY & SPRAY PAINTING .		1,200.00	1,000.00
			2,580.00	1,990.00
GRAND TOTAL			8,917.40	5,602.56
RECOMMENDED COST OF REPAIRS				5,602.56

Report Ref No. CC4/ASM18013472/T1ha3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## Service Request Details

Claim	S88A009412
Reference	CC4/ASAM18013472/11ha3a2 
Loss Date	23 July 2018
Report Date	23 Jul 2018 4:39:00 PM
Request Date	17 October 2018
Due Date	

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SLC662G
Make	TPVD MAZDA
Model	2
Service Address	

Primary Contact/Insured	
LIM YEOW SUNG	
21 CAMBERRA DRIVE #09-44, 768076, Singapore 96526250	
LIM.CHRISTINE31@GMAIL.COM	

Claim Handler	
HO Winnie	
6568804833	
winnie.ho@axa.com.sg	















### Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type	Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED
 LK0Invoice1 (3).pdf	Invoice	Supervisor/ Assessor expense	LK AUTO CONSULTANTS PTE LTD (TP)	26 February 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 LOD.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2018
 LKXInspection (1).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 LKXAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2018
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 TP LOD.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 February 2019
 AXA IMMEDIATE ADVICE.pdf	Letters and Correspondence	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	7 November 2018
 LETTER TO GIL.pdf	Letters and Correspondence	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	7 November 2018
 Email from Gil dtd 031018.pdf	Letters and Correspondence	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	3 October 2018
 Q1 SCENE PHOTOS.pdf	Evidence	Photos	LKX AUTO CONSULTANTS PTE LTD (TP)	3 October 2018
 LKX REINSPECTION PHOTOS.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	25 September 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKX INSPECTION PHOTOS.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	25 September 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKX AUTO CONSULTANTS PTE LTD (TP)	27 July 2018
 SLCC63G TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	23 July 2018
 SLW1034L INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	23 July 2018
 TP P11 FROM WORKSHOP.png	Letters and Correspondence	Workshop	DHAKAL Raghav	23 July 2018