



**SINGAPORE  
POLICE FORCE**



T/20180720/2007

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

4 of 4

Report No. T/20180720/2007

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

Staff Sgt TAUFIQ BIN JUPRI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/07/2018 01:31

Officer In Charge Of Case:

TP / GIT /

Sgt 3 RASHIDAH BINTE AZMAN

Contact No.: 65476216

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force

Accident Photo





Accident Photo






Accident Photo



Accident Photo

FUJI HEAVY INDUSTRIES LTD.			
BUILT DATE		AUG 15	
GVM 2100	GALR:F 1150	GALR:R 1200	
VIN JF2BS9KC2FG013584			
GVM/BVM	2100 kg	GCM/BKM	3600 kg
GA/BA 1	1150 kg	GA/BA 2	1200 kg
VIN JF2BS9KC2FG013584		Applied Model BS9AKLC	
Trim Code J20	Color Code 61K	Option Code KC64	
Engine Type: FB25AJYHAA		Transmission Type: TR580SHACA	



20.07.2018 08:59