

2/8/2002

ASS. REC. BY:

REF:

CS / SMO18013514 / Ggbnz

Special Instructions:

Surveyor

## ASSIGNMENT (Office)

From (Person):

Grue Teo

of

SMO

Date/Time: 25/7/2018 11:33am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 2766U

Insured:

at Workshop m/s

City Auto

Tel:

6453 1235

of

160 Sin Ming Dr #05-01

Policy No:

Claim No:

CMTD1803019 / NSW

Sum Insured:

Excess:

Waived

Make of Veh:

D.O.A. 12072018

(Client's Record)

CA / REV / REP. / REV 24 HRS

26/7/2018 @ 1pm owner waiting (Blk 8 Sin Ming)

H.O.D. Endorsement:

#01-60

Date/Time:

25/7/2018

12pm

Person Contacted:

Vanica

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 2766U - X

27/7/18 @ 2:51pm revised to Ghawn Ngo by email.

(08/11/13) wef

ASS. REC. BY:

REF: SMO

66498

## ASSIGNMENT

From: Date: 26/7/18

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKY 27664

at Workshop m/s City Auto

of Blk 8 Sin Ming # 01-60

Insured:

Policy No.

Claims No.

Sum Insured: Excess: waived

(Client's Record) ~~1pm @ owner waiting~~

Make of Veh:

SKK 5059K

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 116K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKU 27664 Yr Regn: 15 Jul 2015

Type: ☒ M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estima c.c. 2362

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 82236 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ACK 5001900 9.1

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

R/Bal. 6 mm

L/Bal. 1 mm

D.O.A.

Survey held at w/s

Des. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/2 Final \$ 4100 with Veronica. (Red \$ 4528.30, 52%)

RECEIVED 01 MAR 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

11/01/3 turner

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

250

Report Format: AETR-02

Lump Sum / I.B.I.: (\$ 4100 )



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1803019/NSW

Date: 27<sup>th</sup> July 2018

Our Ref: CS/SMO18013514/Gqb

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SKU 2766U .**


We thank you for the instruction on 25/07/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/07/2018 at the premises of M/s CITY AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,501.80</u> .
Revised Estimate Amount	: S\$ <u>4,808.30</u> .
"Check" Items Amount	: S\$ <u>2,810.50</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorized repair.

Yours faithfully

Guo Qiang  
Automobile Assessor

## Catherine Chong (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Wednesday, 25 July, 2018 11:33 AM  
**To:** City Auto; admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; Henry, Irene James  
**Subject:** CMTD1803019/NSW - SUV(LKK)/ OD SKU2766U D.O.A: 12/07/2018

Our Claim Reference : CMTD1803019/NSW

Hi Vronica,

We acknowledged receipt of your claim documents.

Please be informed that Shawn Ngo the handler of this case.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

**Authorisation will be further advised upon survey.**

**Excess - WAIVED**

Aside to **LKK AUTO**,

Please assist to conduct motor survey on Own Damage basis.

Please submit with your preliminary report upon completion of survey to my colleague, Shawn Ngo.

**Kindly proceed to authorise if consistent.**

**Excess applicable – WAIVED**

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @



or



**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** City Auto [mailto:cityauto@singnet.com.sg]  
**Sent:** Wednesday, July 25, 2018 9:26 AM  
**To:** Claims - Motor Survey  
**Cc:** Teo, Grace  
**Subject:** Arrange survey on SKU2766U D.O.A: 12/07/2018

Hi Arrangement survey dept,

Kindly arrange survey on following vehicle :

OD Survey

Our vehicle : SKU2766U

D.O.A : 12/07/2018

LOCATION : Blk 160, Sin Ming Drive, Sin Ming Auto City #05-01 Singapore 575722

Thank you.

**Best Regards,**

*Vronica Law*

*City Auto Pte Ltd*

*Blk 8 Sin Ming Industrial Estate,*

*#01-60/62 Sin Ming Road,*

*Singapore 575643*

*Tel : 6453 1235*

*Fax : 6453 7944*

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 27 July 2018 2:51 PM  
**To:** 'Teo, Grace'; assignments; 'Shawn.Ngo@sompo.com.sg'  
**Cc:** 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR  
**Subject:** RE: CMTD1803019/NSW - SUV(LKK)/ OD SKU2766U D.O.A: 12/07/2018  
**Attachments:** CSSMO18013514Gqb.pdf

Dear Grace,

Enclosed herewith preliminary advice of SKU 2766U.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 25 July 2018 12:03 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Ngo, Sau Wei Shawn' <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1803019/NSW - SUV(LKK)/ OD SKU2766U D.O.A: 12/07/2018

Dear Grace,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]  
**Sent:** Wednesday, 25 July, 2018 11:33 AM  
**To:** City Auto <[cityauto@singnet.com.sg](mailto:cityauto@singnet.com.sg)>; admin-d@lkkauto.com; [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** Ngo, Sau Wei Shawn <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** CMTD1803019/NSW - SUV(LKK)/ OD SKU2766U D.O.A: 12/07/2018

Our Claim Reference : CMTD1803019/NSW

Hi Vronica,

We acknowledged receipt of your claim documents.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6649Z

### Vehicle Details

Vehicle No.:	SKU2766U
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2AZJ146930
Chassis No.:	ACR500190091
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$28,854.00
Original Registration Date:	15 Jul 2015
First Registration Date:	15 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$32,396.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2025
PARF Rebate Amount:	\$24,297.00

### Intended COE Rebate Details

COE Expiry Date:	14 Jul 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,501.00
COE Rebate Amount:	\$45,605.00
Total Rebate Amount:	\$69,902.00

The information contained herein is correct as at 27 Jul 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/07/2018 11:46
Date Of Accident	12/07/2018 15:30
Exact Location Of Accident	YISHUN AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU2766U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG SOR CHOON
NRIC No	S7506649Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96712899
Alternative Phone No	OTHERS-NOPHONE

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01010555
Cover Note Number	

### Driver

Name of Driver	NG SOR CHOON
NRIC No	S7506649Z
Date Of Birth	01/03/1975
Occupation	INDOOR
Date Of Driving Pass	04/10/1996
Driving Experience	21 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96712899
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	NOEMAIL



Address APT BLK 148 MEI LING #03-107  
 Postcode 140148  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF9166R  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name  
NRIC/ID No

CITY AUTO PTE LTD  
Blk 8 Sin Ming Road  
#01-58/60/62 Sin Ming Ind Est  
Singapore 56643  
Tel: 6453 1235 Fax: 6451 1944  
(Claims Section)

# Accident Sketch Plan



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Yishun Ave 1 towards

Yishun Ave 6 before Junction of Lenton Avenue

on lane 2 vehicle B in front jammed brake then

I could not stop in time then I collided onto

the front vehicle B.

*[Signature]*

## DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

## CITY AUTO PTE LTD

Blk 8 Sin Ming Road  
#01-58/60/62 Sin Ming Ind Est  
Singapore 575643  
Tel: 6453 1235 Fax: 6453 7944  
(Claims Section)

Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No.



# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643  
TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
24hrs Towing Services Tel: 9823 9898  
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

SOMPO INSURANCE SINGAPORE PTE. LTD.  
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER  
RAFFLES PLACE  
SINGAPORE LAND TOWER  
SINGAPORE 048623  
Attention: Ng Sor Choon  
Contact : 96712899 Fax No. : 62213302

Estimate : QUOT201807-000440(00)

Date : 26/07/2018

Vehicle No. : SKU2766U

Make/Model : TOYOTA ESTIMA AERAS 2.4 A

Mileage (km) : 0

Chassis No. : ACR500190091

Accident Date : 12/07/2018 00:00:00

Claim No. :

Reference : SKU2766U

Policy No. : D18MTPV01010555

S/No	Particular	Quantity	Unit Price	Amount S\$
<b>NET ITEMS</b>				
1	Front bumper / <i>re</i>	1.0	350.00	350.00 /
2	Front bumper towing cover RH / <i>cut</i>	1.0	18.00	18.00 /
3	Front bumper lower grille / <i>CRA</i>	1.0	165.00	165.00 /
4	Front bumper RH side cover / <i>re</i>	1.0	35.00	35.00 /
5	Front bumper retainer / <i>del</i>	2.0	45.00	90.00 /
6	Front bumper sponge / <i>CRA</i>	1.0	45.00	45.00 /
7	Front bumper reinforcement / <i>BT</i>	1.0	185.00	185.00 /
8	Front bumper reinforcement bracket / <i>NN</i>	2.0	115.00	230.00 X
9	Headlamp / <i>cut</i>	2.0	585.00	1,170.00 /
10	Front grille base / <i>CRA</i>	1.0	245.00	245.00 /
11	Front grille logo / <i>del</i>	1.0	45.00	45.00 /
12	Support top panel / <i>X Repair</i>	1.0	185.00	185.00 X
13	Support top garnish / <i>re</i>	1.0	95.00	95.00 /
14	Bonnet / <i>BT</i>	1.0	250.00	250.00 /
15	Bonnet hinge / <i>BT, RH X NN</i>	2.0	45.00	90.00 45
16	Bonnet lock / <i>BT</i>	1.0	65.00	65.00 /
17	Bonnet lock stay / <i>BT</i>	1.0	75.00	75.00 /
18	Air cond condenser / <i>cut</i>	1.0	550.00	550.00 /
19	Air cond liquid pipe / <i>X</i>	1.0	350.00	350.00 X
20	Air cond discharge pipe / <i>X</i>	1.0	185.00	185.00 X
21	Air cond suction pipe / <i>X</i>	1.0	155.00	155.00 X
22	Radiator / <i>X</i>	1.0	585.00	585.00 X
23	Radiator top cover / <i>re</i>	1.0	105.00	105.00 46
24	Fan cowling / <i>X</i>	1.0	150.00	150.00 X
25	Fan motor / <i>X</i>	2.0	185.00	370.00 X
26	Fan blade / <i>X</i>	2.0	65.00	130.00 X
27	Horn / <i>cut</i>	2.0	85.00	170.00 55
Total Parts Purchased S\$				6,088.00
10% Of The Above Parts S\$:				608.80
Based on Cost Plus S\$:				6,696.80
<b>SPECIAL NET</b>				
1	Number plate / <i>BT</i>	1.0	20.00	20.00
2	Number plate casing / <i>re</i>	1.0	25.00	25.00

CONTINUE NEXT PAGE



# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643  
TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
24hrs Towing Services Tel: 9823 9898  
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

**Estimate : QUOT201807-000440(00)**

SOMPO INSURANCE SINGAPORE PTE. LTD.  
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER  
RAFFLES PLACE  
SINGAPORE LAND TOWER  
SINGAPORE 048623  
Attention: Ng Sor Choon  
Contact : 96712899 Fax No. : 62213302

Date : 26/07/2018  
Vehicle No. : SKU2766U  
Make/Model : TOYOTA ESTIMA AERAS 2.4 A  
  
Mileage (km) : 0  
Chassis No. : ACR500190091  
Accident Date : 12/07/2018 00:00:00  
Claim No. :  
Reference : SKU2766U  
Policy No. : D18MTPV01010555

S/No	Particular	Quantity	Unit Price	Amount S\$
	SPECIAL NET Total S\$:			45.00
	<b>LABOUR</b>			
	*To check wiring and lighting	1.0	60.00	60.00
	*To change air cond parts and to vacuum and recharger air con gas	1.0	120.00	120.00
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	650.00	650.00
	- Spray painting on affected & replace parts	1.0	850.00	850.00
	*To change radiator and to perform leakage test	1.0	80.00	80.00
				1,760.00

5 Days.  
Lumpsum repair.  
After repair photos.  
Gino Ricap - 8288 0282  
26/7/18  
Excess: waived.  
Authorised.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

E. & O.E.

Total S\$: 8,501.80  
GST 7% S\$: 595.13  
Amount Due S\$: 9,096.93

5152.28  
20% 1030.46

8628.30

for CITY AUTO PTE LTD



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18013514/Gqbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 04-03-2019



Code : SMO

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKU 2766U
Policy No.	D18MTPV01010555	Coverage (\$)	0.00
Claim No.	CMTD1803019/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	25/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA ESTIMA	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ACR500190091	Colour	BLACK
Odometer	82236	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	YOKOHAMA	6 mm
L/H Front Tyre	225/50 R18	YOKOHAMA	6 mm
R/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm
L/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	12/07/2018	Inspection Date	26/07/2018
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

## 5a. Remarks

A) THE MARKET VALUE IS S\$116,000.00 (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 2766U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (N)(WCP)	DEFORMED	350.00	350.00
1	FRONT BUMPER TOWING COVER RH (N)(WCP)	CUT	18.00	18.00
1	FRONT BUMPER LOWER GRILLE (N)(WCP)	CRACKED	165.00	165.00
1	FRONT BUMPER RH SIDE COVER (N)(WCP)	DEFORMED	35.00	35.00
2	FRONT BUMPER RETAINER @\$45.00 (N)(WCP)	NECESSARY	90.00	90.00
1	FRONT BUMPER SPONGE (N)(WCP)	CRACKED	45.00	45.00
1	FRONT BUMPER REINFORCEMENT (N)(WCP)	BENT	185.00	185.00
2	FRONT BUMPER REINFORCEMENT BRACKET @\$115.00 (N)(WCP)	NOT NECESSARY	230.00	-
2	HEADLAMP @\$585.00 (N)(WCP)	CUT	1,170.00	1,170.00
1	FRONT GRILLE BASE (N)(WCP)	CRACKED	245.00	245.00
1	FRONT GRILLE LOGO (N)(WCP)	NECESSARY	45.00	45.00
1	SUPPORT TOP PANEL (N)(WCP)	TO REPAIR SEE LABOUR	185.00	-
1	SUPPORT TOP GARNISH (N)(WCP)	DEFORMED	95.00	95.00
1	BONNET (N)(WCP)	BENT	250.00	250.00
2	BONNET HINGE @\$45.00 (N)(WCP)	N/S BENT / O/S NOT NECESSARY	90.00	45.00
1	BONNET LOCK (N)(WCP)	BENT	65.00	65.00
1	BONNET LOCK STAY (N)(WCP)	BENT	75.00	75.00
1	AIR COND CONDENSER (N)(WCP)	CUT	550.00	550.00
1	AIR COND LIQUID PIPE (N)(WCP)	NOT NECESSARY	350.00	-
1	AIR COND DISCHARGE PIPE (N)(WCP)	NOT NECESSARY	185.00	-
1	AIR COND SUCTION PIPE (N)(WCP)	NOT NECESSARY	155.00	-
1	RADIATOR (N)(WCP)	NOT NECESSARY	585.00	-
1	RADIATOR TOP COVER (N)(WCP)	DEFORMED	105.00	46.00
1	FAN COWLING (N)(WCP)	NOT NECESSARY	150.00	-
2	FAN MOTOR @\$185.00 (N)(WCP)	NOT NECESSARY	370.00	-
2	FAN BLADE @\$65.00 (N)(WCP)	NOT NECESSARY	130.00	-
2	HORN @\$85.00 (N)(WCP)	CUT	170.00	55.00
1	FRONT BUMPER LOWER GRILLE CHROME (N)(WCP) (ADDITIONAL)	CRACKED	115.00	86.71
	COST PLUS 10%		620.30	361.57
			<b>6,823.30</b>	<b>3,977.28</b>

Report Ref No. CS/SMO18013514/Gqbn2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	NUMBER PLATE (SN)	BENT	20.00	20.00
1	NUMBER PLATE CASING (SN)	DEFORMED	25.00	25.00
			45.00	45.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING AND LIGHTING.		60.00	30.00
	TO CHANGE AIR COND PARTS AND TO VACUUM AND RECHARGER AIR CON GAS.		120.00	60.00
	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF SUPPORT TOP PANEL.		650.00	400.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		850.00	600.00
	TO CHANGE RADIATOR AND TO PERFORM LEAKAGE TEST.		80.00	40.00
			1,760.00	1,130.00
	<b>GRAND TOTAL</b>		<b>8,628.30</b>	<b>5,152.28</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,100.00</b>

Report Ref No. CS/SMO18013514/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.