

ASS. REC. BY: \_\_\_\_\_ REF: CS/C1118013525/T1qb n2 Special Instruction: \_\_\_\_\_

ASSIGNMENT (Office)

From (Person): Irene Jay of CTL Date/Time: 25/07/2018 9am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SLP 8966J Insured: SJL 4736C

at Workshop m/s Pegasus Tel: \_\_\_\_\_

of 74 Kiam Teck Road

Policy No: DMHCSN1804471800 Claim No: SNM18DD338JCO2

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 08072018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wpr \_\_\_\_\_ H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 25/07/2018 11:38am Person Contacted: Wee Vehicle IN / OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	<u>SLP 8966J - X</u>
	<u>SJL 4736C - X</u>
<u>12/10/18 @</u>	<u>2.49pm confirmed with Lionel Chua final fig \$1155, 4 days. (Red \$4400.65, 79%)</u>

2018/10/12

Taufik

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop no/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: 9LP8966J Yr Regn: 2017 June

Type: MCA / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Mazda 3 C.C. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 7030 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM 6BN 22A 8M 0154462

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 205 / 60 R16

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wastlake

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 25/7/18 @ 11:55pm

Survey held at Pegaras

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

RECEIVED 12 OCT 2018

Date/Time, File Pass to?  : Preli. Report

1) 12/10/18  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$)

) S+RS, SI

: Interview (\$)

) Photos

: Tech. Invs (\$)

) Others

: Weekend (\$)

Report Format: WEB-TP

Lump Sum / I.B.I: (\$) 1155

220

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jul 2018		25 Jul 2018 09:00 Assign				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	THE LOCAL LEASING COMPANY PTE LTD, Co. Reg. No.: 201632096M			
Main Claimant:	GRAB RENTALS PTE LTD			
Vehicle Reg. No.:	SL8966J	Date of Loss:	08/07/2018 16:00 - :59	
Claim Type:	TP / SNM18D03382C02	Policy/Cover Note No.:	DMHCSN1804471800 (TP, Fire & Theft)	
Vehicle Reg. No. (Insured):	SJL4736C	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road, 628800 Pioneer - Tel: 65137751			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/08/2018]			
Adj Ass. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.			

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS											<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					
No results.														

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 12 October 2018 2:49 PM  
**To:** 'Pegasus Engineering'  
**Cc:** SUR; Admin-D (LKKAuto)  
**Subject:** RE: SLP8966J TP-China Taiping (DOA-08/07/2018) Finalised on a Without Prejudice basis

Dear Lionel,

WITHOUT PREJUDICE

Confirm final fig \$1,155.00 and 4 repair days.

Best Regards,

**Shiau Chan (Ms) | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pegasus Engineering <ar\_claims@pegasusengrg.com.sg>  
**Sent:** Tuesday, 4 September 2018 6:20 PM  
**To:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Subject:** SLP8966J TP-China Taiping (DOA-08/07/2018) Finalised on a Without Prejudice basis

**Dear Taufikh,**

**Please find the calculation for your confirmation.**

**Parts by Parts repair \$1,155.00 and 4 days repair.**

**The attached copies of the documents for your attention.**

**Thanks & Regards,**

**Lionel Chua**  
**Pegasus Engineering & Trading Pte Ltd**  
**74 Kian Teck Road**  
**Singapore 628800**  
**Tel : 6513 7748**  
**Fax : 6251 3161**  
**Email : ar\_claims@pegasusengrg.com.sg**



Virus-free. [www.avast.com](http://www.avast.com)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1345N
Vehicle Details	
Vehicle No.:	SLP8966J
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520446433
Chassis No.:	JM6BN22A8H0154462
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,761.00
Original Registration Date:	21 Jun 2017
First Registration Date:	21 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$9,761.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jun 2027
PARF Rebate Amount:	\$7,320.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,489.00
COE Rebate Amount:	\$41,594.00
<b>Total Rebate Amount:</b>	<b>\$48,914.00</b>

The information contained herein is correct as at 09 Jul 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/07/2018 17:53
Date Of Accident	08/07/2018 15:30
Exact Location Of Accident	BLK 429 PASIR RIS DRIVE 6 OPEN CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP8966J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

### Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 SEDAN 1.5 AT EU6
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

### Driver

Name of Driver	CHAN YUE WAH
NRIC No	S1226505J
Date Of Birth	17/03/1957
Occupation	OUTDOOR
Date Of Driving Pass	31/10/1978
Driving Experience	39 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97385850
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address APT BLK 680 CHOA CHU KANG CRESCENT #12-568 SINGAPORE 680680  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - MAJOR/MINOR RD  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I was stationary and waiting to pick up my passenger, suddenly I notice a vehicle going on the opposite direction going very fast around the carpark bend. I wanted to horn at the vehicle but before I manage to horn, the vehicle front bumper already hit my right side of my car. The driver immediately reverse and I do not get to take any picture of the accident. No injury involved. We exchange particulars.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: RETRIEVING  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJL4736C  
 Vehicle Make/Model/Colour NISSAN/LATIO CVT 1.5L ABS D/AIRBAG 2WD 4DR/PURPLE  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver MD HAKIM BIN SAMAT  
 NRIC/Passport Number S8610780E  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorised Driver.
  3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
  - (b) All insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Handwritten Signature]* 9/7/18


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Mohammad Azaly Bin Abdulfah

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



**ACCIDENT STATEMENT (2000 characters)**

I was stationary and waiting to pick up my passenger, suddenly I notice a vehicle going on the opposite direction going very fast around the carpark bend. I wanted to horn at the vehicle but before I manage to horn, the vehicle front bumper already hit my right side of my car. The driver immediately reverse and I do not get to take any picture of the accident.

No injury involved.

We exchange particulars.


Taxi Voucher No.:

**DECLARATION**

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHAMMAD AZALY BIN ABDULLAH

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 July 2018 at 2:11 PM

Date/Time:

9 July 2018 at 2:11 PM



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>
<b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : QUAY SIEW TENG
Tel :
Email :

<b>Customer :</b>
<b>GRAB RENTALS 2 PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn: :
Tel :
Fax No. :

<b>Quotation No. :</b> QO18/07-1140	<b>Quotation Date :</b> 12/07/2018	<b>Terms :</b> 30 DAYS
<b>Vehicle No. :</b> SLP8966J	<b>Chassis No. :</b> JM6BN22A8H0154462	<b>Third Party Insurer :</b>
<b>Model :</b> MAZDA 3	<b>Date of Accident :</b> 09/07/2018	
<b>Remarks :</b>		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	O/S REAR FENDER	1	1,175.0000	Rx 1,175.00
2	O/S REAR FENDER AIR VENT	1	72.0000	X 72.00
3	O/S REAR FENDER LOWER PANEL	1	155.8000	X 155.80
4	O/S REAR FENDER INNER TRIM	1	236.0000	X 236.00
5	O/S REAR FENDER INNER TRIM CLIPS	6	5.0000	X 30.00
6	O/S REAR DOOR	1	1,006.0000	Ry 1,006.00
7	O/S REAR DOOR WEATHERSTIRP	1	121.0000	X 121.00
8	O/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	117.0000	X 117.00
9	O/S REAR DOOR OUTER WEATHERSTRIP MOULDING	1	140.0000	X 140.00
10	O/S REAR DOOR WINDOW FRAME GARNISH TOP	1	71.4000	X 71.40
11	O/S REAR DOOR WINDOW FRAME GARNISH FRONT	1	108.0000	X 108.00
12	O/S REAR DOOR 1/4 GLASS PILLAR	1	110.0000	X 110.00
13	O/S REAR DOOR 1/4 GLASS PILLAR WEATHERSTIRP	1	41.0000	X 41.00
14	O/S FRONT DOOR	1	123.0000	Rx 123.00
15	O/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	103.0000	X 103.00
16	O/S REAR WHEEL RIM HUB CAP	1	412.0000	X 412.00
17	O/S REAR FENDER STICKER	1		
18	LESS:20% (ITEM 1-17)	1	-860.5500	-860.55
19	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000	30 120.00
20	TO TRANSFER OF TYRE, RIM AND ON WHEEL BALANCING	1	50.0000	n1 X 50.00
21	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,200.0000	500 1,200.00

C/F 0.00



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

**From :**  
**PEGASUS ENGINEERING & TRADING PTE LTD**  
 74 KIAN TECK ROAD  
 SINGAPORE 628800  
 Officer in Charge : QUAY SIEW TENG  
 Tel :  
 Email :

**Customer :**  
**GRAB RENTALS 2 PTE LTD**  
 18 SIN MING LANE  
 #01-08 MIDVIEW CITY  
 SINGAPORE 573960  
 Attn :  
 Tel :  
 Fax No. :

Quotation No. : QO18/07-1140	Quotation Date : 12/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8966J	Chassis No. : JM6BN22A8H0154462	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 09/07/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
22	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,000.0000	B/F 0.00 600 1,000.00

*Tanjong 974 95749  
 - WP  
 Resurvey after repair  
 su@lkkauto.com  
 4 days. 25/7/18.  
 205/60K16. C115pm  
 wastlab.  
 26/7/18*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

5611.96

**Sub Total** 5,530.65  
**GST(7.00%)** 387.15  
**Total (SGD)** 5,917.80



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b> <b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> 74 KIAN TECK ROAD SINGAPORE 628800  Officer in Charge : QUAY SIEW TENG Tel : Email :	<b>Customer :</b> <b>GRAB RENTALS 2 PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573980  Attn : Tel : Fax No. :
--	---

Quotation No. : QO18/07-1140	Quotation Date : 12/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8966J	Chassis No. : JM6BN22A8H0154462	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 09/07/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	O/S REAR FENDER	1	1,175.0000	Ry 1,175.00
2	O/S REAR FENDER AIR VENT	1	72.0000	X 72.00
3	O/S REAR FENDER LOWER PANEL	1	155.8000	X 155.80
4	O/S REAR FENDER INNER TRIM	1	236.0000	X 236.00
5	O/S REAR FENDER INNER TRIM CLIPS	6	5.0000	X 30.00
6	O/S REAR DOOR	1	1,006.0000	Ry 1,006.00
7	O/S REAR DOOR WEATHERSTIRP	1	121.0000	X 121.00
8	O/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	117.0000	X 117.00
9	O/S REAR DOOR OUTER WEATHERSTRIP MOULDING	1	140.0000	X 140.00
10	O/S REAR DOOR WINDOW FRAME GARNISH TOP	1	71.4000	X 71.40
11	O/S REAR DOOR WINDOW FRAME GARNISH FRONT	1	108.0000	X 108.00
12	O/S REAR DOOR 1/4 GLASS PILLAR	1	110.0000	X 110.00
13	O/S REAR DOOR 1/4 GLASS PILLAR WEATHERSTIRP	1	41.0000	X 41.00
14	O/S FRONT DOOR	1	123.0000	Ry 123.00
15	O/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	103.0000	X 103.00
16	O/S REAR WHEEL RIM HUB CAP	1	412.0000	X 412.00
17	O/S REAR FENDER STICKER	1 <i>wt</i>		25/- <i>7</i>
18	LESS:20% (ITEM 1-17)	1	-860.5500	-860.55
19	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000	30 120.00
20	TO TRANSFER OF TYRE, RIM AND ON WHEEL BALANCING	1	50.0000	X 50.00
21	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,200.0000	500 1,200.00



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b> <b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> 74 KIAN TECK ROAD SINGAPORE 628800  Officer In Charge : QUAY SIEW TENG Tel : Email :	<b>Customer :</b> <b>GRAB RENTALS 2 PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960  Attn : Tel : Fax No. :
--	---

Quotation No. : QO18/07-1140	Quotation Date : 12/07/2018	Terms : 30 DAYS
Vehicle No. : SLP8966J	Chassis No. : JM6BN22A8H0154462	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 09/07/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
22	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,000.0000	600 1,000.00

Tanjong 974 95749  
 - WP  
 Resurvey after repair  
 sur @ lukanto.com  
 4 days.  
 205/60K16.  
 Westlake.

Sub Total	5,530.65
GST(7.00%)	387.15
<b>Total (SGD)</b>	<b>5,917.80</b>

Please conduct the survey at  
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118013525/T1QBN2

Date: 15/10/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1804471800
Claimant Vehicle No :	SLP8966J	Insured Vehicle No :	SJL4736C
Date of Loss:	08/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03382C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLP8966J	Engine No:	P520446433
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0154462
Reg. Date:	21/06/2017 (Man. Year: 2017)	Odometer:	70301 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,241.96	25.00	3,216.96	99.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,130.00	1,240.00	52.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,611.96</b>	<b>1,155.00</b>	<b>4,456.96</b>	<b>79.42</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>392.84</b>	<b>80.85</b>	<b>311.99</b>	<b>79.42</b>
<b>Nett Amount (S\$)</b>	<b>6,004.80</b>	<b>1,235.85</b>	<b>4,768.95</b>	<b>79.42</b>

## INSPECTION

Date of Assignment:	25/07/2018	
Date Inspected:	25/07/2018	Inspected At: Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2018)
<b>Parts:</b> 143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLP8966J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S REAR FENDER	Repair	1,175.00 FL	*- FL
2	1		*O/S REAR FENDER AIR VENT	Not Necessary	72.00 FL	*- FL
3	1		*O/S REAR FENDER LOWER PANEL	Not Necessary	155.80 FL	*- FL
4	1		*O/S REAR FENDER INNER TRIM	Not Necessary	236.00 FL	*- FL
5	6		*O/S REAR FENDER INNER TRIM CLIPS	Not Necessary	30.00 FL	*- FL
6	1		*O/S REAR DOOR	Repair	1,006.00 FL	*- FL
7	1		*O/S REAR DOOR WEATHERSTRIP	Not Necessary	121.00 FL	*- FL
8	1		*O/S REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	Not Necessary	117.00 FL	*- FL
9	1		*O/S REAR DOOR OUTER WEATHERSTRIP MOULDING	Not Necessary	140.00 FL	*- FL
10	1		*O/S REAR DOOR WINDOW FRAME GARNISH TOP	Not Necessary	71.40 FL	*- FL
11	1		*O/S REAR DOOR WINDOW FRAME GARNISH FRONT	Not Necessary	108.00 FL	*- FL
12	1		*O/S REAR DOOR 1/4 GLASS PILLAR	Not Necessary	110.00 FL	*- FL
13	1		*O/S REAR DOOR 1/4 GLASS PILLAR WEATHERSTRIP	Not Necessary	41.00 FL	*- FL
14	1		*O/S FRONT DOOR	Repair	123.00 FL	*- FL
15	1		*O/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	Not Necessary	103.00 FL	*- FL
16	1		*O/S REAR FENDER STICKER	Cut	25.00 FS	*25.00 FS
17	1		*O/S REAR WHEEL RIM HUB CAP	Not Necessary	412.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,046.20</b>	<b>25.00</b>
- List Item Discount on L Items 20.00/20.00% (S\$)	804.24	0.00
<b>Total Parts (S\$)</b>	<b>3,241.96</b>	<b>25.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	30.00
2	TO TRANSFER OF TYRE,RIM AND ON WHEEL BALANCING	New	50.00	-
3	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,200.00	500.00
4	OUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,370.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >