

CC 6, At 6:30 13575, Web34

LKK  
IDAC



U.S. CASE OWNER:

Surveyor: MARINS

DOI: 24/7/18

Date / Time: 24/7/18

Registered in Meritem: 20/7/18

Pre-assign / CCU / FTE



Insured Vehicle No. : 5DE36364  
 Name of Insured : Goh Yong Hock  
 Insured Tel No. : \_\_\_\_\_ HP: 97885211  
 Excess Sec II :SS \_\_\_\_\_ D.O.A: 18/7/2018  
 Is driver the owner? (YES) NO ) Nature of Accident : \_\_\_\_\_

Claim No. : 47AY20915554  
 Policy No. : 1700010118-01  
 Make / Model : Mercedes-Benz E250  
 Place of Accident : PIE TWDS-ADAM Rd Slip Rd.

If NO, Driver Name / Age : \_\_\_\_\_  
 Driver Tel No. : \_\_\_\_\_ (VL: YES/NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Insured Liability : % Final ? Yes / No

XB9539J



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_

WFX  
MFM



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
<u>21/7/18</u> <u>Wahker</u>	Non-Reporting ltr (1st)	
	Non-Reporting ltr (2nd)	
	Non-Reporting ltr (Final)	
	Notification ltr (if non-pickup):	
	Call Of: <u>SMR 2-9-18</u>	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act	
Release Voucher:		
Final Repair Bill:		
Car Rental Invoice:		
Towing Invoice		
LTA / GIA:		
Medical Bill:		
PIR:		
Mandate/Reject Instruction:		
LOD		
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: cls

Repair Cost: 13 S\$1,300.00 ( 2 days) Reduction: 61 % Email  Call

FINAL SETTLEMENT Date/Time: 18-12-18 Confirm with: \_\_\_\_\_ Email  Call

Final Liability: 100% % 50 (Agreed / Assessed) BOLA S/N No. : 18 If NO or B 28, Ass. Lia : \_\_\_\_\_

Repair Cost: 13 S\$ 695.50 OI MOVE PLONG MEEHNG LANE

Loss of Rental (LOR): - S\$ - ( days)  
 Loss of Use (LOU): 1300 S\$ 150.00 (3150 x 3 days)  
 Loss of Income (LOI): - S\$ - (3 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search 3 S\$ 0.00  
 Medical: - S\$ -  
 Disbursement: - S\$ - (e.g. Tow/Independent)  
 Legal Cost: - S\$ -

Total: 1300 S\$ 841.50 Global Sum S\$:  
 FINAL PAYMENT Date/Time: 18-12-18 Confirm with: Wahker Email  Call

Payee 1: S\$841.50 Name 1: WFA AND SERVICE PTE LTD  
 Payee 2: (Strike if N.A.) S\$ Name 2: \_\_\_\_\_  
 Payee 3: (Strike if N.A.) S\$ Name 3: \_\_\_\_\_

**COPY SENT**

(08/11/13) wsf

ASS. REC. BY: MORCIS

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XB39539J

at Workshop m/s v' fix 10.30

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seent: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS L7A24389

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: XB39539J Yr Regn: 9,02

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLVO FMX370 c.c. 10837

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 582576 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: YV2JIEID4CA732717

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl.: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 315/80R22.5

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front R/Bal: 6 mm Rear R/Bal: 6/6 6/6 mm

L/Bal: 6 mm L/Bal: 6/6 6/6 mm

D.O.A. 18/7/18 D.O.I. 24/7/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s. Pre.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	95. 41,300 (RED. + 2,012.70 6.1%)

Date/Time, File Pass to?  : Preli. Report  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (\$ \_\_\_\_\_)  Interview (\$ \_\_\_\_\_)  Tech. Invs (\$ \_\_\_\_\_)  Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
\$ + RS \$	
Photos	
Others	
TOTAL	



Vfix Auto Service Pte Ltd  
 60 Kaki Bukit Ave 6 Ark@KB  
 Singapore 417892  
 Email : contact@vfixauto.com.sg  
 Tel : 6448 9268 Fax: 6445 2368  
 UEN / GST Reg No. : 201602964H

*Not Allowed  
 24/7/18  
 4/5 @ 1300  
 2 day  
 take photo after repair*

M/S AIG ASIA PACIFIC INS PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BLDG  
 SINGAPORE 079120

**ESTIMATE**

DATE : 19/07/2018  
 ACC DATE : 18/07/2018  
 REF NO : VFIX - TP20180503  
 POLICY NO :

**Attention: Motor Claim Department**

**RE : VEHICLE NO :XB9539J VOLVO FMX**

DESCRIPTION	AMOUNT S\$
1 1 FRONT BUMPER LH	Dof 490.00 ✓
2 1 FRONT BUMPER END GARNISH NO1	cm 138.00 —
3 1 FRONT BUMPER END GARNISH NO2	cm 145.00 —
4 1 STEP BOARD GARNISH	cm 680.00 —
5 1 STEP PLATE	R 450.00 X
	<u>1,903.00</u>
	LESS 10%
	<u>190.30</u>
	<b>S 1,712.70</b>

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged parts with all necessary components/attachments apply hot-works where necessary straighten step board bracket replace new parts refit align into position with all necessary components attachmets	800.00 320
2 To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	12 800.00 X
	<u>S 1,600.00</u>

**GRAND TOTAL : S 3,312.70**

SINGAPORE DOLLARS : THREE THOUSAND THREE HUNDRED TWELVE & CENTS SEVENTY ONLY

**Vfix Auto Service Pte Ltd**



I, the undersigned, hereby acknowledge and agree to the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Final price survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18013575/Ueb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 26-07-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDE 3636Y	Veh. Inspected	XB 9539J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/07/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	18/07/2018	Inspection Date	24/07/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Friday, 21 September 2018 12:23 PM  
**To:** MARTINGOH@CKRGROUP.COM.SG  
**Subject:** ACCIDENT INVOLVING SDE 3636Y AND XB 9539J ON 18/07/2018

**Our Ref: CC6/AIG18013575/Ueb3**

21 SEPT 2018

**GOH YONG HOCK**

Dear Sir/Madam,

**ACCIDENT INVOLVING SDE 3636Y AND XB 9539J ON 18/07/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

To: AIG ASIA PACIFIC INS PTE LTD  
78 SHENTON WAY  
#07-16 AIG BLDG  
SINGAPORE 079120

Dear Sir / Madam,

Claimant:

ACCIDENT INVOLVING XB9539J AND SDE3636Y ON 18/07/2018 AT  
SLIP RD BETWEEN EXIT LORNIE -> LORNIE RD

I/We, EXPRESS TPT SERVICES & CONSTRUCTION P L, am/sre the registered owner of  
motor car no. XB9539J.

Please be informed that I have assigned all compensation monies due to me/us in the above  
accident to VFIX AUTO SERVICE PTE LTD.

I/We hereby authorized you to release all monies pertaining to the above mentioned accident  
to VFIX AUTO SERVICE PTE LTD and forward the settlement cheque to VFIX AUTO SERVICE PTE  
LTD whom I/we have authorized to collect the said compensation monies.

Thank you,



x

Signature of Claimant &  
Company Stamp if applicable  
IC no.: 199506970Z  
Date: 30/08/18



Signature of Witness  
IC no.: S1527552I  
Date: 30/08/18

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, VFIX AUTO SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$695.50 (Repair Cost), S\$150.00 (Loss of Use/Rental), S\$2.00 (Disbursement) for vehicle no. XB 9539J that was damaged pursuant to the accident which occurred on 18/07/2018 (date) along SLIP RD BETWEEN EXIT LORNIE - LORNIE RD (location) involving vehicle no/s SDE 3636Y.

This is pursuant to the inspection conducted on 24/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner EXPRESS TPT & SVCS & CONSTRUCTION P/L ("the third party claimant") of vehicle no. XB 9539J make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to XB 9539J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 18 (day) of DEC (month) 20 18 (year)

  
\_\_\_\_\_  
Signed by appointed surveyor **CKS**

  
  
\_\_\_\_\_  
Signed by "the workshop" (with chop)

\*\*\* This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim on a later date.

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.



Vfix Auto Service Pte Ltd  
60 Kaki Bukit Ave 6 Ark@KB  
Singapore 417892  
Email: contact@vfixauto.com.sg  
Tel: 64552957 Fax: 64452368  
UEN/GST Reg No. : 201602964H

AIG ASIA PACIFIC INS PTE LTD  
78 SHENTON WAY  
#07-16 AIG BLDG  
SINGAPORE 079120

**FINAL REPAIR BILL**

DATE : 30/08/2018  
VEHICLE NO : XB9539J  
MAKE/MODEL : VOLVO FMX370 64R  
ACC DATE : 18/07/2018  
CLAIM NO : VFIX-TP20180503  
POLICY NO :

---

AMOUNT S\$

LUMP SUM REPAIR COST

Repair Amount	1,300.00
7% GST	91.00
<b>Total</b>	<b>1,391.00</b>

SINGAPORE DOLLARS : ONE THOUSAND THREE  
HUNDRED & NINETY ONE ONLY

VFIX AUTO SERVICE PTE LTD

Ken Tan





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-110371  
Date of Request: 19/07/2018

Your Ref No: Online Purchase

Vfix Auto Service Pte Ltd  
60 Kaki Bukit Ave 6  
ARK@KB  
Singapore 417892

TP 503  
KB 9539 J

Dear Sir/Madam,

Enquiry Date: 19/07/2018  
Enquiry By: Kelvin Poh Leong Hock  
Vehicle No.: SDE3636Y  
Accident Date: 18/07/2018

#### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SDE3636Y	AIG Asia Pacific Insurance Pte. Ltd.	02/06/2018-01/06/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-110371

Date of Request: 19/07/2018

Your Ref No:

Online Purchase

 Vfix Auto Service Pte Ltd  
 60 Kaki Bukit Ave 6  
 ARK@KB  
 Singapore 417892

Dear Sir/Madam,

 Enquiry Date 19/07/2018  
 Enquiry By Kelvin Poh Leong Hock  
 Vehicle No. SDE3636Y  
 Accident Date 18/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO  Cash  Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jul 2018 <a href="#">Edit Reg</a>		24 Jul 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>GOH YONG HOCK</b> , ID: S0184074F								
Main Claimant:	<b>EXPRESS TPT &amp; SVCS &amp; CONSTRUCTION P/L</b> Co. Reg. No.: 199506970Z								
Vehicle Reg. No.:	<b>XB9539J</b>	Date of Loss:	18/07/2018 00:00 - :59 [70 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4794249155SG</b>	Policy/Cover Note No.:	1700010118 (Comprehensive) Coverage: 02/06/2018 - 01/06/2019						
Vehicle Reg. No. (Insured):	<b>SDE3636Y</b>	Policy No. (Claimant):	2017-V0089256						
Repairer:	<b>Vfix Auto Service Pte Ltd (HQ)</b> 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 64552957								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] Bernard.JIQian.Ler@aig.com								
Claimant's Insurer:	<b>Great American Insurance Company (HQ)</b> - Tel: 6804 6047								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 06/08/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (27/07/2018): Request To Upload TP GIA Report									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*XB9539J (4794249155SG)  
[SDE3636Y]  
TP  
EXPRESS TPT & SVCS & CONSTRUCTION P/L  
Jul 18 2018 12:00AM  
[GOH YONG HOCK]  
Vfix Auto Service Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>
<b>Letters/Correspondences</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b> <b>Print</b>
1	(Draft)	Third Party Express Settlement – Payment Breakdown	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Edit</a>
<b>Photos/Images</b>			3 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b> <b>Print</b>
1	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
2	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
3	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
4	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
5	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
6	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
7	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
8	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
9	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
10	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
11	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
12	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
13	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
14	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
15	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
16	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
17	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
18	31/07/18 08:04	General View	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
19	31/07/18 08:04	Odometer Reading	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
20	31/07/18 08:04	Chassis Number	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b> <b>Print</b>
1	30/07/18 10:09	TP GIA REPORT	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load PDF</a>
2	21/09/18 12:23	LETTER TO OI	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load PDF</a>
3	28/12/18 12:31	WORKSHOP INVOICE	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load PDF</a>
4	28/12/18 12:31	AUTHORISATION TO ACT FORM	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load PDF</a>
5	28/12/18 12:31	Release Voucher	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load PDF</a>
6	28/12/18 12:31	GIA SEARCH	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load PDF</a>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	<b>Thumbnail</b> <b>Print</b>
1	27/07/18 11:55	OI GIA REPORT	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">1</span> <a href="#">Load PDF</a>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>   <a href="#">Save</a>   <a href="#">Print</a>
----------------------------	--

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SDE3636Y (Insd veh)	Model:	VOLVO FM370 10.8 D (M)
	XB9539J (TP veh)		
Date of Accident:	18/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	3,544.59	
Final Repair Cost	:	\$	695.50	
Loss of Use	:	\$	150.00	2.00 days at \$150.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	847.50	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For <b>Non GIA Registered Workshop</b> : Agreed Liability <u>50</u> (%)				
B) For <b>GIA Registered Workshop</b> : BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Vfix Auto Service Pte Ltd	:	\$ 847.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

28 Dec  
2018

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG18013575/UEB3Q2  
**Date:** 28/12/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700010118
<b>Claimant Vehicle No :</b> XB9539J	<b>Insured Vehicle No :</b>	SDE3636Y
Date of Loss: 18/07/2018	Nature of Claim:	TP <span style="float: right;">Claim No: 4794249155SG</span>

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XB9539J	Engine No:	D11262041
Make & Model:	VOLVO FM370, 10.8 D (M)	Chassis No:	YV2J1E1D4CA732717
Reg. Date:	04/09/2012 (Man. Year: 2012)	Odometer:	582576 km
Colour:	White		
Engine Capacity:	10837 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D/D)
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6/6/6/6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6/6/6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,712.70	1,307.70	405.00	23.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	320.00	1,280.00	80.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,312.70</b>	<b>1,627.70</b>	<b>1,685.00</b>	<b>50.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
	(S\$) 3,312.70	1,300.00	2,012.70	60.76
<b>+ GST 7.00/7.00% (S\$)</b>	231.89	91.00	140.89	60.76
<b>Nett Amount (S\$)</b>	<b>3,544.59</b>	<b>1,391.00</b>	<b>2,153.59</b>	<b>60.76</b>
<b>+ Loss of Use (2.0 x S\$150.00/day) (S\$)</b>		300.00		
		(S\$) 1,691.00		
<b>Liab Amount (50.00%) (S\$)</b>		<b>845.50</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>847.50</b>		

#### INSPECTION

Date of Assignment: 24/07/2018

Date Inspected: 24/07/2018 Inspected At: Vfix Auto Service Pte Ltd (HQ)  
60 Kaki Bukit Ave 6, ARK@KB  
Singapore 417892

Estimated Period of Repair: 2.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER LH	Distorted	490.00 FL	*490.00 FL	
2	1		*FRONT BUMPER END GARNISH NO1	Cracked	138.00 FL	*138.00 FL	
3	1		*FRONT BUMPER END GARNISH NO2	Cracked	145.00 FL	*145.00 FL	
4	1		*STEP BOARD GARNISH	Cracked	680.00 FL	*680.00 FL	
5	1		*STEP PANEL	Repair	450.00 FL	*- FL	
					<b>Sub Total (S\$)</b>	<b>1,903.00</b>	<b>1,453.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>190.30</b>	<b>145.30</b>
					<b>Total Parts (S\$)</b>	<b>1,712.70</b>	<b>1,307.70</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN STEP BOARD BRACKET REPLACE NEW PARTS REFIT ALIGN INTO POSITION WITH ALL NECESSARY COMPONENTS ATTACHMENTS	New	800.00	320.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	800.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,600.00</b>	<b>320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >