

2/7/93/2002

REF: CS/ACT 19013589 / NVBsz Special Instruction:

ASS. REC. BY:

Surveyor

ASSIGNMENT (Office)

From (Person): Eileen Lee of FCJ Date/Time: 25/7/2018 10:17am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1218Y Insured:

at Workshop m/s Comfort Delgro Tel:

of 59 Loyang Drive

Policy No: Claim No: D18/5600M / CT / EE / OD

Sum Insured: Excess:

Make of Veh: D.O.A. 19/7/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction ( ) Estimate Investigation
	SHD 1218Y - X
26/7/18	Revert to Eileen, vehicle T/L. pending investigation
14/9/18	Submit Ext T/L - BV \$ 25,921.33 LTA: \$ 18,800 NV: \$ 7119.33

NAR


RZF:

FCI

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TPRES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop No: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.



Sal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / FR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: S1D 42189 Reg: 10 MAY 2012  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_

Make: HYUNDAI SONATA Yr: 1991  
 Colour: BLUE Insured: Std / NI / NA  
 Sp. Reading: N/A Burnt Radio: Insured Std / NI / NA

Eng No: \_\_\_\_\_  
 Cr No: KMHBF41VMCA825050  
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or  
 Tyre Size: F: \_\_\_\_\_ R: 215 / 60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or WESTLAK (R) (F) BURNT

Front	Rear
R/Bal. <u>BURNT</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>BURNT</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>19/7/18</u>	D.O.I. <u>25/7/18</u>

Survey held at EDGE LOYANG  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
WHOLE VEHICLE BURNT  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

FCI E/S

RECEIVED 17 SEP 2018

14/9/2018

160x15=2400  
2400+170=2570

Date/Time File Pass to:  Prel. Report  
 Final Report  
 Date/Time File Return to:

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Survey Fee  
 Transportation  
 2570  
 50  
 8  
 2628+500

14/9 - typist  
 Report Format:  
 Lump Sum / I.B.: 3

Add Fee:  Site Insp: \$  
 Inter. : \$  
 Tech. : \$  
 Vehicle : \$

LKK (QA)  
 16/9/18

500/-

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 26 July 2018 2:08 PM  
**To:** Bryan Ang (LKKAuto); Eileen Lee; SUR; Naz (LKKAuto)  
**Subject:** RE: SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor // FC REF: D18/5600M/CT/EE/OD  
**Attachments:** SHD 4218Y PRELI ADVISED.pdf

Dear Eileen,

Enclosed preliminary revised of vehicle SHD 4218Y  
Date of survey: 25/7/2018

We have Not authorise repair.

Vehicle recommended Total Loss.

Pending investigation and Book Value.

**Dear Naz,**

**FYNA on investigation.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Bryan Ang (LKKAuto)  
**Sent:** Wednesday, 25 July 2018 10:20 AM  
**To:** Eileen Lee <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Subject:** RE: SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor // FC REF: D18/5600M/CT/EE/OD

Dear Assignment Team

Please assign this case to Naz.

Best Regards,

**Bryan Ang**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [bryanang@lkkauto.com](mailto:bryanang@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Eileen Lee [<mailto:EileenLee@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 25 July 2018 10:17 AM  
**To:** SUR <sur@lkkauto.com>; Bryan Ang (LKKAuto) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Subject:** FW: SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor // FC REF: D18/5600M/CT/EE/OD  
**Importance:** High

Dear LKK,

We refer to the above matter.

We have attached the accident report as well as estimate provided by our insured.

We would like to appoint you for the survey as well as investigation into the cause of fire for this matter.  
Please revert for instructions.

Please do the necessary investigation on the repairs, service, maintenance and replaced parts as per the maintenance record. Please also comment if the vehicle deem as roadworthy and release to driver etc.

Taxi is grounded at 59 Loyang Drive.  
Kindly contact Mr Lim Tien Siong @ 6214 8398 if you need any other information.

kindly continue to quote our reference in your reply.

Appreciate your correspondences, if any, via email, please.

Thank You.

Regards,  
Eileen Lee (Ms)  
Motor Claims Dept.



**Change of email address**  
eileenlee@msfirstcapital.com.sg

Motor Claims E-mail : motorclaims@msfirstcapital.com.sg  
Website: <http://www.msfirstcapital.com.sg>

MS First Capital Insurance Ltd | 36 Robinson Rd #16-01 City House Singapore 068877 | TEL : 6507 3848 |  
Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

*Personal Data Protection Act 2012 ("PDPA"):  
Under the PDPA, there are various requirements that regulate the processing of your personal data.  
Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.*

*Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.  
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.  
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.*

**From:** Doris Lim Puay Noi <doris\_lim@cdgtaxi.com.sg>  
**Sent:** Wednesday, July 25, 2018 9:20 AM

**To:** Eileen Lee <EileenLee@msfirstcapital.com.sg>  
**Cc:** CTPL Motor <CTPL@msfirstcapital.com.sg>; Lim Tien Siong <limts@cdge.com.sg>; Roger How Keen Meng <rogerhow@cdge.com.sg>; Tan Pei Wei <tanpw@cdge.com.sg>; Christine Tay Siew Hway <christine\_tay@cdgtaxi.com.sg>  
**Subject:** SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor  
**Importance:** High

Dear Eileen

Pls assist to appoint surveyor for the above matter.

Taxi is grounded at 59 Loyang Drive.

Kindly contact Mr Lim Tien Siong @ 6214 8398 if you need any other information.

Thank you.

Regards  
Doris Lim  
Fleet Safety Department  
Comfort Transportation Pte Ltd / Citycab Pte Ltd  
Hotline: 6550 8768 / DID: 6550 8606 / Fax: 6453 0491

" Think Safety. Drive Safely."

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

CityCab Pte Ltd Registration No. 199502839G

Comfort Transportation Pte Ltd [Registration No. 199303821R]

---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18/5600M/CY/EE/OD  
Our ref: CS/FCI18013589/Nvb

Date: 26/7/2018

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 4218Y**

We thank for your instruction on 25/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 25/7/2018 at the premises of M/s COMFORTDELGRO ENGINEERING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$170,459.24
Revised Estimate Amount	: S\$TOTAL LOSS
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:  
The vehicle caught fire.



Comments/Present Status:  
Repair Cost Not Economical

Pending investigation.

Yours faithfully,

Muhd Nazril  
Technical Investigator

## Catherine Chong (LKK Auto)

---

**From:** Eileen Lee <EileenLee@msfirstcapital.com.sg>  
**Sent:** Wednesday, 25 July, 2018 10:17 AM  
**To:** LKK SUR; Bryan Ang (LKKAuto); 'assignments@lkkauto.com'  
**Subject:** FW: SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor // FC REF: D18/5600M/CT/EE/OD  
**Attachments:** SHD4218X - Estimate.pdf; MCD618093536-SHD4218Y.PDF  
**Importance:** High

Dear LKK,

We refer to the above matter.

We have attached the accident report as well as estimate provided by our insured.

We would like to appoint you for the survey as well as investigation into the cause of fire for this matter. Please revert for instructions.

Please do the necessary investigation on the repairs, service, maintenance and replaced parts as per the maintenance record. Please also comment if the vehicle deem as roadworthy and release to driver etc.

Taxi is grounded at 59 Loyang Drive.

Kindly contact Mr Lim Tien Siong @ 6214 8398 if you need any other information.

*kindly continue to quote our reference in your reply.*

*Appreciate your correspondences, if any, via email, please.*

Thank You.

Regards,  
Eileen Lee (Ms)  
Motor Claims Dept.



**Change of email address**  
eileenlee@msfirstcapital.com.sg

Motor Claims E-mail : motorclaims@msfirstcapital.com.sg  
Website: <http://www.msfirstcapital.com.sg>

MS First Capital Insurance Ltd | 36 Robinson Rd #16-01 City House Singapore 068877 | TEL : 6507 3848 |  
Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

*Under the PDPA, there are various requirements that regulate the processing of your personal data.  
Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.*

*Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.  
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.  
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.*

---

**From:** Doris Lim Puay Noi <doris\_lim@cdgtaxi.com.sg>  
**Sent:** Wednesday, July 25, 2018 9:20 AM  
**To:** Eileen Lee <EileenLee@msfirstcapital.com.sg>  
**Cc:** CTPL Motor <CTPL@msfirstcapital.com.sg>; Lim Tien Siong <limts@cdge.com.sg>; Roger How Keen Meng <rogerhow@cdge.com.sg>; Tan Pei Wei <tanpw@cdge.com.sg>; Christine Tay Siew Hway <christine\_tay@cdgtaxi.com.sg>  
**Subject:** SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor  
**Importance:** High

Dear Eileen

Pls assist to appoint surveyor for the above matter.

Taxi is grounded at 59 Loyang Drive.

Kindly contact Mr Lim Tien Siong @ 6214 8398 if you need any other information.

Thank you.

Regards  
Doris Lim  
Fleet Safety Department  
Comfort Transportation Pte Ltd / Citycab Pte Ltd  
Hotline: 6550 8768 / DID: 6550 8606 / Fax: 6453 0491

" Think Safety. Drive Safely."

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

CityCab Pte Ltd Registration No. 199502839G

Comfort Transportation Pte Ltd [Registration No. 199303821R]

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHD4218Y
Vehicle to be Exported:	No
Intended De-registration Date:	26 Jul 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	D4EAC092695
Chassis No.:	KMHET41VMCA825050
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,537.00
Original Registration Date:	10 May 2012
First Registration Date:	10 May 2012
Transfer Count:	0
Actual ARF Paid:	\$14,537.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 May 2020
PARF Rebate Amount:	\$9,449.00
Intended COE Rebate Details	
COE Expiry Date:	09 May 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$41,914.00
COE Rebate Amount:	\$9,353.00
<b>Total Rebate Amount:</b>	<b>\$18,802.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Jul 2018

OK

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 20/07/2018 08:47  
 Date Of Accident 19/07/2018 11:50  
 Exact Location Of Accident PIE(TUAS) NEAR JURONG TOWN HALL EXIT  
 Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SHD4218Y  
**Insured/Policyholder**  
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD  
 Co Reg No 199303821R  
 Email Address FLEETSAFETY@CDGTAXI.COM.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-65508768

**Vehicle Particulars**

Manufacturer HYUNDAI  
 Model SONATA  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken REPORTING ONLY  
 Vehicle Category TAXI

**Insurance Company**

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD  
 Type Of Coverage - Repeat personal thing lost THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number - hired. 2012. Driving from start. D-18088936MFSH  
 Cover Note Number

**Driver**

Name of Driver ANG TECK GEE  
 NRIC No S0166961C  
 Date Of Birth 29/10/1952  
 Occupation OUTDOOR  
 Date Of Driving Pass 27/05/1974  
 Driving Experience 44 YEARS AND 1 MONTH  
 Gender MALE  
 Mobile Number (LOCAL) +65-98244967  
 Fax Number  
 Contact Number  
 EMail Address VEE.AJQ@GMAIL.COM

- 3 passengers. Jung west.  
 - alarm not.  
 - smoke fr bonnet  
 - taxi driver help take fire extinguisher  
 - fire come out fr side  
 - use but too big fire  
 - use than 10 min they can 2 put out fire.  
 - police came late  
 - 15 min fire put out.  
 - police take statement  
 - 30 min tow truck come  
 - follow go comfort

Address	BLK 239 SERANGOON AVENUE 2 #12-29
Postcode	550239
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

### General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE
Passenger 3	NAME: : - GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

PLS REFER TO ATTACHED

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan Pg. 1

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

CSO/AVC Sketch/Plant form\_V2



Sketch Plan Pg. 2

SKETCH PLAN

A) SHD42187

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer attachment

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199203321R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SR Moorthy  
CSO  
19/7/18

Annex A1

Statement

Date: 19/7/18

To: Officer-in charge,

I, Ang Teck Gee (hirer's name) NRIC S016696/C, of vehicle D42184

would like to share my experience of the accident/ incident as follows:

Today 19/7/18 was my servicing. I Reported to logan workshop at 0840 hrs for my Servicing. I reported my bonnet support was faulty. Around 1116 hrs I collected my vehicle. My first trip was from Changi Airport to Jurong West. During my trip to Jurong West near Jurong Town Hall exit, I felt the aircon was not cold but also I realised smoke was coming out from the bonnet. From the first lane I had slowly change lanes to stop at the road shoulder. Another taxi driver came to help me take out my fire extinguisher but the same time my vehicle caught heavy fire. Another passerby assisted me to call Civil Defense to assist putting out the fire. My passenger in the taxi was not injured. From the time I collect my vehicle from Logan Workshop I did not face any loss power or saw any indicator light on.

Your sincerely,

Ang Teck Gee  
(Signature)

Name of Hirer: Ang Teck Gee

Date: 19/7/2018

SP Society  
19/7/18

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3821R
<b>Vehicle Details</b>	
Vehicle No.:	SHD4218Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	24 Jul 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	D4EAC092695
Chassis No.:	KMHET41VMCA825050
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,537.00
Original Registration Date:	10 May 2012
First Registration Date:	10 May 2012
Transfer Count:	0
Actual ARF Paid:	\$14,537.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 May 2020
PARF Rebate Amount:	\$9,449.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 May 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$41,914.00
COE Rebate Amount:	\$9,382.00
<b>Total Rebate Amount:</b>	<b>\$18,831.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Jul 2018.

OK

Report ID : ZPTC122  
 DATE : 24.07.2018  
 TIME : 15:09:33

Contract Transportation Pl.  
 Vehicle No for Fleet Safety Division  
 AS AT 30.06.2018

USER ID : CTRN03  
 PAGE : 1

Co. Code : CTR  
 Licence Pl. No : SHD5218Y  
 Old Asset No :  
 Ven. Model : Hyundai, Scania  
 Reg. Date : 10.05.2012  
 Cap. Date : 10.05.2012  
 Accident Date : 19.07.2018  
 Ven. Age : 076

Asset No	SA. No	Bal. Dep. Mchrs	Per. Mch. Dep	Bal. Dep. Value	Asset Description 1	Cost	Op. Acc. Dep	Cur. Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated FAAR Refund
10029070	0	016	242.54	3,880.64	SHD4218Y HSN 10.05.2012 BASIC COSE \$21830 W ALUMIN	21,830.00	16,493.02-	1,455.27-	17,948.29-	3,881.71	1.00
10029070	1	016	32.30	516.60	SHD4218Y HSN 10.05.2012 INVERT IDTY	2,907.30	2,196.53-	193.82-	2,390.45-	516.65	0.00
10029070	2	016	64.61	1,033.76	SHD4218Y HSN 10.05.2012 APT 100NORWS14537	14,537.00	4,393.55-	387.67-	4,781.22-	9,755.78	8,722.00
10029070	3	016	465.71	7,451.36	SHD4218Y HSN 10.05.2012 COE 804	41,914.00	31,668.35-	2,794.27-	34,462.62-	7,451.36	0.00
10029070	4	000	0.00	0.00	SHD4218Y HSN 10.05.2012 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10029070	5	016	0.00	0.00	SHD4218Y HSN 10.05.2012 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10029070	6	016	0.00	0.00	SHD4218Y HSN 10.05.2012 PAINTER DIGITAL THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10029070	7	016	0.00	0.00	SHD4218Y HSN 10.05.2012 PAINTER DIGITAL FL	0.00	0.00	0.00	0.00	0.00	0.00
10029070	8	016	1.55	24.96	SHD4218Y HSN 10.05.2012 VEH REG FEE	140.00	105.78-	9.34-	115.12-	24.88	0.00
			866.72	12,907.52		81,328.30	54,857.33-	4,850.37-	59,697.70-	21,630.60	
		COE	465.71	7,451.36	Vehicle : WILSON T/M & COE	39,414.30	23,188.98-	2,046.10-	25,235.08-	14,179.22	
		Vehicle	341.01	5,456.16	Vehicle : WILSON T/M, WITH COE	81,328.30	54,857.33-	4,850.37-	59,697.70-	21,630.60	
		Text-Enter	866.72	12,907.52	Text-Enter	0.00	0.00	0.00	0.00	0.00	

Cost 81,328.30  
 Depreciation =  $\frac{65}{100} \times 81,328.30$   
 = 52,866.40

Depreciation = (81,328.30 - 9,449.05) ÷ 96  
 = 71,879.25 ÷ 96  
 = 748.94

Book Value = 748.94 × 22 + 9,449.05  
 = 16,676.72 + 9,449.05  
 = 26,125.77

Net Value = 26,125.77 - 18,802  
 = 7,323.77

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/07/2018 08:47
Date Of Accident	19/07/2018 11:50
Exact Location Of Accident	PIE(TUAS) NEAR JURONG TOWN HALL EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4218Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	ANG TECK GEE
NRIC No	S0166961C
Date Of Birth	29/10/1952
Occupation	OUTDOOR
Date Of Driving Pass	27/05/1974
Driving Experience	44 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98244967
Fax Number	
Contact Number	
EEmail Address	VEE.AJQ@GMAIL.COM

Address	BLK 239 SERANGOON AVENUE 2 #12-29
Postcode	550239
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE
Passenger 3	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

J R MOODY  
CSO  
19/7/18

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN

A) SHD 42184

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer attachment

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFRT TRANSPORTATION PTE LTD  
CO. REG. NO. 198203321R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*SR Moorthy*  
CSO  
19/7/18

Annex A1

Statement

Date: 19/7/18

To: Officer-in charge,

I, Ang Teck Gee (hirer's name) NRIC S016696/C, of vehicle D42184

would like to share my experience of the accident/ incident as follows:

Today 19/7/18 was my servicing. I Reported to logan workshop at 0840 hrs for my Servicing. I reported my bonnet support was faulty. Around 1116 hrs I collected my vehicle. My first trip was from Changi Airport to Jurong west. During my trip to Jurong west leaving Jurong town Hall exit, I felt the aircon was not cold but also I realised smoke was coming out from the bonnet. From the first lane I had slowly change lanes to stop at the road shoulder. Another taxi driver came to help me take out my fire extinguisher but the same time my vehicle caught heavy fire. Another passerby assisted me to call Civil Defense to assist putting out the fire. My Passenger in the taxi was Not injured. From the time I collect my vehicle from Logan workshop I did Not face any loss, power or saw any indicator light on.

Your sincerely,

Ang Teck Gee  
(Signature)

Name of Hirer: Ang Teck Gee

Date: 19/7/2018

S R MacIntyre  
S R MacIntyre  
19/7/18

Reply | ▾ Delete Junk | ▾ ...

## Re: SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor

Doris Lim Puay Noi

Reply | ▾

Wed 25/7/2018 10:27 AM

To: Eileen Lee <EileenLee@msfirstcapital.com.sg>

Cc: CTPL Motor <CTPL@msfirstcapital.com.sg>; Lim Tien Siong; Roger How Keen Meng; Tan Pei Wei; Christine Tay Siew Hway

Inbox

Dear Eileen

Noted with thanks.

---

Aside to Roger / Tien Siong

Please take note.

Regards

Doris Lim

Fleet Safety Department

Comfort Transportation Pte Ltd / Citycab Pte Ltd

Hotline: 6550 8768 / DID: 6550 8606 / Fax: 6453 0491

" Think Safety. Drive Safely."

---

**From:** Eileen Lee <EileenLee@msfirstcapital.com.sg>

**Sent:** Wednesday, 25 July 2018 10:17 AM

**To:** Doris Lim Puay Noi

**Cc:** CTPL Motor; Lim Tien Siong; Roger How Keen Meng; Tan Pei Wei; Christine Tay Siew Hway

**Subject:** RE: SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor

Dear All,

We have engaged LKK for this matter.

-  
Thank You.

Regards,

Eileen Lee (Ms)

Motor Claims Dept.



Change of email address

Reply | Delete | Junk | ...

Motor Claims E-mail : [motorclaims@msfirstcapital.com.sg](mailto:motorclaims@msfirstcapital.com.sg)

Website: <http://www.msfirstcapital.com.sg>

MS First Capital Insurance Ltd | 36 Robinson Rd #16-01 City House Singapore 068877 | TEL : 6507 3848 |  
Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

*Personal Data Protection Act 2012 ("PDPA"):*

*Under the PDPA, there are various requirements that regulate the processing of your personal data.*

*Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.*

*Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.*

*If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.*

*If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.*

---

**From:** Doris Lim Puay Noi <doris\_lim@cdgtaxi.com.sg>  
**Sent:** Wednesday, July 25, 2018 9:20 AM  
**To:** Eileen Lee <EileenLee@msfirstcapital.com.sg>  
**Cc:** CTPL Motor <CTPL@msfirstcapital.com.sg>; Lim Tien Siong <limts@cdge.com.sg>; Roger How Keen Meng <rogerhow@cdge.com.sg>; Tan Pei Wei <tanpw@cdge.com.sg>; Christine Tay Siew Hway <christine\_tay@cdgtaxi.com.sg>  
**Subject:** SHD4218Y - Fire on 19/07/18 (CT18070565) To appoint surveyor  
**Importance:** High

Dear Eileen

Pls assist to appoint surveyor for the above matter.

Taxi is grounded at 59 Loyang Drive.

Kindly contact Mr Lim Tien Siong @ 6214 8398 if you need any other information.

Thank you.

Regards

Doris Lim

Fleet Safety Department

Comfort Transportation Pte Ltd / Citycab Pte Ltd

Hotline: 6550 8768 / DID: 6550 8606 / Fax: 6453 0491

" Think Safety. Drive Safely."

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying,

Reply | ▾ Delete Junk | ▾ ...

incidental purposes only and are subject to approval. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

CityCab Pte Ltd Registration No. 199502839G

Comfort Transportation Pte Ltd [Registration No. 199303821R]

---

REPA IRESTIMATE\*

VEHICLE NO : SHD 4218X

MAKE :

MODEL : HYUNDAI SONATA

LKK

(Email Attached)

DATE 25/7/2018 (Wed)

Fire Case

06 pages

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 1,151.80
	Bonnet Rubber (LH)			\$ 18.00
	Bonnet Rubber (RH)			\$ 7.10
	Bonnet Hinge (LH/RH)	\$	87.50	\$ 175.00
	Bonnet Moulding			\$ 120.90
	Bonnet Lock			\$ 48.80
	Bonnet Absorber			\$ 70.80
	Bonnet Insulator			\$ 232.80
	Bonnet Seal			\$ 36.60
	Bonnet Insulator Clips			\$ 10.00
	Bonnet Cable			\$ 45.50
	Radiator Grille			\$ 282.10
	Radiator Grille U Moulding			\$ 108.90
	Front Bumper Cover			\$ 538.80
	Front Bumper Sponge			\$ 136.30
	Front Bumper Reinforcement			\$ 504.10
	Front Bumper Grille (LH/RH)	\$	17.60	\$ 35.20
	Front Bumper Centre Grille			\$ 131.10
	Front Bumper Lip			\$ 59.90
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80
	Front Bumper Protector (LH/RH)	\$	29.20	\$ 58.40
	Front Bumper Bracket (LH/RH)	\$	20.10	\$ 40.20
	Front Bumper Side Bracket	\$	14.30	\$ 28.60
	Front Bumper Retainer Mounting			\$ 9.20
	Front Bumper Clips 10 pcs			\$ 22.00
	Headlamp Support Panel Assy			\$ 1,023.00
	Headlamp (LH/RH)	\$	797.90	\$ 1,595.80
	Headlamp Halogen Bulb (LH/RH)	\$	13.80	\$ 27.60
	Radiator			\$ 814.80
	Radiator Fan Blade,Cowling,Motor Assy			\$ 651.30
	Radiator Bracket			\$ 6.20
	Radiator Hose Upper			\$ 45.40
	Radiator Hose Lower			\$ 45.40
	Radiator Expansion Tank			\$ 46.00
	Horn Unit (LH/RH)	\$	83.10	\$ 166.20
	Horn Wire			\$ 150.00
	Front Fender (LH/RH)	\$	593.00	\$ 1,186.00
	Front Fender Apron Panel (LH/RH)	\$	1,120.50	\$ 2,241.00
	Front Fender Shield (LH/RH)	\$	86.00	\$ 172.00
	Front Fender Mudflap (LH/RH)	\$	15.50	\$ 31.00
	Front Fender Signal Lamp (LH/RH)	\$	45.40	\$ 90.80
	Front Fender Retainer	\$	9.20	\$ 18.40
	Air Cleaner Assy			\$ 254.30
	Air Filter			\$ 52.50
	Air Cleaner Cover			\$ 33.00
	Air Duct			\$ 197.50

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Air Flow Sensor			\$ 606.90
	Air Duct B			\$ 251.00
	Air Cleaner Body			\$ 101.80
	Aircon Blower Motor Unit			\$ 1,389.70
	Aircon Expansion Valve			\$ 210.00
	Aircon Sensor Pressure - Suc/Liq			\$ 233.90
	Aircon Condenser			\$ 1,089.90
	Aircon Receiver			\$ 68.50
	Aircon Suction & Liquid Hose			\$ 631.40
	Aircon Discharge Hose			\$ 223.50
	Aircon Blower Motor			\$ 251.20
	Aircon Compressor			\$ 2,738.50
	Aircon Evaporation Coil & Heater Unit			\$ 2,388.50
	Aircon Control Assy			\$ 817.20
	Battery Tray			\$ 53.00
	Battery Stay			\$ 20.00
	Fuse Box Front			\$ 398.00
	Front Door (LH/RH)	\$	1,345.00	\$ 2,690.00
	Front Door Rubber	\$	110.40	\$ 220.80
	Front Door Glass (LH/RH)	\$	363.70	\$ 727.40
	Front Door Gear / Regulator (LH/RH)	\$	313.10	\$ 626.20
	Front Door Hinge Upper (LH/RH)	\$	51.10	\$ 102.20
	Front Door Hinge Lower (LH/RH)	\$	51.10	\$ 102.20
	Front Door Check (LH/RH)	\$	105.50	\$ 211.00
	Front Door Inner Lock (LH/RH)	\$	334.40	\$ 668.80
	Front Door Key Lock Set (LH/RH)	\$	82.40	\$ 164.80
	Front Door Outer Handle (LH/RH)	\$	37.00	\$ 74.00
	Front Door Outer Moulding (LH/RH)	\$	61.00	\$ 122.00
	Front Door Mirror (LH/RH)	\$	545.50	\$ 1,091.00
	Front Door Power Motor	\$	508.40	\$ 1,016.80
	Front Door Trim Board (LH/RH)	\$	1,147.00	\$ 2,294.00
	Front Door Protector (LH/RH)	\$	74.90	\$ 149.80
	Door Centre Pillar Outer (LH/RH)	\$	1,711.70	\$ 3,423.40
	Door Pillar Enforcement (LH/RH)	\$	857.00	\$ 1,714.00
	Door Centre Pillar Inner			\$ 1,407.80
	Door Pillar Inner Garnish			\$ 30.00
	Frnt Safety Belt (Assy) (LH/RH)			\$ 548.70
	Frnt Safety Belt Duckle			\$ 82.40
	Rocker Panel Enforcement (LH/RH)	\$	1,114.80	\$ 2,229.60
	Rocker Panel Inner (LH/RH)	\$	404.40	\$ 808.80
	Rocker Panel Outer Garnish	\$	463.40	\$ 926.80
	Rocker Panel Outer	\$	1,280.50	\$ 2,561.00
	Rocker Inner Side Panel (LH/RH)	\$	112.70	\$ 225.40
	Rocker Panel Step Garnish (Front) (LH/RH)	\$	30.30	\$ 60.60
	Rocker Panel Step Garnish (Rear) (LH/RH)	\$	30.30	\$ 60.60
	Rear Door (LH/RH)	\$	1,294.70	\$ 2,589.40
	Rear Door Rubber (LH/RH)	\$	121.20	\$ 242.40
	Rear Door Glass (LH/RH)	\$	231.20	\$ 462.40
	Rear Door 1/4 Glass (LH/RH)	\$	104.80	\$ 209.60

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door Inner Moulding (LH/RH)		\$ 146.00	\$ 292.00
	Rear Door Outer Moulding (LH/RH)		\$ 203.30	\$ 406.60
	Rear Door Inner Handle (LH/RH)		\$ 34.20	\$ 68.40
	Rear Door Outer Handle (LH/RH)		\$ 39.60	\$ 79.20
	Rear Door Switch (LH/RH)		\$ 13.80	\$ 27.60
	Rear Door Channnel (LH/RH)		\$ 70.50	\$ 140.99
	Rear Door Gear / Regulator (LH/RH)		\$ 313.10	\$ 626.20
	Rear Door Lock Assy		\$ 308.40	\$ 616.80
	Rear Door 1/4 Glass Rubber (LH/RH)		\$ 53.70	\$ 107.40
	Rear Door 1/4 Glass Pillar (LH/RH)		\$ 77.50	\$ 155.00
	Rear Door Hinge Upper (LH/RH)		\$ 51.00	\$ 102.00
	Rear Door Hinge Lower (LH/RH)		\$ 51.00	\$ 102.00
	Rear Door Check (LH/RH)		\$ 72.30	\$ 144.60
	Rear Door Trim Board (LH/RH)		\$ 855.30	\$ 1,710.60
	Rear Door Protector (LH/RH)		\$ 54.50	\$ 109.00
	Front Windscreen Glass			\$ 1,015.00
	Front Windscreen Moulding			\$ 60.00
	Front Windscreen Pillar Outer(LH/RH)		\$ 1,766.20	\$ 3,532.40
	Front Windscreen Pillar Inner(LH/RH)		\$ 1,666.30	\$ 3,332.60
	Front Windscreen Enforcement(LH/RH)		\$ 1,114.80	\$ 2,229.60
	Front Windscreen Pillar Inner Garnish(LH/RH)		\$ 112.70	\$ 225.40
	SunVisor			\$ 270.00
	Wiper Blade			\$ 70.50
	Wiper Motor			\$ 552.00
	Wiper Arm			\$ 53.70
	Wiper Panel Top Garnish			\$ 87.40
	Wiper Link			\$ 408.20
	Wiper Container			\$ 59.00
	Wiper Container Motor			\$ 63.00
	Wiper Washer Tank Hose			\$ 80.00
	Wiper Container Pipe			\$ 70.00
	Front Wheel Rim (LH/RH)		\$ 284.70	\$ 569.40
	Front Wheel Hub Cap (LH/RH)		\$ 145.00	\$ 290.00
	Front Wheel Bearing		\$ 258.50	\$ 517.00
	Front Shock Absorber (Assy) (LH/RH)		\$ 203.70	\$ 407.40
	Front Shock Absorber Mounting (LH/RH)		\$ 72.00	\$ 144.00
	Front Shock Absorber Fork (LH/RH)		\$ 203.30	\$ 406.60
	Front Suspension Upper Arm (LH/RH)		\$ 240.00	\$ 480.00
	Front Drive Shaft (LH/RH)		\$ 1,025.00	\$ 2,049.99
	Rack & Pinion Assy			\$ 2,093.00
	STG Tie Rod		\$ 155.20	\$ 310.40
	STG Tie End		\$ 66.50	\$ 133.00
	Stabilizer Bar			\$ 213.20
	Stabilizer Bar Bush (LH/RH)		\$ 12.80	\$ 25.60
	Stabilizer Bar Link		\$ 78.30	\$ 156.60
	Brake Calisper (LH/RH)		\$ 649.00	\$ 1,298.00
	Stabilizer Bracket		\$ 23.00	\$ 46.00
	Front Suspension Lower Arm (LH/RH)		\$ 685.20	\$ 1,370.40
	Front Chasis Member (LH/RH)		\$ 1,219.80	\$ 2,439.60

BN

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Knuckle Arm (LH/RH)		\$ 558.60	\$ 1,117.20
	Knuckle Arm Bearing (LH/RH)		\$ 122.10	\$ 244.20
	Timing Cover Upper			\$ 121.40
	Timing Cover Lower			\$ 110.00
	Timing Gear			\$ 204.10
	Timing Meter			\$ 325.20
	Timing Belt			\$ 234.30
	Timing Tensioner Assy			\$ 228.00
	Fan Belt			\$ 155.00
	Brake Master Pump			\$ 416.70
	Brake Booster Pump			\$ 981.50
	Brake Vacuum Pump			\$ 420.10
	Engine Mounting			\$ 461.80
	Oil Sump			\$ 417.40
	Oil Pump			\$ 1,044.40
	Engine Under Cover			\$ 328.70
	Engine Crossmember			\$ 2,143.70
	Engine Lower Cover			\$ 54.00
	Front Seat Adjuster Outer Garnish (LH/RH)	\$	580.30	\$ 1,160.60
	Front Seat Adjuster (Outer) (LH/RH)	\$	1,162.00	\$ 2,324.00
	Front Seat Adjuster (Inner) (LH/RH)	\$	1,020.20	\$ 2,040.40
	Front Cushion Seat (LH)			\$ 3,019.90
	Front Cushion Seat (RH)			\$ 5,742.30
	Engine Mtg (Front)			\$ 225.50
	Engine Mtg (Rear)			\$ 268.00
	Engine Support Bracket Assy			\$ 523.80
	Hand Brake Cable			\$ 322.00
	Hand Brake Handle			\$ 529.00
	Gearbox Mounting			\$ 328.20
	Gearbox Shift Assy			\$ 989.00
	Gearbox Cross Member			\$ 380.20
	Roof Upholstery			\$ 2,875.00
	Roof Panel Assy			\$ 1,194.90
	Roof Moulding			\$ 132.30
	Instrumental Panel			\$ 1,595.00
	Dashboard Complete			\$ 2,576.00
	Dashboard Re-Inforcement Bar			\$ 631.30
	Console Box Assy			\$ 1,840.00
	Console Box Cover			\$ 409.60
	Glove Box Cover			\$ 509.20
	Glove Box Panel Lower Cover			\$ 850.20
	Dashboard Speedo Meter Assy			\$ 2,760.00
	Pstg Hose & Bracket			\$ 73.20
	Power Steering Pump			\$ 722.70
	Power Steering Tank			\$ 174.10
	Power Steering Pressure Hose Assy			\$ 588.60
	Power Steering Outlet Hose & Bracket			\$ 73.20
	Power Steering Pipe Assy			\$ 73.20
	Power Steering Pulley			\$ 65.30

BN



Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Number Plate			\$ 25.00	Nett
	Front No Plate Trim Cover			\$ 30.00	Nett
	Front Fender Advertisement Logo (LH/RH)	S	100.00	\$ 200.00	Nett
	New Battery			\$ 207.00	Nett
	Front Door Comfort Logo (LH/RH)	S	75.00	\$ 150.00	Nett
	Front Door Advertisement Logo (LH/RH)	S	100.00	\$ 200.00	Nett
	Rear Door Advertisement Logo (LH/RH)	S	100.00	\$ 200.00	Nett
	Rear Door Tel No. Sticker (LH/RH)	S	10.00	\$ 20.00	Nett
	Front Windscreen Sealant			\$ 46.00	Nett
	Front ERP Sticker			\$ 30.00	Nett
	Front Tyre (LH/RH)	S	207.00	\$ 414.00	Nett
	Gearbox			\$ 5,800.00	Nett
				<b>\$ 7,322.00</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ 3,000.00	
	Spray Painting Charge			\$ 1,800.00	
	Wiring Charge			\$ 100.00	
	Tuff Kote			\$ 100.00	
	Towing Charge			\$ 60.00	
	Front Chassis Alignment Charge			\$ 800.00	
	Remove/Refix Undercarriage (FRT)			\$ 400.00	
	FRT Wheel Alignment			\$ 120.00	
	Remove/Refix Radiator			\$ 90.00	
	Remove/Refix Aircon & Refill Gas			\$ 150.00	
	Remove/Refix Engine			\$ 500.00	
	Remove/Refix Dashboard			\$ 450.00	
	Remove/Refix Fuse Box			\$ 180.00	
	Remove/Refix Front Windscreen Glass			\$ 120.00	
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	
	Remove/Refix Steering Rack/Wheel/Dr Shaft			\$ 150.00	
	Remove/Refix Power Steering Pump			\$ 120.00	
	Remove/Refix Roof Top Taxi Digital Sign			\$ 150.00	
	R/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$ 550.00	
				<b>\$ 8,930.00</b>	
				<b>\$ 170,459.24</b>	
	<p>NAZ LKK</p> <p>25/7/18 1645</p> <p>Vehicle totally burnt</p> <p>Uneconomical to repair.</p> <p>request book value.</p> <p>request past 6 months servicing records.</p>				

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

BN

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

A member of COMFORTDELGRO

Date/Time: 20.07.2018 09:49 Page : 1

Team: ARC Repair OD(CLSO)1 **JOB CARD** Sales Order: JC NO.: 305190070


CUSTOMER <b>COMFORT TRANSPORTATION PTE LTD</b> 7010045 CUSTOMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (O) L (R) (P)	REGN NO: SHD4218Y	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL SONATA	DATE/TIME IN 19.07.2018 11:50
	YR OF MANU 10.05.2012	TARGET DATE
	CHASSIS CODE RMHET41VMCA825050	COMPLETION DATE/TIME:
	SCOUNT CARD NO.	

Accident Date: 19.07.2018  
 NATURE: OD 19.07.18 \*\*FIRE CASE\*\*

JOB DESCRIPTION

S/NO LABO CODE

DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD4218Y  
 License No.: LIMTS

Vehicle No.: SHD4218Y

Signature/Date

Name of Service Advisor Date

Returned to Service Reception upon collection

To be kept by Security Guard