

15/5/2010

LKK
IDAC:

INS CASE NUMBER

ASSIGNMENT

Surveyor:

MADEN

DOI:

26/8/18

Date / Time:

26/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SK 1578L

Name of Insured:

ABDUL KARIM B. Abd. Rahim

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Excess Sec II :SS

D.O.A:

24/8/2018

Make / Model:

Blue V6 Tempus ST 44mccp.

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJ674905

INSRS:
WSP:
Tel:
Liability:
RMKS:Hock wah
GedokINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

21/8

21/8

SJ674905 - C6/AKA1407096/6pm3p2 - 00721/1/4

- C64/AKA1407096/6pm3p2 - 00721/1/4

SK 1578L - X

21/8 DIVER - sent out 1st letter.

non reporting case, mother had been little
privacy, private settlement form

Had After report photo X

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI

After call ltr to OI

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA :

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos:

Sent By:

08/11/03 wel
ASS REC BY: MDCWJ

REF:

A14/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJA 74905

at Workshop m/s: Kocleuch 3/m.

of SKC 278L

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. of Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No 0.629F

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 14/7/2008

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SJA 74905 Yr Reg: 15/7 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: C/A,

Make: Toyota WSL C.C. 1794

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 143939 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDER12W 503000450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO (YOKO) or

Front: 6 Rear: 6

R/Bal: mm R/Bal: mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 24/7/08 D.O.I: 26/7/08

Survey held at:

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

1/5 R1.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/7/08 LIA 36750
Contacted 1/5 & PSD with Anysee.

4/516 350.00 (Rush 1,496.11 / 66.62%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ - RS - \$

Photos

Other

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S0270629F
FOO CHENG THENG
NO 10 TOH AVENUE

SINGAPORE 508036
TEL : FAX :
PH : 96812846
ATTN :

ESTIMATE BILL

Number : EB00004909
Date : 25/07/2018
Case No : AD00009870
Vehicle No : SJG7490S
Chassis : JTDER12W503000450
Year of Mfr : 2008
Policy No :
Model : TOYOTA WISH 1.8 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER	1.0	557.60	25	418.20
2	FRONT BUMPER RETAINER LH	1.0	75.48	25	56.61
3	FRONT FENDER SHIELD LH	1.0	188.40	25	141.30
List Price - Parts Sub Total					616.11
4	FRONT BUMPER SPOILER	1.0	680.00	0	680.00
5	FRONT FENDER LH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					680.00
Parts Total					1,296.11
6	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
7	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
8	ANTI-RUST COATING	1.0	150.00	0	150.00
Labour 1 Sub Total					1,250.00
SINGAPORE DOLLARS : TWO THOUSAND SEVEN HUNDRED TWENTY-FOUR AND CENTS THIRTY-FOUR ONLY					
Less Excess					0.00
SUBTOTAL					2,546.11
GST 7.00%					178.23
TOTAL					2,724.34

Date of accident : 24/07/2018 12:35 PM. Place : BLK415 TAMPINES STREET 44 MSCP

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0629F
Vehicle Details	
Vehicle No.:	SJG7490S
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1ZZ3122012
Chassis No.:	JTDER12W503000450
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,803.00
Original Registration Date:	15 Jul 2008
First Registration Date:	15 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$18,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$36,888.00
COE Rebate Amount:	\$36,750.00
Total Rebate Amount:	\$36,750.00

The information contained herein is correct as at 27 Jul 2018

OK

View Received Message

This mail is associated with :

***SJG74905 (5197194718SG)
[SKC5278L]**

TP
FOO CHENG THENG
Jul 24 2018 12:00PM
[ABDUL KARIM BIN ABUL RAHIM]
Hock Wah Motor Workshop Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 27/07/2018 14:36 PM.
To LKK_HQ
Subject No OI GIA Report (SKC5278L VS SJG74905)

Hi

Pls be advice that no OI GIA report received
Pls find OI details below for your further actions

OI name : Abdul Karim Bin Abdul Rahim

Address :
Blk 479 Tampines St 44 #04-233
Singapore 520479

Thank you.

Regards,

Syaza Irdina Azlan

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18013599/Ufa3

07th Aug 2018

Abdul Karim Bin Abdul Rahim

Blk 479 Tampines St 44

#04-233

Singapore 520479

Dear Sirs,

**ACCIDENT INVOLVING SKC 5278L AND SJG 7490S ON 24.07.2018 ALONG/
AT BLK 415 TAMPINES STREET 44 MULTI STOREY CAR PARK**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Poh Kin, Chong

Claims

Tel : 6841 2132

Fax: 6741 4108

Email : pohkin@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Wednesday, 14 August 2019 5:51 PM
To: Ler, Bernard-JQ
Cc: Admin A
Subject: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKC 5278L (OI) AND SJG 7490S (TP) ON 24/07/2018

Importance: High

AIG Ref: **TP / 5197194718SG**
Our Ref: CC6/AIG18013599/Ufa3

Dear Bernard,

We refer to the above matter.

Please be informed that Our Insured manage to settled this matter privately with Third Party Claimant/repairer. Private Settlement Form uploaded in Merimen for your kind attention.

In view of this, we will submit our without prejudice report to your good office soonest.

Thank you.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

PRIVATE SETTLEMENT

1. Details of Accident:

Date & Time: 24/07/2018 12:35hrs Location: WALKERS TAMPINES STREET 44 MSCP

2. A) Motor – Vehicle Registration No. SG 74905 (party receive compensation)

Driven by: FOO HENG THENG (Name as per IC)

Owned by: _____ (Name as per IC)

B) Motor – Vehicle Registration No. SKC5278L (party paying compensation)

Driven by: ABDUL KARIM BIN ABDUL RAHIM (Name as per IC)

Owned by: _____ (Name as per IC)

3. There are no personal injuries or death involved.

4. Parties have agreed to settle this matter by compensating the other party for any loss of damages (direct or indirect) incurred or to be incurred as a result of the accident.

5. Without any admission of liability, the party paying compensation had made the payment **amount of \$ 535-00-**. Owner receiving compensation hereby acknowledge the receipt therefore in full and final settlement of all damages and costs incurred and/or to be incurred as a result of the accident.

6. Both parties have not and will not make a police report and accident report of this accident.

A) Name (party receive): FOO HENG THENG

Tel: 96812846

NRIC / Passport no.: S0270629F

Signature: 

B) Name (party paying): ABDUL KARIM BIN ABDUL RAHIM

Tel: 96367669

NRIC / Passport no.: S00801502-

Signature: 

Witness Name & Workshop Stamp: 



...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2018 Edit Reg		26 Jul 2018 00:00 Edit Adj Rpt	\$850.00 Edit Estimates	\$850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	ABDUL KARIM BIN ABUL RAHIM , ID: S0080150Z								
Main Claimant:	FOO CHENG THENG , ID: S0270629F								
Vehicle Reg. No.:	SJG7490S	Date of Loss:	24/07/2018 12:00 - :59 [120 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5197194718SG	Policy/Cover Note No.:	2100345490						
Vehicle Reg. No. (Insured):	SKC5278L	Policy No. (Claimant):	5092546041-01						
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (27/07/2018): No OI GIA Report (SKC5278L VS SJG7490S)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJG7490S (5197194718SG)
[SKC5278L]
TP
FOO CHENG THENG
Jul 24 2018 12:00PM
[ABDUL KARIM BIN ABUL RAHIM]
Hock Wah Motor Workshop Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Photos/Images														3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
2	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
3	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
4	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
5	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
6	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
7	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
8	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
9	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
10	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
11	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
12	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
13	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
14	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
15	26/07/18 17:13	General View											Load JPG	<input checked="" type="checkbox"/>		
16	26/07/18 17:13	Odometer Reading											Load JPG	<input checked="" type="checkbox"/>		
17	26/07/18 17:14	Chassis Number											Load JPG	<input checked="" type="checkbox"/>		
Documentation														1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	26/07/18 14:42	TP GIA REPORT											Load PDF			
2	05/08/18 23:21	TP ESTIMATE-MARKED											Load PDF			
3	07/08/18 11:54	Non reporting letter											Load PDF			
4	14/08/19 17:48	Private settlement form											Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18013599/UFA3Q2

Date: 19/08/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100345490
Claimant Vehicle No :	SJG7490S	Insured Vehicle No :	SKC5278L
Date of Loss:	24/07/2018	Nature of Claim:	TP
		Claim No:	5197194718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG7490S	Engine No:	1ZZ3122012
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W503000450
Reg. Date:	15/07/2008 (Man. Year: 2008)	Odometer:	143939 km
Colour:	Blue		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,296.11	474.81	821.30	63.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	600.00	650.00	52.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,546.11	1,074.81	1,471.30	57.79
Approved Total (Overridden) (S\$)		850.00		
(S\$)	2,546.11	850.00	1,696.11	66.62
+ GST 7.00/7.00% (S\$)	178.23	59.50	118.73	66.62
Nett Amount (S\$)	2,724.34	909.50	1,814.84	66.62
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	26/07/2018	
Date Inspected:	26/07/2018 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01- 2008/2010/2012 Singapore 489977
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	557.60 FL	*557.60 FL
2	1		*FRONT BUMPER RETAINER LH	Bent	75.48 FL	*75.48 FL
3	1		*FRONT FENDER SHIELD LH	Not Necessary	188.40 FL	*- FL
4	1		*FRONT FENDER LH (NPA)	Not Necessary	0.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Repair	680.00 FS	*- FS
					Sub Total (\$\$)	1,501.48 633.08
					- List Item Discount on L Items 25.00/25.00% (\$\$)	205.37 158.27
					Total Parts (\$\$)	1,296.11 474.81

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	600.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	500.00	400.00
3	ANTI-RUST COATING	New	150.00	0.00
Gross Labour Cost (S\$)			1,250.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >