

136291 10ph3

ACKNOWLEDGMENTS

Veh No: SLE 68770 Yr Regn: 07 16

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make Mit Lancer Ex 1310

Colour M. Green A/C Insured / Std / NI / NA

Sp. Reading 68512' T/Radio: Insured / Std / NI / NA

Eng/No

C/No JmyPRCY/AG U 005611

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: In~~order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim of

Tyre Size: F: 205/60R16

R:

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO at

Roadstone

Front 7 mm Rear 6 mm
R/Bal. mm R/Bal. mm

L/Bal. 7 mm L/Bal. 6 mm

DOA 23/7/18 DOI 7/8/18

Survey held at ☐ ☒

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

By nls

8/8 File parts into

☐: Prelim. Report☐ Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Y. S. + F. 74

Add Fee: Site Insp (\$☐ Interview: \$

Tech. Inc. \$

 Want up to \$

Lump Sum / LEH: 13