

Surveyor

REF: CS3 / ASM18009945 / R14b1

Special Instruction:

1/5: \$ 5150.00

ASSIGNMENT (Office)

From (Person): Heng Xinyi of Seah Ong Date/Time: 25/07/2018
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: PRO Plus Automobile

Workshop: Thiam Heng Auto

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: GW 8062P Insured: GBC 5714B

at Workshop m/s Thiam Heng Auto Tel: 6469 5691

of Blk 1, Bukit Butok Crescent #03-17

Policy No: 18.74698 PD-0 Claim No: 58M001WX

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/05/2018

(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 6 days)

Date/Time: 01/8/18 Submit Final Fig 3550, 6 days (Red \$ 1600 / 3 %; Original 6 days)

Date/Time	Action/Instruction
	<u>GW 8062P - CS3 / ASM18009945 / R14b1</u>
	<u>GBC 5714B - X</u>
	<u>U/S</u>
	<u>Repair Days 6</u>

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 2 AUG 2018

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

150

150

1) Date/Time 01/8/18 File Pass to tu 1/31

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

4) Date/Time _____ File Return to _____

6) Date/Time _____ File Return to _____

ASSIGNMENT		REF 983 / ASM 18009945 / R 2462	
SPW / CLAIM		ASSIGNMENT (Office)	
From (Person)	Ruth Chua	At	Asm
Dated/Time	30052018 1008am		
Rated/Of Cost		DUE	
OD / (R) WS / TP RES / OD RES / CA / INV / INV / CA			
To Inspect Vehicle No.	GW 8062P	Insured	381 5714B
at Workshop no.	Thiam Heng Motor	TEL	9855 8158
of	1 Bukit Batok Crescent 413-17		
Policy No.		Claim No.	SSM001WX
Sum Insured		Excess	
Make of Vch		DATE	28052018
(Client's Name)		7A Jin Pagan (Mr Ang - 98389479)	
CA / REV / REP / REV 24HRS WP		Johnny	
DUE/Time	01062018 359pm	Vehicle	(R) 0011
DUE/Time	As scheduled	X	Y
5/6/18	Dismantled		
12/6/18	After repair		

Signature

P. Tan

REF:

5778R

LOEPRIN: 2018/05

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No: GW 8062P

at Workshop mis THIAN HON MOTR

of 7A JLN PAPAN

Insured: AXA

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

GW 8062P

Yr Regn: 2003 / NOV

Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN CASHMIR

C.C 3153

Colour: GRAY

A/C Insured / Std / NI / NA

Sp Reading: 504540

T/Radio: Insured / Std / NI / NA

Eng No:

C/No: JN1SF4F2320844478

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: 195 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Com DOR

Front

Rear

R/Bal: 7 mm

R/Bal: 5/5 mm

L/Bal: 7 mm

L/Bal: 5/5 mm

D.O.A: 28/05/18

D.O.I: 05/06/18 @ 0228pm

Survey held at: THIAN HON

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT M/S

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time

Action / Instruction

NO GIA Report

7/6/18

Submit PR Report

RECEIVED 11 JUN 2018

Calc/Time File Pass to?

☐

: Prel. Report

or

☐

: Final Report

Calc/Time File Return to?

or

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1 S + RS. \$

Photos

Others

TOTAL:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

100

100

Catherine Chong (LKK Auto)

From: Xin Yi <xinyi@seahong.com.sg>
Sent: Wednesday, 25 July, 2018 12:54 PM
To: 'Catherine Chong (LKK Auto)'
Cc: Chee Kiong; samson@seahong.com.sg
Subject: GW8062P [Our file ref: 18.24698 PD-O]
Attachments: TP LOD.pdf

Dear Catherine,

CLAIMANT : THIAM HENG AUTO (S) PTE LTD
VEHICLE NUMBER : GW 8062P
ALLEGED ACCIDENT DATE : 28 MAY 2018
AXA VEHICLE NUMBER : GBC 5714B

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.

Please let us hear from you on the following: -

- a. If you have conducted post-repair inspection already, please let us have your survey report urgently.
- b. If you have not conducted post-repair inspection, please let us arrange for inspection with the claimant's solicitor and let us have your survey report in due course.

May we hear from you on the above soonest.

Thanks & Best Regards

Heng Xinyi

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

GURDEEP SINGH SEKHON
CHIA KOK SENG
REY FOO JONG HAN
GOH LAM CHUAN
NAVINDER SINGH
P. PADMAN
KWEH SOON HAN
PRADEEP KUMAR GOBIND
HUE JIAPEI
MUNIRAH BINTE MYDIN
JASPREET KAUR PURBA
LIM YUN HENG

S GP
JURIS LLP
Advocates & Solicitors • Commissioners for Oaths
Notary Public

*Celebrating 25 Years of
Professional and Personalised
Legal Service*

MAIN OFFICE:
10 Hoe Chiang Road, #13-03A
Keppel Towers,
Singapore 089315
Tel: 6538 3611
Fax: 6538 3708

Website : www.kscgp.com
(Fax/Email not for service of court documents)
Registered in Singapore with limited liability
as a Limited Liability Partnership
Registration Number T10LL1855L

Your Ref : S8M00IWX MC/RC
Our Ref : GS/18/3888/TH/jp/sc
Date : 6 July 2018

61160598

DID: 3152 0985
Email: jiapei@kscgp.com

AXA Insurance Pte Ltd
8 Shenton Way
#24-01, AXA Tower
Singapore 068811



Dear Sirs,

THIAM HENG AUTO (S) PTE LTD
C/o 10 Hoe Chiang Road #13-03A Keppel Towers Singapore 089315
ACCIDENT INVOLVING GW 8062P AND GBC 5714B ALONG 11 SUNVIEW WAY ON
28.05.18

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 28 May 2018 along 11 Sunview Way, involving our client's vehicle bearing registration number GW 8062P and vehicle bearing registration number **GBC 5714B** which was insured by you at the material time.

We are instructed that the accident was caused by the negligent driving and/or management of the motor vehicle by the driver of **GBC 5714B**. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

(1)	Cost of repairs (inclusive of GST)	- \$ 5,510.50
(2)	Loss of use (8 days x \$180 per day)	- \$ 1,440.00
(3)	Survey fee	- \$ 748.00
(4)	Accident report	- \$ 44.00
(5)	LTA searches/services	- \$ 20.00
(6)	ACRA Business Profile search	- \$ 10.00
(7)	Incidentals	- \$ 100.00
(8)	Costs	- \$ 900.00
(9)	GST on items (7) & (8)	- \$ 70.00
		<u>\$ 8,842.50</u>

BRANCH: PRIVATE PROPERTY CONVEYANCING
400 Lorong 6 Toa Payoh Bldg 3 Lobby 2
#09-18 HDB Hub
Singapore 310490
Tel: 6591 7696 Fax: 6258 1825

BRANCH: HDB CONVEYANCING
400 Lorong 6 Toa Payoh Bldg 3 Lobby 2
#09-18 HDB Hub
Singapore 310490
Tel: 6591 7696 Fax: 6258 1409

BRANCH: SHIPPING, ADMIRALTY & COMMERCIAL
92 Arab Street #03-01 & #03-02
Singapore 199788
Tel: 6634 1346 Fax: 6634 1358

BRANCH: CORPORATE & LITIGATION
81 Robinson Road
#15-02 Robinson Centre
Singapore 068893
Tel: 6817 8795 Fax: 6224 1612

The information contained in this letter / facsimile message is CONFIDENTIAL and may also be LEGALLY PRIVILEGED, intended only for the individual or entity named above. If you are not the intended recipient, you are hereby notified that any use, revelation, dissemination, distribution or copying of this document is strictly prohibited. If you have received this document in error, please notify us immediately by telephone (call the number above) and destroy the original message.

A copy each of the supporting documents are enclosed.

S/NO.	AVAILABLE DOCS	PARTICULARS
<u>Client's Documents</u>		
1.	28.05.18	GIA Statement / Traffic Police report
2.		Witness(es) Statement
3.		Photos taken at the accident site
4.		Video footage / CCTV / CD recording
5.	22.06.18	Repair bill / invoice / Excess Tax invoice
6.		Rental bill / invoice and agreement / receipts
7.		Vehicle Entry Permit receipt / E-day license for off-peak vehicle
8.		Towing fees / receipt (Singapore / Malaysia)
9.		Client sold off vehicle and produce letter from LTA
10.		Spare Part Ordering Form
11.		Levy at Custom / receipts
12.	22.06.18	Survey invoice / receipt and surveyor's report
13.	undated	28 Original / Copies of damage photographs
14.	19.06.13	Enquire PARF / COE Rebate for Registered Vehicle
15.		Enquire Transfer fee
16.	23.10.17	Certificate of Insurance / Motor Cover Note / New Policy Schedule / Registration Card / Grant / Road Tax
17.	28.05.18 & 30.05.2018	Pre-repair Inspection Notices
18.		Estimates & Finalised of repairs cost with agreement by surveyors (exclusive of GST)
19.		Traffic Police investigation results
20.	31.05.18 & 03.07.18	Tax invoices and searches result from General Insurance Association of Singapore (GIA) and Traffic Police search fees
<u>Third Party's Documents</u>		
21.	03.07.18	GIA Statement / Traffic Police report
22.		Admission Note
23.	28.05.18	LTA searches / receipt / tax invoice
24.		Malaysia Vehicles Searches / service
25.	05.07.18	RCB/ ACRA search
26.		Enhanced Individual search / receipt
27.		Property tax search / receipt
Others ()		
28.		

We have on 28 and 30 May 2018 notified you of the accident and a pre-repair inspection of our client's vehicle was carried out by your duly appointed surveyors on 5 and 12 June 2018.

Subject to our client's instructions, please confirm in writing within 7 days hereof if you/your insured wish to conduct a re-inspection.

Please note that you should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insured. In this event, you will be liable for any and all legal costs incurred.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter, which we will then forward to our client and/or the insurers for consideration on a without prejudice basis.

For avoidance of doubt, kindly note that this claim is made without prejudice to our client's driver/passenger's personal injury claims.

Yours faithfully,



(Main Office)

Enc.

Cc client

Cc owner – AAK-Logistic Services

– Ang Geok Hua trading as AAK-Logistic Service

– Ang Ann Kiat trading as AAK-Logistic Service

Cc driver – Mohamad Norisham Bin Hussain

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the CAA Traffic Management Centre established by the Ternal Insurance Association of Singapore (TIA) for archiving and first copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if needed.

ACCIDENT STATEMENT

Date Of Report 28/05/2018 15:15
 Date Of Accident 28/05/2018 13:00
 Exact Location Of Accident 11 SUNVIEW WAY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GW8062P
 Insured/Policyholder
 Name Of Registered Owner THIAM HENG AUTO (S) PTE LTD
 Co Reg No 199905778R
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE 94401614

Vehicle Particulars

Manufacturer NISSAN
 Model CABSTAR
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy NO
 Policy Number 6075219005-02

Cover Note Number

Driver

Name of Driver K RAMINDRAN
 NRIC No S1673240J
 Date Of Birth 14/01/1964
 Occupation INDOOR
 Date Of Driving Pass 28/03/1985
 Driving Experience 33 YEARS AND 2 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-94401614
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 990C JURONG WEST ST 93 #10-777
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER RENTAL
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other motorist or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY-1

Vehicle Registration Number GBC5714B
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (A) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

28/5/18
15.05

IVAC RUMIT BAYAN KUALA

Reporting Centre Personnel's Signature
Name:
NAC/PIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When going up the ramp, I took a left sharp turn. Then the van was going down the ramp very fast on my lane. When I saw him I stop and he hit my vehicle head on the left.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time: 2015/10/15 15.05

IDA BIKKI BATOK (VAC)

Reporting Centre Personnel's Signature
Name:
NIC/TIN No.:



添興車商(新)私人有限公司

THIAM HENG AUTO (S) PTE LTD

GST Reg. No/Co Reg. No.: 199905778 R

1 Bukit Batok Crescent #03-17/18 WCEGA Plaza Singapore 658064

Tel: 6469 5691 Fax: 6468 9985

Website: <http://www.thiamhengmotor.com>

Email: thm5691@singnet.com.sg

22 June 2018

M/s Thiam Heng Auto (S) Pte Ltd

1 Bukit Batok Crescent

#03-17/18 WCEGA Plaza

Singapore 658064

FINAL REPAIR COSTS

GW 8062 P

Nissan Cabstar 3.0D

To cost of repair lump sum as recommend by surveyor.....\$5,150.00 NETT
Add 7% GST \$ 360.50

=====

\$5,510.50 NETT

=====

**SINGAPORE DOLLARS : FIVE THOUSAND FIVE HUNDRED TEN AND
FIFTY CENTS ONLY**





**PRO
PLUS
AUTOMOBILE
ENGINEER**

221 Balestier Road #10-01 Rocco Balestier Singapore 329928
Tel: (65) 6256 6256 Fax: (65) 6352 6802 Email: ethan88@singnet.com.sg / ethan88@gmail.com
Mobile: +65 96730595 / +65 9788 9808 / +65 96999248
Company Registration No: 40155500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

M/s Thiam Heng Auto (S) Pte Ltd
1 Bukit Batok Crescent
#03-17/18 WEGA Plaza
Singapore 658064

INVOICE NO. 25565
OUR REFERENCE : PP/ET/CT.8062.TP.6-18
YOUR REFERENCE: Third Party
DATE : 22 June 2018

VEHICLE REGISTRATION NO : GW 8062 P
VEHICLE MAKE /MODEL : Nissan Cabstar 3.0D

- ☒ TO INSPECTION / APPRAISAL FEES
- ☐ TO AFFIRM AFFIDAVIT ON
- ☐ TO COURT ATTENDANCE ON
- ☐ TO REINSPECTION FEES
- ☒ TO PHOTOGRAPHY
- ☒ TO TRANSPORTATION CHARGES & follow-up reinspection

☐ OTHERS (SPECIFY)

☐

☐ SINGAPORE DOLLARS: SEVEN HUNDRED & FORTY EIGHT ONLY

S\$ 748.00

E.



for PRO PLUS AUTOMOBILE ENGINEERS



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

Our Ref : PP/ET/CT.8062.TP.6-18

22 June 2018

M/s Thiam Heng Auto (S) Pte Ltd
1 Bukit Batok Crescent
#03-17/18 WCEGA Plaza
Singapore 658064

WITHOUT PREJUDICE

Dear Sirs,

**Re : Third Party Claim
Vehicle Registration No. GW 8062 P**

We refer to your instruction to appraise the above-mentioned vehicle on 28 May 2018

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by Messrs Thiam Heng Auto (S) Pte Ltd for \$9,836.40 as per our attached schedule has been rechecked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacements and rectifications accordingly.

Our revised quotation for the repair is \$6,420.73. In our opinion, we consider it to be excessive. We, therefore, recommend a contract lump sum repair cost. This is more economical than to have the vehicle repaired on a parts by/for parts basis. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair this vehicle for \$5,150.50 NETT (inclusive of 7% GST \$360.50) which, in our opinion is fair and reasonable.


The repairer has agreed to undertake the repairs to your requirements at the recommended contract lump sum. However, we have not given authorisation and instruction to the repairer to proceed with the repairs.

The entire repair of the damaged vehicle should be completed within a reasonable period of 6 (six) days, excluding weekends and public holidays.

We are reverting the matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Very truly yours,
PRO PLUS AUTOMOBILE ENGINEERS


Errol Tan
Licensed Appraiser & Automobile Engineer
Encls:

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please contact us immediately by telephone so that we can arrange for its return.



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

VEHICLE INSPECTION REPORT

To: M/s Thiam Heng Auto (S) Pte Ltd
1 Bukit Batok Crescent
#03-17/18 WCEGA Plaza
Singapore 658064

Insured :
Policy Number :
Claim Number :
Our Reference : PP/ET/CT.8062.TP.6-18
Own Damage/Sum Insured :
Excess :
Third Party/Insce Company :
Date : 22 June 2018

Instructed By : Mr Johnny Yeo
Date of Assignment : 28 May 2018
Date of Accident : 28 May 2018
Date of Inspection : 30 May 2018
Name of Workshop : Thiam Heng Auto (S) Pte Ltd
Place of Inspection : 1 Bukit Batok Crescent
#03-17/18 WCEGA Plaza
Singapore 658064

PARTICULARS OF DAMAGED VEHICLE

Registration Number	: GW 8062 P	Odometer Reading	: 904 540 Km
Make/Model	: Nissan Cabstar 3.0D	Radio/Cassette/CD	: Fitted
Year of Manuf/Reg	: 2003	Air Conditioner	: Fitted
Engine Number	: QD32183509	View Mirrors	: Fitted -O/s & n/s
Chassis Frame Number	: JN1SF23Z0851220	Seat Belts	: Fitted -Front only
Class/Type	: Lorry (Metal Body/Goods)	Other Accessories	
Colour	: Metallic Silver	(Specify)	

PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	: Good	Any Apparent Engine	
Paintwork	: Good	Modification/s	
Footbrakes	: Serviceable	Market Value	
Steering	: Serviceable	Scrap Value (PARF/OMV)	
Undercarriage (Front)	: Serviceable		
Undercarriage (Rear)	: Serviceable		

TYRE CONDITIONS ON VEHICLE

		NEAR SIDE	OFF SIDE
Front (Size)	: 195R15	70%	70%
MAKE	: Condor		
Rear (Size)	: 155R12 X 2	70% X 70%	70% X 70%
MAKE	: Yokohama		
SPARE (Size)	: -		
MAKE	: -		
Type of Road Wheels	: Standard		

NOTE: The above percentages represent the estimated remaining life of the tyre threads


* Denotes damaged component/s

PRO PLUS AUTOMOBILE ENGINEERS

IMPACT OF VEHICLE

Direction of Impact (→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the front n/s portion of the vehicle.



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



Damages sustained were the front body panel & its inner reinforcement- dented/buckled/warped over an extensive area, front apron panel- buckled, front bumper assembly, front door pillar n/s- buckled, n/s front door & its inner reinforcement- bent etc.

Note : Follow-up reinspection of damaged components & works-in-progress on 6 June 2018.

Follow-up reinspection of vehicle on 12 June 2018 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.

ESTIMATE

The estimate submitted by **M/s Thiam Heng Auto (S) Pte Ltd** as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts :	6896.40	4260.73	Estimated number of days for repairs: 6
Labour Charges :	1250.00	1000.00	
Paint Work :	1000.00	700.00	
Towing Charges :	60.00	0.00	Number of photographs taken at time of static inspection: 28
Others :	630.00	460.00	
TOTAL	9836.40	5420.73	

Remarks: The repairer has agreed to undertake the repairs at a contract lump sum of \$5,510.50 NETT [inclusive of 7% GST \$360.50], corresponding to supply of parts, labour and spray painting charges. Irvariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.

PRO PLUS AUTOMOBILE ENGINEERS

Continuation Sheet No: 1

APPRAISEMENT SCHEDULE

Registration No: GW 8062 P

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$	Revised Amount \$	
<u>PARTS REPLACEMENT- LIST ITEMS</u>						
1	1 pc	Front body panel	Dented/buckled	1457.40	1457.40	DD ✓
2	1 pc	Front corner panel n/s	Serviceable	402.10	Rejected	
3	1 pc	Front apron panel	Bent/securing clips snapped	346.40	346.40	BT ✓
4	1 pc	Front bumper	Distorted	663.60	663.60	DD ✓
5	1 pc	Front bumper reinforcement	Bent/buckled	682.20	682.20	BT ✓
				3551.70	3149.60	✓
Less : 30% by Pro Plus Automobile Engineers					944.88	✓
				3551.70	2204.72	✓
<u>PARTS REPLACEMENT- NETT ITEMS</u>						
1	1 pc	Front windscreen weatherstrip	Essential	79.90	79.90	NNX
2	1 pc	Front windscreen lower garnish	Distorted/cracked	430.80	430.80	BR ✓
3	1 pc	Front windscreen lower garnish 'NISSAN' decal	Essential	24.10	24.10	NEG ✓
4	1 pc	Front apron panel 'NISSAN' motif	Essential	48.20	48.20	NEG ✓
5	2 pcs	Headlamp assembly @\$258.40	O/s serviceable n/s smashed	516.80	258.40	BR ✓
6	2 pcs	Front combination lamp assembly @\$131.30	O/s intact n/s base cracked	262.60	131.30	BR ✓
7	1 pc	Air conditioner blower assembly	Sandwiched	490.90	To check	NNX
8	1 pc	Air conditioner cooling coil	Sandwiched/jammed	1064.70	1064.70	NNX
9	1 pc	Engine mounting (front)	Split on impact	168.70	Refer special nett items	NNX
				3086.70	2037.40	892.30
Less : 10% by Pro Plus Automobile Engineers					203.74	89.28
				3086.70	1833.66	803.52
Sub -Total				6638.40	4038.38	3008.24

APPRAISEMENT SCHEDULE

Registration No: GW 8062 P

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢
			B/F	6638.40	4038.38 3008.24
		<u>PARTS REPLACEMENT- SPECIAL NETT ITEMS</u>			
1	1 pc	Engine mounting	50% depreciation	0.00	84.35 NN X
2	2 pcs	Terostat @\$120.00	Essential	240.00	120.00 NN X
3	1 pc	Front licence plate	Bent	18.00	18.00 BT ✓
			Sub - Total	6896.40	3026.24 -4260.73

APPRAISEMENT SCHEDULE

Registration No: GW 8062 P

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate	Revised Amount
			B/F	\$	\$
		<u>LABOUR & MISC. CHARGES</u>		6896.40	-4260.73 3026.24
1		To towing charges .		60.00	Rejected
2		To disconnect front wire harness of electrical components to facilitate repairs, reconnect & check functions including to focus headlamps.		40.00	20.00
3		To dismantle/install front windscreen to facilitate repairs.		120.00	80.00
4		To dismantle/check/install air conditioner blower, evaporator/cooling coil, pipes & hoses etc to facilitate repairs & refill with refrigerant [Climatiseur R134a specification].		220.00	180.00 NNX
5		To dismantle/install instrumental panel/glove box compartment to facilitate repairs.		250.00	180.00 150
6		To dismantle/renew the front accident damaged portion. To heat, cut/weld damaged body panels & components including to heat, knock-out, reshape, straighten, orientate, restore & align repairable constituents to symmetrical dimensions.		1250.00	1000.00 600.00 +100
7		To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.))))))		
8		To rustproofing & cavities preservation to the replaced and repaired panels.))))))	1000.00	400.00 700.00 +100
			Grand Total	9836.40	6420.73

Note: The repairer has agreed to undertake the repairs at a contract lump sum of \$5,510.50 NETT [inclusive of 7% GST \$360.50], corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers

ERROLIAN

B.A.Econ (Hons).UK

Dip. Auto Engr. & Motor Trade Management .UK
Automobile Engineer & Licensed Appraiser

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 199905778R
Owner ID Type: Company
Owner Name: THIAM HENG AUTO (S) PTE LTD
Registered Address: 1 BUKIT BATOK CRESCENT #03-17/18 WCEGA PLAZA SINGAPORE 658064
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: GWR062P
Previous Vehicle No.: -
Effective Date of Ownership: 10 Jun 2013
Original Regn Date: 06 Nov 2003
Registration Date: 06 Nov 2003
Year of Manufacture: 2003
Vehicle Type: Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Scheme: -
Vehicle Attachment 1: No Attachment
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: NISSAN
Vehicle Model: CABSTAR
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 1
Chassis No.: JN1SF4F23Z0851220
Engine No.: QD32183609
Engine Capacity/Power Rating: 3153 cc / -
Maximum Power Output: -
Propellant: Diesel
Max Unladen Weight: 1480 kg
Maximum Laden Weight: 3360 kg
Open Market Value: \$21,232.00
PARF Eligibility: No
PARF Eligibility Expiry Date: -
Minimum PARF Benefit: -
No. of Transfers: 2
IU Label No.: 1041875890
COE No.: 2003110105000480H
COE Expiry Date: 30 Sep 2018
COE Category: C - Goods Vehicle & Bus
COE Registration Category: C - Goods Vehicle & Bus
Quota Premium (QP) / Prevailing Quota Premium: \$9,889.00 / -
PQP Paid: \$31,858.00
QP (Regn Cat): \$9,889.00
OPC Cash Rebate

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLE (THIRD PARTY RISKS) RULES, 1960 (MALAYSIA)

Certificate Number : 5075219005-02

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: GW8062P

Chassis Number

: JN1SF4F2320651220

2. Name of Policyholder

: THIAM HENG AUTO (S) PTE LTD

3. Effective Date of Insurance

: 01 Nov 2017

4. Expiry Date of Insurance

: 31 Oct 2018

5. Persons or Classes of Persons entitled to drive

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

(b) Use for the carriage of passengers or goods in connection with the Policyholder's or Hirer's business.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

Limitations rendered Inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)

: N/A

EXCESS (SECTION 2)

: S\$1,500

INSURE WITH COE

: N/A

HIRE PURCHASE COMPANY

: N/A

SUM INSURED

: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: THIAM HENG AUTO (S) PTE LTD (00000613992)

Date of Issue

: 23 Oct 2017 08:32 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

Your Ref : GBC 5714B

Email: accident@kscgp.com

Our Ref : GW 8062P/TH/jp/in

Date : 28 May 2018

AXA Insurance Pte Ltd

By Email

DATE OF ACCIDENT: 28 MAY 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of GW 8062P to notify you of a road traffic accident on 28 May 2018 at about 1.00pm along 11 Sunview Way, involving our client's vehicle bearing registration number GW 8062P and the vehicle bearing registration number **GBC 5714B**, which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

f JP

(Main Office)

Cc client

Your Ref : S8M00IWX MC/RC
Our Ref : GW 8062P/TH/jp/ln
Date : 30 May 2018

Email: accident@ksecgp.com

AXA Insurance Pte. Ltd.

By Email

Dear Sirs,

DATE OF ACCIDENT: 28 MAY 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your letter of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor	Company Name
1.	Errol Tan	Pro Plus Automobile Engineers
2.	Dave Chang	Sincere Appraisal Services
3.	Lee Kok Weng	Lee Automobile Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : **Thiam Heng Motor**
1 Bukit Batok Crescent
#03-17/18, WCEGA Plaza
Singapore 658064

Contact Person/Hp/Tel : **Mr Johnny / Tel: 9855 8158**

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,

f JP


Your Ref : S8M00IWX MC/RC
Our Ref : GW 8062P/TH/jp/in
Date : 30 May 2018

18 3888 TH

Acknowledgement

This is to confirm that I Mohammed Rasul [Full Name of Surveyor] of
LKK Guru [Surveyor's Company] have completed as
follows:-

(a) Pre- Repair Survey/Inspection on 05/06/18 [Date] at 1420 [Time].




office : 67418434

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:


(b) Pre- Repair Survey/Inspection (after dismantling) on 05/06/18 [Date] at 1735 [Time].



Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-Inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].



Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post - Repair Survey/Inspection on 12/06/18 [Date] at 1655 [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-083252

Date of Request: 31/05/2018

Your Ref No: GS/18/3888/TH/JP/JN

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 28/05/2018

Location of Accident: 11 SUNVIEW WAY

Client Vehicle No: GW8062P

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
GBC5714B	No match found.	

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-083252
Date of Request: 31/05/2018

Your Ref No: GS/18/3888/TH/JP/JN

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 28/05/2018
Location of Accident: 11 SUNVIEW WAY
Client Vehicle No: GW8062P

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inc usive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-101352

Date of Request: 03/07/2018

Your Ref No:

GS/18/3883/TH/JP/JN

KSCGP JURIS LLP
10 Hoe Chlang Road #13-03A
Kappel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Time of Accident: 28/05/2018
Place of Accident: 11 SUNVIEW WAY
Client Vehicle No: GW8062P

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
GBC5714B	ALONG SUNVIEW WAY	28/05/2018 15:45

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

* This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048583
Phone: +65 6224 0010 Fax: +65 6224 0090
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-101352

Date of Request: 03/07/2018

Your Ref No: GS/18/3888/TH/JP/JN

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 28/05/2018

Place of Accident: 11 SUNVIEW WAY

Client Vehicle No: GW8062P

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

TAX INVOICE

Our Ref No: GR-18-101357

Date of Request: 03/07/2018

Your Ref No: GS/18/3888/TH/JP/JN

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Date of Accident: 28/05/2018

Vehicle No: GW8062P

Place of Accident: 11 SUNVIEW WAY

Involving Vehicle No: GBC5714B

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBC5714B	11 SUNVIEW WAY	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official Use:

By:

☒ GIRO ☐ Cash ☐ Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/07/2018 10:45
Date Of Accident 28/05/2018 15:45
Exact Location Of Accident ALONG SUNVIEW WAY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBC5714B
Insured/Policyholder
Name Of Registered Owner AAK-LOGISTIC SERVICES
Vehicle Particulars
Manufacturer TOYOTA
Model HIACE MANUAL
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 199903512M
Cover Note Number

Driver

Name of Driver MOHAMAD NORISHAM BIN HUSSAIN
NRIC No S7707534H
Address APT BLK 848 TAMPINES STREET 82 #02-193 SINGAPORE 520848

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
Number of Passengers (Including Driver) 1

Circumstances of Accident

REFERS TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GW8062P


Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the date 28/05/2018 at about 1543 hrs along sunview way. I was driving my vehicle A (GBC 5714 B). At the sunview way, there have many parked container within my lane. I have no choice to choose the right lane. when I slowly to drive, there are vehicle B (GW 8062 P) coming forward. I accidentally collided the front of the vehicle B (GW 8062 P).

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

AAK Logo

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Vehicle & Owner Information (Vehicle No. GBC5714B As At 28 May 2018 / 13:00:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: GW8062P

Current Owner Details

Owner ID Type: Business

Owner ID: 52826735C

Owner Name: AAK-LOGISTIC SERVICES

Registered Address Type: HDB / HUDC

Registered Block/House No.: 153

Registered Street Name: BUKIT BATOK STREET 11

Registered Unit No.: # 03 - 292

Registered Building Name: -

Registered Postal Code: 650153

Current Vehicle Details

Vehicle No.: GBC5714B

Make Description/Model: TOYOTA / HIACE MANUAL

Insurance Company Name: AXA INSURANCE PTE LTD

> Back to OneMotoring

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 28 May 2018 / 15:47:50

Receipt Date/Time : 28 May 2018 / 15:47:50

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180528-001616

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBC5714B				
As at 28 May 2018/13:00:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - GBC5714B Enquiry Fee 20180528154621824593	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				-0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx9236	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF



BizInsights

ACRA
ACCOUNTING AND CORPORATE
REGULATORY AUTHORITY

Business Profile (BPFBIZ)

AAK-LOGISTIC SERVICES

Particulars

Name	: AAK-LOGISTIC SERVICES
Registration Number / UEN	: 52826735C
Date of Registration	: 30-07-1996
Date of Change (Name)	: -
Commencement Date	: 26-07-1996
Date of Last Renewal	: 18-06-2018
Date of Expiry	: 30-07-2019
Constitution	: PARTNERSHIP
Registered Address	: 153 BUKIT BATOK STREET 11 #03-292 SINGAPORE 650153
Date of Change (Address)	: 01-05-2002
Status	: LIVE
Status Effective Date	: 30-07-1996
Principal Activity Code (I)	: 52291
Principal Activity Description (I)	: VALUE ADDED LOGISTICS PROVIDERS
Principal Activity Code (II)	: 49231
Principal Activity Description (II)	: FREIGHT TRANSPORT BY ROAD

Previous Alias(es)

This company has no previous alias

Business Owner(s)

No.	Name	UEN / ID No.	Origin / Nationality	Date of Appointment	Date of Change (Address)
1	ANG GEOK HUA	S1597230J	SINGAPORE CITIZEN	03-10-1996	-
Address					
179 BUKIT BATOK WEST AVENUE 8 #01-211 SINGAPORE 650179					

No.	Name	UEN / ID No.	Origin / Nationality	Date of Appointment	Date of Change (Address)
2	ANG ANN KIAT	S1779251B	SINGAPORE CITIZEN	26-07-1996	18-05-2015
Address					
42 TOH TUCK ROAD #01-05 GOODLUCK GARDEN SINGAPORE 596718					

Authorised Representative(s)

NA

Nominee/Trustee(s)

NA

Withdrawn Personnel

No.	Name	UEN / ID No.	Origin / Nationality	Date of Appointment	Date of Withdrawal
1	LIM KIM HUAT	S0707679Z	SINGAPORE CITIZEN	10-06-1999	12-09-2003
Address				Date of Change (Address)	Position
176 ANG MO KIO AVENUE 4 #07-737 SINGAPORE 560176				06-03-2006	OWNER

No.	Name	UEN / ID No.	Origin / Nationality	Date of Appointment	Date of Withdrawal
2	TAN HENG HOW	S1760571B	SINGAPORE CITIZEN	26-08-1996	09-10-1999
Address				Date of Change (Address)	Position
46 YUNNAN CRESCENT SINGAPORE 638347				28-12-2014	OWNER

No.	Name	UEN / ID No.	Origin / Nationality	Date of Appointment	Date of Withdrawal
3	ANG ANN KIAT	S1779251B	SINGAPORE CITIZEN	26-07-1996	03-01-2016
Address				Date of Change (Address)	Position
42 TOH TUCK ROAD #01-05 GOODLUCK GARDEN SINGAPORE 596718				18-05-2015	MANAGER

*With effect from 03 Jan 2016, under the Business Registration Act, if there is at least one owner of the business residing in Singapore, all active managers will be shown as withdrawn on 03 Jan 2016.

Disclaimer

The information in this report is extracted by BizInsights from a database comprising information filed with Accounting & Corporate Regulatory Authority (ACRA) on or before 03 July 2018 and presented using a business intelligence solution from Elixir Technology Pte Ltd. The statements or ratios published by Elixir Technology are solely statements of opinion and not statements of fact or recommendations to purchase, hold, or sell any securities or make any other investment decisions. Subscribers should not rely on any such statements or ratios in making any investment decision. This report may not be reproduced in whole or in part in any form or manner. The report may contain information compiled from information which ACRA, Elixir Technology and BizInsights do not control and which has not been verified unless indicated in this report. Whilst every endeavor is made to ensure that the information provided is updated and correct, ACRA, BizInsights and Elixir Technology disclaim any liability for any damage or loss that may be caused as a result of any error or omission arising out of or in any way related to the contents of this report. Certain figures in the financial statements may have been adjusted for analytical classification purposes in accordance with established methodology and research processes.

Your Ref: S8M00IWX

Date: 06th Aug 2018

Our Ref: CS3/ASM18009945/R1qbe2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GW 8062P
INSURED VEHICLE: GBC 5714B
ACCIDENT DATE: 28/05/2018

We thank you for your instruction on 25/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GW 8062P from M/s Pro Plus Automobile Engineers.
- b) Singapore Accident Statement of Vehicles GW 8062P and GBC 5714B.
- c) Final Repair Bill of GW 8062P from M/s Thiam Heng Auto (S) Pte Ltd.
- d) Colour damaged vehicle photographs of GW 8062P.

Pre-Repair Inspection Date : 05/06/2018 at M/s Thiam Heng Auto (S) Pte Ltd, 7A Jln Papan.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GW 8062P
Make & Model	: Nissan Cabstar 3.0D
Year of Registration	: 2003
Chassis Number	: JN1SF23Z0851220
Engine Capacity	: 3153 cc

2. We recommend that the repairs of the entire damage require about 6(Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 8062P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BODY PANEL	DENTED	1,457.40	1,457.40
1	FRONT CORNER PANEL N/S	SERVICEABLE	402.10	-
1	FRONT APRON PANEL	BENT	346.40	346.40
1	FRONT BUMPER	DENTED	663.60	663.60
1	FRONT BUMPER REINFORCEMENT	BENT	682.20	682.20
	LESS 30% DISCOUNT		-	-944.88
			3,551.70	2,204.72
<u>NETT ITEMS</u>				
1	FRONT WINDSCREEN WEATHERSTRIP (N)	NOT NECESSARY	79.90	-
1	FRONT WINDSCREEN LOWER GARNISH (N)	BROKEN	430.80	430.80
1	FRONT WINDSCREEN LOWER GARNISH 'NISSAN' DECAL (N)	NECESSARY	24.10	24.10
1	FRONT APRON PANEL 'NISSAN' MOTIF (N)	NECESSARY	48.20	48.20
2	HEADLAMP ASSEMBLY @\$258.40 (N)	O/S BROKEN	516.80	258.40
2	FRONT COMBINATION LAMP ASSEMBLY @\$131.30 (N)	O/S BROKEN	262.60	131.30
1	AIR CONDITIONER BLOWER ASSEMBLY (N)	NOT NECESSARY	490.90	-
1	AIR CONDITIONER COOLING OIL (N)	NOT NECESSARY	1,064.70	-
1	ENGINE MOUNTING (FRONT) (N)	NOT NECESSARY	168.70	-
	LESS 10% DISCOUNT		-	-89.28
			3,086.70	803.52
<u>SPECIAL NETT ITEMS</u>				
1	ENGINE MOUNTING (NPA) (SN)	NOT NECESSARY	-	-
2	TEROSTAT @\$120.00 (SN)	NOT NECESSARY	240.00	-
1	FRONT LICENCE PLATE (SN)	BENT	18.00	18.00
			258.00	18.00
<u>LABOUR</u>				
	TO TOWING CHARGES.	NOT NECESSARY	60.00	-
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO FOCUS HEADLAMPS.		40.00	20.00
	TO DISMANTLE / INSTALL FRONT WINDSCREEN TO FACILITATE REPAIRS.		120.00	80.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE / CHECK / INSTALL AIR CONDITIONER BLOWER, EVAPORATOR / COOLING COIL, PIPES & HOSES ETC TO FACILITATE REPAIRS & REFILL WITH REFRIGERANT [CLIMATISEUR R134a SPECIFICATION].	NOT NECESSARY	220.00	-
	TO DISMANTLE / INSTALL INSTRUMENTAL PANEL / GLOVE BOX COMPARTMENT TO FACILITATE REPAIRS.		250.00	150.00
	TO DISMANTLE / RENEW THE FRONT ACCIDENT DAMAGED PORTION. TO HEAT, CUT / WELD DAMAGED BODY PANELS & COMPONENTS INCLUDING TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE, RESTORE & ALIGN REPAIRABLE CONSTITUENTS TO SYMMETRICAL DIMENSIONS.		1,250.00	700.00
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		-	-
	TO RUSTPROOFING & CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		1,000.00	500.00
			2,940.00	1,450.00
GRAND TOTAL			9,836.40	4,476.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,550.00

Report Ref No. CS3/ASM18009945/R1qbe2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.