

A.G.S. REC. BY:

REF: CS/SMO18013660/Kqd3

n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Melvin Yong

of

SMO

Date/Time:

26/7/18 @ 5:03pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCV 8832L

Insured:

at Workshop m/s:

Comfort Delgro

Tel:

6383 7890

of

205 Braddell Road

Policy No:

Claim No:

CMTD1803158

Sum Insured:

Excess:

waived

Make of Veh:

D.O.A.

22/07/2018

(Client's Record)

27/07/18 @ 10am ow

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5:15pm @ 26/7/18

Person Contacted:

Rohini

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SCV 8832L - NA / LIP 150/3057/h4

DOA: 1/8/15

27/7/18 @

3.11pm revised to Shawn Ngo by email.

01610.20 Carbur

cred \$ 1816.20, 53%

no lump sum

(08/11/13) wef

ASS. REC. BY:

REF: SMO

ASSIGNMENT

From:

Date:

27/07/18

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SCV 8832L

at Workshop m/s

Comfort Delgro

of

205 Braddell Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

waived


(Client's Record)

10 am @ owner waiting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

847k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

☒ if consistent

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SCV 8832L Yr Regn: 06, 10

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. E260 C6i c.c. 1796

Colour:

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

142222

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W002120482-A184555

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

225/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

22/7/18

D.O.I.

27/7/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/7 File pass to Cashier

RECEIVED 14 SEP 2018

Date/Time, File Pass to?



Preli. Report

11/24/9 by [signature]



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

250

Report Format :

DD

Lump Sum / I.B.I. (\$

1610.20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18013660/Kqd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 26-07-2018



Code : SMO

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SCV 8832L
Policy No.	Coverage (\$)	0.00
Claim No. CMTD1803158	Excess (\$)	0.00
Assign From MELVIN YONG	Assign Date	26/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/07/2018	Inspection Date	27/07/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD Blk C, 3rd Floor SINGAPORE 579701.		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1803158

Date: 30th July 2018

Our Ref: CS/SMO18013660/Kqd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Melvin

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SCV 8832L


We thank you for the instruction on 26/07/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/07/2018 at the premises of M/s COMFORTDELGRO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,426.40</u>
Revised Estimate Amount	: S\$ <u>1,674.80</u>
"Check" Items Amount	: S\$ <u>585.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 2 days.

We have NOT authorize repair.

Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Thursday, 26 July 2018 5:03 PM
To: CDGE Braddell Private Cars Crash Repair Operation; assignments@lkkauto.com; admin-d@lkkauto.com
Cc: CDGE Braddell Private Cars Crash Repair Counter; Patrick Chung Chan Kim; Teo, Grace; Henry, Irene James; Ngo, Sau Wei Shawn
Subject: RE: SCV8832L DOA22072018 ARRANGE SURVEY ODWR CLAIM
Attachments: SCV8832L DOA22072018 ESTIMATE.PDF; SCV8832L DOA22072018 SAS.PDF

Our Ref : CMTD1803158

Hi William,

We acknowledged receipt of your claim documents.

Please be informed that Mr Shawn Ngo is the handler of this case.

Please be informed that we have appointed LKK to conduct the survey.

Excess - Waive

Aside to LKK,

Please assist to conduct motor survey on Own Damage basis as repair estimate attached.

Please revert with your preliminary report upon completion of survey to my colleague, Shawn.

Authorise if consistent.

Excess applicable – Waive

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]

Sent: Thursday, 26 July, 2018 2:04 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: CDGE Braddell Private Cars Crash Repair Counter <braddell_cr@sparkcarcare.com>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>; Teo, See Ling <seeling.teo@sompo.com.sg>

Subject: SCV8832L DOA22072018 ARRANGE SURVEY ODWR CLAIM

Dear Sir/Madam,

Kindly arrange for survey at CDGE Braddell.

Please reply with confirmation.

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 30 July 2018 3:11 PM
To: 'Ye, Yong Kang Melvin'; assignments; 'Shawn.Ngo@sompo.com.sg'
Cc: 'Teo, Grace'; 'Henry, Irene James'; SUR
Subject: RE: SCV8832L DOA22072018 ARRANGE SURVEY ODWR CLAIM
Attachments: CSSMO18013660Kqd3.pdf

Dear Shawn,

Enclosed herewith preliminary advice of SCV 8832L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 26 July 2018 5:43 PM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SCV8832L DOA22072018 ARRANGE SURVEY ODWR CLAIM

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Thursday, 26 July 2018 5:03 PM
To: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>; assignments@lkkauto.com; admin-d@lkkauto.com
Cc: CDGE Braddell Private Cars Crash Repair Counter <braddell_cr@sparkcarcare.com>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>
Subject: RE: SCV8832L DOA22072018 ARRANGE SURVEY ODWR CLAIM

Our Ref : CMTD1803158

Hi William,

We acknowledged receipt of your claim documents.

Please be informed that Mr Shawn Ngo is the handler of this case.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4091C
Vehicle Details	
Vehicle No.:	SCV8832L
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jul 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	27186030044285
Chassis No.:	WDD2120482A184555
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$52,976.00
Original Registration Date:	02 Jun 2010
First Registration Date:	02 Jun 2010
Transfer Count:	1
Actual ARF Paid:	\$52,976.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jun 2020
PARF Rebate Amount:	\$29,136.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jun 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$34,600.00
COE Rebate Amount:	\$6,362.00
Total Rebate Amount:	\$35,498.00

The information contained herein is correct as at 30 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/07/2018 17:07
Date Of Accident	22/07/2018 17:00
Exact Location Of Accident	ALONG SERANGOON ROAD JUNCTION ST BARNABAS LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCV8832L
Insured/Policyholder	
Name Of Registered Owner	LIANG WAI YIN
NRIC No	S2554091C
Email Address	KENLWY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96660693
Alternative Phone No	OFFICE-96660693

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E 200CGI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01017328
Cover Note Number	

Driver

Name of Driver	LIANG WAI YIN
NRIC No	S2554091C
Date Of Birth	24/11/1949
Occupation	INDOOR
Date Of Driving Pass	28/04/1983
Driving Experience	35 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96660693
Fax Number	
Contact Number	OFFICE-96660693
Email Address	KENLWY@GMAIL.COM

Address	2 MARTIN PLACE #19-02
Postcode	237988
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THE ACCIDENT HAPPENED FROM THE SERANGOON ROAD TO THE SIDE LANE, ST BARNABAS LANE ON THE LEFT. 2. I SIGNALLLED MY CAR LEFT INTO ST BARNABAS LANE AT APPROX 5 pm. (SUNDAY, 22/7/2018). 3. THE BUS REFUSED TO GIVE WAY AFTER THE BUS STOP AND STARTED MOVING OUT. 4. I STOPPED MY CAR, THE BUS THEN HIT AT THE BACK OF THE CAR. 5. THE DRIVER IN THE CAR BEHIND ME COULD BE A POSSIBLE WITNESS BUT HE DROVE AWAY BEFORE I COULD REACH AND CONTACT HIM. SELF RECORDED STATEMENT BY DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SG5183K
Vehicle Make/Model/Colour	VOLVO/B9TL 9.4L/WHITE
Details Of Properties	
Vehicle Category	BUS
Name of Driver	FONG CHUN FOU
NRIC/Passport Number	G2537832L
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/email packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


X *Hashim*
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

VERIFIED BY
HASHIM S1439236Z

Witnessed by Reporting Centre
Personnel 23/07/18

Sketch Plan



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2554091C



Name

LIANG WAI YIN
@LIANG VUI HYEN

梁偉賢

Race

CHINESE

Date of birth

24-11-1949

Sex

M

S2554091C

Country/Place of birth

MALAYSIA



REPUBLIC OF SINGAPORE DRIVING LICENCE



Source Number S2554091C

Name

LIANG WAI YIN

Birth Date 24 Nov 1949

Issue Date 11 Mar 2003



000279355F

5881746



NRIC No. S2554091C



Date of issue

01-03-2018

Address

2 MARTIN PLACE
#19-02
SINGAPORE 237988

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

28 Apr 1983

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms



Licence No. S2554091C

NP 428A

ACCIDENT STATEMENT (2000 characters)

THE ACCIDENT HAPPENED FROM THE SERANGOON ROAD TO THE SIDE LANE,
ST BARNABAS LANE ON THE LEFT.

2. I SIGNALLED MY CAR LEFT INTO ST BARNABAS LANE AT APPROX 5 pm.
(SUNDAY, 22/7/2018).

3. THE BUS REFUSED TO GIVE WAY AFTER THE BUS STOP AND STARTED
MOVING OUT.

4. I STOPPED MY CAR, THE BUS THEN HIT AT THE BACK OF THE CAR.

5. THE DRIVER IN THE CAR BEHIND ME COULD BE A POSSIBLE WITNESS BUT
HE DROVE AWAY BEFORE I COULD REACH AND CONTACT HIM.

SELF RECORDED STATEMENT BY DRIVER.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

23 July 2018 at 12:35 PM

Date/Time:

23 July 2018 at 12:43 PM



Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No. T/20180723/2121

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/07/2018 16:24	Vide Report No.:	Station Diary No.: 140
--	------------------	---------------------------

Informant's Particulars

Name of Informant: LIANG WAI YIN			Address: 2 MARTIN PLACE #19-02 SINGAPORE 237988	
ID Type / ID No.: NRIC NO / S2554091C			Contact No.: Home/Office:	Mobile: 96660693
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 68	Date of Birth: 24/11/1949	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Management consultant			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 22/07/2018 17:00	Type of Location: Straight Road
Location: Along Road 1 SERANGOON ROAD				
Serangoon Road towards Upper Serangoon Road, turning left into Barnabas Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SCV8832L	Car	MERCEDES BENZ	E 200CGI	Black	Slightly Damaged	0
SG5183K	Bus/Coach/Mi nibus				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SCV8832L	TENET SOMPO INSURANCE PTE. LTD.	D17MTPV0101732 8	02/12/2017	01/12/2018



**SINGAPORE
POLICE FORCE**



T/20180723/2121

2 of 3

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No. T/20180723/2121

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIANG WAI YIN	ID No.	S2554091C
Related Vehicle	SCV8832L (Car)	Contact No.	96660693
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	FONG CHUN FOU	ID No.	G2537832L
Related Vehicle	SG5183K (Bus/Coach/Minibus)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/07/2018 at about 1700hrs, I was driving my vehicle SCV8832L along Serangoon Road towards Upper Serangoon Road on the 3rd lane. I was trying to make a turn towards Barnabas Lane which was just in front of a bus stop. The traffic at that time point in time was very heavy and it was a 4 lane road.

While I drove pass the bus stop, there were 4 bus stationary at the bus stop. Hence I continued driving forward and make a turn. When I make the turn the first bus (SG5183K) then drove forward and hit onto my vehicle rear bumper which cause a bump onto my rear.

I wish to state that no one was injured and no government property was damaged. I am lodging this report for insurance claim purposes.



**SINGAPORE
POLICE FORCE**



T/20180723/2121

3 of 3

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No. T/20180723/2121

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 PEA WEI LIANG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No: 65476151

SN 172

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:

23/07/2018 16:24

Classification Of Case:

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D17MTPV01017328
Insured : LIANG WAI YIN @ LIANG VUI HYEN
Motor Car (Registration No.) : SCV8832L
Cover : Comprehensive - ExcelDrive Prestige Plan
Policy Commencement Date : 02 DECEMBER 2017 00:00
Policy Expiry Date : 01 DECEMBER 2018 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$600 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A.
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting


It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP-27

Sompo Insurance Singapore Pte. Ltd.



Authorised Signatory

Date/Time of Issue : 27 NOVEMBER 2017 10:18

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car.
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- o On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11D01104 & DIRECT-CLIENT (CASH TERM) CI Code: 22A DTDZZL2NJRY0K4AH

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M200903196

PRIVATE CAR POLICY SCHEDULE

Intermediary Code : 11D01104

Policy No. : D17MTPV01017328

This Schedule is issued in accordance and should be read in conjunction with the terms, conditions and exceptions of the
PRIVATE CAR Policy wordings, ref. MTP.27

Insured : LIANG WAI YIN @ LIANG VUI HYEN
Address : 2 MARTIN PLACE
#19-02
MARTIN PLACE RESIDENCES
SINGAPORE 237988

Business/Profession : DIRECTOR

INSURED DETAILS

Date of Birth & Age : 24 NOV 1949 & 68 years old
Driving Experience in : 34 years
Singapore
Identification Type : NRIC(Singaporean)

Marital Status : MARRIED
Gender : Male

Identification No. : S2554091C

Period of Insurance : 02 DECEMBER 2017 00:00 TO 01 DECEMBER 2018 23:59

Persons or Classes of Persons entitled to drive : Refer to Certificate of Insurance

Limitations as to use : Refer to Certificate of Insurance

VEHICLE DETAILS

Vehicle Registration No. : SCV8832L
Chassis No. : WDD2120482A184555
Engine No. : 27186030044285
Vehicle Make & Model : MERCEDES BENZ BENZ
E200 CGI
Engine Capacity/Tonnage : 1796
Type of Body : SALOON
Year of Registration : 2010
Seating Capacity (including driver) : 5
Estimated value of Vehicle : Market value at time of loss
Hire Purchase Owner : NIL

PREMIUM DETAILS

Premium	2,304.69
Less No Claim Discount (50%)	(1,152.35)
Less Offence free Discount (5%)	(57.62)
Add others :	
Less Loyalty Discount(5%)	(54.74)
Total	S\$ 1,039.98
GST	S\$ 72.8
Premium (incl. GST)	S\$ 1,112.78

Coverage : Comprehensive - ExcelDrive Prestige Plan

Excess : \$ 600 - Section I

(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)

Voluntary Excess : N.A

Additional Excess : Named Young and/or Inexperienced Drivers or Elderly Drivers - \$1,500
Un-named Young and/or Inexperienced Drivers or Elderly Drivers - \$3,000
Un-named All Other Drivers - \$500

The terms shall be defined as follows:

'Young Drivers' shall be defined as drivers (including the Insured) who are below 25 years old.

'Inexperienced Drivers' shall be defined as drivers (including the Insured) who have less than 2 years of driving experience in Singapore

'Elderly Drivers' shall be defined as drivers (including the Insured) who are above 70 years old.

Paragraph 2 of Endorsement E in the policy will not apply to insured's spouse provided he/she is 25 years old & above but less than 70 years old &/or has 2 or more years driving experience.

Windscreen Excess : S\$100.00 - Waived if Repair at ExcelDrive Workshop

**Endorsements
Applicable**

Endorsement D - Young and/or Inexperienced or Elderly Drivers Excess
Endorsement E - Excess Clause
Endorsement H - Total Loss
Endorsement M - Inclusion Of Special Perils
Endorsement P6 - Riot And Strike Endorsement
Endorsement V - No Claim Discount Protection

**SOMPO**

Innovation for Wellbeing

ExcelDrive Workshop Recommendation (Somp Insurance)

*Please sign in the box of our recommendation

Ver 02112017

Vehicle No: **SCV8832L****NORTH**

Name of Authorized Workshop	Signature	Name of Authorized Workshop	
Ah Lim Motor Company 10 Ang Mo Kio Industrial Park 2A #01-09 AMK Autopoint Singapore 568047 6483 1244 Contact:		Comfort Delgro Engineering Pte Ltd 7 Sungei Kadut Way Singapore 728791 No: 6553 1111 Contact:	
Ah Lim Motor Company 176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721 Contact: 6456 3637		GoldBell Engineering Pte Ltd 29 Tanjong Penjuru Singapore 609026 Contact No: 6864 0637 / 9755 7336	
Cheng Hoe Motor Pte Ltd 38 Woodlands Industrial Park E1 #05-04/05 Singapore 757700 Contact No: 6755 6142		GoldBell Engineering Pte Ltd 59 Senoko Road Singapore 758123 Contact No: 6864 0637 / 9755 7336	
Cheng Hoe Motor Pte Ltd 10 Ang Mo Kio Autopoint #01-04 Singapore 568047 Contact No: 6755 6142		Lai Huat (Meng Kee Workshop) Pte Ltd 160 Sin Ming Drive #04-01/02/03 Sin Ming Autocity Singapore 575722 Contact No: 6453 8110 / 6453 3757	
Cheng Hoe Motor Pte Ltd Blk 1019 Yishun Industrial Park A #01-374 / 382 Singapore 768761 Contact No: 6765 6142		Motor Image Enterprises Pte Ltd (SUBARU) No 19 Lorong 8 Toa Payoh Singapore 319255 Contact No: 6474 7077 PRESTIGE PLANS ONLY	
City Auto Pte Ltd Blk 8 Sin Ming Industrial Estate #01-58 to #01-66 Sin Ming Road Singapore 575643 Contact No: 6453 1235		Tan Chong Motor Sales Pte Ltd (NISSAN) 17 Lorong 8 Toa Payoh Singapore 319254 Contact No: 6469 4091 / 6466 7711 / 9011 7711 PRESTIGE PLANS ONLY	
Comfort Delgro Engineering Pte Ltd 383 Sin Ming Drive Singapore 4088053 Contact No: 6553 1111		Su Brothers Workshop Blk 5034 Ang Mo Kio Industrial Park 2 #01-341/343 Singapore 569537 Contact No: 6482 4355	
Comfort Delgro Engineering Pte Ltd 205 Braddell Road Singapore 508969 Contact No: 6553 1111		NA	NA

WEST

Name of Authorized Workshop	Signature	Name of Authorized Workshop	
Comfort Delgro Engineering Pte Ltd 45 Pandan Road Singapore 575717 Contact No: 6553 1111		Hitachi Capital Singapore Pte Ltd 8 Fourth Lok Yang Road Singapore 629705 Contact: 6466 3022 9118 5263 (ENG) 91197253 (JAP)	
Ethoz Protect Pte Ltd 30 Bukit Batok Crescent Singapore 658075 Contact No: 6654 7777		Puan Chew Motor Work Pte Ltd Blk K Pandan Loop Estate #01-12 Singapore 128232 Contact No: 9633 8181	
Glass Fix Pte Ltd 1 Bukit Batok Crescent #08-11 WCEGA Plaza Singapore 658065 Contact No: 6278 0887		Sng Ah Tee Motor and Panel Service Blk 3 Pioneer Road North #01-18 Singapore 628457 Contact No: 6268 6183	

**SOMPO**

Innovation for Wellbeing

ExcelDrive Workshop Recommendation (Sompo Insurance)

*Please sign in the box of our recommendation

Ver 02112017

WEST			
Name of Authorized Workshop	Signature	Name of Authorized Workshop	
Tan Chong Industrial Machinery Pte Ltd (For Commercial Vehicle Only) 23 Jalan Buroh Singapore 619479 Contact No: 6662 2293 / 9630 5141		TC AutoClinic Pte Ltd (NISSAN) 1 Sixth Lok Yang Road Singapore 628099 Contact No: 6262 2212 / 9749 9977	
EAST			
Name of Authorized Workshop	Signature	Name of Authorized Workshop	
Autolution Industrial Pte Ltd (NISSAN) 19 Ubi Road 4 Singapore 408623 Contact: 6490 9666 24 hours Towing: 9011 7711		GoldBell Engineering Pte Ltd 48 Changi South Street 1 Singapore 486130 Contact No: 6864 0637 / 9755 7336	
Comfort Delgro Engineering Pte Ltd 320 Ubi Road 3 Singapore 408649 Contact No: 6553 1111		Kan Fook Sing Motor Workshop 61 Defu Lane 12 Singapore 539147 Contact No: 6747 9560	
Comfort Delgro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Contact No: 6553 1111		Kan Fook Sing Motor Workshop Blk 1 Kaki Bukit Avenue 6 #01-13 Singapore 417883 Contact: 6743 5344	
Ethoz Protect Pte Ltd 22 Tampines Street 92 Singapore 528876 Contact No: 6654 7777		SME Motors Pte Ltd 1 Kaki Bukit Avenue 6 Singapore 417883 #02-15/16/17/18 Contact: 6747 6106	
Glass Fix Pte Ltd 52 Ubi Avenue 3 #04-42 Frontier Singapore 408867 Contact No: 6278 0887		Tan Chong Motor Sales Pte Ltd (NISSAN) 913 Bukit Timah Road Singapore 589622 Contact No: 6469 4091 / 6466 7711 / 9011 7711 PRESTIGE PLANS ONLY	
Others	Signature	Others	Signature
1. Own Workshop I have been advised and recommended by the AJAX MARS Reporting Officer to send my vehicle to Sompo Insurance Approved Workshop; I have decided / insisted on sending my vehicle to a non-approved Sompo Insurance workshop stated below to repair / claim the damages to my vehicle against the 3rd party. Workshop Name: Address: Contact No:		3. Private Settlement The 3rd party driver and I have agreed on a private settlement. As advised by AJAX MARS Reporting Officer, a copy of the signed Private Settlement Form will be forwarded to AJAX MARS / Sompo Insurance. 4. Others Please state reason here. NOT DECIDED YET	
2. Not Claiming / Not Repairing The damage is minimal or no visible damage. I have decided not to send my vehicle for repair or claim			
By signing the below I acknowledge the following:			
1) No other workshop was recommended by the AJAX MARS Reporting Officer / AJAX MARS Call Agent apart from the above indicated and initialled.			
2) I understand that the next step would be to send my vehicle to an Sompo Insurance Approved Workshop who will assist and advise me further on the repair and/or claim of my vehicle.			
3) However, should I choose <u>not</u> to use Sompo Insurance approved workshop, Sompo Insurance will <u>not</u> guarantee the quality of any repairs undertaken or any issues arising with regards to the claim.			
Name:	Signature:	Date: 23 July 2018	



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ODWRVehicle No. : SCV8832LMake & Model : MER.E200CGIYear of Manufacture : 2010Chassis No. : WDD2120482A184555Ins Company : SOMPOEngine No. : 27186030044285

Excess : _____

Policy No. : D17MTPV01017328Date of Accident : 22/07/18Time of Accident : 17:00

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : ROHANI

Signature : _____

Contact No

Parts (a) Cost / List Price Items \$2,224.00Plus/Less 10% \$222.40Total of Cost / List \$2,446.40(b) Nett Price Items \$-

Less _____

Total of Nett Item _____

(c) Special Nett Items \$-Total Parts Cost (Appendix A) \$2,446.40Labour (Appendix B) \$980.00Total Repair Cost \$3,426.4063837466 – Patrick
patricktia@sparkcarcare.com

63838115 – WILLIAM

63837656 - Ngo
ngotw@cdge.com.sg

63837730 – Brenda Ng

Ashtar
Penney B4 paint

The above total will be subjected to 7% G.S.T.

Name of Surveyor : KennethCompany : CLKKSurvey conducted on : 27/7/18 at _____Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair 02 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ Nil(e) Signature of surveyor : Sc Date: 27/7/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SCV8832L Case Owner : ROHANI

Make & Model : MER.E200CGI Year Manufacture : 2010

Chassis No : WDD2120482A184555 Engine No : 27186030044285

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : ODWR

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	REAR BUMPER TOP <i>Bu</i>	1	\$750.00			✓
2	REAR BUMPER LOWER <i>R Bumper</i>	1	\$290.00			X
3	REAR BUMPER CHROME MOULDING RH <i>my car</i>	1	\$70.00			✓
4	REAR BUMPER CHROME MOULDING CENTER <i>CM</i>	1	\$92.00			✓
5	REAR BUMPER CHROME MOULDING LH <i>my</i>	1	\$70.00			✓
6	REAR BUMPER REINFORCEMENT <i>R</i>	1	\$390.00			X
7	REAR BUMPER SPONGE	1	NA			
8	REVERSE SENSOR RH <i>Ru</i>	1	\$130.00			X
9	REVERSE SENSOR RH INNER <i>su</i>	1	\$130.00			X
10	REVERSE SENSOR LH <i>su</i>	1	\$130.00			X
11	REVERSE SENSOR LH INNER <i>su</i>	1	\$130.00			X
12	REAR BUMPER SIDE REATINER RH <i>su</i>	1	\$21.00			X
13	REAR BUMPER SIDE REATINER LH <i>su</i>	1	\$21.00			X
14	0	1				
15	0	1				
16	0 <i>plus 10%</i>	1				
17	0	4				
18	0	0				
19	0	1				
20	0	0				
21	0	1				
22	0	1				
23	0	1				
24	0	1				
25	0	1				
26	0	1				
27	0	1				
28	0	0				
29	0	0				
30	0	0				

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

: 2010

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18013660/Kqd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 18-09-2018



Code : SMO

Policy Particulars :- OWN DAMAGE

1.

Insured Veh.		Veh. Inspected	SCV 8832L
Policy No.	D17MTPV01017328	Coverage (\$)	0.00
Claim No.	CMTD1803158	Excess (\$)	0.00
Assign From	MELVIN YONG	Assign Date	26/07/2018

Vehicle Particulars & Condition

2.

Make & Model	MERCEDES E 200 CGI (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2120482A184555	Colour	METALLIC BLACK
Odometer	142222	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre	225/55 R16	MICHELIN	9 mm
L/H Front Tyre	225/55 R16	MICHELIN	9 mm
R/H Rear Tyre	225/55 R16	MICHELIN	7 mm
L/H Rear Tyre	225/55 R16	MICHELIN	7 mm

Description of Damages

4.

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

General Information

5.

Accident Date	22/07/2018	Inspection Date	27/07/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD Bik C, 3rd Floor SINGAPORE 579701.		

Remarks

5a.

- A) THE MARKET VALUE IS S\$47,000.00 (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Estimate Days of Repair

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCV 8832L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER TOP (WCP)	BUCKLED	750.00	750.00
1	REAR BUMPER LOWER (WCP)	TO REPAIR SEE LABOUR	290.00	-
1	REAR BUMPER CHROME MOULDING RH (WCP)	NECESSARY	70.00	70.00
1	REAR BUMPER CHROME MOULDING CENTER (WCP)	CRACKED	92.00	92.00
1	REAR BUMPER CHROME MOULDING LH (WCP)	NECESSARY	70.00	70.00
1	REAR BUMPER REINFORCEMENT (WCP)	TO REPAIR SEE LABOUR	390.00	-
1	REVERSE SENSOR RH (WCP)	SERVICEABLE	130.00	-
1	REVERSE SENSOR RH INNER (WCP)	SERVICEABLE	130.00	-
1	REVERSE SENSOR LH (WCP)	SERVICEABLE	130.00	-
1	REVERSE SENSOR LH INNER (WCP)	SERVICEABLE	130.00	-
1	REAR BUMPER SIDE RETAINER RH (WCP)	SERVICEABLE	21.00	-
1	REAR BUMPER SIDE RETAINER LH (WCP)	SERVICEABLE	21.00	-
	COST PLUS 10%		222.40	98.20
			2,446.40	1,080.20
LABOUR				
	TO PANEL BEAT ON REAR AFFECTED AREAS, REPLACE DAMAGE PARTS AND REALIGNMENT. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER AND REAR BUMPER REINFORCEMENT.		400.00	200.00
	TO PUTTY, RESPRAY ON REAR BUMPER, END PANEL AND AFFECTED AREAS.		500.00	250.00
	CHECK LIGHTING AND WIRING, REPLACE SENSOR.		80.00	80.00
			980.00	530.00
GRAND TOTAL			3,426.40	1,610.20
RECOMMENDED COST OF REPAIRS				1,610.20

Report Ref No. CS/SMO18013660/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.