

Workshops

59 Loyang Drive Singapore 508969
 383 Sin Ming Drive Singapore 575717
 45 Pandan Road Singapore 609286
 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156
 7 Sungei Kadut Way Singapore 728791
 501 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 24.07.2018 10:11 Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305191440

TOMER
 VIS COMFORT TRANSPORTATION PTE LTD
 TOMER NO. 7010045
 PRESS 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 (R) 65508755 (O)
 (P)

REGN NO.: SH 7815C	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 24.07.2018 09:40
YR OF MANU. 21.04.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU087774	COMPLETION DATE/TIME:


EQ INS

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 20.07.2018
 NATURE: 3P 20.07.2018

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 7815C LKE

Vehicle No.: SH 7815C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard