

Surveyor

REF: CS3/ASM18004304/BSB-1

Special Instruction:

ASSIGNMENT (Office)

HS: \$ 6700.00

From (Person): Heag Xinyi of Seah Ong Date/Time: 26/7/2018

Third Parties:

Estimated Cost: Bill to:

Claimant:

Surveyor: Constant Appraiser

Workshop: N-51 Automotive

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJZ 8773U Insured: GBF 4864S
at Workshop m/s N-51 Automotive Tel: 68420051
of 2 Kaki Bukit Ave 2 #01-17

Policy No: Claim No: IS-24715 PD-0

Sum Insured: Excess:

Make of Veh: D.O.A. 05032018
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 6 days)

Date/Time: 01/08/18 Submit Final Fig \$3000/- , 5 days (Red \$3300/- 55%; Original 6 days)

Date/Time	Action/Instruction
	SJZ 8773U - CS3 / ASM18004304 / GJ302
	GBF 4864S - NA / NC18004366 / B
	DCA: 05032018
	DIA: 05032018
	RECEIVED 01 AUG 2018
	L/S
	Repair days 5

Handwritten signature and date: 1/8/18

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by:	Fee Charged:	Date:
Salvage Value : _____		Basic & Add	150
Nett Value : _____		Transport	
		Photos	
		Others	
		Total	150

- 1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
- 3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
- 5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____

12/03/2018
ASS. REC. BY: GD REF: CS3/AXA 1800 1304/G1038 ^{ASM} Special Instruction:

Surveyor: John Cynthia of AXA ASSIGNMENT (Office) Date/Time: 6/3/18 @ 2:35pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS
To Inspect Vehicle No: SJZ 8773U Insured: GBF 4864S
at Workshop m/s: N-51 Automotive Tel: 68420051
of 2 Raki Bk1 Ave 2 # 01-18

Policy No: Claim No: S8M00A37
Sum Insured: Excess:

Make of Vehl: D.O.A. 5/3/18
(Client's Record)

CA / REV / REP. / REV 24 HRS 1wp H.O.D. Endorsement:
Date/Time: 2:46pm @ 6/3/18 Person Contacted: Melody Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	H.O.D.
	<u>SJZ 8773U - NA INCI 1800 4266/13</u>	<u>D.O.A. 5/3/18</u>
	<u>GBF 4864S - NA INCI 1800 4266/13</u>	<u>D.O.A. 5/3/18</u>
	<u>After repair: 9/13/2018.</u>	
	<u>Dismantle: 7/13/2018</u>	

Catherine Chong (LKK Auto)

From: Xin Yi <xinyi@seahong.com.sg>
Sent: Thursday, 26 July, 2018 5:25 PM
To: 'Catherine Chong (LKK Auto)'
Cc: Chee Kiong; samson@seahong.com.sg
Subject: SJZ 8773U [Our file ref: 18.24715 PD-O]
Attachments: TP LOD.pdf

Dear Catherine,

CLAIMANT : THIAN CHAI HOCK
VEHICLE NUMBER : SJZ 8773U
ALLEGED ACCIDENT DATE : 05 MARCH 2018
AXA VEHICLE NUMBER : GBF 4864S

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.

Please let us hear from you on the following: -

- a. If you have conducted post-repair inspection already, please let us have your survey report urgently.
- b. If you have not conducted post-repair inspection, please let us arrange for inspection with the claimant's solicitor and let us have your survey report in due course.

May we hear from you on the above soonest.

Yours faithfully,
Heng Xinyi, on behalf of Mr Tan Chee Kiong
(Secretary to Mr Tan Chee Kiong)
Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

3 0 1 9 4 3 1 0 5 7 - - -

VISION LAW LLC

61163616

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SUI-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINXIAN SELWYN

Unique Entity Number: 200721148H

✓ **Head Office:**

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch:

490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

Branch:

133 New Bridge Road
#10-03 Chinatown Point
Singapore 059413

HEAD OFFICE:

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356602 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH
TEL : (65) 63580703
TEL : (65) 65330668

BRANCH
TEL : (65) 65342811 (Hunting)
TEL : (65) 65330668

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this

Our Ref : AKN-atv-Ins-N63-107053-18
Your Ref : GBF 4864 S

Date: 20 July 2018

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

ZHEN PIN TRADING

Apt Blk 426 Woodlands Street 41
#12-202
Singapore 730426

Dear Sir,

CLAIMANT :

THIAN CHAI HOCK

ACCIDENT INVOLVING SJZ 8773 U & GBF 4864 S ON 05-MAR-2018 ALONG WEST COAST WAY TOWARDS WEST COAST ROAD AT ABOUT 1500HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **05-MAR-2018 ALONG WEST COAST WAY TOWARDS WEST COAST ROAD AT ABOUT 1500HOURS** involving our client's vehicle registration number **SJZ 8773 U** and vehicle registration number **GBF 4864 S** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair	\$7,169.00
02.	Rental fees	\$ 480.00
03.	Survey report fees	\$ 697.00
04.	Towing fees	\$ 100.00
05.	GIA & LTA search / report fees	\$ 41.84
06.	Cost Contribution (at this stage)	\$1,605.00
07.	Disbursements (at this stage)	\$ 50.00

TOTAL \$10,142.84

.../2 to be continued next page

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AKN-atv-Ins-N63-107053-18
Your Ref : GBF 4864 S

Date: 20 July 2018

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

ZHEN PIN TRADING

Apt Blk 426 Woodlands Street 41
#12-202
Singapore 730426

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of SJZ 8773 U;
 - (b) Photographs taken at scene of accident;
 - (c) LTANet Search;
 - (d) Certificate of Insurance;
 - (e) Registration Card;
 - (f) Rental agreement, rental invoice & rental receipt;
 - (g) Final Repair Bill;
 - (h) Surveyor's report & invoice; and
 - (i) 97 coloured photographs depicting the damages to motor vehicle SJZ 8773 U.
- (P.S:- Original photographs will be sent to insurance co. only)

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



(HEAD OFFICE)



Enc.


cc: client: Thian Chai Hock

As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.







TWINCAR RENTAL

Business Registration Number : 53092815M
2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921
Tel : 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :
LIAN CHAI HOCK
BLK 261B SENGKANG EAST WAY
#16-404
SINGAPORE 542261

INVOICE

Invoice No. 13-2121
Date 9/3/2018

Hirer's Car No.	VHA No.	Terms
SJZ8773U	71617	CASH

No. of Day	Description	Per Day	Amount (S\$)
4	Car Rental from the period of 06/03/2018 to 09/03/2018. Vehicle no. SLP4051A	120.00	480.00
Total			\$480.00

TWINCAR RENTAL



Authorized Signature



TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18
Singapore 417921 Tel: 6744 0510 / 6842 0051

VHA No: 71617
SJE 87734 (N51)

ROC NO. 53092815M

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR
 Name: (as in I/C) THIAN CHAI HOCK
 NRIC/PASSPORT No: S 8391581G
 Address (Res): BLK 261B SENGKANG FASTWAY #06-404 S(542261)
 Name & Address of Employer: _____
 Occupation: _____ Driving Exp: _____
 Driving Licence No: S 8391581G D/L Type: Local / International
 Pass Date: 25/08/2006 Date of Birth: 14/06/1983
 Tel: (O) _____ (R) _____ HP 96253578

ADDITIONAL DRIVER'S PARTICULARS
 Name: (as in VC) _____
 NRIC/PASSPORT No: _____
 Address (Res): _____
 Driving Licence No: _____ D/L Type: Local / International
 Pass Date: _____ Date of Birth: _____
 Occupation: _____ Driving Exp: _____

Vehicle No: SLP40512 Replace Veh No: _____
 Mileage Out: _____ Mileage Out: _____
 Make & Model: Toyota Axi Auto / Manual Group: _____
 OUT: Date 6/3/18 Time: 10.50am
 HIRE/PERIOD EXPIRY _____
 NON-WAIVER EXCESS: \$ fuel

CHARGES					
Daily	@ \$	120	per day	4	480 00
Weekly	@ \$		per week		
Monthly	@ \$		per month		
Hours	@ \$		per hour		
Others	@ \$				
CDW	@ \$		per day/month		
PAI	@ \$		per day/month		
Delivery Service					
SUB-TOTAL \$					

VEHICLE CHECKLIST

INDICATE:
 D - DENTS
 S - SCRATCHES
 A - ACCIDENTS

RIGHT FRONT TOP LEFT

PETROL LEVEL

Out	E	1/4	1/2	3/4	F
In	E	1/4	1/2	3/4	F

EXTENSION
 Collection Service _____
 Misc. _____

TOTAL CHARGE \$ 480 00

Rented out by: _____

Hirer's Signature

Addition Driver's Signature _____

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCAR RENTAL in connection with this Agreement is true.

*** IMPORTANT**

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
09/03/2018	17:40hrs				

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

THIAN CHAI HOCK
BLK 261B SENGKANG EAST WAY #06-404
SINGAPORE 542261

Contact : 96253518, 97725417

TAX INVOICE

Date : 12/06/2018
Date in : 06/03/2018
Vehicle Num. : SJZ8773U
Make/Model : VOLKSWAGEN SCIROCCO 1.4L AT TSI 1372Q5-2010
Chassis/Eng# : WVWZZZ13ZBV016392/CAV235700
Accident Date : 05/03/2018
Claim No : CLM14444
Reference : MAR-10/2018
Policy No. : 5079331637-01 (30/06/2018)

LUMP SUM REPAIR BILL	Amount S\$
AS PER SURVEYOR REPORT	6,700.00
REF : <u>CAS/18-05/059</u> DATED 07/03/2018	
BY CONSTANT APPRAISER SERVICES	



E. & O.E.	Sub S\$:	6,700.00
Add GST (7 %)	S\$:	469.00
Total Amount	S\$:	<u>7,169.00</u>

for N-51 AUTOMOTIVE PTE LTD



bizSAFE₃

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 11:56
Date Of Accident	05/03/2018 15:00
Exact Location Of Accident	WEST COAST WAY TWDS WEST COAST RD INFRT CARABELLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ8773U
Insured/Policyholder	
Name Of Registered Owner	THIAN CHAI HOCK
NRIC No	S8381581G
Email Address	SKYTHIAN1983@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97725417
Alternative Phone No	OTHERS-97725417
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	SCIROCCO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5079331637-01
Cover Note Number	
Driver	
Name of Driver	THIAN CHAI HOCK
NRIC No	S8381581G
Date Of Birth	14/06/1983
Occupation	INDOOR
Date Of Driving Pass	25/08/2006
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97725417
Fax Number	
Contact Number	OTHERS-97725417
Email Address	SKYTHIAN1983@GMAIL.COM

Address BLK 261B SENGKANG EAST WAY
#06-404
Postcode 54226
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : JIMMG NG
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG WEST COAST WAY TWDS WEST COAST RD ON A SINGLE LANE, TWO WAY RD. SOMEWHERE INFRT CARABELLE CONDO VEH AHEAD OF ME STOPPED AS TO MAKE TURN INTO THE SAID CONDO. AS SUCH I APPLIED BRAKE AND STOPPED ACCORDINGLY. OUT OF THE SUDDEN VEH B CAME FROM REAR AND COLLIDED DIRECTLY INTO THE REAR PORTION OF MY VEH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF4864S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver HUO ZONG YI
NRIC/Passport Number
Contact Number 94351596
Address
Postcode
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any untruthful representation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

 06/03/18
Reports Centre Personnel's Signature
Name
NRIC No.

Enquire Vehicle & Owner Information (Vehicle No. GBF4864S As At 05 Mar 2018 / 15:00:00)

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: N63-107053-18

Owner ID Type: Business
Owner ID: 53347114A
Owner Name: ZHEN PIN TRADING
Registered Address Type: HDB / HUDC
Registered Block/House No.: 426
Registered Street Name: WOODLANDS STREET 41
Registered Unit No.: # 12 - 202
Registered Building Name: -
Registered Postal Code: 730426

Vehicle Details

Vehicle No.: GBF4864S
Make Description/Model: FIAT / DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Insurance Company Name: AXA INSURANCE PTE LTD



Ng Ching Boon Eric has successfully logged out.
 Your last login date and time was 19 Jul 2018, 18:41:32.
 To return to ONE.MOTORING, please click [here](#)
 For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	GBF4864S	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	19 Jul 2018 / 18:41:54

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

INVOICE

To: Thian Chai Hock
Blk 261B Sengkang East Way
#06-404
Singapore 542261


Date : 31/05/2018

Invoice No : IV18-05059/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SJZ 8773U (Inclusive Of Photographs And Transport Charges) Our reference : CAS/18-05/059	\$697.00
Total	\$697.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: Thian Chai Hock Blk 261B Seng Kang East Way #06-404 Singapore 542261	Date : 31/05/2018 Reference No : CAS/18-05/059																				
<u>General Information</u>																					
Registration No. : SJZ 8773U Accident Date : 05/03/2018																					
<u>Particulars of Damaged Vehicle</u>																					
Colour : White Engine Capacity : 1390 cc Mileage (KM) : 91664 Chassis No. : WVWZZZ13ZBV016392 Registration Date : 01/01/2011	Make & Model : Volkswagen Scirocco 1.4L Pre-Accident Condition : Good Engine No. : CAV235700 Steering : In Order Brake : In Order																				
<u>Tyre Condition</u>																					
	<table><thead><tr><th></th><th>Size</th><th>Make</th><th>Balance</th></tr></thead><tbody><tr><td>R/H Front Tyre</td><td>235/40R18</td><td>PIRELLI</td><td>80%</td></tr><tr><td>L/H Front Tyre</td><td>235/40R18</td><td>PIRELLI</td><td>80%</td></tr><tr><td>R/H Rear Tyre</td><td>235/40R18</td><td>PIRELLI</td><td>80%</td></tr><tr><td>L/H Rear Tyre</td><td>235/40R18</td><td>PIRELLI</td><td>80%</td></tr></tbody></table>		Size	Make	Balance	R/H Front Tyre	235/40R18	PIRELLI	80%	L/H Front Tyre	235/40R18	PIRELLI	80%	R/H Rear Tyre	235/40R18	PIRELLI	80%	L/H Rear Tyre	235/40R18	PIRELLI	80%
	Size	Make	Balance																		
R/H Front Tyre	235/40R18	PIRELLI	80%																		
L/H Front Tyre	235/40R18	PIRELLI	80%																		
R/H Rear Tyre	235/40R18	PIRELLI	80%																		
L/H Rear Tyre	235/40R18	PIRELLI	80%																		
<u>Inspection</u>																					
Repairer : N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2, #01-18 Kaki Bukit Autohub, Singapore 417921																					
<u>Adjustment And Recommendation Cost Of Repair</u>																					
Repairer's Estimate : \$9,290.00 Revised Amount : \$6,700.00 Less Excess : - Nett Total : \$6,700.00																					
<u>Remarks</u>																					
(A) Survey was done on 07/03/2018 (B) Re-survey was done on 07/03/2018 (C) Re-survey after repair was done on 12/03/2018 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.																					

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : SJZ 8773U

Our ref : CAS/18-05/059

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT – LIST ITEMS</u>						
1	1pc	Rear bumper	Dented/Broken	720.00	✓ 720.00	CAT ✓
2	1pc	Rear bumper center retainer	Broken	105.00	✓ 105.00	BR ✓
3	2pcs	Rear bumper number plate lamp L/R @ \$55.00	Cracked	110.00	✓ 110.00	BR ✓
4	2pcs	Rear bumper reflector L/R @ \$55.00	Mounting Broken	110.00	✓ 110.00	BR ✓
5	1pc	Rear bumper reinforcement	Dented/Bent	410.00	410.00	RX
6	2pcs	Rear bumper side retainer L/R @ \$65.00	Broken	130.00	✓ 130.00	BR ✓
7	1pc	Rear bumper tow hook cover	Serviceable	32.00	-	
8	1pc	Rear end panel 'inner'	Dented	790.00	790.00	RX
9	1pc	Rear end panel 'outer'	Dented/Warped	370.00	370.00	RX
10	1pc	Rear end panel inner top garnish	Deformed	270.00	270.00	GRA
11	4pcs	Rear end panel inner top garnish clips @ \$6.50	Necessary	26.00	26.00	NECV
12	1pc	Rear exhaust aluminium heat shield	Repair	175.00	-	
13	1pc	Rear exhaust RH mounting with bracket	Repair	55.00	-	
14	3pcs	Rear exhaust rubber mounting @ \$25.00	Serviceable	75.00	-	
15	1pc	Rear exhaust silencer box	Dented/Bent	780.00	780.00	SVCX
16	1pc	Rear tailgate 'logo' emblem	Necessary	95.00	95.00	} NEC
17	1pc	Rear tailgate 'scirocco' emblem	Necessary	95.00	95.00	
18	1pc	Rear tailgate 'TSI' emblem	Necessary	85.00	85.00	
19	1pc	Rear tailgate weather strip	Distorted	220.00	220.00	SVCX
20	8pcs	Rear taillamp clips @ \$6.50	Necessary	52.00	52.00	NECV
21	2pcs	Rear taillamp L/R @ \$280.00	Cracked/Broken	560.00	560.00	BR ✓
Sub total				5,265.00	4,928.00	
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			@ 10%			
1	1set	Rear bumper clips - set	Necessary	30.00	30.00	NECV
2	1pc	Rear bumper number plate	Dented/Twisted	25.00	25.00	NNX
3	1pc	Rear bumper number plate holder	Twisted	50.00	50.00	NNX
4	1set	Rear bumper reverse sensor - set	Damaged	350.00	✓ 250.00	CAT ✓
5	1set	Rear tailgate inner trim board clips - set	Necessary	30.00	30.00	NNX
Sub total				5,750.00	5,313.00	
					1911.70	

Constant Appraiser Services

Vehicle No : SJZ 8773U

Our ref : CAS/18-05/059

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>LABOUR & MISC. CHARGES</u>					
1		To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor		100.00	80.00 50.00 ✓
2		To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		140.00	100.00 50.00 ✓
3		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident		1,600.00	1,200.00 400.00 ✓
4		To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident		180.00	100.00 +200 ✓
5		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		1,400.00	1,000.00 600.00 ✓
6		To apply anti-rust chemical on repaired and replaced panel		120.00	120.00 60.00 ✓
Grand total				9,290.00	7,913.00-
Recommended cost of lump sum repair (To its pre-accident condition)					6,700.00-

43

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$6,700.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,
Constant Appraiser Services


Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

Repair days 5

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180306-000869

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBF4864S As at 05 Mar 2018/15:00:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - GBF4864S Enquiry Fee 20180306112117432229	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx2392		Credit Card: Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1581G

Vehicle Details

Vehicle No.: SJZ8773U
Vehicle to be Exported: No
Intended De-registration Date: 06 Mar 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour: White
Manufacturing Year: 2010
Engine No.: CAV235700
Chassis No.: WWZZZ13ZBV016392
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$24,811.00
Original Registration Date: 01 Jan 2011
First Registration Date: 01 Jan 2011
Transfer Count: 2
Actual ARF Paid: \$24,811.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 31 Dec 2020
PARF Rebate Amount: \$14,886.00

Intended COE Rebate Details

COE Expiry Date: 31 Dec 2020
COE Category: A - Car (1600cc & below)

COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$10,987.00
Total Rebate Amount:	\$25,873.00

The information contained herein is correct as at 06 Mar 2018

OK



Your Ref: 18.24715 PD-O

Date: 02nd Aug 2018

Our Ref: CS3/ASM18004304/Bsbe2-1

M/s AXA Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJZ 8773U

INSURED VEHICLE: GBF 4864S

ACCIDENT DATE: 05/03/2018

We thank you for your instruction on 26/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJZ 8773U from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles SJZ 8773U.
- c) Final Repair Bill of SJZ 8773U from N-51 Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SJZ 8773U.

Pre-Repair Inspection Date : 06/03/2018 at M/s N-51 Automotive Ptd Ltd, 2 Kaki Bukit Ave 2 #01-17, Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJZ 8773U
Make & Model	: Volkswagen Scirocco 1.4L
Year of Registration	: 2011
Chassis Number	: WVWZZZ13ZBV016392
Engine Capacity	: 1390 cc

2. We recommend that the repairs of the entire damage require about 5(Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 8773U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CUT	720.00	720.00
1	REAR BUMPER CENTER RETAINER	BROKEN	105.00	105.00
2	REAR BUMPER NUMBER PLATE LAMP L/R @\$55.00	BROKEN	110.00	110.00
2	REAR BUMPER REFLECTOR L/R @\$55.00	BROKEN	110.00	110.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	410.00	-
2	REAR BUMPER SIDE RETAINER L/R @\$65.00	BROKEN	130.00	130.00
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	32.00	-
1	REAR END PANEL 'INNER'	TO REPAIR SEE LABOUR	790.00	-
1	REAR END PANEL 'OUTER'	TO REPAIR SEE LABOUR	370.00	-
1	REAR END PANEL INNER TOP GARNISH	CRACKED	270.00	270.00
4	REAR END PANEL INNER TOP GARNISH CLIPS @\$6.50	NECESSARY	26.00	26.00
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	TO REPAIR SEE LABOUR	175.00	-
1	REAR EXHAUST RH MOUNTING WITH BRACKET	TO REPAIR SEE LABOUR	55.00	-
3	REAR EXHAUST RUBBER MOUNTING @\$25.00	SERVICEABLE	75.00	-
1	REAR EXHAUST SILENCER BOX	SERVICEABLE	780.00	-
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	95.00	95.00
1	REAR TAILGATE 'SCIROCCO' EMBLEM	NECESSARY	95.00	95.00
1	REAR TAILGATE 'TSI' EMBLEM	NECESSARY	85.00	85.00
1	REAR TAILGATE WEATHER STRIP	SERVICEABLE	220.00	-
8	REAR TAILLAMP CLIPS @\$6.50	NECESSARY	52.00	52.00
2	REAR TAILLAMP L/R @\$280.00	BROKEN	560.00	560.00
	LESS 10% DISCOUNT		-	-235.80
			5,265.00	2,122.20
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BUMPER NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS3/ASM18004304/Bsbe2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER REVERSE SENSOR (SN)	CUT	350.00	250.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
			485.00	280.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		100.00	50.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR).		140.00	50.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,600.00	600.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	180.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT, INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, REAR END PANEL 'INNER', REAR END PANEL 'OUTER', REAR EXHAUST ALUMINIUM HEAT SHIELD AND REAR EXHAUST RH MOUNTING WITH BRACKET.		1,400.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			3,540.00	1,360.00
	GRAND TOTAL		9,290.00	3,762.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CS3/ASM18004304/Bsbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.