

ASS. REC. BY:

REF:

TP / CS / TP18013675 / Krbnz

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.1B/1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

27/7

File pass to Catherine

SL 8177Z - X

81460.07 Cabins

Red: \$4335.08, 741

RECEIVED 25 OCT 2010

Date/Time, File Pass to?



: Prell. Report

1) typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

TP- Independent

Lump Sum / I.B.I. (\$

1460.07

135

50

50

16

80

331

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/07/2018 14:13
Date Of Accident	04/07/2018 11:50
Exact Location Of Accident	ALONG JLN LINGKARAN DALAM (MALAYSIA)
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT8177Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	N.A.

### Driver

Name of Driver	PANG SIEW CHOON
NRIC No	S7362541F
Date Of Birth	04/11/1973
Occupation	OUTDOOR
Date Of Driving Pass	29/08/2005
Driving Experience	12 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97671590
Fax Number	
Contact Number	
EMail Address	PANGSC6112@YAHOO.COM.SG

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JSF1128 (PRIVATE CAR)
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TRAFIK JOHOR BAHRU
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I was travelling along JLN LINGKARAN DALAM towards CITY, car in front of me stop & I managed to stopped in time suddenly a car JSF1128 just hit onto rear of my SLT8177Z. No injuries involved.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING FROM DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JSF1128
Vehicle Make/Model/Colour	UNKNOWN MODEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAI FOO WAH
NRIC/Passport Number	960201016411
Contact Number	0167737683
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

I was travelling along JLN LINGKARAN DALAM towards CITY, car in front of me stop & I managed to stopped in time suddenly a car JSF1128 just hit onto rear of my SLT8177Z. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

5 July 2018 10:32 am

Date/Time:

5 July 2018 10:32 am

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers or the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand and agree and consent that:  
(a) My insurer, my workplace and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MOHD FADZLY BIN ISMAIL

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan



## POLICE REPORT

POL316



POLIS DIRAJA MALAYSIA  
CAWANGAN TRAFIK  
ISU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN,  
JALAN TEBRAU, 80250 JOHOR BAHRU  
07-2237977

Resit Akuan Penerimaan Repot Polis :

Nama Pengadu : PANG SIEW SHOON  
No Kad Pengenalan / Pasport : K0199671G  
No Repot Polis : TRAFIK JOHOR BAHRU(S)/015877/18  
Tarikh @ Masa Repot Polis : 04/07/2018 @ 12:21  
Pengesahan Penerimaan Repot :

Tandatangan Ketua Pejabat Pertanyaan

Pegawai Penyiasat :

Nama Pegawai Penyiasat : (R123364) S/N SYED AMRAN B. SYED ABAS  
Tempat Tugas : JOHOR , J/BAHRU SELATAN  
No Telefon Pejabat : No Telefon Bimbit : 019-7776066  
Tarikh @ masa Perjumpaan : 4/7/18 1400  
Pengesahan Penerimaan Repot :

SYED AMRAN SYED ABAS (S/N 123364)  
PEN. PEG. PENYIASAT TRAFIK  
BALA POLIS JOHOR (JHS)  
Tandatangan Pegawai Penyiasat

Juru Gambar :

Nama : No Badan : Pangkat :

Tarikh @ Masa Gambar Diambil :

Pengesahan Gambar Diambil :

Tandatangan Juru Gambar

Unit Pembekalan Dokumen Siasatan :

No Telefon Unit Pembekalan Dokumen :

Maklumat Pejabat :

Jenis - Siasatan :  
08:00 Pagi - 01:00 Tengah Hari  
01:00 Pagi - 04:30 Petang  
01:00 Pagi - 04:30 Tengah Hari  
04:30 Petang - 04:30 Petang  
Grafik Umum / Khas : Tutup

Jenis Dokumen Dibekal Kepada Pengadu :

1. Salinan Repot Polis ☒
2. Gambar Kenderaan ☐
3. Rajah Kasar Kemalangan ☒
4. Keputusan Siasatan ☒
5. Lain-lain Dokumen ☐

Tarikh @ Masa Dokumen Diserah :

Pengesahan Kaunter Pembekalan Dokumen :

Tandatangan Pegawai Kaunter Pembekalan Dokumen

Maklumat Pejabat :  
Jenis - Siasatan :  
08:00 Pagi - 01:00 Tengah Hari  
01:00 Pagi - 04:30 Petang  
01:00 Pagi - 04:30 Tengah Hari  
04:30 Petang - 04:30 Petang  
Grafik Umum / Khas : Tutup

07-2237977/00\_pol316.asp?repotid=021499/01587718

5/4/2018





# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLT 8177 Z

Not Notified  
Resurvey Blgiam

Parts	(a) Cost / List Price Items	\$	3,180.10
	Plus/Less 25%	\$	- 795.03
	Total of Cost / List	\$	3,975.13 2385.07
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	4,175.13
Labour		\$	1,620.00
Total		\$	5,795.13 4205.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 26/7/18 at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Date: 26/7/18



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : **SLT 8177 Z**  
Make & Model : **TOYOTA PRIUS**  
Chassis No. : **JTDKB3FU803575251**

Submit By : **Carmen Lim**  
Year Manufacture : **2017**  
Engine No. : \_\_\_\_\_

## Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	1	\$200.00	S.N	X
2	Rear bumper <i>Bur</i>	1	\$497.50		—
3	Rear bumper clip <i>Sn</i>	10	\$40.00		—
4	Rear bumper side retainer LH <i>Sn</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70		X
6	Rear bumper reinforcement <i>R</i>	1	\$398.90		X
7	Rear bumper lower garnish centre <i>Na</i>	1	\$582.60		✓
8	Rear bumper lower garnish LH <i>Sn</i>	1	\$149.70		X
9	Rear bumper lower garnish RH <i>Sn</i>	1	\$149.70		X
10	Tail end panel <i>R</i>	1	\$596.60		X
11	Tail end panel garnish <i>Sn</i>	1	\$151.60		X
12	Tail end panel garnish clip <i>na</i>	10	\$35.00		X
13	Boot weatherstrip <i>Sn</i>	1	\$353.10		X
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ESTEEM PERFORMANCE PL *			Ref : CS/TP18013675/Krbn2	
BLK 5033, #01-259, ANG MO KIO INDUSTRIAL PARK 2, SINGAPORE 569536			Date : 01-11-2018	
ON BEHALF OF GRAB RENTALS PTE LTD			Code : TP053	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	Veh. Inspected	SLT 8177Z	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	26/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU803575251	Colour	METALLIC SILVER
	Odometer	90308	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	4 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	4 mm
	R/H Rear Tyre	195/65 R15	DAVANTI	9 mm
	L/H Rear Tyre	195/65 R15	DAVANTI	9 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/07/2018	Inspection Date	26/07/2018
	Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 8177Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	BUCKLED	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	398.90	-
1	REAR BUMPER LOWER GARNISH CENTRE	DENTED	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	SERVICEABLE	149.70	-
1	REAR BUMPER LOWER GARNISH RH	SERVICEABLE	149.70	-
1	TAIL END PANEL	TO REPAIR SEE LABOUR	596.60	-
1	TAIL END PANEL GARNISH	SERVICEABLE	151.60	-
10	TAIL END PANEL GARNISH CLIP	NOT NECESSARY	35.00	-
1	BOOT WEATHERSTRIP	SERVICEABLE	353.10	-
	LESS 25% DISCOUNT		-795.03	-280.03
			2,385.07	840.07
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
<b><u>LABOUR</u></b>				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER,END PANEL).INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND TAIL END PANEL.		600.00	300.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER,END PANEL).		600.00	250.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
	TO TUFF COAT.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
			1,620.00	620.00
<b>GRAND TOTAL</b>			<b>4,205.07</b>	<b>1,460.07</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,460.07</b>

Report Ref No. CS/TP18013675/Krbn2



Report Ref No. CS/TP18013675/Krbn2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**