

22/03/2002

ASS. REC. BY:

REF

CS3/MSG18013694/ U4J3eb

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MS1G

Date/Time:

26/7/18 @ 4:00pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KC 8943E

Insured:

SLC 7497X

at Workshop m/s

C.H. Motor Vehicle

Tel:

G 748 8888

of

Blk 3019 Ubi Rd 1 # 01-30

Policy No:

2895 8999 DMA

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/07/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

9:36am @ 27/7/18

Person Contacted:

Mrs. Quek

Vehicle

☒ IN

OUT

Date/Time

Action/Instruction

(4)

Estimate

8KC 8943E - x

SLC 7497X - CC3/AIG 16011011/Kvbma

DOA: 3/6/2016

30/7/18

Discontinued.

(08/11/13) Wef

ASS REC BY: MORIS

REF:

MSIA/

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC 8943Eat Workshop m/s C.M. Molen

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 26

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

87241

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKC 8943E Yr Regn: APR / 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /Make: Volkswagen New Golf cc 1390Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 15.2664 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVWZZZ1K2AW303730

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 22/7/18 D.O.I. 27/7/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ree

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

no scatter prs LTA 171031 yrs. Ind. Rep 9k. next 8875-7k.8/7/18 submit MLC report

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 120

Transportation: \_\_\_\_\_

S ~ RS ~ SI

Photos 10

Others \_\_\_\_\_

TOTAL

130

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Est. Hgt	Adj. Submitted	Ins. Auth'd	Status
Main	24 Jul 2018	26 Jul 2018 16:00 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All				
<b>CLAIM SUBFOLDER DETAILS</b>								
<b>[Created by insurer]</b>								
Insured:	<b>ZHU XIANGFENG</b> , ID: S8474414Z							
Main Claimant:	<b>CHEO LYE HOCK</b> , ID: S77087241							
Vehicle Reg. No.:	<b>SKC8943E</b>	Date of Loss:	22/07/2018 00:00 - :59 [98 Months and 29 Days From LTA Reg Date (Man Yr)]					
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	28958999DMA Coverage: 25/05/2018 - 24/05/2019					
Vehicle Reg. No. (Insured):	<b>SLC7497X</b>	Policy No. (Claimant):						
		Excess:						
Repairer:	<b>C.h.motor Vehicle Repair Training (HQ)</b> BLK 3019A UBI ROAD 1 #01-30, 408713 Ubi - Tel:							
Handling Insurer:	<b>MS1G Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]							
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 27/07/2018]</b>							
Adj. Asg. Remarks:	Liability is down, TP disagree with SJE. To proceed to appoint LKK. Contact Person: Joe / 6841 8841 / 6748 8888							
<b>ASSOCIATED MAIL RECEIVED</b>								
<a href="#">View All</a> <a href="#">Compose Case Mail</a>								
There are no mail for this case.								
<b>ALL ASSOCIATED TASKS</b>								
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>								
Due Date	Priority	Task Name	Next	Handler	Assigned By	Completed On	Created On	Done?
No results.								



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18013694/Usd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-07-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 7497X	Veh. Inspected	SKC 8943E
Policy No.	28958999DMA	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	27/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	22/07/2018	Inspection Date	27/07/2018
Survey held at	C H MOTOR VEHICLE REPAIR TRAINING BLK 3019A UBI ROAD 1 #01-30 SINGAPORE 408713		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKC8943E		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	VOLKSWAGEN		
Vehicle Model :	NEW GOLF 1.4 AT 5K13G5		
Chassis No. :	WVWZZZ1KZAW303730		
Propellant :	Petrol		
Engine No. :	CAX488388		
Engine Capacity :	1390 cc		
Maximum Power Output :	90.0 kW ( 120 bhp)		
Maximum Laden Weight :	1850 kg		
Unladen Weight :	1241 kg		
Year Of Manufacture :	2010		
Original Registration Date :	23 Apr 2010		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$28,389.00		
COE Expiry Date :	22 Apr 2020		
Road Tax Expiry Date :	22 Oct 2018		
PARF Eligibility Expiry Date :	22 Apr 2020		
Inspection Due Date :	22 Apr 2019		
Intended Transfer Date :	30 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 22 Oct 2018. You may renew the road tax from 23 Jul 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 22 Oct 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 23 Oct 2018 to 22 Apr 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	310.00	-	310.00
Total Amount Payable :			335.00
Amount Payable (From 23 Oct 2018 to 22 Oct 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	620.00	-	620.00
Total Amount Payable :			645.00

You may print this page for reference.

OK      Print

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8724I
Vehicle Details	
Vehicle No.:	SKC8943E
Vehicle to be Exported:	No
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	NEW GOLF 1.4 AT 5K13G5
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	CAX488388
Chassis No.:	WVWZZZ1KZAW303730
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,266.00
Original Registration Date:	23 Apr 2010
First Registration Date:	23 Apr 2010
Transfer Count:	1
Actual ARF Paid:	\$22,266.00 <i>/// } }</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Apr 2020
PARF Rebate Amount:	\$12,246.00
Intended COE Rebate Details	
COE Expiry Date:	22 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$28,389.00
COE Rebate Amount:	\$4,857.00
<b>Total Rebate Amount:</b>	<b>\$17,103.00</b>

The information contained herein is correct as at 06 Aug 2018

OK



**CELEBRATE NATIONAL DAY WITH  
OUR SG53 PROMOTION**

**BOOK A TEST DRIVE >**

### Post an Advertisement

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**

[Post an Ad](#)

[Advertiser Login](#)

[Ways of Selling](#)

**2010 Audi A4 Only \$40k! Cheapest In The Market!**



1 Owner With Low Mileage!  
Clocked! Hurry Contact Us  
Before It's Gone Again!  
AutoPrestige Gallery StarAd

Free VICO  
Free groom  
In-house w  
Member of  
100% depo



Browse by Category ▼

« Back ( 1 2 ) Next »

Sort b

**24 vehicles**

Volkswagen Golf

Advanc

Make Model Price Depreciation Reg Date Eng Cap Mil

#### Search Selection

Volkswagen Golf

Any

Any

2010

Any



**Volkswagen Golf 1.4A TSI**

**\$29,800**

**\$8,220 /yr**

**12-Nov-2010**

**1,390 cc**

**11**

15% Down Payment Available! Flexible Loan And Insurance Packages Available! High Trade In Welcome! Offer 2.78% B  
Loan At 3.38% For This Month Only! STA Evaluation Welcome!...

Posted: 05-Aug-2018 Tags: 2010 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



**Volkswagen Golf Sport 1.4A  
TSI**

**\$28,300**

**\$8,500 /yr**

**13-Aug-2010**

**1,390 cc**

**11**

10% Down Payment From Only \$813 Monthly! High Trade In/Flexible Loan Options Available! Hottest Selling German Ha  
Efficient! Smooth Changing Of The DSG Is One Of A Kind! Sporty G...

Cars 88 Pte Ltd

Posted: 04-Aug-2018 Tags: 2010 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



**Volkswagen Golf 1.4A TSI**

**\$22,800**

**\$7,990 /yr**

**01-Feb-2010**

**1,390 cc**

**52**

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto & Marine

Posted: 02-Aug-2018 Tags: 2010 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



**Volkswagen Golf GTI 3DR**

**\$36,500**

**\$12,440 /yr**

**06-Apr-2010**

**1,984 cc**

**13**

Sport White On Nice Interior, In House Flexible Loan Available, 100% Accident Free, Price Negotiable!

Sng Auto Trading

Posted: 02-Aug-2018 Tags: 2010 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen

[Car Buying](#)

[Car Selling](#)

[Car Ownership](#)

[Car Aftermarket](#)

[On The Move](#)

[Lifestyle](#)

► Buy  
► Lat

[Compare](#)



Volkswagen Golf

Price Range ▼

Depreciation ▼

2010 ▼

Vehicle Type ▼

[Home](#) » [Used Cars](#) » [Prem Roy Motoring](#) » Volkswagen Golf 1.4A TSI

## Resources

[Car Buying](#)[Car Selling](#)[Car Ownership](#)[Car Aftermarket](#)[On The Move](#)[Lifestyle](#)

## Volkswagen Golf 1.4A TSI

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

RENTCARLEASE PTE LTD in affiliation with

**PRM**  
Prem Roy Motoring Pte Ltd  
DRIVE YOUR DREAM

COMPLETE CAR TR

[Add to Shortlist](#)[Add to Compare](#)[Add a Note](#)[Report Error](#)[More Actions](#)

## Car Details

<b>Price</b>	<b>\$28,800</b>	?
<b>Depreciation</b>	\$9,370 /yr <a href="#">View models with similar depreciation</a>	?
<b>Reg Date</b>	15-Apr-2010 (1yr 8mths 8days COE left)	?
<b>Manufactured</b>	2010	?
<b>Mileage</b>	152,000 km (18.3k /yr)	?
<b>Transmission</b>	Auto	?
<b>Engine Cap</b>	1,390 cc	?
<b>Road Tax</b>	\$620 /yr	?
<b>Power</b>	118.0 kW (158 bhp) <a href="#">View specs of the Volkswagen Golf GTI (2003-2009)</a>	?
<b>Curb Weight</b>	1,286 kg	?
<b>Features</b>	Smooth Powerful And Fuel Efficient 1.4L Turbocharged Engine, 7 Speed DSG Auto Transmission, Paddle Shifters, Reverse Sensors.	
<b>Accessories</b>	Leather Seats, Rear Aircon, Factory MP3 Audio System With Multi Function Steering Control, Fog Lamps, Retractable Side Mirrors.	
<b>Description</b>	Well Taken Care By 2nd Owner. 1 Year Old Rims And Tyres. 3 Sets Bridgestone RE003 And 1 Pirelli Cinturato Manufactured 2017. Gasket, Oil Seal, Seal Ring, Oil	



Location Ma

## Car Tyres

[Compare](#)



### ...CLAIM SUBFOLDER...(Pending for Survey Report)




































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jul 2018		26 Jul 2018 16:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  














































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>ZHU XIANGFENG</b> , ID: S8474414Z								
Main Claimant:	<b>CHEO LYE HOCK</b> , ID: S7708724I								
Vehicle Reg. No.:	<b>SKC8943E</b>	Date of Loss:	22/07/2018 18:00 - :59 [98 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 565756</b>	Policy/Cover Note No.:	P28958999DMA (Comprehensive) Coverage: 25/05/2018 - 24/05/2019						
Vehicle Reg. No. (Insured):	<b>SLC7497X</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>C.h.motor Vehicle Repair Training (HQ)</b> BLK 3019A UBI ROAD 1 #01-30, 408713 Ubi - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Imm.Advice due 27/07/2018]								
Adj Asg. Remarks:	Liability is down, TP disagree with SJE. To proceed to appoint LKK. Contact Person: Joe / 6841 8841 / 6748 8888								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKC8943E (565756)  
[SLC7497X]  
TP  
CHEO LYE HOCK  
Jul 22 2018 6:00PM  
[ZHU XIANGFENG]  
C.h.motor Vehicle Repair Training

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	27/07/18 14:30	Chassis Number		 Load JPG	<input checked="" type="checkbox"/>					
2	27/07/18 14:30	Odometer Reading		 Load JPG	<input checked="" type="checkbox"/>					
3	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
4	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
5	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
6	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
7	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
8	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
9	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
10	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
11	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
12	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
13	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
14	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
15	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
16	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
17	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
18	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
19	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
20	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
21	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
22	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
23	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
24	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
25	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
26	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
27	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
28	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
29	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
30	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
31	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
32	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
33	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
34	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
35	27/07/18 14:30	General View		 Load JPG	<input checked="" type="checkbox"/>					
36	27/07/18 14:30	General View		Load JPG	<input checked="" type="checkbox"/>					
37	27/07/18 14:30	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
53	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
54	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
55	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
56	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
57	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
58	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
59	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
60	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
61	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
62	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
63	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
64	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
65	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
66	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
67	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
68	27/07/18 14:30	General View	 Load JPG	<input checked="" type="checkbox"/>
69	27/07/18 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
70	27/07/18 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
71	27/07/18 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
72	27/07/18 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
73	27/07/18 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
74	27/07/18 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
75	27/07/18 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
76	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	30/07/18 20:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	30/07/18 20:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	30/07/18 20:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	30/07/18 20:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	30/07/18 20:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	30/07/18 20:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/07/18 15:24	PRI - Vision Law	 Load PDF	
2	24/07/18 15:25	Email to TP our SJE list	 Load PDF	
3	25/07/18 10:48	TP disagree with our SJE list. We proceed to appoint LKK	 Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

^

v

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18013694/UZ4D3E2

Date: 08/08/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: P28958999DMA

Claimant Vehicle No : SKC8943E

Insured Vehicle No : SLC7497X

Date of Loss: 22/07/2018

Nature of Claim: TP

Claim No: 565756

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKC8943E

Make &amp; Model: VOLKSWAGEN NEW GOLF 5K13G5, 1.4 (A)

Engine No: CAX488388

Reg. Date: 23/04/2010 (Man. Year: 2010)

Chassis No: WWWZZZ1KZAW303730

Colour: Grey

Odometer: 152664 km

Engine Capacity: 1390 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 26/07/2018

Date Inspected: 27/07/2018 Inspected At:

C.h.motor Vehicle Repair Training (HQ)  
BLK 3019A UBI ROAD 1 #01-30  
Singapore 408713

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$7,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Aug 2018)
<b>Parts:</b> 144	VOLKSWAGEN NEW GOLF 5K13G5 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKC8943E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >