

12/03/2003

ASS. REC. BY:

REF: CS3/EGJ18013702/T1240362 Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGJ

Date/Time:

27/7/18 @ 9.20am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 3089E

Insured:

YN 5405M

at Workshop m/s

Unity Contractors

Tel:

83158040

of

No. 9B Jalan Papar

Policy No:

Claim No:

DSMCH1801176

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/06/2018

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time: 11:20am @ 27/7/18

Person Contacted:

Mr. Soleiman

Vehicle

IN

OUT

Date/Time

Action/Instruction

(4) Estimate

YN 3089E - X

YN 5405M - CS / AWA / SO2 / SAS / Kg. bc2

(08/11/13) • wef

ASS. REC. BY:

REF:

ERGO

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OP / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 18 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____



Veh No: YN3089E Yr Regn: Aug / 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Canter c.c 2977

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FE83BEA20870

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7.00 R16

R: 185 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front Rear

R/Bal. 4 mm R/Bal. 6/6 mm

L/Bal. 4 mm L/Bal. 6/6 mm

D.O.A. D.O.I. 27/7/18 01545

Survey held at Unity 98 Jalan Papiin

Des. of Damages: F/Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	83158040
	NO GIA
	Estimated repair range \$15,000 - \$18,000
1/8	Submit PRS report.
	Range + No. of days
	1/8/18
	RECEIVED 03 AUG 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format : PRE

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: 18

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: 50

Transportation: _____

_____ S + RS, SI

Photos

Others

TOTAL

50

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 27 July 2018 9:21 AM
To: admin-d@lkkauto.com
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : YN5405M / TP : YN3089E & GBG6122G/LKK / DOA : 22/07/2018 (DSMCH1801176)
Attachments: YN5405M - SAS.pdf; 1ST VEH XD2023R - SAS.pdf; 2ND VEH YN3089E - SAS.pdf; 3RD VEH GBG6122G - SAS.pdf; RE: Yr Ref No. YN 5405M (Our Ref. BSA 9461) . YN 3089E (25.0 KB); RE: Yr Ref No. YN 5405M (Our Ref. BSA 9462) . GBG 6122G (25.0 KB)

Dear Catherine & Nivitha,

We have rejected to their PRS list, please assist to conduct these survey (**2 third parties vehicles**) from **BSA LAW CHAMBERS LLC**,

ADDRESS : **NO 9B JALAN PAPAN**
SINGAPORE 619414

PERSON TO CONTACT : WILL UPDATE ONCE RECEIPT OF CONTACT NO. FROM LAWYER

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via Survey.Report@ergo.com.sg.

Attached are insured and Third Party's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel. : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 27 July 2018 10:31 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: RE: OI : YN5405M / TP : YN3089E & GBG6122G/LKK / DOA : 22/07/2018 (DSMCH1801176)

Dear Ladies,

Contact details for TP workshop – Unity Contractors Pte Ltd is Mr Soleiman 83158040

Rgds
Pei Li

From: Survey Report (ERGO Insurance Pte. Ltd.)
Sent: Friday, 27 July, 2018 9:21 AM
To: admin-d@lkkauto.com
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : YN5405M / TP : YN3089E & GBG6122G/LKK / DOA : 22/07/2018 (DSMCH1801176)

Dear Catherine & Nivitha,

We have rejected to their PRS list, please assist to conduct these survey (**2 third parties vehicles**) from **BSA LAW CHAMBERS LLC**,

ADDRESS : **NO 9B JALAN PAPAN**
SINGAPORE 619414

PERSON TO CONTACT : WILL UPDATE ONCE RECEIPT OF CONTACT NO. FROM LAWYER

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via Survey.Report@ergo.com.sg.

Attached are insured and Third Party's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax: +65 6829 9247

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	YN3089E		
Vehicle Type :	B30 - Goods (Open) Lorry (Wooden Body)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	FE83BEOSRDEA		
Chassis No. :	FE83BEA20870		
Propellant :	Diesel		
Engine No. :	4M42A90838		
Engine Capacity :	2977 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	5000 kg		
Unladen Weight :	2240 kg		
Year Of Manufacture :	2012		
Original Registration Date :	01 Aug 2012		
Lifespan Expiry Date :	31 Jul 2032		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$55,805.00		
COE Expiry Date :	31 Jul 2022		
Road Tax Expiry Date :	31 Jul 2018		
Inspection Due Date :	31 Jul 2018		
Intended Transfer Date :	30 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 31 Jul 2018. You may renew the road tax from 01 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 31 Jul 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 01 Aug 2018 to 31 Jan 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	82.00	-	82.00
Total Amount Payable :			107.00
Amount Payable (From 01 Aug 2018 to 31 Jul 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0601G
Vehicle Details	
Vehicle No.:	YN3089E
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jul 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FE83BEOSRDEA
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	4M42A90838
Chassis No.:	FE83BEA20870
Maximum Power Output:	-
Open Market Value:	\$35,164.00
Original Registration Date:	01 Aug 2012
First Registration Date:	01 Aug 2012
Transfer Count:	1
Actual ARF Paid:	\$1,759.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,805.00
COE Rebate Amount:	\$22,337.00
Total Rebate Amount:	\$22,337.00

The information contained herein is correct as at 30 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2018 17:47
Date Of Accident	20/06/2018 18:45
Exact Location Of Accident	TANAH MERAH COAST ROAD LAMP POST 506A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN3089E
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	POH LI HENG BUILDING CONSTRUCTION PTE LTD
Co Reg No	199700601G
Email Address	ACCTUNITY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84954599
Alternative Phone No	OFFICE-67607420

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FE83BEOSRDEA-3.0 D B31 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2018-V0103455-VCV
Cover Note Number	

Driver

Name of Driver	SANDHU BALKAR SINGH
Passport No/FIN	G8314456X
Date Of Birth	16/03/1989
Occupation	OUTDOOR
Date Of Driving Pass	08/06/2015
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84954599
Fax Number	
Contact Number	
EEmail Address	ACCTUNITY@GMAIL.COM

Address	NO 10 BUKIT BATOK CRESCENT #04-07 THE SPIRE
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 391 NEW BRIDGE ROAD POLICE CANTONMENT COMPLEX BLOCK A , POSTCODE: 088762 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2369999 - FAX NO: 62268438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer to statement & police report


Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF INJURED PERSON 1

Name	KULBIR SINGH
Approximate Age	
Injuries Sustain	DEAD
Injured person in which vehicle?	
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle 1 broke down at 6:25 pm on 20th June 2018 and came to a stationary position at Tanah Merah Coast Road Lamp post 506A Leftmost lane beside the designated cycling lane. Drivers of Vehicle 1 and 2 went to vehicle 1 to give assistance for repairs. Vehicle 2 was park stationary at the distance of 2 meter from Vehicle 1, Vehicle 3 was park stationary at the distance of 1.5 meters from vehicle-2. Behind Vehicle 3, we had placed 3 safety cones at the distance of 4 meters from Vehicle-3 and breakdown sign was placed after the traffic safety cones at another 2 meters distance apart for further safety measures. Our Company driver, Mr Kulbir Singh (A), who was driving XD 7413R, passed by the vehicle breakdown location.

Report As per Attach police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/06/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 24/06/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180621/2119

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

1 of 3

Report No. T/20180621/2119

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/06/2018 15:18		Vide Report No.:		Station Diary No.: 105	
Informant's Particulars					
Name of Informant: FOO MING CHIE			Address: APT BLK 183 JELEBU ROAD #15-46 SINGAPORE 670183		
ID Type / ID No.: NRIC NO / S7900979B			Contact No.: Home/Office: Mobile: 91057079		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 22/01/1979	Type of Informant: Informant		
Race: Chinese			Language: English		Institution / School Name:
Occupation: OPERATION MANAGER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Fatal Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 20/06/2018 18:45	Type of Location: Straight Road
Location: Along Road 1 TANAH MERAH COAST ROAD				
Lamp Post Number: 506				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Brief Details.

I am the operation manager of Unity Contractors Pte Ltd.

On 20 June 2018 at about 6.25pm, a vehicle (registration plate number: XD2023R) came to a stationary position at Tanah Merah Coast Road Lamp Post 506A on the extreme left most lane beside the designated cycling lane. The driver of vehicle XD2023R is namely Shah Alam, Fin: G8388162W, contact number: 98200760, address: 500 Old Chua Chu Kang Road, 698924. The driver for vehicle registration plate number YN3089E, namely Sandhu Balkar Singh, Fin: G8314456X, contact number: 83812569, address: 500 Old Chua Chu Kang Road, S698924 and the driver of vehicle registration plate number GBG6122G namely Maninder Singh, Fin: G6599801M, contact number: 81959208, address: 500 Old Chua Chu Kang Road, S698924 drove down to the scene to give assistance for vehicle XD2023R for repairs. All the above mentioned vehicles and drivers belongs to my company namely Unity Contractors Pte Ltd.



**SINGAPORE
POLICE FORCE**



T/20180621/2119

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

2 of 3

Report No. T/20180621/2119

CONTINUATION OF REPORT

Vehicle YN3089E was park stationary at the distance of 2 meters from vehicle XD2023R. Vehicle GBG6122G was park stationary at the distance of 1.5meters from vehicle YN3089E.

Behind vehicle GBG6122G, we had placed 3 safety cones at the distance of 4 meters from vehicle GBG6122G and breakdown sign was placed after the traffic safety cones at another 2 meters distance apart for further safety measures.

Our company driver namely Kulbir Singh, FIN: G8424596N, Nationality Indian, who was driving another vehicle XD7413R, passed by the vehicle breakdown location. He parked his lorry in front of all vehicles and came to vehicle XD2023R to offer help. He was standing between vehicle XD2023R and YN3089E.

Suddenly, at about 6.45pm, a vehicle (registration plate number: YN5405M) came rushing at very high speed and crashed into vehicle GBG6122G from the rear. The impact was tremendous and caused vehicle GBG6122G which was parked stationary with handbrakes applied to hit vehicle YN3089E which also had the handbrakes applied. Vehicle YN3089E then hit vehicle XD2023R and Kulbir Singh who was standing inbetween of vehicle XD2023R and YN3089E. Kulbir Singh was badly injured on his head and died on the spot.

After the incident, the mobile phone of vehicle YN5405M flew out of the windscreen and dropped near vehicle YN3089E which is way in front. The driver of vehicle YN5405M immediately ask the driver of vehicle YN3089E to help him pick up his mobile phone as he mentioned he wanted to call his family. The driver of vehicle YN3089E then picked up and passed the mobile phone and returned to him.

I wished to state that police officers and ambulance attended to the scene. Kulbir Singh was pronounced dead on the spot by the paramedics. The driver of XD2023R namely Shah Alam and the driver of YN5405M were conveyed to Changi General Hospital. The IO in charge of the case was Mohammad Sharil Bin Abdullah from Traffic Police and I was told to lodge a Traffic Police Accident report.



**SINGAPORE
POLICE FORCE**



T/20180621/2119

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

3 of 3

Report No. T/20180621/2119

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

Sgt 2 ELSON SIM JUN SHENG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / FAIT /

SI MOHAMMAD SHAHRIL BIN ABDULLAH

Contact No.: 65476083

Signature Of Informant:

Date/Time:



21/06/2018 15:18

Classification Of Case:

Authentication Stamp

NP168



PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18013702/T1z4d3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 03-08-2018		
FIVE SINGAPORE 038985				
Code: EGI				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YN 5405M	Veh. Inspected	YN 3089E	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCH1801176	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	27/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER		c.c	2977
Engine No.	HIDDEN		Year of Reg.	2012
Chassis No.	FE83BEA20870		Colour	WHITE
Odometer	-		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16	FALKEN	6 mm	
L/H Front Tyre	7.00 R16	FALKEN	6 mm	
R/H Rear Tyre	185 R14 (D)	FALKEN	6/6 mm	
L/H Rear Tyre	185 R14 (D)	FALKEN	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
5. General Information				
Accident Date	20/06/2018		Inspect Date / Time	27/07/2018 (02:35 PM)
Survey held at	UNITY CONTRACTORS- NO 9B JALAN PAPAN			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$18,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			18 Working Days	

Report Ref No. CS3/EGI18013702/T1z4d3e2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.