

ASS. REC. BY:

REF: CSS/ICS 18013709 / N24bez

Special Instruction:

SUIVOR

N24

## ASSIGNMENT (Office)

Mufman.

From (Person):

Janice Groh

of

ICS

Date/Time: 25/7/2018 454pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 6862M

Insured:

SKW 9601E

at Workshop m/s

Hlan Her Motors

Tel:

8299 0599

of

Blk 5038 Annk Ind Park 2 #01-405

Policy No:

Claim No:

DMP C1800303H / DL

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22072018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

27/7/2018 2149pm

Person Contacted:

James

Vehicle (IN) OUT

Date/Time

Action/Instruction (X) Estimate

SLP 6862M - X

SKW 9601E - X

31/7/18

Disassembled.

EH range 2 repair done

DATE

NAZ

REF:

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP NS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLP 6862 M Yr Regn: 14 JUN 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA VEZEL HYBRD c.c. 1496

Colour:

BROWN

A/C: Insured / Std / NI / NA

Sp. Reading

N/A

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU 31230387

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F:

215/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/7/18

D.O.I.

27/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S, O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/8

Estimated repair range. \$12,000 - \$15,000.  
Submit PRS report.

*[Signature]*  
16/8/2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

14

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

100

Transportation

100

) \$ + RS. SI

) Photos

) Others

10

TOTAL

210

Report Format :

PRS

Lump Sum / I.B.I. (\$

## Catherine Chong (LKK Auto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Wednesday, 25 July, 2018 4:54 PM  
**To:** Prestina Moh; assignments  
**Cc:** ECICS Claims  
**Subject:** RE: NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIAM CASES  
**Attachments:** 20180725154900.pdf

Without Prejudice

Dear Prestina

Thank you for your email with attachment.

We are not agreeable with your list of surveyor.  
We will arrange LKK for the PRS.

Aside to LKK

Please arrange PRI for TP's vehicle and refer to the attachment for the details.

Our claim ref is DMPC1800303H/DL and case handler is Desmond Lee.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY**, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

---

**From:** Prestina Moh [mailto:prestinaMoh@visionlawllc.com]  
**Sent:** Wednesday, 25 July, 2018 3:53 PM  
**To:** ECICS Claims  
**Subject:** RE: NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIAM CASES

**WITHOUT PREJUDICE**  
**Our ref: SLP 6862 M**

Dear Sir/Mdm

Please refer to our reply of even date.

Regards,

Prestina Moh (Secretary)  
Vision Law LLC  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
Tel: 6534-2811 (Ext. 146)  
Fax: 6535-6802

---

**From:** ECICS Claims [mailto:claims@ecics.com.sg]

**Sent:** Wednesday, 25 July, 2018 1:52 PM

**To:** Prestina Moh

**Cc:** ECICS Claims

**Subject:** RE: NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIAM CASES

**Without prejudice**

Dear Prestina

We refer to your email below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

---

**From:** Prestina Moh [<mailto:prestinamoh@visionlawllc.com>]

**Sent:** Wednesday, 25 July, 2018 12:06 PM

**To:** ECICS Valerie Yap; ECICS Tan Tracy; Phoebe Jay Xie (ECICS, Claims)

**Subject:** NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIAM CASES

## IMMEDIATE ATTENTION

WITHOUT PREJUDICE

Our ref: SLP 6862 M

Dear Sir,

Please find enclosed our letter today on notice to conduct pre-repair survey on our client's vehicle.

Regards,

Prestina Moh (Secretary)  
Vision Law LLC  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
Tel: 6534-2811 (Ext. 146)  
Fax: 6535-6802

---

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

### DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

---

---

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON  
RAYNEY WONG KENG LEONG  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI D/O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
ONG BOCK KEE  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

## ✓ HEAD OFFICE

133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6

#03-11 HDB Hub  
Singapore 310490

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX : (65) 65356802 (General)  
✓: (65) 65355905 (Litigation)  
E-mail : yvonne@visionlawllc.com

## BRANCH

TEL : (65) 63580703  
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref : SLP 6862 M (PM)  
Your Ref : SKW 9601 E

25 July 2018

ECICS Limited  
7 Temasek Boulevard  
10-01 Suntec Tower One  
Singapore, 038987  
Attention: Nurul'Ain - Motor Claims Department

BY FAX 6338 9267 & EMAIL

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SLP 6862 M & SKW 9601 E ON 22 JULY 2018 ALONG JUNCTION OF EUNOS ROAD AND EUNOS AVENUE 3 AT ABOUT 0920 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email on even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : LIAN HER MOTORS  
Block 5038 Ang Mo Kio Avenue 3  
#01-405 Ang Mo Kio Industrial Park 2  
Singapore 569541  
Contact Person : Mr. James @ 8299 0599 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

JANICE HAN  
(HEAD OFFICE)

cc: SLP 6862 M - By fax: 64816131 only

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

## CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/07/2018 16:20
Date Of Accident	22/07/2018 09:20
Exact Location Of Accident	JUNCTION OF EUNOS RD 5 / EUNOS AVE 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP6862M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	L H CAR RENTAL PTE LTD
Co Reg No	200009761N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91597845
Alternative Phone No	OFFICE-91597845

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5083404689-02
Cover Note Number	

### Driver

Name of Driver	CHOO HONG FAI (ZHU HANHUI)
NRIC No	S7235433H
Date Of Birth	11/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	25/05/1996
Driving Experience	22 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91597845
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	BLK 247 TAMPINES ST 21 #05-287
Postcode	521247
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	KIV
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW9601E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name CHOO HONG FAI (ZHU HANHUI)  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLP6862M  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name UNKNOWN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLP6862M  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

#### DETAILS OF INJURED PERSON 3

Name UNKNOWN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLP6862M  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

L.H CAR RENTAL PTE LTD

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20180723/2017

1 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180723/2017

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 23/07/2018 09:01			Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>						
Name of Informant: CHOO HONG FAI			Address: APT BLK 247 TAMPINES ST 21 #05-287 HDB-TAMPINES SINGAPORE 521247			
ID Type / ID No.: NRIC NO / S7235433H			Contact No.: Home/Office: Mobile: 91597845			
Nationality: SINGAPORE CITIZEN			Email:			
Sex: Male	Age: 45	Date of Birth: 11/09/1972	Type of Informant: Driver			
Race: Chinese			Language: English		Institution / School Name:	
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3,4,5 Date of Expiry:			

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 22/07/2018 09:20	Type of Location:
Location: Junction of Road 1 and Road 2 EUNOS ROAD 5 EUNOS AVENUE 3				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKW9601E	Car					0
SLP6862M	Car					2



**SINGAPORE  
POLICE FORCE**



T/20180723/2017

2 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180723/2017

**CONTINUATION OF REPORT**

**Brief Details.**

**ON THE ABOVE MENTIONED DATE TIME AND LOCATION**

I WAS TRAVELLING ON EUNOS RD 5 HEADING TOWARDS SIMS AVE WITH 2 PASSENGERS. I WAS IN THE MIDDLE OF THE JUNCTION OF EUNOS RD 5 AND EUNOS AVE 3 WHEN I SAW A VEHICLE (SKW9601E) COMING FROM MY LEFT ON EUNOS AVE 3. THE SIDE WHERE THE VEHICLE WAS COMING FROM HAD A STOP LINE AND THE VEHICLE DID NOT STOP AT THE STOP LINE. THE VEHICLE COLLIDED INTO MY CAR. THE COLLISION CAUSED MY CAR TO SPIN ALL THE WAY TO THE OTHER LANE. POLICE AND AMBULANCE CAME. MY PASSENGERS AND I WAS CONVEYED TO THE HOSPITAL. I WAS BROUGHT TO TAN TOCK SENG HOSPITAL WHERE I WAS DISCHARGED ON THE SAME DAY AND RECEIVED 3-DAYS MC.



SINGAPORE  
POLICE FORCE



T/20180723/2017

3 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180723/2017

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
TP /  
MUHAMMAD SYUKRI BIN ABU BAKAR ✓

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIT /  
Staff Sgt MOHAMMAD ZULKARNIAN BIN  
SAMSUDIN  
Contact No.: 65476429

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
23/07/2018 09:01

Classification Of Case:



SINGAPORE  
POLICE FORCE

Signature:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2018 08:24 <a href="#">Edit Reg</a>		25 Jul 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: <b>L H CAR RENTAL PTE LTD</b> , Co. Reg. No.: 200009761N									
Vehicle Reg. No.: <b>SLP6862M</b>		Date of Loss: 22/07/2018 09:00 - :59 [13 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>SKW9601E</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Lian Her Motors (HQ)</b> Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2, 569541 Ang Mo Kio - Tel: 82990599									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 10/08/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




































## Claim Documents

\*SLP6862M  
[SKW9601E]  
TP  
L H CAR RENTAL PTE LTD  
Jul 22 2018 9:00AM  
[-]  
Lian Her Motors

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
2	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
3	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
4	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
5	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
6	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
7	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
8	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
9	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
10	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
11	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
12	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
13	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
14	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
15	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
16	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
17	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
18	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
19	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
20	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
21	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
22	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
23	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
24	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
25	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
26	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
27	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
28	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
29	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
30	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
31	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
32	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
33	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
34	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
35	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
36	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	
37	07/08/18 11:35	General View					Load JPG	<input checked="" type="checkbox"/>	



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/08/18 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	07/08/18 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	07/08/18 11:36	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
85	07/08/18 11:36	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
86	07/08/18 11:36	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
87	07/08/18 11:36	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
120	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
121	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
122	07/08/18 11:36	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18013709/NZ4BE2

Date: 21/08/2018

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SLP6862M

Insured Vehicle No :

SKW9601E

Date of Loss: 22/07/2018

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP6862M

Make &amp; Model: HONDA VEZEL, 1.5 HYBRID (A)

Engine No: LEB5930400

Reg. Date: 14/06/2017 (Man. Year: 2016)

Chassis No: RU31230387

Colour: Brown

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 25/07/2018

Date Inspected: 27/07/2018 Inspected At:

Lian Her Motors (HQ)  
Block 5038 Ang Mo Kio Avenue 3, #01-405  
Ang Mo Kio Industrial Park 2  
Singapore 569541

Estimated Period of Repair: 14.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$12,000.00 - \$15,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2018)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLP6862M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >