

26.07.18

ON

Our	Dof	- 1
Our	Rei	20

Dear Sir

AND OTHER

T 0718 / SHD4817T /WT(st)

Your Ref:

Date

01-Aug-18

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr

Singapore 508969

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sg

Workshops

Braddell

59 Loyang Drive Singapore 508969 Sin Ming 383 Sin Ming Drive Singapore 575717

Singapore 609286

Singapore 408649 Senoko 24 Senoko Loo

Singapore 758156 Sungei Kadut

7 Sungei Kadut Way Singapore 728791

hun Industrial Park A Singapore 768732

CHINA INSURANCE CO LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn : Motor Claims Department

WITHOUT PREJUDICE

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor SHD4817T which was involved in the captioned accident with your insured Vehicle No: vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

ACCIDENT INVOLVING OUR TAXI SHD4817T YOUR INSURED GBF7428Z

As the accident was caused by the negligent act of your insured driving GBF7428Z we are submitting these claims for your consideration on behalf of the claimants.

## TAXI OWNER'S CLAIM

TAX	OWNER'S CLAIM		\$ 1,337.50
1	Cost of Repair  2 days Loss of Rental @ \$ 117.28 per day		\$ 234056 ish
2	Survey Report Fees (Surveyed by M/s LKK)		\$ -
3			\$ 7.49
4	LTA Search Fees		\$
5	GIA / Police Report Fees Towing / Medical / Transporation Fees		\$ -
6	Towing / Wedical / Transporation 1 666	Sub Total:	\$ 1,579.55

HIRER'S CLAIM

160.00 80.00 per days 2 days Loss of Income @ \$ 1,739.55 Total Claims: \$

We enclose herewith the following documents to support the claims: -

Original repair bill and photocopies of photographs: a) **GBF7428Z** 

b) LTA search slip/s of: SHD4817T

GIA / Police report/s of : c) Letter of authority from owner / hirer / operator d)

( ) Traffic Compound ( ) Towing/Medical bill/receipts ( ) Certificate of Insurance

(x) Rental Rate letter ( X ) Photograph/s of Accident Scen ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully William Ian

Deputy Manager

**CDGE Claims Department** 

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of







pcs.

4



FTTED	OF	ALITHO	RISATION
FILER	UF	AUINU	KIDALION

(NAF / PAF)

ACCIDENT INVOLVING i 40 SHD4817T , GBF7428Z

ON 26-Jul-18 06:15

ALONG

SLIP ROAD FROM CLEMENTI AVE 6 TO AYE TWDS CHANGI

I / We

NG CHENG HUAT

(Hirer) NRIC No.: **S0227225C** 

and/or

(Relief) NRIC No .:

Taxi Number

SHD4817T

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

26-Jul-2018

Name of Hirer

NG CHENG HUAT

Hirer NRIC

S0227225C

Signature:

122

Address

226 CHOA CHU KANG CENTRAL #05...

680226

Contact No.

96783579



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

## TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649 24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 76873

COMPANY REG. NO.: 199506048W

Page: 1

801.001.2

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

ANSON ROAD #16-00 SINGAPORE 079909

CONTACT NO: 62222366

VKHCLK NO SHD4817T

NO/DATK 91386945 31.07.2018

MAKE HYUNDAT JOB NO. 305192359

M()I)KL I - 40

OIXOMETER READING

DATE OF REG 04.03.2014

CHASSIS CODE

JOR TYPE

KMHLB41UMEU047686

Description: 3P 26.07.18

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt 7,000 %

Total Invoice amount

1,337.50

1,250.00

Issued by

: KATHERINETAN 31.07.2018 10:43:03

Repair Payment

Type : CLSO/57/57 Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. **AMOUNT** BANK/CHQ No.

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18070748

Date: 31 July 2018



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

26/07/2018 @ 06:15 hrs

**ALONG** 

SLIP ROAD FROM CLEMENTI AVE 6 TO AYE TWDS

CHANGI

INVOLVING

**GBF7428Z** 

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHD4817T (the "Taxi"). The Taxi was hired to NG CHENG HUAT IC NO S0227225C a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$117.28 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

		101		HOURS OPERATED (TIME)	TED (TIME)		GIVIOR TO TARALIA	MIIFAGE
DATE	NAME OF DRIVER	MILEAGE READING	TRAVELLED	FROM	10	DALE	NAME OF DRIVER	
			1	TUK	(			
2007113	HOLDEN			PE T				
2010	Repair	}	CWL					
	_							
		1						
					,			
6								

d.

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

GBF7428Z 26 Jul 2018 / 06:15:00 Successful C01 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous OK

SUD 4817 T









