

2/20/2018

ASS. REC. BY:

REF: CS/II 18013780/Gtd3et

Special Instruction:

Surveyor: Guo Qiang

ASSIGNMENT (Office)

From (Person): Gabriel Wee

of

III

Date/Time: 30/7/18 @ 11:15am

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FY 73404

Insured:

SH 7153D

at Workshop m/s

GING Motor Trading

Tel:

62836560

96642992

of

31k6 De fu Lane 10 #01-564

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time: 11:29am @ 30/7/18

Person Contacted:

Elaine

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

FY 73404 - x

SH 7153D - XCA / III 17021551 / Alcor 3y2

NA: 9/11/2017

lump sum \$700 2days (Red: 725: 50%)

REF:

III

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s: _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 1/2 days Res: Yes or NoLump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Yr Regn: 16 Dec 2004

Type: M/Car / M/Lyco / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make _____

Colour _____

Sp. Reading _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal: 4 mmR/Bal: 4 mm

L/Bal: _____ mm

L/Bal: _____ mm

D.O.A. _____

D.O.I. _____

Survey held at: _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 15 NOV 2018

Date/Time: File Pass to?

1511 Typist

Date/Time: File Return to?

To

Report Format: _____

Lump Sum I.B.I.: (\$ _____)

☐ : Prel. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech Insp (\$ _____)☐ Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

F. S + RS \$ _____

F. Price _____

F. Costs _____

TOTAL

250

10

260

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 30 July 2018 11:15 AM
To: Alice; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FY7340U (Accident involving FY7340U and SH7153D on 20.07.2018) Our Ref: BSA. 9481.ay

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FY7340U and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 10B Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Alice [mailto:alice@bsalaw.com.sg]
Sent: 30 July, 2018 11:01 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: jaya@bsalaw.com.sg; 'Bala' <bala@bsalaw.com.sg>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FY7340U (Accident involving FY7340U and SH7153D on 20.07.2018) Our Ref: BSA. 9481.ay

Dear Mr. Gabriel Wee

We refer to your email of 26 July 2018.

We have received instructions from our client to appoint LKK Auto Consultants Pte Ltd to conduct the PRI.

Please note that our client's motorcycle is available for inspection at the following address:

GNG Motor Trading Co
Block 6 Defu Lane 10
#01-564
Singapore 539187
Tel: 6283 6560/966448992
Attention: Mr. Ong

Thank you

Regards

Alice

for and on behalf of
Mr Bala
M/s BSA Law Chambers LLC
DID: 6435 0020
Email: alice@bsalaw.com.sg

M/s BSA LAW CHAMBERS LLC (UEN No. 201502330R)
133 New Bridge Road
#10-04 Chinatown Point
Singapore 059413
Tel : 6236 2001
Fax : 6532 0412
Email : bala@bsalaw.com.sg

Disclaimer:

This e-mail is confidential and may also be privileged. If you are not the intended recipient please notify us immediately at Telephone : 6236 2001 or Fax No. 6532 0412. You should not copy this e-mail or use it for any purpose nor disclose its contents to any other person.

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, July 26, 2018 10:33 AM
To: bala@bsalaw.com.sg
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. FY7340U (Accident involving FY7340U and SH7153D on 20.07.2018)

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



Virus-free. www.avast.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS/III18013780/Gtd3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 30-07-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7153D	Veh. Inspected	FY 7340U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	30/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/07/2018	Inspection Date	30/07/2018
Survey held at	G.N.G MOTOR TRADING CO. BLK 6 DEFU LANE 10 #01-564 SINGAPORE 539187		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7804E
Vehicle Details	
Vehicle No.:	FY7340U
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	WAVE 125R A
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	NF125MPE0005930
Chassis No.:	NF125MP0005930
Maximum Power Output:	-
Open Market Value:	\$1,670.00
Original Registration Date:	16 Dec 2004
First Registration Date:	16 Dec 2004
Transfer Count:	1
Actual ARF Paid:	\$251.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2019
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,160.00
COE Rebate Amount:	\$416.00
Total Rebate Amount:	\$416.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Nov 2018

OK

Denise Tay (LKKAuto)

To: Sithara
Cc: SUR; assignments; Bryan Ang (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D18004988MFSH/1

Dear Sithara,

According to our surveyor, the damages is consistent to *to 1?* *a to* *diversion.* *a collision impact force* *of the front and rear portion*

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sithara <Sithara@msfirstcapital.com.sg>
Sent: Tuesday, 13 November 2018 5:53 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D18004988MFSH/1

Dear Denise,

Please let us have your reply urgently.

Thanks and regards,

Sithara G S
Motor Claims



Change of email address
Sithara@msfirstcapital.com.sg

MS First Capital Insurance Ltd | 36 Robinson Rd #16-01 City House Singapore 068877 | TEL : 6507 3848 | Fax No. : 6507 3849 |
Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Sithara
Sent: Thursday, November 8, 2018 7:18 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004988MFSH/1

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/07/2018 11:19
Date Of Accident	20/07/2018 14:40
Exact Location Of Accident	UPPER CHANGI ROAD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FY7340U
Insured/Policyholder	
Name Of Registered Owner	FAYZAL KHAN BIN RAHMAN KHAN
NRIC No	S1587804E
Email Address	FAYZALKHAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96224431
Alternative Phone No	OTHERS-96224431

Vehicle Particulars

Manufacturer	HONDA
Model	WAVE 125
Exact Purpose for which vehicle was being used at time of accident	PTE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5047378302-07
Cover Note Number	

Driver

Name of Driver	FAYZAL KHAN BIN RAHMAN KHAN
NRIC No	S1587804E
Date Of Birth	10/12/1963
Occupation	OUTDOOR
Date Of Driving Pass	24/06/1994
Driving Experience	24 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96224431
Fax Number	
Contact Number	OTHERS-96224431
Email Address	FAYZALKHAN@GMAIL.COM

Address	BLOCK 842D TAMPINES STREET 82 #11-56
Postcode	524842
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 6 TAMPINES AVE 4 , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5871999 - FAX NO: 65871699
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 20/07/2018 at about 1440hrs, I was driving along Upper Changi Road North towards Loyang avenue. I saw a blue Comfort Sonata parked at the kerbside of Upper Changi Road North, with no hazard light and it was stationary. I then proceed to drive beside the taxi to go over, when it suddenly move and made a u turn. I then crashed into the side part of the taxi, as I was trying to drive past it. I was flunged over and landed face down about 10m away from the taxi. The taxi driver then reversed his vehicle and parked at the kerbside before she alight and make a check on myself. She then apologized to me and admitted that it was her fault. I did not managed to exchange particulars with the said driver. My motorcycle was damaged in this accident. The front part of my motorcycle was damage, by my assessment. However, I was not able to made a check as I was injured. A passer by then called for ambulance, which arrive shortly. I wish to state that Traffic Police was also there before I was conveyed. I was then conveyed to Changi General Hospital, where I seek medical treatment for the following injuries: 1) Bruises on right and left knee, 2) Abrasion on the right ankle, 3) A cut on my chin area, 4) Swelling and pain on both palms I was given MC for 7 days MC from Changi General Hospital.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH7153D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	FAYZAL KHAN BIN RAHMAN KHAN
Approximate Age	55
Injuries Sustain	
Injured person in which vehicle?	FY7340U
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 842D #11-56 TAMPINES STREET 82
Postcode	524842

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers, and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 24/7/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name: Cassandra

NRJC/TIN No.:



Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to Police Report No. T/20180720/2210.

Insured vehicle cannot be driven, photos provided by driver.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name: Cassandra
NRIC/TIN No.



Police Report



**SINGAPORE
POLICE FORCE**



T/20180720/2210

Police Station Of Origin:
Tampines N.P.C
8 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

1 of 4

Report No. T/20180720/2210

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/07/2018 22:05		Vide Report No.:		Station Diary No.: 114	
Informant's Particulars					
Name of Informant: FAYZAL KHAN BIN RAHMAN KHAN			Address: APT BLK 842D TAMPINES STREET 82 #11-56 SINGAPORE 524842		
ID Type / ID No.: NRIC NO / S1587804E			Contact No.: Home/Office: Mobile: 96224431		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 10/12/1963	Type of Informant: Rider		
Race: Indian			Language:		Institution / School Name:
Occupation: SENIOR SERVICE AGENT			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 20/07/2018 14:40	Type of Location: Straight Road
Location: Along Road 1 UPPER CHANGI ROAD NORTH ROAD OPPOSITE CHANGI BAPTIST CHURCH				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FY7340U	Motorcycle	HONDA	WAVE 125R A	Silver	Slightly Damaged	0

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date	
FY7340U	NTUC Income Insurance Co-Operative Limited	5047378302-07	23/12/2017	15/12/2018	

Police Report



**SINGAPORE
POLICE FORCE**



T/20180720/2210

2 of 4

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20180720/2210

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	FAYZAL KHAN BIN RAHMAN KHAN	ID No.	S1587804E
Related Vehicle	FY7340U (Motorcycle)	Contact No.	96224431
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	20/07/2018	Date Discharge	20/07/2018
No. of Days granted Medical Leave	07	Degree of Injury	NIL

Brief Details.

On 20/07/2018 at about 1440hrs, I was driving along Upper Changi Road North towards Loyang avenue. I saw a blue Comfort Sonata parked at the kerbside of Upper Changi Road North, with no hazard light and it was stationary.

I then proceed to drive beside the taxi to go over, when it suddenly move and made a u turn. I then crashed into the side part of the taxi, as I was trying to drive past it. I was flunged over and landed face down about 10m away from the taxi.

The taxi driver then reversed his vehicle and parked at the kerbside before she alight and make a check on myself. She then apologized to me and admitted that it was her fault. I did not managed to exchange particulars with the said driver.

My motorcycle was damaged in this accident. The front part of my motorcycle was damage, by my assessment. However, I was not able to made a check as I was injured.

A passer by then called for ambulance, which arrive shortly. I wish to state that Traffic Police was also there before I was conveyed. I was then conveyed to Changi General Hospital, where I seek medical treatment for the following injuries :

- 1) Bruises on right and left knee
- 2) Abrasion on the right ankle
- 3) A cut on my chin area
- 4) Swelling and pain on both palms

I was given MC for 7 days MC from Changi General Hospital.

Police Station Of Origin:
Marshall NPP
16 Marshall Lane #01-183 SINGAPORE 730016
Tel No: 1800-3679999



1 of 3
Report No. T/20110822/9056



REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/08/2011 15:09
Vide Report No.:
Station Diary No.: 14

Name of Informant		BATTAR BIN LATIF	
Address:		APT BLK 544 WOODLANDS DRIVE 16 #04-99 SINGAPORE 730544	
ID Type / ID No.:	NRIC NO / S1715084G		
Sex:	Age:	Date of Birth:	Type of Informant:
Male	46	07/07/1965	Driver
Race:		Language:	
Indonesian		English	
Occupation:	Driving Licence Information:		
Supervisor	Class: 2B, 2A, 2J		
Date of Expiry:		Institution / School Name:	

Type of Accident:		Non-Injury		Hit and Run		Drink Drive:		Date/Time of Accident:		Type of Location:	
								22/08/2011 11:00		X-Junction	
Location:											
Along Road 1											
SIMS WAY											
Junction Sims Avenue											
Weather:		Road Surface:		Road Speed Limit:							
Clear		Dry									
Traffic Flow:		Traffic Control:		Traffic Light - Working		Light		Volume		Anyone conveyed by ambulance:	
Two Way											
Type of Collision:		Between Moving Vehicles - Side Swipe - Same Direction									
		No									

Details of Vehicle Involved											
No.	Vehicle	Type	Make	Color	Condition	No. of Passenger	Insurance Company	Insurance No.	Effective Date	Expiry Date	
SDQ9099	Car	MERCEDES	ES BENZ			0					
R	SGX1122	Car	HONDA	Black	Slightly Damaged	0	AXA Insurance	VPA/P05 91400	13/08/2011	12/08/2012	

Brief Details. This report shall be signed by the informant.

No. 22/08/2011 at around 1100 hrs, I was driving my m/car (SDH2621D) travelling in front of my vehicle. I was driving in the left lane (4 lanes traffic). There was a m/taxi (SHD2621D) travelling in front of my vehicle. I stopped just behind the m/taxi. Out of sudden, a m/car (SDH2621D) from the second lane graze the right side of my m/car. Subsequently it then hit the traffic light junction of Sims Way by Sims Avenue, the traffic light was red. I stopped just behind the m/taxi. The extreme left lane (4 lanes traffic).
0122/022081021 CR/100562
4 to 3



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Marshall NPP
16 Marshall Lane #01-183 SINGAPORE 730016
Tel No: 1800-3679999

Police Report

Police Report



**SINGAPORE
POLICE FORCE**



T201807202210

Police Station Of Origin:
Tampines N.P.C

8 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5671999

4 to 44168
Authentication Stamp
Report No. T201807202210

CONTINUATION OF REPORT

Contact No.:

TP /

Officer In Charge Of Case:

Classification Of Case:

Sketch Plan

Informant is not able to provide sketch plan

Date: 22/08/2011 15:09

Date:

Signature Of Informant:

Signature Of Interpreter:

Suziman B Jurnari

Signature Of Officer Recording The Report:

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MUHAMMAD SYARAFUDDIN BIN SHARIFF

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/07/2018 22:05

No Sketch Plan Drawn

Sketch Plan

Officer In Charge Of Case:

TP / GIT /

Sgt 2 YAN-MINGSHENG DANIEL

Contact No.: 65476252

Classification Of Case:

Tel No: 1800-3679999

16 Marsiling Lane #01-183 SINGAPORE 730017

Marsiling NPP

Police Station Of Origin:

Authentication Stamp



Certificate of Insurance



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number :	5047378307-07	Cover :	Third Party, Fire & Theft
1. Index mark and Registration Number of Vehicle			FY734DU
Chassis Number			NF125MPO005930
2. Name of Policyholder			FAYZAL KHAN BIN RAHMAN KHAN
3. Effective Date of Insurance			23 Dec 2017
4. Expiry Date of Insurance			15 Dec 2018
5. Persons or Classes of Persons entitled to drive			
(a) Named Driver(s) Only,			
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.			
6. Limitations as to Use			
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession,			
This Policy does not cover:			
(a) Use for hire or reward,			
(b) Use for racing, pace making, reliability trial or speed-testing,			
(c) Use for the carriage of goods (other than samples) in connection with any trade or business,			
(d) Use for any purpose in connection with the Motor Trade.			
* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 55 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.			

EXCESS (SECTION 1)	N/A
EXCESS (SECTION 2)	N/A
EXCESS (THEFT OUTSIDE SINGAPORE)	PLEASE REFER OVERLEAF
INSURE WITH COE	YES
NAMED DRIVER (1)	FAYZAL KHAN BIN RAHMAN KHAN
NAMED DRIVER (2)	N/A
HIRE PURCHASE COMPANY	N/A
SUM INSURED	MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : A S PHOON PTE LTD (00000571911)
Date of issue : 13 Dec 2017 12:33 hrs
Reprint : 13 Dec 2017 12:34 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

Scene Photo




Photo Provided by Driver




Photo Provided by Driver



DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number of Driver's Own Vehicle (if applicable)
Insurance Company of Driver's Own Vehicle (if applicable)

General Information of the Accident

Type Of Accident
Side Swipe- Same Direction
Weather Conditions
Clear
Road Surface
Dry

Other Information

Was any body injured in the Accident?
No
Was any other material or property damaged?
Yes

Details of Police Action

Was the accident reported to the police?
Yes

If Yes, Please state which Police Station

Police Station Name

Police Station Address

Police Station Contact

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE SEE POLICE REPORT

Are accident photos available for attachment?
Yes

Marsiling Neighbourhood Police Post
ROAD Blk 16 Marsiling Lane, POSTCODE: 730016, COUNTRY: Singapore
TEL NO: 1800-3679999 - FAX NO: 63682380

No



T/20110822/9056

1 of 3

Report No. T/20110822/9056

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/08/2011 15:09		Vide Report No.:		Station Diary No.: 14
Informant's Particulars				
Name of Informant: BATLAR BIN LATIF		Address: APT BLK 344 WOODLANDS DRIVE 16 #04-99 SINGAPORE		
ID Type / ID No.: NRIC NO / S1715084G		Contact No.: 730544		
Sex: Male		Home/Office: Mobile/Pager: 93870882		
Age: 46	Date of Birth: 07/07/1965	Type of Informant: Driver		
Race: Indonesian		Language: English		
Occupation: Supervisor		Driving Licence Information: Class: 2B,2A,2,3		
		Date of Expiry:		
General Information of the Accident				
Non-Injury		Drink Drive:		Date/Time of Accident:
		Type of Location:		X Location:

Photo Provided by Driver



Photo Provided by Driver



Photo Provided by Driver



Photo Provided by Driver



Photo Provided by Driver



62564315 - DENISE..



南藝摩 G. N. G. MOTOR TRADING CO.

REG. NO: 24/134/00-A

Block 6, Defu Industrial Estate, #01-565, Singapore 19055
Defu Lane 10 #01-565, Singapore 19055

TEL: 2836610, 2805065

AGENT FOR ALL TYPES OF MOTOR CYCLE & INSURANCE

Fax 64815

Fax 63833763

Your Ref:

INDIA INSURANCE

Our Ref:

FY7340U.

Date:

25/7/18

1pc. REAR BRAKE PEDAL - \$47 X NA

1pc. SPEEDOMETER CABLE - \$20 X 1

1pc. SPEEDOMETER GAUGE - \$38 X 1

1sq. Front Fork Assy - \$240 / BT

✓ 1pc. Front Fork UNDER BRACKET - \$95 X NA

1pc. Front WHEEL - \$150 X NA

1pc. Front BRAKE DISC - \$85 / BT

1pc. Front NO. PLATE - \$10 / NA

1sq. Front BRAKE CALIPER ASSY - \$125 / NA

1pc. Front WHEEL SHAFT & BOLT - \$25 / NA

1pc. REAR BOX - \$125 / NA

1sq. STEERING CONE - \$85 / NA

TOWING - \$30 /

LABOUR CHARGE - \$350

2 Days.

Lumpsum Repair

After repair photos

Gua Qi Ong (LKR) - \$282

790

-90%

711

100 Labour 210

Total: 921

Lump Sum \$7007



Only GNG GUARANTEE



南藝摩 G. N. G. MOTOR TRADING CO.

Block 6, Defu Industrial Estate Park C, Avenue
Defu Lane 10 #01-564, Singapore 1555
TEL: 2836560, 2805065

REG NO 24124/06-A

代理各款摩托車及保險
AGENT FOR ALL TYPES OF MOTOR CYCLE & INSURANCE

Signature
Date

LKK Fax
62564815

Fax 63333763

Your Ref:

INDIA INSURANCE

Our Ref:

FY7340U

Date 25/7/18

- 1pc. Rear Brake Pedal - \$47 X NN
- 1pc. Speedometer Cable - \$20 X
- 1pc. Speedometer Gauge - \$38 X } NN
- 1sq. Front Fork Assy - \$240 / BT
- 1pc. Front Fork Under Bracket - \$95 X NN
- 1pc. Front Wheel - \$150 X NN
- 1pc. Front Brake Disc - \$85 / BT
- 1pc. Front No. Plate - \$10 / LT
- 1sq. Front Brake Caliper Assy - \$125 / LT
- 1pc. Front Wheel Shaft & Bolt - \$25 / LT
- 1pc. Rear Box - \$125 / LT
- 1sq. Steering Cone - \$85 / MC

Towing - \$30 /

\$1100

Labour charge - \$350 180

US
\$650

2 Days.

30/7/18

Improm Repair

After repair photos

Gua Qiang (LKK) - 82880282

Only FMS ATTACH



REG NO: 247-2800-4

南藝摩嘜公司

G. N. G. MOTOR TRADING CO.

Block 6, Defu Industrial Estate Park C, Avenue 1

Defu Lane 10, #01-564, Singapore 1953.

TEL: 2836560, 2805065

X
keep
record.◀ 代理各種摩嘜西卡及保險 ▶
AGENT FOR ALL TYPES OF MOTOR-CYCLE & INSURANCE

Your Ref: INDIA INTERNATIONAL INS. PIELTA.

Our Ref: FY7340 U HONDA WAVE 125S Date: 25/7/18

- 1pc. HEADLIGHT COWLING - \$45 / Cut
- 1SG. HEADLIGHT UNIT - \$55 X NV
- 1pc. L.H. UNIT - \$155. So NEXT / Cut
- 1pc. HANDLE BAR - \$48 / BT
- 1pc. HANDLE BRACKET - \$45 X NV
- 1SG. HANDLE BARANCHER - \$35 / Cut
- 1SG. MIRROR - \$30 / Cut
- 1pc. BRAKE LEVER - \$20 / BR
- 1pc. FRONT ^{RH} ~~LEFT~~ SIGNAL - \$25 / CRAFT
- 1pc. BASKET - \$25 X Repair.
- 1pc. FRONT HORN COVER - \$35 / Cut
- 1pc. FRONT MUDGUARD - \$55 / Cut
- 1pc. REAR MUDGUARD - \$35 / el
- 1pc. RIGHT OUTER COWLING - \$55 / Cut
- 1pc. RIGHT INNER COWLING - \$45 / Cut
- 1pc. FOOTREST BRACKET - \$45 / BT
- 1SG. FOOTREST RUBBER - \$20 / TN






































...CLAIM SUBFOLDER...(Pending for Survey Report)





























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018 Edit Reg		30 Jul 2018 00:00 Edit Adj Rpt	\$5700.00 Edit Estimates	\$5700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	FAYZAL KHAN BIN RAHMAN KHAN , ID: -								
Vehicle Reg. No.:	FY7340U	Date of Loss:	20/07/2018 00:00 - :59 [163 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18070608	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH7153D	Policy No. (Claimant):							
		Excess:							
Repairer:	Gng Motor Trading (HQ) BLK 6 DEFU LANE 10 #01-564, 539187 Defu Lane - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FY7340U (MCT18070608)**
[SH7153D]
TP
FAYZAL KHAN BIN RAHMAN KHAN
Jul 20 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Gng Motor Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
2	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
3	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
4	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
5	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
6	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
7	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
8	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
9	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
10	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
11	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
12	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
13	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
14	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
15	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
16	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
17	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
18	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
19	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
20	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
21	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
22	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
23	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
24	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
25	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
26	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
27	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
28	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
29	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
30	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
31	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
32	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
33	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
34	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
35	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/11/18 17:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	15/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 08:51	Singapore Accident Statement	 Load PDF	
2	12/11/18 14:22	Letter of Demand from Third Party BSA LAW CHAMBERS LLC	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18013780/GTD3E2

Date: 16/11/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: FY7340U Insured Vehicle No: SH7153D
 Date of Loss: 20/07/2018 Nature of Claim: TP Claim No: MCT18070608

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FY7340U
 Make & Model: HONDA WAVE 125, 125cc Engine No: NF125MPE0005930
 Reg. Date: 16/12/2004 (Man. Year: 2004) Chassis No: NF125MP0005930
 Colour: Silver Odometer: 96510 km
 Engine Capacity: 125 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/80-17 Rear Tyre Size: 80/90-17
 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,045.00	711.00	334.00	31.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	380.00	210.00	170.00	44.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,425.00	921.00	504.00	35.37
Approved Total (Overridden) (S\$)		700.00		
Nett Amount (S\$)	1,425.00	700.00	725.00	50.88

INSPECTION

Date of Assignment: 30/07/2018
 Date Inspected: 30/07/2018 Inspected At: Gng Motor Trading (HQ)
 BLK 6 DEFU LANE 10 #01-564
 Singapore 539187
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Nov 2018)	
Parts:	N/A	HONDA WAVE 125 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FY7340U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BRAKE PEDAL	Not Necessary	47.00 F	*- FL
2	1		*SPEEDOMETER CABLE	Not Necessary	20.00 F	*- FL
3	1		*SPEEDOMETER GAUGE	Not Necessary	38.00 F	*- FL
4	1		*FRONT FORK ASSY	Bent	240.00 F	*240.00 FL
5	1		*FRONT FORK UNDER BRACKET	Bent	95.00 F	*95.00 FL
6	1		*FRONT WHEEL	Not Necessary	150.00 F	*- FL
7	1		*FRONT BRAKE DISC	Bent	85.00 F	*85.00 FL
8	1		*FRONT NO.PLATE	Cut	10.00 F	*10.00 FL
9	1		*FRONT BRAKE CALIPER ASSY	Cut	125.00 F	*125.00 FL
10	1		*FRONT WHEEL SHAFT & BOLT	Cut	25.00 F	*25.00 FL
11	1		*REAR BOX	Cut	125.00 F	*125.00 FL
12	1		*STEERING CONE	Necessary	85.00 F	*85.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	1,045.00	790.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	79.00
Total Parts (S\$)	1,045.00	711.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	30.00	30.00
2	LABOUR CHARGE	New	350.00	180.00
Gross Labour Cost (S\$)			380.00	210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >