

ASS. REC. BY:

REF: es!AIG18013816 / Usd3ⁿ²

Special Instruction:

Surveyor

Marius

ASSIGNMENT (Office)

From (Person):

Mithoo Singh

of

AIG

Date/Time:

30/7/18 @ 2:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 3195Y

Insured:

YN 5321X

at Workshop m/s

Mah Lian Motor

Tel:

6282 3336

of

NO. 38 Defu Lane 9

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/07/2018

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

30/7/18 @ 3:10pm

Person Contacted:

Si hui

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SJU 3195Y-X

YN 5321X - CC4 / ASM18005410 / M / pb3

DOA: 20/03/2018

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 534 31954

at Workshop m/s: Michelin

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 24

IDAC Accident Rpt: _____ Consistent?: Yes or No

GLA / PR Seen: 2 Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 7886

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 534 31954 Yr Regn: 11.09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer of A1

Make: Renault KOLEOS C.C. 2488

Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: 252348 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: VF1VYOCOVU C284237

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/52

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or maxxis

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 26/7/18 D.O.I. 30/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS Bl, N/S, B/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/4/16 319 1yrs. Yrly. Dep 9(c). net 764

13/8/18 continued 2/5 @ 6750 with Shiku.

(\$ 5,702.70 Red - 46%)

RECEIVED 15 AUG 2018

Date/Time, File Pass to?

15/08/18

: Preli. Report

: Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS - SI

Photos

Others

TOTAL

250
20
270

Report Format :

Lump Sum / I.B.I.: (\$ 6,750/- 115)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18013816/Usd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 30-07-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 5321X	Veh. Inspected	SJU 3195Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MITHOOSINGH	Assign Date	30/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/07/2018	Inspection Date	30/07/2018
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Your password will expire in 14 days. [Click here to change it.](#)

- Pre repair inspection request - SJU3195Y VS YN5321X (OI) DOA: 26/07/2018

From: Mithoosingh, Aashweenjeetkaur

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi

Sent: 30/7/2018 2:44:04 PM

Attachments: 1592_001.pdf; 0385_001.pdf

Hi,

Please refer to the enclosed request from VISION LAW LLC.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Mithoosingh, Aashweenjeetkaur

Sent: Friday, July 27, 2018 5:00 PM

To: jactan@visionlawllc.com

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Azlan, Syazairdina; Chan, Yoke Shi

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN5321X AND SJU3195Y ON 26/07/2018

Without Prejudice

Your Reference : AM.jt.Ins.M46.SJU3195Y.18 (sj)

Our Reference : YN5321X

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YING XIAN SELWYN

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ **HEAD OFFICE**
TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com
BRANCH
TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.M46.107468.18 (sj)
Your Ref: YN 5321 X

27 July 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

BY FAX: 6415-3727
Email: aashweenjeetkaur.mithoosingh@aig.com
Email: noormariesa.abukassim@aig.com

Dear Sirs,

ACCIDENT INVOLVING SJU 3195 Y & YN 5321 X ON 26 JULY 2018 ALONG SLE NEAR THOMSON EXIT AT ABOUT 1450 HOURS

We refer to your letter dated 27 July 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus Chua of LKK Auto Consultants or Lawrence Ng from Priority Services as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Mah Lian Motor Vehicle Repairer
No.38 Defu Lane 9
Singapore 539278
Contact Person: Mr Goh / Ms Si Hui (6282 3336)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: SJU 3195 Y – By Fax: 6289-3336

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7185E
Vehicle Details	
Vehicle No.:	SJU3195Y
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jul 2018
Vehicle Make:	RENAULT
Vehicle Model:	KOLEOS 2.5 CVT ABS D/AB 4WD 6DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	2TRA703P009912
Chassis No.:	VF1VY0C0VUC284237
Maximum Power Output:	126.0 kW (168 bhp)
Open Market Value:	\$25,318.00
Original Registration Date:	30 Nov 2009
First Registration Date:	30 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$25,318.00 <i>12659</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2019
PARF Rebate Amount:	\$13,924.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$18,002.00
COE Rebate Amount:	\$2,395.00
Total Rebate Amount:	\$16,319.00

The information contained herein is correct as at 31 Jul 2018

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Honda Fit 1.3A GF (New 5-yr COE) @ \$29800 Only!



In House Finance With Low
 Down Payment Of \$2800!
 Installment At \$590 Only! Call!
 Speedo Motoring StarAd



[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Browse by Category ▾

Sort by

1 vehicles

Renault Koleos

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	Renault Koleos		Any	Any	2010	Any	
	Renault Koleos	2.5A	\$26,800	\$9,010 /yr	25-Feb-2010	2,488 cc	12
In-House Loan And Balloon Scheme Available, Mileage Done At 14600Km Yearly, Auto HID Lights, Cruise Control, Silver ... Good For Short Term Drive Or Renew New COE, CaseTrust ...							
Posted: 28-Jul-2018 Tags: 2010 Renault Koleos, Renault Koleos, Renault, Koleos, Used Renault							

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
------	-------	-------	--------------	----------	---------	---------

For old advertisements, view [Expired ads](#)

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [For](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, buy used Renault Koleos, Renault Koleos Singapore, used Renault Koleos Singapore, used Renault Koleos, used vehicles Singapore or even buy from dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, comments

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warranties

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

*Not Affected
 2/5 6750
 30/7/18*

M/S : *ALG* Insurance Pte Ltd

S

Estimate No: ES1700281
Date: 30 Jul 2018
Policy No: GA294710
Veh Reg No: SJU3195Y
Make/Model: RENAULT KOLEOS 2.5
 CVT ABS D/AB 4WD
 6DR

TEL: FAX:
 ATTN: Motor Claim Department

Your Ref No: PANG SOO LEE
 Claim Type: Third Party
 Accident Date: 26/07/2018

Chassis No: VF1VY0C0VUC284237
 Engine No: 2TRA703P009912
 Reg. Date: 30/11/2009

Estimate Repair Cost to Vehicle No :SJU3195Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Front Bumper <i>D.S</i>	1,160.00	1 PC	1,160.00	—
2 Front Fender LH <i>Body</i>	570.00	1 PC	570.00	—
3 Front Door LH <i>Body</i>	1,850.00	1 PC	1,850.00	—
4 Rear Door LH <i>Body</i>	1,850.00	1 PC	1,850.00	—
5 Front Door Handle Outer LH <i>Deep cut</i>	180.00	1 PC	180.00	—
6 Rear Door Handle Outer LH <i>Deep cut</i>	180.00	1 PC	180.00	—
7 Side Mirror Assy LH <i>300</i>	1,180.00	1 PC	1,180.00	—
8 Side Mirror Glass LH <i>Complete</i>	200.00	1 PC	200.00	X
9 Side Mirror Cover LH <i>300</i>	75.00	1 PC	75.00	X
10 Fender Side End Plate LH <i>11</i>	110.00	1 PC	110.00	X
11 Front Fender Signal Lamp LH <i>300</i>	38.00	1 PC	38.00	X
12 Front Door Window LH <i>Deep cut</i>	520.00	1 PC	520.00	—
13 Front Door Window Moulding Outer LH <i>11</i>	110.00	1 PC	110.00	X
14 Front Headlamp Assy LH <i>11</i>	1,550.00	1 PC	1,550.00	X
15 Quarter Panel LH <i>R</i>	1,950.00	1 PC	1,950.00	X
16 Side Fender End Spoiler LH (Black Cover) <i>11</i>	180.00	1 PC	180.00	X
			11,703.00	
	Less 10%		1,170.30	10,532.70
Labour				
17 To remove & refit front door LH & rear door LH ,transfer ,realignment ,etc .	100.00	1 JOB	100.00	✓
18 To move & refit headlamp LH & signal lamp & realignment .	80.00	1 JOB	80.00	20
19 Labour charge to cut ,weld ,dismantle ,remove ,refit all above parts .	650.00	1 JOB	650.00	600
20 To spray & painting at accident dented area .	850.00	1 JOB	850.00	—
21 To rush proofing at accident dented area .	150.00	1 JOB	150.00	100
22 To remove & refix front door window LH & moulding .	60.00	1 JOB	60.00	X
23 To remove & refix side mirror LH & realignment .	30.00	1 JOB	30.00	X
			1,920.00	1,920.00

*7528
 6775.2*

645.2

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S: **Alh** Insurance Pte Ltd

TEL: _____ FAX: _____
 ATTN: Motor Claim Department

Your Ref No: PANG SOO LEE
 Claim Type: Third Party
 Accident Date: 26/07/2018

Estimate No: ES1700281
 Date: 30 Jul 2018
 Policy No: GA294710
 Veh Reg No: **SJU3195Y**
 Make/Model: RENAULT KOLEOS 2.5
 CVT ABS D/AB 4WD
 6DR
 Chassis No: VF1VY0C0VUC284237
 Engine No: 2TRA703P009912
 Reg. Date: 30/11/2009

Estimate Repair Cost to Vehicle No :SJU3195Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 12,452.70
			Add GST @ 7%	871.69
			Total Amount Payable	SS 13,324.39

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND THREE HUNDRED TWENTY FOUR AND CENTS THIRTY NINE ONLY

**For MAH LIAN MOTOR VEHICLE
 REPAIRER**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18013816/USD3N2
Date: 16/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800063353
 Claimant Vehicle No : SJU3195Y Insured Vehicle No : YN5321X
 Date of Loss: 26/07/2018 Nature of Claim: TP Claim No: 4109475761SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU3195Y
 Make & Model: RENAULT KOLEOS, 2.5 4X2 (A) Engine No: 2TRA703P009912
 Reg. Date: 30/11/2009 (Man. Year: 2009) Chassis No: VF1VY0C0VUC284237
 Colour: Black Odometer: 252348 km
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
 Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
 Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,532.70	6,775.20	3,757.50	35.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,670.00	250.00	13.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,452.70	8,445.20	4,007.50	32.18
Approved Total (Overridden) (\$\$)		6,750.00		
	(\$\$)	6,750.00	5,702.70	45.79
	+ GST 7.00/7.00% (\$\$)	472.50	399.19	45.79
	Nett Amount (\$\$)	7,222.50	6,101.89	45.79

INSPECTION

Date of Assignment: 30/07/2018
 Date Inspected: 30/07/2018 Inspected At: Mah Lian Motor Vehicle Repairer (HQ)
 NO. 38 DEFU LANE 9
 Singapore 539278
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,160.00 FL	*1,160.00 FL
2	1		*FRONT FENDER LH	Badly Dented	570.00 FL	*570.00 FL
3	1		*FRONT DOOR LH	Badly Dented	1,850.00 FL	*1,850.00 FL
4	1		*REAR DOOR LH	Dented/Bent	1,850.00 FL	*1,850.00 FL
5	1		*FRONT DOOR HANDLE OUTER LH	Deep Cut	180.00 FL	*180.00 FL
6	1		*REAR DOOR HANDLE OUTER LH	Deep Cut	180.00 FL	*180.00 FL
7	1		*SIDE MIRROR ASSY LH }	Broken	1,180.00 FL	*1,180.00 FL
8	1		*SIDE MIRROR GLASS LH }		200.00 FL	*- FL
9	1		*SIDE MIRROR COVER LH }		75.00 FL	*- FL
10	1		*FENDER SIDE END PLATE LH	Not Necessary	110.00 FL	*- FL
11	1		*FRONT FENDER SIGNAL LAMP LH	Broken	38.00 FL	*38.00 FL
12	1		*FRONT DOOR WINDOW LH	Deep Cut	520.00 FL	*520.00 FL
13	1		*FRONT DOOR WINDOW MOULDING OUTER LH	Not Necessary	110.00 FL	*- FL
14	1		*FRONT HEADLAMP ASSY LH	Not Necessary	1,550.00 FL	*- FL
15	1		*QUARTER PANEL LH	Repair	1,950.00 FL	*- FL
16	1		*SIDE FENDER END SPOILER LH (BLACK COVER)	Not Necessary	180.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,703.00	7,528.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,170.30	752.80
Total Parts (\$\$)	10,532.70	6,775.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT DOOR LH & REAR DOOR LH,TRANSFER,REALIGNMENT,ETC	New	100.00	100.00
2	TO REMOVE & REFIT HEADLAMP LH & SIGNAL LAMP & REALIGNMENT	New	80.00	20.00
3	LABOUR CHARGE TO CUT,WELD,DISMANTLE,REMOVE,REFIT ALL ABOVE PARTS	New	650.00	600.00
4	TO SPRAY & PAINTING AT ACCIDENT DENTED AREA	New	850.00	850.00
5	TO RUSH PROOFING AT ACCIDENT DENTED AREA	New	150.00	100.00
6	TO REMOVE & REFIX FRONT DOOR WINDOW LH & MOULDING	New	60.00	-
7	TO REMOVE & REFIX SIDE MIRROR LH & REALIGNMENT	New	30.00	-
Gross Labour Cost (S\$)			1,920.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >