

SSA REC. BY:

REF:

CS/SPF18013862/Nsb52

Special Instruction:

Surveyor

Naz

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

31/07/2018

Estimate Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCZ 5455R

Insured:

QX 226M

at Workshop m/s

Eurokars Habitat

Tel:

63602446

of

12 Sungai Kachut Ave

Policy No:

Claim No:

AEMD / 105 / 009 / 2018 / 092

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2507 2018

10am-10-30 @ 6/8/2018 owner waiting

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

31/07/2018

10-10am

Person Contacted:

Eva

Vehicle IN /

DUB

Date/Time	Action/Instruction (✓) Estimate
	SCZ 5455R - CC4 / AXA 160024003 / TP0392
	QX 226M - X

DA: 31/07/2018

Surrender

NA2

REF:

FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL2 5455R Yr Regn: 26 MAR 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MINI COOPER S C.C. 1998

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 40,446 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMWXS720102B60388

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/45 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 25/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 6/8/18

EuroKARS SURVEY KNIGHT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Vehicle has not sent in to repair

RECEIVED 28 AUG 2018

FCI P/P

Date/Time, File Pass to?

28/08/18

1)

Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

) \$ + RS \$ _____

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

280



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18013862/Nsb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 31-07-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 226M	Veh. Inspected	SCZ 5455R
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/092	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	31/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/07/2018	Inspection Date
Survey held at	EUROKARS HABITAT PTE LTD NO.12 SUNGEI KADUT AVE SINGAPORE 729648	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SCZ5455R

Our Ref : AEMD/105/009/2018/092

Date : 30 July 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax Only: 62564315

Dear Sir/Madam,

RTA ON 25 JULY 2018 INVOLVING GOVT VEHICLE QX226M AND OTHER VEHICLE SCZ5455R

We refer to the above matter.

- 2 Please assist to arrange for a PRI of Vehicle no. SCZ5455R at M/s Eurokars Habitat Pte Ltd of 12 Sungei Kadut Avenue, Singapore 729648.
- 3 For appointment kindly contact Jobi Thomas at Tel: 63602446.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for Assistant Director

A FORCE FOR THE NATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 26/07/2018 14:49
Date Of Accident 25/07/2018 18:55
Exact Location Of Accident BOUNDARY ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCZ5455R
Insured/Policyholder
Name Of Registered Owner BOB YAP CHENG CHEE
NRIC No S1766713J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96616765
Alternative Phone No OTHERS-96616765
Vehicle Particulars
Manufacturer MINI
Model COOPER S 5DR FWD LED ABS NAV

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number D-18089952MVPC (COMP)
Cover Note Number

Driver

Name of Driver YAP YU HAN, BRENNAN
NRIC No S9704248I
Date Of Birth 01/02/1997
Occupation OUTDOOR
Date Of Driving Pass 19/05/2017
Driving Experience 1 YEAR AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-81252502
Fax Number
Contact Number
EMail Address NOEMAIL

Address	22 RICHARDS PLACE
Postcode	546349
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX226M
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS 1.6 AUTO
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

VAN

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of this accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Ministry of Home Affairs of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's signature
Date & Time

Insurer's signature
Name of the authorised agent
Date & Time 20/7/14 14:51

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: kakbb@singnet.com.sg
Name:
REG / TR / AG

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

/We declare the foregoing particulars are true as every ingore

$$\text{val } y \text{ of } \text{hd}(\text{list}) = 1 \text{ to } 4 \text{ do } \text{print } y$$

$$\text{val } x = 2 \text{ of } \text{list}$$

Ques.

$$x_1, \dots, x_n \in \mathbb{R}^n, \quad x_i = (x_{i1}, \dots, x_{in})^T$$

26/7/18 1455

~~IOAC KAKI BUKIT (VAC)~~

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492306

Email: vackb@singnet.com.sg

2001-2002

$$N_{\text{eff}} = 1.5$$



**SINGAPORE
POLICE FORCE**



T/20180726/7000

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180726/7000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/07/2018 01:59	Vide Report No.: F/20180725/0225	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: YAP YU HAN, BRENNAN			Address: 29A RICHARDS PLACE SINGAPORE 546382		
ID Type / ID No.: NRIC NO / S9704248I			Contact No.: Home/Office: Mobile: 81252502		
Nationality: SINGAPORE CITIZEN			Email: brennanyap@hotmail.com		
Sex: Male	Age: 21	Date of Birth: 01/02/1997	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 25/07/2018 18:55	Type of Location: Straight Road
Location: BOUNDARY ROAD				
Weather: Clear	Road Surface: Dry	Road Speed Limit: 50 Km/h		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Rear	Anyone conveyed by ambulance: No			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX226M	Car				Slightly Damaged	2
SCZ5455R	Car					0

Details of Person Involved

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



**SINGAPORE
POLICE FORCE**



T/20180726/7000

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180726/7000

CONTINUATION OF REPORT

Driver			
Name	Jasrianto Bin Jasni	ID No.	S8732153C
Related Vehicle	QX226M (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YAP YU HAN, BRENNAN	ID No.	S9704248I
Related Vehicle	SCZ5455R (Car)	Contact No.	81252502
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was driving normally when the car in front slowed down, I slowed down as well but the police car behind me didn't manage to slow down in time and crashed into my car. This was the first bang. The car behind the police car also couldn't stop in time and banged into the police car which then caused the police car to bang into me a second time.

We were travelling on boundary road and 1 van, 1 police car, 1 car was involved in the accident.

I had a video camera that was capturing everything but it was taken by the traffic police for further inspection



SINGAPORE
POLICE FORCE



T/20180726/7000

3 of 3

Report No. T/20180726/7000

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
LIM JUN HUI, ADRIAN
Contact No.: 65476350

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
26/07/2018 01:59

Classification Of Case:



SINGAPORE POLICE FORCE
ACKNOWLEDGEMENT SLIP

Ref: Report No: F/20180725 / 0225

I, Sgt T120006 Jonathan Leo
(Recipient's Name, Contact No. / NRIC or Passport No. / Rank and No.)

of TP
(Address / Police Station / NPC / NPP)

hereby acknowledge receipt of the below mentioned items of:

- 1 One IRADA micro SD 64GB
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10

from Yap Yu Han Brennan, 897042481
(Name, NRIC or Passport No. / Rank and No.)

of SCZ 5455R
(Address / Police Station / NPC / NPP)

on 25/7/18 at 1855
(Date) (Time)

Witnessed by / * Handed over by:
(* Delete if applicable)

OK

(Signature)

Brennan Yap 897042481
(Name, NRIC or Passport No. / Rank and No.)

Received by:

[Signature]

(Signature)

Sgt T120006 Jonathan Leo
(Name, Contact No. / NRIC or Passport No. / Rank and No.)

Other Remarks: _____

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S97042481



Name

YAP YU HAN, BRENNAN

叶宇涵

Race

CHINESE

Date of birth

01-02-1997

Sex

M

Country of birth

SINGAPORE

S97042481

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S97042481

Name: YAP YU HAN, BRENNAN

Birth Date: 01 Feb 1997

Issue Date: 19 May 2017



4868706



NRIC No. S97042481

Date of issue

03-08-2012

22 RICHARDS PLACE
SINGAPORE 546349

NRIC No. S97042481

Date: 18/07/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight \leq 2500kg 19 May 2017

NP 428A





EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



SPF ACCIDENT CLAIMS SECTION		NAME : Mr Yap Cheng Ghee Bob	WIP : 20758
AUTOMOTIVE ENGG & MGMT DIV		ADDRESS : 22 Richards Place	EXCESS :
POLICE LOGISTICS DEPARTMENT		Singapore 546349	DATE: 30.07.2018
NO. 1 MOUNT PLEASANT ROAD		TEL : 91053684	<i>ms. Yap: 96616765</i>
BLOCK 8 OLD POLICE ACADEMY SINGAPORE 298333			
ATTN. :	MOTOR CLAIMS / FAX 64784848		
VEH NO :	SCZ5455R	DATE IN :	CONTACT PERSON : JOBI THOMAS 6360 2446
CHASSIS NO :	WMWXS720102B60388	MILEAGE :	TYPE OF CLAIM : TP AGAINST QX226M
MODEL :	F55 COOPER S	DATE REG.: 26.03.2015	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description		QTY	REVISED	PRICES
1	REAR BUMPER		1		\$ 953.19
2	TOWING COVER		1		\$ 46.44
3	REAR BUMPER LOWER CHROME		1		\$ 186.19
4	REAR BUMPER LOWER GRILLE		1		\$ 91.38
5	LOGO "COOPER S"		1		\$ 66.50
6	TAIL LIGHT LH		1		\$ 382.75
7	TAIL LIGHT CHROME RING RH		1		\$ 59.00
8	TAIL LIGHT CHROME RING LH		1		\$ 59.00
9	BLIND RIVET		10		\$ 36.30
10	REAR BUMPER FOG LIGHT		1		\$ 65.25
11	SENSOR PARKASSIST (PAINTED)		1		\$ 475.81
12	SENSOR PARKASSIST (BLACK)		1		\$ 310.88
13	SENSOR		4		\$ 25.24
14	TAIL PIPE CHROME		2		\$ 262.26
15	REAR BUMPER GUIDE LH		1		\$ 108.94
16	CLIP		4		\$ 6.24
17	REAR BUMPER REINFORCEMENT		1		\$ 505.94
18	REINFORCEMENT SEAL		2		\$ 10.88
19	HEX NUT		4		\$ 14.52
TOTAL PARTS					\$ 3,666.71
TOTAL PARTS COST					\$ 3,666.71

Labour Description		
1	TO REMOVE / REPLACE REAR BUMPER & OTHER DAMAGED PARTS & TO REPAIR TAILGATE AREAS AFFECTED BY THE ACCIDENT.	\$ 2,100.00
2	TO RESPRAY REAR BUMPER & TAILGATE.	\$ 1,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 250.00
4	TO TRANSFER THE REVERSE SENSORS.	\$ 500.00

5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00	150
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 350.00	250
7	SUNDRIES.	NETT	\$ 100.00	50
		TOTAL LABOUR	\$ - \$ 5,350.00	
		TOTAL PARTS	\$ - \$ 3,666.71	
		TOTAL	\$ - \$ 9,016.71	
		LESS EXCESS	\$ - \$ -	
		TOTAL AFTER EXCESS	\$ -	
		GST 7%	\$ - \$ -	
		GRAND TOTAL	\$ - \$ -	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultant - please notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged car (s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill will - confirmation is required
- Item(s) must be resurveyed and approved by Insurance Company

Known by Repairer:
Signature:
Date:

NAZ CXX

6/8/18 1030

PIP

AFTER RE

4-5 \$ 1 DAY

BEFORE PAINT PHOTO

6741 8434



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18013862/Nsbs2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE) 1 MOUNT
PLEASANT ROAD BLK 8 OLD POLICE
ACADEMYSINGAPORE 298333

Date : 28-08-2018



ATTN: ABDUL RAHMAN

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 226M	Veh. Inspected	SCZ 5455R
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/092	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	31/07/2018

2. Vehicle Particulars & Condition

Make & Model	MINI COOPER S	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMWXS720102B60388	Colour	GREY
Odometer	40446	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45R17	MICHELIN	6 mm
L/H Front Tyre	205/45R17	MICHELIN	6 mm
R/H Rear Tyre	205/45R17	MICHELIN	6 mm
L/H Rear Tyre	205/45R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/07/2018	Inspection Date	06/08/2018
Survey held at	EUROKARS HABITAT PTE LTD NO.12 SUNGEI KADUT AVE SINGAPORE 729648		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCZ 5455R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	953.19	953.19
1	TOWING COVER	CRACKED	46.44	46.44
1	REAR BUMPER LOWER CHROME	NECESSARY	186.19	186.19
1	REAR BUMPER LOWER GRILLE	BENT	91.38	91.38
1	LOGO "COOPER S"	NECESSARY	66.50	66.50
1	TAIL LIGHT LH	SERVICEABLE	382.75	-
1	TAIL LIGHT CHROME RING RH	CRACKED	59.00	59.00
1	TAIL LIGHT CHROME RING LH	* CHECK	59.00	-
10	BLIND RIVET	NECESSARY	36.30	36.30
1	REAR BUMPER FOG LIGHT	* CHECK	65.25	-
1	SENSOR PARKASSIST (PAINTED)	* CHECK	475.81	-
1	SENSOR PARKASSIST (BLACK)	SERVICEABLE	310.88	-
4	SENSOR	NECESSARY	25.24	25.24
2	TAIL PIPE CHROME	SCRATCHED	262.26	262.26
1	REAR BUMPER GUIDE LH	* CHECK	108.94	-
4	CLIP	NECESSARY	6.24	6.24
1	REAR BUMPER REINFORCEMENT	* CHECK	505.94	-
2	REINFORCMENT SEAL	* CHECK	10.88	-
4	HEX NUT	* CHECK	14.52	-
			3,666.71	1,732.74
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
			100.00	50.00
<u>LABOUR</u>				
TO REMOVE/REPLACE REAR BUMPER & OTHER DAMAGED PARTS & TO REPAIR TAILGATE AREAS AFFECTED BY THE ACCIDENT.			2,100.00	1,680.00
TO RESPRAY REAR BUMPER & TAILGATE.			1,800.00	1,600.00
TO CARRY-OUT BODY CAVITY PRESERVATION.			250.00	150.00
TO TRANSFER THE REVERSE SENSORS.			500.00	420.00
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			250.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	250.00
			5,250.00	4,250.00
	GRAND TOTAL		9,016.71	6,032.74
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,240.34 NETT)			6,032.74

Report Ref No. CS/SPF18013862/Nsbs2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.