

3/2002

S. REC. BY:

REF: CS/CTI18013874 / N/d32

Special Instruction:

rveyor

From (Person):

Ndz

ASSIGNMENT (Office)

of CTI

Date/Time: 30/7/18 @ 5:19pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

GBF 808G

Insured:

SLF 9652K

at Workshop m/s

Automobile Integrated

Tel:

9745 1591

of

28 Sin Ming Lane #07-147 midview city

Policy No:

DMPCSN 3091731701

Claim No:

SNM18D03702002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/07/2018

1/8/17 @ 10am-10:30am

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS (up)

Date/Time:

30/07/18 @ 11:55am

Person Contacted:

shery

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBF 808G - CC4/4C17011720/Uph3n2

DOA: K/6/2017

SLF 9652K - X

13/9/18

LS \$ 2650 confirmed by email (Ref 3601, 58/3)

(08/11/13) wef

ASS-REG-BY:

NAZ

REF: CII

ASSIGNMENT

call her once reach

From:

Date: 01/08/2018

Estimated Cost:

On ☒ TP / ☒ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

GBF 808G

at Workshop m/s

Automobile Integrated

of

28 Sin Ming Lane #07-47

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

10am-10:15am

overwaiting

Make of Veh:

Sherry @ 97451591

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

RECEIVED 14 SEP 2018

ALT L/S.

Veh No: GBF 808G Yr Regn: 22 JUN 2016

Type: M.Car / M.Cycle / Bus ☒ Van ☐ Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HACE 3.0 c.c. 2982

Colour

WHITE

A/C: ☒ Insured / ☐ Std / ☐ NI / NA

Sp. Reading

63837

T/Radio: ☒ Insured / ☐ Std / ☐ NI / NA

Eng/No:

JTFH02P000199370

C/No:

Gen. Cond: Good ☒ Fair ☐ Poor ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

195 R15C

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / ☒ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/7/18

D.O.I.

1/8/18

Survey held at

AUTOMOBILE INTEGRATED

Des. of Damages: Frt / ☒ Rear ☐ O/S / ☐ N/S / ☐ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 13/9- typist

Report Format :

merimen

Lump Sum / I.B.I. (\$

2650k)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

220

Transportation:

S + RS. SI

Photos

Others

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI18013874/Nvd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 31-07-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 9652K	Veh. Inspected	GBF 808G	
Policy No.	DMPCSN3091731701	Coverage (\$)	0.00	
Claim No.	SNM18D03702C02	Excess (\$)	0.00	
Assign From	MERIMEN (HWANG SHIANG YI)	Assign Date	31/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/07/2018	Inspection Date	01/08/2018	
Survey held at	AUTOMOBILE INTEGRATED- 28 SIN MING LANE #01-147			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		30 Jul 2018 17:19 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NEWARK ENGINEERING PTE LTD		
Main Claimant:	JW-MECH ENGINEERING, Co. Reg. No.: 52934724E		
Vehicle Reg. No.:	GBF808G	Date of Loss:	27/07/2018 08:00 - :59
Claim Type:	TP / SNM18D03702C02	Policy/Cover Note No.:	DMPCSN3091731701
Vehicle Reg. No. (Insured):	SLF9652K	Policy No. (Claimant):	2100472189-02
		Excess:	S\$0.00
Repairer:	Automobile Integrated Management Pte Ltd (HQ) 28 SIN MING LANE, #07-147 MIDVIEW CITY, 573972 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/08/2018]		
Adj Asg. Remarks:	PLEASE ARRANGE MARCUS CHUA AS SJE SURVEY ON 31 JULY @2.30PM.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2018 16:15
Date Of Accident	27/07/2018 08:20
Exact Location Of Accident	KJE YEW TEE FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF808G
Insured/Policyholder	
Name Of Registered Owner	JW-MECH ENGINEERING
Co Reg No	52934724E
Email Address	JW-MECH2000@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-66943554

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	ON THE WAY TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	2100472189-02
Cover Note Number	

Driver

Name of Driver	WANG WAI LEONG
NRIC No	S1522339A
Date Of Birth	31/03/1962
Occupation	OUTDOOR
Date Of Driving Pass	03/03/1982
Driving Experience	36 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90305263
Fax Number	
Contact Number	
Email Address	JW-MECH2000@HOTMAIL.COM

Address	BLK 431B YISHUN AVENUE 1 #12-591
Postcode	762431
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE TO LOAD VIDEO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF9652K
Vehicle Make/Model/Colour	TOYOTA AXIO SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE JIAN TECK
NRIC/Passport Number	S9216270B
Contact Number	96897533
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT PORTION
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be completed by the **Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the individual companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available if/when:
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and declare that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insured(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) investigating, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions in responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as to the external carrier of any postal mail package); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes";
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/has been disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sites outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (b) above may be shared:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Insured's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Witness's Signature
Name: **BEIRN**
Address: **3777057**

Sketch Plan #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHMENT

DECLARATION

I hereby declare that the information provided is true and correct.



Signature of Engineer

[Signature]

Signature of the person who
provided the information
(Name & Title)

[Signature]


Signature of the person who
provided the information
(Name & Title)
Bren
S7870002

Sketch Plan #3

GBF 808 G
 TOYOTA HIACE
 JH-MECH ENGINEERING
 WANG WA LEOH
 S1522339A

SIF 9652 K
 TOYOTA AXIO
 LEE JIAN TECK
 S9216270 B

KIE YEW TEE FLYOVER



Heavy jam at KIE, Yew Tee Flyover towards Tuas due to earlier accident near exit to Choa Chu Kang Drive. My van GBF 808 G follows the jam thereafter signal to change lane No 2 to No 4 as behind vehicle SIF 9652 K is 2 to 3 vehicles empty space away. After changing lane and stop, behind vehicle SIF 9652 K hit on my van back and damaged the back panel door and bumper on Friday 27-07-2018 at around 8.22 am

ESTIMATE

VEHICLE NO : GBF808G
MAKE/MODEL: TOYOTA HIACE 3.0
DATE OF REG: 22/6/2016
DATE OF ACCT: 27/7/2018

ITEM	DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
1	1 TAIL GATE <i>2051.60</i>		1,955.00 <i>BT</i>
2	1 TAIL GATE WEATHERSTRIP		330.00 <i>ASV</i>
3	1 TAIL GATE LOCK		509.00 <i>BUC</i>
4	1 REAR BUMPER <i>466.00 25%</i>		577.00 <i>DT</i>
<u>SPECIAL NETT</u>			
1	1 TAIL GATE WINDSCREEN GLASS MOULDING	X 90.00	<i>one m</i>
2	1 TAIL GATE WINDSCREEN GLASS SEALANT	X 50 90.00	<i>one m</i>
3	1 STICKER 70KM/H	15 25.00	<i>one</i>
4	1 STICKER 6PAX	15 25.00	<i>one</i>
5	1. Reverse sensor	200 300.00	<i>one</i>
<u>LABOUR & MISCELLANEOUS:</u>			
1	To remove damaged body panels with all necessary components/attachments apply hot-works where necessary straighten rear floor panel repair/reshape dented panels in accordance with factory specifications, replace new parts refit align into position refit all necessary components/attachments		1,000.00 <i>400</i>
2	To spray paint replaced/repared body panels inclusive of preparatory works and painting materials		1,000.00 <i>400</i>
3	To remove/refit rear windscreen glass and water test		150.00 <i>50</i>
4	To transfer tail gate components with all necessary components		150.00 <i>50</i>
NA2 LKK 1/8/18 1045 L/S. 3 days <i>After repair photo</i>			6251
Total \$			5,901.00

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 13 September 2018 4:21 PM
To: 'AIM'
Cc: Naz (LKKAUTO); SUR
Subject: RE: GBF 808G After Repair Photos

Dear Sir,

Noted with thanks.

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: AIM <automim.claim@gmail.com>
Sent: Thursday, 13 September 2018 2:33 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Naz (LKKAUTO) <Naz@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: GBF 808G After Repair Photos

We accept the offer.

On Wed, Sep 12, 2018 at 11:31 AM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$2650/- @ 3 working days

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: AIM <automim.claim@gmail.com>
Sent: Tuesday, 11 September 2018 4:00 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Naz (LKKAuto) <Naz@lkkauto.com>
Subject: Re: GBF 808G After Repair Photos

Hi Veron

Attached the photos.

On Monday, September 10, 2018, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Sir,

Vehicle completed?

If yes, please forward us after paint photos and finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Automobile Integrated Management Pte Ltd <automim.claim@gmail.com>
Sent: Thursday, 23 August 2018 10:25 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: GBF 808G After Repair Photos

Hi

The repair is not complete yet. Will email you the photos when ready.

On Thu, Aug 23, 2018 at 10:14 AM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Sir,

Kindly advise vehicle status.

If vehicle has been repaired, please forward us after paint photos and finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Naz (LKKAUTO)
Sent: Thursday, 23 August 2018 10:08 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Fw: GBF 808G After Repair Photos

From: Naz (LKKAUTO)
Sent: Tuesday, 7 August 2018 12:51 PM
To: automim.claim@gmail.com
Cc: Veron Chen (LKKAUTO)
Subject: GBF 808G After Repair Photos

To whom it may concern

This is Investigator Naz from LKK Auto Consultants. Kindly provide the after repair photos so that I can finalize the repair.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2018		30 Jul 2018 17:19 Edit Adj Rpt	\$2,650.00 Edit Estimates	\$2,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NEWARK ENGINEERING PTE LTD, Co. Reg. No.: -								
Main Claimant:	JW-MECH ENGINEERING, Co. Reg. No.: 52934724E								
Vehicle Reg. No.:	GBF808G	Date of Loss:	27/07/2018 08:00 - :59 [25 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03702C02	Policy/Cover Note No.:	DMPCSN3091731701						
Vehicle Reg. No. (Insured):	SLF9652K	Policy No. (Claimant):	2100472189-02						
		Excess:	\$0.00						
Repairer:	Automobile Integrated Management Pte Ltd (HQ) 28 Sin Ming Lane, #07-147 Midview City, 573972 Bishan - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 08/08/2018]								
Adj Asg. Remarks:	PLEASE ARRANGE MARCUS CHUA AS SJE SURVEY ON 31 JULY @2.30PM.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF808G (SNM18D03702C02)**
[SLF9652K]
TP
JW-MECH ENGINEERING
Jul 27 2018 8:00AM
[NEWARK ENGINEERING PTE LTD]
Automobile Integrated Management Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
1	28/07/18 14:08	Accident Statement	 Load HTM	
2	28/07/18 14:16	Addendum Sheet	 Load TIF	
3	28/07/18 14:16	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
1	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
11	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
12	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
13	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
14	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
15	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
16	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
17	28/07/18 13:38	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
18	28/07/18 13:39	Driving License [Linked Accident Report Documents]	 Load JPG	☒
19	28/07/18 13:39	Identification Card [Linked Accident Report Documents]	 Load JPG	☒
20	28/07/18 13:45	Driving License [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/08/18 00:43	General View	 Load JPG	☒
2	04/08/18 00:43	General View	 Load JPG	☒
3	04/08/18 00:43	General View	 Load JPG	☒
4	04/08/18 00:43	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
5	04/08/18 00:43	General View	Load JPG	☒
6	04/08/18 00:43	General View	Load JPG	☒
7	04/08/18 00:43	General View	Load JPG	☒
8	04/08/18 00:43	General View	Load JPG	☒
9	04/08/18 00:43	General View	Load JPG	☒
10	04/08/18 00:43	General View	Load JPG	☒
11	04/08/18 00:43	General View	Load JPG	☒
12	04/08/18 00:43	General View	Load JPG	☒
13	04/08/18 00:43	General View	Load JPG	☒
14	04/08/18 00:43	General View	Load JPG	☒
15	04/08/18 00:43	General View	Load JPG	☒
16	04/08/18 00:43	General View	Load JPG	☒
17	12/09/18 11:01	Reinspection Photo	Load JPG	☒
18	12/09/18 11:01	Reinspection Photo	Load JPG	☒
19	12/09/18 11:01	Reinspection Photo	Load JPG	☒
20	12/09/18 11:01	Reinspection Photo	Load JPG	☒
21	12/09/18 11:01	Reinspection Photo	Load JPG	☒
22	12/09/18 11:01	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/07/18 17:16	TP NOTIFICATION	Load PDF	
2	30/07/18 17:18	OI REPORT	Load PDF	
3	31/07/18 11:55	TP NOTIFICATION	Load PDF	
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
1	28/07/18 13:59	Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
2	28/07/18 13:59	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	☒
3	28/07/18 13:59	Sketch Plan #3 [Linked Accident Report Documents]	Load JPG	☒
4	28/07/18 14:02	INSURANCE RENEW LETTER [Linked Accident Report Documents]	Load TIF	
5	28/07/18 14:03	INSURANCE CERT [Linked Accident Report Documents]	Load TIF	
6	28/07/18 14:04	INSURANCE POLICY [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
1	28/07/18 14:08	Accident Statement	Load HTM	
2	28/07/18 14:16	Addendum Sheet	Load TIF	
3	28/07/18 14:16	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
1	28/07/18 13:38	Accident Photo	Load JPG	☒
2	28/07/18 13:38	Accident Photo	Load JPG	☒
3	28/07/18 13:38	Accident Photo	Load JPG	☒
4	28/07/18 13:38	Accident Photo	Load JPG	☒
5	28/07/18 13:38	Accident Photo	Load JPG	☒
6	28/07/18 13:38	Accident Photo	Load JPG	☒
7	28/07/18 13:38	Accident Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
8	28/07/18 13:38	Accident Photo	 Load JPG	☒
9	28/07/18 13:38	Accident Photo	 Load JPG	☒
10	28/07/18 13:38	Accident Photo	 Load JPG	☒
11	28/07/18 13:38	Accident Photo	 Load JPG	☒
12	28/07/18 13:38	Accident Photo	 Load JPG	☒
13	28/07/18 13:38	Accident Photo	 Load JPG	☒
14	28/07/18 13:38	Accident Photo	 Load JPG	☒
15	28/07/18 13:38	Accident Photo	 Load JPG	☒
16	28/07/18 13:38	Accident Photo	 Load JPG	☒
17	28/07/18 13:38	Accident Photo	 Load JPG	☒
18	28/07/18 13:39	Driving License	 Load JPG	☒
19	28/07/18 13:39	Identification Card	 Load JPG	☒
20	28/07/18 13:45	Driving License 3RD PARTY DRIVING LICENCE	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Diplomat Parts Pte Ltd (HQ)	Thumbnail	Print
1	28/07/18 13:59	Sketch Plan	 Load JPG	☒
2	28/07/18 13:59	Sketch Plan #2	 Load JPG	☒
3	28/07/18 13:59	Sketch Plan #3	 Load JPG	☒
4	28/07/18 14:02	INSURANCE RENEW LETTER	 Load TIF	
5	28/07/18 14:03	INSURANCE CERT	 Load TIF	
6	28/07/18 14:04	INSURANCE POLICY	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18013874/NVD3E2

Date: 14/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3091731701

Claimant Vehicle
No: GBF808GInsured Vehicle
No: SLF9652K

Date of Loss: 27/07/2018

Nature of Claim: TP

Claim
No: SNM18D03702C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF808G

Make & Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD2624438

Reg. Date: 22/06/2016 (Man. Year: 2016)

Chassis No: JTFHT02P000199370

Colour: White

Odometer: 63837 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Sumitomo 7 mm

Rear Left Side: Sumitomo 7 mm

Front Right Side: Sumitomo 7 mm

Rear Right Side: Sumitomo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,951.00	2,427.65	1,523.35	38.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	900.00	1,400.00	60.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,251.00	3,327.65	2,923.35	46.77
Approved Total (Overridden) (\$\$)		2,650.00		
Nett Amount (\$\$)	6,251.00	2,650.00	3,601.00	57.61

INSPECTION

Date of Assignment: 30/07/2018

Date Inspected: 01/08/2018 Inspected At:

Automobile Integrated Management Pte
Ltd (HQ)
28 Sin Ming Lane, #07-147 Midview City
Singapore 573972

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Sep 2018)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF808G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,955.00 F	*1,955.00 FL
2	1		*TAIL GATE WEATHERSTRIP	Serviceable	330.00 F	*- FL
3	1		*TAIL GATE LOCK	Buckled	509.00 F	*509.00 FL
4	1		*REAR BUMPER	Dented	577.00 F	*466.20 FL
5	1		*TAIL GATE WINDSCREEN GLASS MOULDING	Not Necessary	90.00 FS	*- FS
6	1		*TAIL GATE WINDSCREEN GLASS SEALANT	Not Necessary	90.00 FS	*- FS
7	1		*STICKER 70KM/H	Necessary	25.00 FS	*15.00 FS
8	1		*STICKER 6PAX	Necessary	25.00 FS	*15.00 FS
9	1		*REVERSE SENSOR	Necessary	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,951.00	3,160.20
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	732.55

Total Parts (S\$)	3,951.00	2,427.65
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PANELS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN REAR FLOOR PANEL REPAIR / RESHAPE DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATION, REPLACE NEW PARTS REFIT ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS	New	1,000.00	400.00
2	TO SPRAY PAINT REPLACED / REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	400.00
3	TO REMOVE / REFIT REAR WINDSCREEN GLASS AND WATER TEST	New	150.00	50.00
4	TO TRANSFER TAIL GATE COMPONENTS WITH ALL NECESSARY	New	150.00	50.00
Gross Labour Cost (S\$)			2,300.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >