

ASS. REC. BY:

REF: CS3/ALG18013887/Kzad307 Special Instruction:

Surveyor  
nummen

Kalvin

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

31/7/18 @ 1:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 7405U

Insured:

SDN 21884

at Workshop m/s

Michelin Engineering

Tel:

8181 0737 / 97 97 3039

of

56 layang way # 06-07

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/07/2018

20/8/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

31/7/18 @ 2:04pm

Person Contacted:

Rizan

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate	
	GBE 7405U - X	10/8/18 - vehicle not in (Rizan)
	SDN 21884 - X	14/8/18 - vehicle still not in (Rizan)
01/08/18 -	called wesp vehicle not in.	he say will get back to me.
3/8/18 -	called wesp no one answered at all.	
17/8/18 -	called repairer arrange on 20/8/18	

(08/11/13) wef

REF:

AIG

ASS. REC. BY:

## ASSIGNMENT

From: \_\_\_\_\_ Date: 20/8/18

Estimated Cost: \_\_\_\_\_

OP / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBE 7405 U

at Workshop m/s

Michelin Engineering

of 56 Loyang way # 06-07

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 14

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBE 74054 Yr Regn: 14 Mar 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan c.c. 1467

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 92420 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VSKYBAM2020/22023

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 185 / 70R14

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Brightway

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/7/18 D.O.I. 20/8/18

Survey held at Michelin Engineering

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt 4 n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No Ex

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: DAR

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

180

20

200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18013887/K1z4d3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 31-07-2018



Code : AIG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SDN 2188H	Veh. Inspected	GBE 7405U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	31/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	28/07/2018	Inspection Date	20/08/2018
Survey held at	MICHELIN ENGINEERING PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

## 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Your password will expire in 13 days. [Click here to change it.](#)

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VE...**

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, Admin A  
Cc: Fong, Andy-SY  
Sent: 31/7/2018 1:49:31 PM  
Attachments:  180731 GIA-GBE7405U (ins).pdf

Hi LKK,

Please assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**From:** Yvonne [mailto:yvonne@ealc.com.sg]  
**Sent:** Tuesday, July 31, 2018 10:22 AM  
**To:** Mithoosingh, Aashweenjeetkaur  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi  
**Subject:** PRI AIG Insured SDN2188H [EAL.2018.5831.MK.ya - GBE7405U]

Our ref : 2018.5831.MK.ya - GBE7405U  
Your ref : SDN2188H

PLEASE REPLY VIA EMAIL ([yvonne@ealc.com.sg](mailto:yvonne@ealc.com.sg))

AIG Asia Pacific Insurance Pte Ltd  
No. 78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Department  
**2 DAYS' PRE-REPAIR NOTICE**

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd		
Vehicle <b>GBE7405U</b> inspected as follows by Name:		
Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

**NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE**

**CLAIMANT: PAN PACIFIC VAN & TRUCK LEASING PTE LTD**

**ACCIDENT INVOLVING GBE7405U & SDN2188H ON 28 JULY 2018 ALONG JALAN LEBAN X JALAN TARUM AT ABOUT 1415 HOURS**

We refer to the above matter wherein we are instructed to act for **PAN PACIFIC VAN & TRUCK LEASING PTE LTD**, the owner of vehicle no. **GBE7405U**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **GBE7405U** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Michelin Engineering Pte Ltd  
56 Loyang Way,  
#06-07 Loyang Enterprise Building,  
Singapore 508775  
Contact: Rizan-81810737 / Mas-97973039

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,  
Yvonne Ang

East Asia Law Corporation  
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413  
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

---

**From:** Mithoosingh, Aashweenjeetkaur  
**Sent:** Tuesday, July 31, 2018 10:16 AM  
**To:** Yvonne  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi  
**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDN2188H AND GBE7405U ON 28/07/2018

Without Prejudice

Your Reference : 2018.5831.MK.ya - **GBE7405U**  
Our Reference : SDN2188H

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services

EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

---

**From:** Yvonne [mailto:yvonne@ealc.com.sg]

**Sent:** Tuesday, July 31, 2018 9:55 AM

**To:** Chan, Yoke Shi

**Cc:** Lim, Sheng Yang; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur

**Subject:** AIG Insured SDN2188H [EAL.2018.5831.MK.ya - GBE7405U]

Our ref : 2018.5831.MK.ya - GBE7405U

Your ref : SDN2188H

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

AIG Asia Pacific Insurance Pte Ltd

No. 78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Department

**NOTICE OF ACCIDENT**

For your information only

Owner of SDN2188H

Linda Oh Ah Hwa

21 Jalan Tarum

Singapore 576740

Dear Sir/Madam,

**CLAIMANT: PAN PACIFIC VAN & TRUCK LEASING PTE LTD**

**ACCIDENT INVOLVING GBE7405U & SDN2188H ON 28 JULY 2018 ALONG JALAN LEBAN X JALAN TARUM AT ABOUT 1415 HOURS**

We are instructed by **PAN PACIFIC VAN & TRUCK LEASING PTE LTD** to notify you (the insurer of **SDN2188H**) of a road traffic accident on **28 JULY 2018 ALONG JALAN LEBAN X JALAN TARUM AT ABOUT 1415 HOURS** involving our client's vehicle registration number **GBE7405U** and vehicle registration number **SDN2188H** driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle **GBE7405U** has been damaged. Before our client proceed to repair the damaged vehicle:

1. Please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle; and
2. Please forward a copy of your insured's report.

Our client proposes to use one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

3. Dennis Yap Teck Wee - Pal's Appraiser Pte Ltd
4. Yap Teck Chye - Mc-Coy appraiser Pte Ltd

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,  
Yvonne Ang

East Asia Law Corporation  
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413  
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	1635R
<b>Vehicle Details</b>	
Vehicle No.:	GBE7405U
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K9KC400D055255
Chassis No.:	VSKYBAM20Z0122023
Maximum Power Output:	-
Open Market Value:	\$19,981.00
Original Registration Date:	14 Mar 2016
First Registration Date:	14 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$1,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,859.00
COE Rebate Amount:	\$28,335.00
<b>Total Rebate Amount:</b>	<b>\$28,335.00</b>

The information contained herein is correct as at 17 Sep 2018

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/07/2018 16:55
Date Of Accident	28/07/2018 14:15
Exact Location Of Accident	JALAN LEBAN X JALAN TARUM
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE7405U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PAN PACIFIC VAN & TRUCK LEASING PTE LTD
Co Reg No	201511635R
Email Address	PANPACIFICLEASING22@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64404428
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	NV200
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5074863750-02
Cover Note Number	

### Driver

Name of Driver	TERRY QUAH TECK GUAN
NRIC No	S7507498J
Date Of Birth	09/03/1975
Occupation	OUTDOOR
Date Of Driving Pass	23/05/1996
Driving Experience	22 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98387582
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 407 SIN MING AVENUE #10-219 S570407
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDN2188H
Vehicle Make/Model/Colour	NIL
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	LINDA OH AH HWA
NRIC/Passport Number	S1513317A
Contact Number	91019821
Address	21 JALAN TARUM SINGAPORE
Postcode	576740
Insurance Company Name	
Nature Of Damage	NIL
No. Of Passenger (Including Driver)	1

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

PAN PACIFIC LEASING LLP  
Co. Reg. No. T146L0530K  
NO. 32 JOO CHAT ROAD, SINGAPORE 437374  
TEL: 6449 4428 FAX: 6545 8616  
Email: [panpacificleasing@panpacificleasing.com.sg](mailto:panpacificleasing@panpacificleasing.com.sg)

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)


Date & Time: 28/7/18  
3:43 pm

Reporting Centre Personnel's Signature  
Name:

NRIC/FIN No.: 28.7.2018

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was going straight along Jalan Ledan suddenly a car (SDN2188H) came out from Jalan Tarum and hit my vehicle.

### DECLARATION

I, HEREBY DECLARE that:-

1. The reporting centre personnel has explained the above statement & sketch plan to me.
2. I fully understand and agree with the above statement.
3. The information given is true and correct to best of my/our knowledge and belief.

*[Signature]*  
Name: Signature & company  
Company: [blank]

GBE740SU

28.7.2018

- ☐ Reporting Only
- ☐ Own Damage Claim
- ☒ Third Party Claim
- ☐ Other Workshop

### DECLARATION

We declare the foregoing particulars are true in every respect

PAN PACIFIC LEASING LLP  
Co. Reg. No: T14/L00596  
NO. 52 JOO CHAT ROAD, SINGAPORE 427324  
TEL: 6440 4428 FAX: 6346 6616  
Email: panpacificleasing@panpacificleasing.com.sg

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

28/07/18  
3.43 pm

Reporting Centre Personnel's Signature

Name: [blank]  
NRIC/FIN No: 28.7.2018

## Condition (CON)

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched (07) Deformed  
 (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn  
 (14) Unconfirmed (15) Not Working

## VAN / LORRY (Fr)

## ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (0)  
 (4) Not Consistent (NC)

Aug 2005

## Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frnt Number Plate			
1002	991887	Frnt Number Plate Base			
1004	991300	Frnt Bumper	BR	✓	
2001	991477	Frnt Bumper Retainer LH	DIS	✓	
2002	991387	Frnt Bumper Tow Eye Cover	CUT	✓	
2003	991449	Frnt Bumper Side Cover			
2004	991443	Frnt Bumper Clips	NEC	✓	6
1006	991325	Frnt Bumper Bracket			
1008	991433	Frnt Bumper Reinforcement	DD	✓	
2005	991466	Frnt Bumper Spanje	CRA	✓	
1017	995100	Frnt LH Bumper Fog Lamp Cover	CUT	✓	
1018	991355	Frnt RH Bumper Fog Lamp Cover			
1019	995079	Frnt LH Bumper Fog Lamp			
1020	995080	Frnt RH Bumper Fog Lamp	CRA	✓	
1021	991793	Frnt Grille	CRA	✓	
1022	991328	Frnt Grille Emblem	NEC	✓	
2006	990247	Frnt Grille Lower Garnish	DIS	✓	
1023	991799	Frnt Grille Chrome Moulding			
2007	991891	Frnt Panel			
2008	991874	Frnt Lower Panel			
2009	991328	Frnt Panel Emblem			
2010	990247	Frnt Panel Sticker			
2011	991893	Frnt Panel Garnish			
1024	991222	Frnt Apron Panel			
2012	991527	Frnt Corner Panel			
2013	991532	Frnt Corner Panel Signal Lamp			
2014	995245	Frnt Signal Lamp LH			
2015	995246	Frnt Signal Lamp RH			
1029	995153	Frnt LH Headlamp Assy	CUT	✓	
1030	991821	Frnt RH Headlamp Assy	?		
1031	995088	Frnt LH Side Lamp			
1032	995089	Frnt RH Side Lamp			
2016	992149	Frnt Wiper Panel			
2017	995043	Frnt Wiper Nozzle			
1120	992140	Frnt Wiper Arm			
1121	992142	Frnt Wiper Blade			
2018	992145	Frnt Wiper Link			
2019	992148	Frnt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frnt Windscreen			
1115	992097	Frnt Windscreen Rubber			
1117	992098	Frnt Windscreen Sealant			
2020	992114	Frnt Windscreen Outer Pillar			
2021	992113	Frnt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frnt Side Mirror (Big)			
2023	991959	Frnt Side Mirror (Small)			
2024	991962	Frnt Side Mirror (Round)			
2025	995015	Frnt Wing Mirror Stay			
1025	992013	Frnt Support Panel	BT R	✓	
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser	?		
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator	?		
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

Vehicle No: GBE 74054

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frnt Cabin Assy			
2028	991501	Frnt Cabin Mounting			
2029	991502	Frnt Cabin Rear Panel			
1092	991520	Frnt LH Chassis Member			
1093	991520	Frnt RH Chassis Member			
1094	990728	Frnt Vertical Cross Member			
1095	991863	Frnt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frnt RH Seat Belt Assy			
1135	995182	Frnt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frnt LH Fender	DD R	✓	
1097	995072	Frnt LH Fender Inner Panel	BT R	✓	
1100	991740	Frnt LH Fender Inner Shield	CRA	✓	
1101	995179	Frnt LH Mudflap			
2035	994966	Frnt LH Wheel Guard			
1102	995170	Frnt LH Wheel Rim			
1104	995065	Frnt LH Tyre			
1105	995071	Frnt RH Fender			
1106	991739	Frnt RH Fender Inner Panel			
1109	991740	Frnt RH Fender Inner Shield			
1110	991884	Frnt RH Mudflap			
2036	994966	Frnt RH Wheel Guard			
1111	992087	Frnt RH Wheel Rim			
1113	995065	Frnt RH Tyre			
1255	995326	Frnt LH Door			
1256	995140	Frnt LH Door Protector			
1257	995104	Frnt LH Door Hinge			
1258	995142	Frnt LH Door Wing Mirror			
1262	995103	Frnt LH Door Glass			
1263	991595	Frnt LH Door Glass Regulator			
1264	991596	Frnt LH Door Glass Regulator Motor			
1265	991662	Frnt LH Door Rubber			
1266	991636	Frnt LH Door Outer Handle			
1272	991617	Frnt LH Door Inner Trim Board			
1316	995327	Frnt RH Door			
1317	991654	Frnt RH Door Protector			
1318	991601	Frnt RH Door Hinge			
1319	991685	Frnt RH Door Wing Mirror			
1323	991584	Frnt RH Door Glass			
1324	991595	Frnt RH Door Glass Regulator			
1325	991596	Frnt RH Door Glass Regulator Motor			
1326	991662	Frnt RH Door Rubber			
1327	991636	Frnt RH Door Outer Handle			
1333	991617	Frnt RH Door Inner Trim Board			
2037	991644	Frnt Door Frt Pillar			
2038	991657	Frnt Door Rear Pillar			
2039	992072	Frnt Wheel Arch Panel			
2040	992069	Frnt Wheel Arch Panel Garnish			
2041	991996	Frnt Step Panel			
2042	994498	Frnt Step Panel Top Garnish			
2043	994495	Frnt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		LH Headlamp Lower Bracket	?		

No of Items:

Assessor:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jul 2018 <a href="#">Edit Reg</a>		31 Jul 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	LINDA OH AH HWA, ID: S1513317A		
Main Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD, Co. Reg. No.: 201511635R		
Vehicle Reg. No.:	GBE7405U	Date of Loss:	28/07/2018 00:00 - :59 [28 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2984111622SG	Policy/Cover Note No.:	2100486776 (Comprehensive)
Vehicle Reg. No. (Insured):	SDN2188H	Policy No. (Claimant):	
		Excess:	
Repairer:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way,, #06-07 Loyang Enterprise Building,, 508775 Loyang - Tel: 64404428		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN ] ... [Final Rpt due 15/08/2018]		

**ASSOCIATED MAIL RECEIVED** View All Compose Case Mail

- AIG\_SG (06/08/2018): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*GBE7405U (2984111622SG)**  
**[SDN2188H]**

**TP**

**PAN PACIFIC VAN & TRUCK LEASING PTE LTD**




















**Jul 28 2018 12:00AM**

**[LINDA OH AH HWA]**

**Michelin Engineering Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>		<b>View</b> <a href="#">View in Browser</a>
<b>Assessment Reports</b>		1 per page <input type="checkbox"/>
No	Finalized On	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> <b>Accident Statement</b> From:OD - Reg. No: SDN2188H, Claimant: LINDA OH AH HWA
1	06/08/18 10:41	<div style="display: flex; align-items: center;"> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div> <div>Load HTM</div> </div>
<b>Photos/Images</b>		3 per page <input type="checkbox"/>
No	Relabel/Reorder	<b>LKK Auto Consultants Pte Ltd (HQ)</b> <b>General View</b>
1	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
2	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
3	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
4	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
5	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
6	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
7	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
8	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
9	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
10	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
11	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
12	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
13	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
14	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
15	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
16	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
17	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
18	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
19	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
20	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
21	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
22	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
23	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
24	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
25	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
26	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
27	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
28	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
29	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
30	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
31	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
32	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>
33	20/08/18 17:21	<div style="display: flex; align-items: center;"><div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div>Load JPG</div>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	20/08/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/08/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/08/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/08/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/08/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/08/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	05/09/18 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18013887/K1Z4D3E2

Date: 18/09/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100486776

Claimant Vehicle No : GBE7405U

Insured Vehicle No : SDN2188H

Date of Loss: 28/07/2018

Nature of Claim: TP

Claim No: 2984111622SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBE7405U

Make &amp; Model: NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)

Engine No: K9KC400D055255

Reg. Date: 14/03/2016 (Man. Year: 2015)

Chassis No: VSKYBAM20Z0122023

Colour: White

Odometer: 92420 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: Brightway 6 mm

Rear Left Side: Brightway 6 mm

Front Right Side: Brightway 6 mm

Rear Right Side: Brightway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 31/07/2018

Date Inspected: 20/08/2018 Inspected At:

Michelin Engineering Pte Ltd (HQ)  
56 Loyang Way., #06-07 Loyang  
Enterprise Building,  
Singapore 508775

Estimated Period of Repair: 4.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	1		*FRT BUMPER RETAINER LH	Distorted	0.00 F	*- F
3	1		*FRT BUMPER TOW EYE COVER	Cut	0.00 F	*- F
4	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
7	1		*FRT LH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
8	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*- F
9	1		*FRT GRILLE	Cracked	0.00 F	*- F
10	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
11	1		*FRT GRILLE LOWER GARNISH	Distorted	0.00 F	*- F
12	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F
13	1		*FRT RH HEADLAMP ASSY	* Check	0.00 F	*- F
14	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
15	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
16	1		*RADIATOR	* Check	0.00 F	*- F
17	1		*FRT LH FENDER	Repair	0.00 F	*- F
18	1		*FRT LH FENDER INNER PANEL	Repair	0.00 F	*- F
19	1		*FRT LH FENDER INNER SHIELD	Cracked	0.00 F	*- F
20	1		*LH HEADLAMP LOWER BRACKET	* Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >