

Surveyor  
menimen

Taufik

ASSIGNMENT (Office)

From (Person):

Elaine cheong

of

CTI

Date/Time:

31/7/18 @ 9:31am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 955G

Insured:

SKE 655D

at Workshop m/s:

Premium Auto

Tel:

6690 0293

of

281 Alexandra Rd

Policy No:

DMPCS N1648601701

Claim No:

SNM18D03670C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/07/2018

CA / REV / REP. / REV 24 HRS

1up

Insp: 24 Benoi sector

3/8/18 @ 8pm owner waiting

H.O.D. Endorsement:

Date/Time:

31/7/18 @ 11:21am

Person Contacted:

Kee Siang

Vehicle-IN

(OUT)

Date/Time

Action/Instruction (✓) Estimate

SLD 955G-X

SKE 655D-CC3/CTI18010028/Kleb3n2

DOA: 31/5/2018

18/04/19

@ 14:20 p.m. check with Kee Siang, Pending liability. Vehicle has not repair.

(08/11/13) wef

ASS. REC. BY:

REF: CT1

## ASSIGNMENT

From:

Date:

3/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLD 955G

at Workshop m/s

Premium

of

24 Benoi Sector

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

3pm @ owner waiting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

92D955G

Yr Regn:

2016 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216D

c.c

1496

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

44397

T/Radio:

Insured / Std / NI / NA

Eng/No:

WBA21332020V.25915

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205 / 60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

3/8/18 @ 340pm

Survey held at

Premium Benoi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 10 APR 2019

Date/Time, File Pass to?

18/04/19



Preli. Report



Final Report

1)

Typ. 52

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

/

Survey Fee:

220

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Print

Lump Sum / I.B.I. (\$

)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18013888/T1sd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 31-07-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKE 655D	Veh. Inspected	SLD 955G
Policy No.	DMPCSN1648601701	Coverage (\$)	0.00
Claim No.	SNM18D03670C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	31/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	24/07/2018	Inspection Date	03/08/2018
Survey held at	24 BENOI SECTOR		
Repairer	PREMIUM AUTOMOBILES PTE LTD		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		31 Jul 2018 09:31 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	CHUA TOH CHOON, ID: S1605111Z		
Vehicle Reg. No.:	SLD955G	Date of Loss:	24/07/2018 13:00 - :59
Claim Type:	TP / SNM18D03670C02	Policy/Cover Note No.:	DMPCSN1648601701
Vehicle Reg. No. (Insured):	SKE655D	Policy No. (Claimant):	5091301973-01
		Excess:	S\$0.00
Repairer:	Premium Autocare Centre (Alexandra) 281 Alexandra Road, 159938 Alexandra - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/08/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

---

**From:** Claims Autocare <claims@premiumautocare.com.sg>  
**Sent:** Saturday, 28 July, 2018 10:17 AM  
**To:** Claims Dept of CTI  
**Cc:** claims@premiumautocare.com.sg  
**Subject:** ACCIDENT INVOLVING SLD 955 G AND YOUR INSURED SKE 655 D DATED ON 24/07/2018  
**Attachments:** SKM\_364e18072810142.pdf

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report for direct settlement for your reference.

We will forward you the estimate once is available.

Kindly arrange the appt of survey on 03/08/2018, Friday, 3 pm. Owner waiting.

Address : 24 Benoi Sector, Singapore 629857

Thank You.

Best Regards,  
**George Wong**  
Claims Advisor

**Premium Autocare Centre**  
281 Alexandra Road, Singapore 159938  
p. +65 6690 0293 f. +65 6471 3733  
e. [claims@premiumautocare.com.sg](mailto:claims@premiumautocare.com.sg) w. [www.premiumautocare.com.sg](http://www.premiumautocare.com.sg)

### Premium Autocare Centre

The only Auto body shop in South East Asia certified in Carbon Fibre Reinforced Polymer repairs, aluminium and chassis straightening.



#### Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/07/2018 17:16
Date Of Accident	24/07/2018 13:20
Exact Location Of Accident	TAMBAK JOHOR MALAYSIA
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD955G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA TOH CHOON
NRIC No	S1605111Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96221882
Alternative Phone No	OTHERS-96221882

### Vehicle Particulars

Manufacturer	BMW
Model	216D
Exact Purpose for which vehicle was being used at time of accident	LEISURE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091301973-01
Cover Note Number	DRIVO PREMIUM

### Driver

Name of Driver	CHUA TOH CHOON
NRIC No	S1605111Z
Date Of Birth	02/03/1963
Occupation	INDOOR
Date Of Driving Pass	19/11/1986
Driving Experience	31 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96221882
Fax Number	
Contact Number	OTHERS-96221882
Email Address	NOEMAIL

Address	BLK 705 #12-255 HOUGANG AVENUE 2
Postcode	530705
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TRAFIK JOHOR BAHRU
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to police report

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE655D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report No: MT/

D.O.A: 24-07-2018

Time: 13:20 hrs

Report Date & Start Time: 25-07-2018 / 17:26

Vehicle No: SLD955G

Reporting Type:

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
25-07-18 / 17:26  
Policyholder's Signature / Date & Time


25-07-18 / 17:26  
Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre

  
Witnessed by Reporting Centre Personnel



SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report


Declaration

I/We declare the foregoing particulars are true in every respect.

  
25-07-18 / 17:26  
Policyholder's Signature / Date & Time

25-07-18 / 17:26  
Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre

  
Witnessed by Reporting Centre Personnel

Salinan Repot Polis



# POLIS DIRAJA MALAYSIA REPOT POLIS

Balai	TRAFFIK JOHOR BAHRU(S)	Pegawai Penyiasat	R92851
Daerah	JBAHRU SELATAN		
Kontinjen	JOHOR		
No Repot	TRAFFIK JOHOR BAHRU(S)/017566/18		
Tarikh	24/07/2018		
Waktu	1334 PM		
Bahasa Diterima	B. Malaysia		
Butir-butir Penerima Repot		No Personal : R197734	Pangkat : KONST/P
Nama : MUHAMAD FAIZUL BIN MAT YA			
Butir-butir Jurubahasa (Jika Ada)		No K/P (Baru) : --	No Polis/Tentera : --
Nama : --		Bahasa Asal : --	
No Pasport : --			
Alamat : --			
Butir-butir Pengadu			
Nama : CHUA TON CHOON		No Polis/Tentera : --	No Pasport : E8409596H
No K/P (Baru) : --			
No Sijil Beranak : --			
Jantina : Perempuan	Tarikh Lahir : 02/03/1963		Umur : 55 tahun 4 bulan
Keturunan : Cina	Warganegara : Singapore		
Pekerjaan : SIVASTA			
Alamat Tempat Tinggal : 705# 12-255 HOUGANG AVE2 SINGAPORE. 530705			
Alamat Ibu/Bapa : --			
Alamat Pejabat : --			
No Tel (Rumah) : --	No Tel (Pejabat) : --		No Tel (HP) : 96221852

## Pengadu Menyatakan:-

ON 24 JULY 2018 AROUND 1320HRS I DRIVE MY CAR PLATE NO SLD955G FROM SINGAPORE GOING TO JOHOR BAHRU BEFORE CIO. ON THE TIME WHEN I ARRIVE AT TAMBAK JOHOR. SUDDENLY ONE CAR PLATE NO SKE656D HIT MY CAR IN BACK. I DONT GET ANY INJURY. MY CAR DAMAGE IS BUMPER BACK. OTHER DAMAGE NOT YET CONFIRM. THAT IS MY REPORT.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

PEJ. SALINAN PEROT  
10 Pencetak | Tarikh @ Masa Cetak: 24/07/2018 02:21:46 PM  
SALINAN JOHOR BAHRU (S)  
SALINAN YANG DISAHKAN BENAR  
(HANYA UNTUK TUNTUTAN SIVIL)

NETUA TERAKHIR BAHAGI JOHOR BAHRU (S) JOHOR  
TIDAK Boleh digunakan untuk tujuan perundangan

Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



# Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PAC/TP/0033/2018/CCS  
Date : 1-Aug-18

Vehicle not in workshop . Kindly arrange for survey.

Your insured vehicle no: SKE 655 D

## China Taiping Insurance (SG) Pte Ltd

105 Cecil Street  
#19-00 The Octagon  
Singapore 069534

### Motor Claims Dept

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mdm Chua Toh Choon  
Address : Blk 705 Hougang Ave 2  
#12-255  
Singapore 530705  
Telephone : (HP) 96221882  
Type of Claim : Third Party Claim  
Policy No. : 5091301973  
Vehicle No : **SLD 955 G**  
Model Code : BMW 216D  
Model / Year : Jun-16  
Engine No : 30489433B37C15A  
Chassis No : WBA2B32020V259915  
Mileage :  
Date In :  
Liability :  
Excess Cost :  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 24-Jul-18  
Place of Accident : Tambak Johor Malaysia.

Tanpin 97495749

WP

3/8/18 @ 3:40pm

Resurvey after repair

sur @ 14/8/18  
3 days

14/8/18

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

## Telefax

### Estimated Labour Charges for Accident Vehicle SLD 955 G.

S/n	Nature of Jobs		Estimated Charges	Remarks
1	To remove and transfer rear wire harness for parking aid system. Check function.	S/N \$	50.00 ✓	
2	To dismantle and renew rear bumper, re-organise rear crash management components. Reinstall all parts removed.	\$	350.00 <sup>300</sup>	
3	To respray rear bumper.	\$	350.00 <sup>300</sup>	
4	To carry out diagnostic check.	S/N \$	100.00 ✓	
TOTAL LABOUR CHARGES		:	<u>\$ 850.00</u>	

# Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

## Telefax

### Material List for Accident Vehicle Regn No. SLD 955 G.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,300.00	RY
2	REAR BUMPER TOW COVER	\$ 55.00	X
3	REAR BUMPER SENSOR BRACKET	4 \$ 40.00	X
4	REAR PARKING AID SENSOR	2 \$ 550.00	X
5	REAR BUMPER SIDE GUIDE - LH/RH	2 \$ 180.00	X
6	REAR BUMPER BRACKET - CENTER	\$ 65.00	?
7	REAR BUMPER RETAINER - LH/RH	2 \$ 180.00	X
8	SUNDRIES	\$ 100.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 2,470.00
TOTAL LABOUR CHARGES		:	\$ 850.00
GRAND TOTAL		:	\$ 3,320.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6474 3323 for appointment.

Yours faithfully,  
Premium Autocare Centre



Allan Wu  
Body Shop Manager



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2018		31 Jul 2018 09:31 <a href="#">Edit Adj Rpt</a>	<b>S\$750.00</b> <a href="#">Edit Estimates</a>	<b>S\$750.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	0, Co. Reg. No.: 0		
Main Claimant:	CHUA TOH CHOON, ID: S1605111Z		
Vehicle Reg. No.:	SLD955G	Date of Loss:	24/07/2018 13:00 - :59 [25 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03670C02	Policy/Cover Note No.:	DMPCSN1648601701
Vehicle Reg. No. (Insured):	SKE655D	Policy No. (Claimant):	5091301973-01
		Excess:	S\$0.00
Repairer:	Premium Autocare Centre (Alexandra) 281 Alexandra Road, 159938 Alexandra - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/08/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents




























**\*SLD955G (SNM18D03670C02)**  
**[SKE655D]**

**TP**  
**CHUA TOH CHOON**  
**Jul 24 2018 1:00PM**  
**[0]**

**Premium Autocare Centre**

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

**View** [View in Browser](#) ▼

<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	25/07/18 17:36	<b>Accident Statement</b>	 Load HTM	
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	25/07/18 17:30	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	25/07/18 17:30	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	25/07/18 17:30	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	25/07/18 17:30	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	25/07/18 17:30	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	25/07/18 17:30	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	25/07/18 17:30	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	25/07/18 17:30	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/19 14:25	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
2	18/04/19 14:25	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
3	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	18/04/19 14:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	18/04/19 14:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	18/04/19 14:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

### Linked Accident Report Documents

## Documents Checklist

[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp\\_docview&domainid=1&objid=729623&extid=278853&corole=4&...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=729623&extid=278853&corole=4&...) 2/3



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013888/T1SD3S2

Date: 23/04/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1648601701
Claimant Vehicle No :	SLD955G	Insured Vehicle No :	SKE655D
Date of Loss:	24/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03670C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLD955G	Engine No:	30489433B37C15A
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) (A)	Chassis No:	WBA2B32020V259915
Reg. Date:	02/06/2016 (Man. Year: 2015)	Odometer:	44399 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,470.00	0.00	2,470.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	750.00	100.00	11.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,320.00</b>	<b>750.00</b>	<b>2,570.00</b>	<b>77.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>232.40</b>	<b>52.50</b>	<b>179.90</b>	<b>77.41</b>
<b>Nett Amount (S\$)</b>	<b>3,552.40</b>	<b>802.50</b>	<b>2,749.90</b>	<b>77.41</b>

## INSPECTION

Date of Assignment:	31/07/2018		
Date Inspected:	03/08/2018	Inspected At:	24 Benoi Sector Repairer: Premium Autocare Centre
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$165.00 NETT)



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2019)
<b>Parts:</b>	M1-MPV	BMW 216D 1.5 D Active Tourer (F45) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLD955G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,300.00 FS	*- FS
2	1		*REAR BUMPER TOW COVER	Not Necessary	55.00 FS	*- FS
3	4		*REAR BUMPER SENSOR BRACKET	Not Necessary	40.00 FS	*- FS
4	2		*REAR PARKING AID SENSOR	Not Necessary	550.00 FS	*- FS
5	2		*REAR BUMPER SIDE GUIDE-LH/RH	Not Necessary	180.00 FS	*- FS
6	1		*REAR BUMPER BRACKET-CENTER	*Check	65.00 FS	*- FS
7	2		*REAR BUMPER RETAINER-LH/RH	Not Necessary	180.00 FS	*- FS
8	1		*SUNDRIES	*Check	100.00 FS	*- FS

F=Franchise part, S=SpcNett.

<b>Total Parts (S\$)</b>	<b>2,470.00</b>	<b>0.00</b>
--------------------------	-----------------	-------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR WIRE HARNESS FOR PARKING AID SYSTEM.CHECK FUNCTION	New	50.00	50.00
2	TO DISMANTLE AND RENEW REAR BUMPER,RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	350.00	300.00
3	TO RESPRAY REAR BUMPER	New	350.00	300.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	100.00	100.00
Gross Labour Cost (\$\$)			850.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >