

NATIONAL Assessment Centre Services [ref: 1 Jan 2005] M/A 118 098725-01

Date In: 31/7/18-11:49	Job description	Date & Time Completed	Done by
Ref No: NA/INC8013294/24	SAS e-filing		
Veh No: 30T8659U	E-mail (within 3hrs, AIC 2hrs)		
DOA: 31/7/18-08:30	i-Motor Claim Form	MT/1005283-001	31/7/18 4:36
<input checked="" type="radio"/> TP Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: ()	Tel: ()	Fax: ()
TP Particulars: Veh No: XE3528P	INC () / Non-INC ()	
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date: ()	Time: ()
Insured/Driver Liability: () %	[Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:
 Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.
 Total Loss Case: to e-mail Insurer URGENTLY.
 Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks: (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions
16/7/18	Amend TP to OD claim
17/08/18	1st closed date = 07/08/2018, reopened by Kim hotat, TP convert to OD claim.

NA1804805 / NA1805153	Invoice Preparation Checklist	Est (\$)	Am't (\$)
Claimant's Particulars:	1) AR: Accident Reporting (\$30);	Est Bill	Add Bill
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$80)		
Contact No:	3) TP: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
QC Checked by (Engr-In-Charge):	5) FT: Follow-Through Survey (Resurvey) \$30		
Auditors' Comments:	6) TR: Re-inspection \$75		
Est 1:	7) NI: Idao DA + SMRT Survey \$160		
Est 2/3:	8) NTUC Additional Services -		
	9) NI2: Idao Mobile 30		
	*N5: Courtesy Car / Tpl Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (N-in INC) against INC \$20		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/07/2018 11:49
Date Of Accident	31/07/2018 08:30
Exact Location Of Accident	CTE (CITY) AFTER AMK AVE 1 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDT8659U
Insured/Policyholder	
Name Of Registered Owner	ZHENG MIANYONG
NRIC No	S8265813J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94889112
Alternative Phone No	OFFICE-94889112

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS J AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093622448
Cover Note Number	

Driver

Name of Driver	ZHENG MIANYONG
NRIC No	S8265813J
Date Of Birth	17/03/1982
Occupation	INDOOR
Date Of Driving Pass	05/08/2017
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94889112
Fax Number	
Contact Number	OFFICE-94889112
EMail Address	NOEMAIL

Address	BLK 862 YISHUN AVEBUE 4 #05-57
Postcode	760862
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE3528P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KUMAR A/L NADESIN
NRIC/Passport Number	F8019782U
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJR6784T
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

HARPREET SINGH SANDHU

NRIC/Passport Number

S8241679Z

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Cody

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG LANE 4 CTE (CITY) AFTER AMK AVE 1 EXIT. SUDDENLY VEHICLE B TRAVELLING ALONG LANE 3 CUT ONTO MY LANE AND HIT ONTO MY VEHICLE REAR RIGHT PORTION. AFTER AN IMPACT, VEHICLE B DID NOT STOP AND HIT ONTO MY VEHICLE RIGHT PORTION. VEHICLE B HIT MY VEHICLE TWICE. AFTER AN IMPACT, MY VEHICLE SPIN AND MOVED TO LANE 2. IN A RESULT, VEHICLE C HIT ONTO MY FRONT LEFT PORTION AND LEFT PORTION. VEHICLE C HIT ONTO MY VEHICLE TWICE.

ACCIDENT STATEMENT

ACCIDENT DATE: 31 / 7 / 18 (DD/MM/YYYY), TIME: 06 : 30 (HH:MM)

LOCATION: (7 E city) after Amk Ave 1 Exit

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SAT 66590
b) INSURANCE COMPANY: NTUC
c) POLICY NUMBER: 5097620448
d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
e) MAKE & MODEL: _____
f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME: Private use
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: Theng M. Anyang (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: S8265813J CONTACT: 90889112
c) ADDRESS: D11C862 Vishnu Avenue 4 #05-57 (760862)

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: _____
c) ADDRESS: _____

*d) DATE OF BIRTH: 12 / 3 / 1982 (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: 38 2012

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)

IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: owner

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)

b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

a) VEHICLE NUMBER: VE 3528P MODEL: _____

b) DRIVER'S NAME: Kumar A/L Kadesin

c) NRIC/FIN/PASSPORT: F8019782U CONTACT: _____

9. THIRD PARTY VEHICLE

d) VEHICLE NUMBER: 5JR 67847 MODEL: _____

e) DRIVER'S NAME: Harpreet Singh Sandhu

f) NRIC/FIN/PASSPORT: S842416792 CONTACT: _____

No of passenger
(including driver)
(1)

No of passenger
(including driver)
(1)

No of passenger
(including driver)
(1)

email = zhengcody@gmail.com

fax = vera@autoncars.com.sg

VIDEO =

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MNA110090725 Vehicle Registration No : SDT8659U

Name(as shown in NRIC): ZHENG MANTONG

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

NRIC/Passport No : S82658133

Address : _____

Contact (Tel) : _____ (H/P) : 9480 9112

(Email) : _____

Date of Accident : 3/10/2018 Time of Accident : 08:30

Place of Accident : CTE (CITY) AFTER ANK AVE 1 EXIT

Insurance Company : NMC INCOME INSURANCE CO-OPERATIVE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

TO AMEND THE REPORT FROM THIRD PARTY CLAIM
TO OWN DAMAGE CLAIM

x Cody

Signature of Vehicle Owner / Driver

Date:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8265813J



Name
ZHENG MIANYONG

郑 绵 勇

Race
CHINESE
Date of birth 17-03-1982 Sex M
Country of birth
CHINA

S8265813J

REPUBLIC OF SINGAPORE DRIVING LICENCE



License No: S8265813J

ZHENG MIANYONG

Birth Date: 17 Mar 1982
Issue Date: 05 Aug 2017



P002711102K



S183897

NIC No: S8265813J



Nationality
CHINESE
Date of issue
07-11-2012

APT BLK 862 YISHUN AVENUE 4 #05-57
SINGAPORE 760862

S8265813J

30/05/2013

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight \leq 2500kg 05 Aug 2017



License No: S8265813J

NP 428A

Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)

My Desktop
Notice of Loss

Policy Query

Policy No: Date of Accident: 31/07/2018 08:30
Vehicle No (For Motor): SDT8659U Certificate Number:

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	SD93622448		ZHENG MIANYONG	S8265813J	GPC	drive CLASSIC	SDT8659U	SDT8659U	25/08/2017	24/08/2018

Policy Information

Policy No.	5093622448	Policyholder Name	ZHENG MIANYONG	Policyholder NRIC	S8265813J
Certificate No.					
Address	BLK 862 #05-57 YISHUN AVENUE 4 SINGAPORE 760862				
Product Name	PRIVATE CAR INSURANCE	Plan			
Group Policy Flag	N				
Policy Issue Date	25/08/2017	Effective Date	25/08/2017 00:00	Expiry Date	24/08/2018 23:59
Excess Type	All Claims Excess				
Third Party Excess	0	Down damage Excess	600	Windscreen Excess	100
Additional Excess	0	DS Premium	0		
Outside Singapore CD Excess	600	Outside Singapore TP Excess	0	Young/Inexperience Driver Excess	
Agent	DICKSON AUTO AGENCY	Agent Tel.	NIL	GST Flag	Y
Co insurance Flag	No				
Open Policy Info					
Certificate Info					

Policyholder Mailing Address

Address 1	BLK 862 #05-57	Address 2	YISHUN AVENUE 4	Address 3	SINGAPORE 760862
Address 4		Address Type	Singapore address	Post Code	760862
Unit No.	05-57	Related Policy Number	5093622448-01		

Insured Object: SDR8659U

Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
----------	---------------------	------------------	--------------------	---------------------

Claim Handling

[Edit](#)

Accident MT/1005383

Policy No	529362448	Vehicle No	5078659U	GST Registration No.	
Certificate No					
Policyholder Name	ZHENG MIANYONG	Cover Type	drive CLASSIC	Policyholder NRIC	58265613J
Product Code	PRIVATE CAR INSURANCE	Contact No (Office)	0	Leasing	0
Contact No (Mobile)	94894112	Special Bonus		Contact No (Home)	0
Driver Address		TGA	<input checked="" type="radio"/> No <input type="radio"/> Yes	eCode	
KPI	<input checked="" type="radio"/> No <input type="radio"/> Yes	ACD Endowment(%)	0	eCode Reason	
ACD Premium	No			Private Hire	No

Accident Details					
Report Date	31/07/2018 14:36	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Change / Cross lane
Date of Accident	31/07/2018	Time of Accident (hh:mm)	20:30	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	074 (217) (ARTERIAL) (A1) (EXIT)				

Excess					
Car Damage Excess	0.00	Additional Excess	0	Windscreen Excess	150.00
Uninsured Driver Excess	0.00	Outside Singapore CD Excess	900.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
GST Registered Information					
GST Registered	No	GST Registration Date			
GST Registration No		GST Status Verified	Yes		
Modification history					

Policyholder Mailing Address					
Address 1	BLK 862 A05-07	Address 2	VISHUN AVENUE 4	Address 3	SINGAPORE 760862
Address 4		Address Type	Singapore address	Post Code	760862
Unit No	05-07	Related Policy Number	5992622448-01		

DI Driver Info					
Driver Name	ZHENG MIANYONG	Driver Type	Man Driver	Driver DOB	17/03/1982
Uninsured Driver Name		Driver NRIC	58265613J	Driving Experience	0
Register Date of Driver License	05/08/2017	Driver Age	36	Contact No (Home)	0
Contact No (Mobile)	94894112	Contact No (Office)	0	Address 1	SINGAPORE 760862
Address 1	BLK 862	Address 2	VISHUN AVENUE 4	Address 3	SINGAPORE 760862
Address 4		Address Type	Singapore address	Post Code	760862
Unit No	05-07	Driver Vehicle No.		Driver Insurer Company	
Does he own a Singapore Registered Car?	<input type="radio"/> Yes <input checked="" type="radio"/> No				
Declaration					
Brooch/chain or Jewel Test Reading?	0 mg	Any injury?	<input type="radio"/> Yes <input checked="" type="radio"/> No		

Modification history

Claim 001 [New](#)

Claim Type *	CD-Ma	Insured Name	ZHENG MIANYONG	Insured NRIC	58265613J
Contact No (Mobile)	94894112	Contact No (Home)		Contact No (Office)	
Email Address		DI Vehicle Number	5078659U	TP Vehicle Number	4E3528P
Claimant Type Claimant Type *	Please Select	Type of Benefit *	Please Select		
Claimant Name *		Claimant NRIC *		Name of Preferred Workshop	
Claim Description	5078659U / 4E3528P ON 31 Jul 2018	Insured Liability *	Not at Fault		
Preferred Workshop Contact No		Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Received
Request Prioritization	Yes	Claim Close Date		Date Received	31/07/2018 00:00
Date Registered	31/07/2018 14:36				
Report Taken By	381400h				
<input checked="" type="checkbox"/> From AA server					

[Save](#) [Submit](#)

Attachment

Accident No: MT/1005383 Claim No: 001
 Last Dis. Received: Yes No Upload Date: 31/07/2018 14:36

File *	Category *	Confidential	Urgency *	Description *
Browse Clear Please Select		<input type="checkbox"/>	Normal	
Browse Clear Please Select		<input type="checkbox"/>	Normal	
Browse Clear Please Select		<input type="checkbox"/>	Normal	
Browse Clear Please Select		<input type="checkbox"/>	Normal	
Clear Please Select		<input type="checkbox"/>	Normal	

Browse

Browse

Clear

Please Select

Normal

Send Message [Upload](#)

Attachment List

Attachment	Uploaded By/Date	Category	Priority	Urgency	Description	Msg Sent (CO)	Action
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	NRIC/ Driving License		Normal	NRIC/ Driving License 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	SAS		Normal	SAS 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:37	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit
	NAC_PAYA_UPI_800603 NATIONAL ASSESSMENT CENTRE SERVIC (CS) on 31 Jul 2018 14:38	Photos		Normal	Photos 2018-7-31		Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
Display in New Window Scan and uploading				

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5813J
Vehicle Details	
Vehicle No.:	SDT8659U
Vehicle to be Exported:	No
Intended De-registration Date:	13 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J AUTO
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	1NZY151017
Chassis No.:	MRO53HY9305183327
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,891.00
Original Registration Date:	14 Jul 2010
First Registration Date:	14 Jul 2010
Transfer Count:	1
Actual ARF Paid:	\$11,891.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2020
PARF Rebate Amount:	\$6,540.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jul 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$17,414.00
COE Rebate Amount:	\$5,654.00
Total Rebate Amount:	\$12,194.00

The information contained herein is correct as at 13 Aug 2018

OK

ASSIGNMENT (IDAC)

By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Motorcar ()
 - b) M/cycle ()
 - c) Bicycle ()
- 2) Vehicle hit ??
 - a) Pedestrian ()
 - b) Animal ()
- 3) Vehicle hit Road Side Objects:
 - a) Govn. Property ()
(Eg. signboard, barrier, tree etc)
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other, _____
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case
 - a) Stolen ()
 - b) Damage found ()
when recovered.
- 8) Fire
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SDT8659U Yr Regn: 14 Jul 2010
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MBV
 / Truck / Trailer or _____
 Make & Model: Toyota Vios J c.c. 1497
 Colour: Red Transmission Type: Auto / Manual
 Eng/No: 1N2Y151017 Sp. Reading: 52989
 C/No: MRO53HY9305183327
 Gen. Cond: Good / Kan / Poor / Burnt or _____
 Steering: Knock / Jammed / Leaked / Burnt or _____
 Brake: Knock / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/60/15
 R: 185/60/15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear	
R/Bal.	<u>7</u> mm	R/Bal.	<u>7</u> mm
L/Bal.	<u>7</u> mm	L/Bal.	<u>7</u> mm

 Parallel Import: Yes / No Towed-In: Yes / No
 Repair Type: LS / I.B.I Towing Required: Yes / No
 No of Repair Days: 12 Vehicle in Idac: Yes / No
 D.O.I. 13.8.2018 Time: 1500

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 - e. Animal () f. Govn Object () g. Road Work Object ()
 - h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 - e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started: _____ Time completed: _____

- 1) CSO _____
- 2) ASS _____
- 3) Entire Operation Completed Time: _____

MOTOR CAR (Frnt)

Vehicle No: **SDT 8659U**

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frnt Number Plate			
1002	991887	Frnt Number Plate Base			
1003	991889	Frnt Number Plate Garnish			
1004	991300	Frnt Bumper			
1005	992341	Frnt Bumper Clips			
1006	991325	Frnt Bumper Bracket			
1007	991462	Frnt Bumper Side Retainer			
1008	991433	Frnt Bumper Reinforcement			
1009	991318	Frnt Bumper Beam			
1010	991468	Frnt Bumper Sponge			
1011	991427	Frnt Bumper Protector			
1012	991420	Frnt Bumper Pad			
1013	991363	Frnt Bumper Grille			
1014	991301	Frnt Bumper Moulding			
1015	991407	Frnt Bumper Lower Spoiler			
1016	991438	Frnt Bumper Sensor			
1017	995100	Frnt LH Bumper Fog Lamp Cover			
1018	991355	Frnt RH Bumper Fog Lamp Cover			
1019	995079	Frnt LH Bumper Fog Lamp			
1020	995080	Frnt RH Bumper Fog Lamp			
1021	991793	Frnt Grille			
1022	991328	Frnt Grille Emblem			
1023	991799	Frnt Grille Chrome Moulding			
1024	991222	Frnt Apron Panel			
1025	992013	Frnt Support Panel			
1026	992025	Frnt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frnt Brace Panel			
1029	995153	Frnt LH Headlamp Assy			
1030	991821	Frnt RH Headlamp Assy			
1031	995088	Frnt LH Side Lamp			
1032	995089	Frnt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990131	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frnt Exhaust Manifold			
1064	991713	Frnt Exhaust Manifold Cover			
1065	991054	Frnt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frnt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frnt LH Chassis Member			
1093	991520	Frnt RH Chassis Member			
1094	990728	Frnt Vertical Cross Member			
1095	991863	Frnt Lower Cross Member			
1096	995070	Frnt LH Fender			
1097	995072	Frnt LH Fender Inner Panel			
1098	995147	Frnt LH Fender Lamp			
1099	995148	Frnt LH Fender Protector			
1100	991740	Frnt LH Fender Inner Shield			
1101	995179	Frnt LH Mudflap			
1102	995170	Frnt LH Wheel Rim			
1103	994025	Frnt LH Rim Cover			
1104	995065	Frnt LH Tyre			
1105	995071	Frnt RH Fender			
1106	991739	Frnt RH Fender Inner Panel			
1107	991744	Frnt RH Fender Lamp			
1108	991752	Frnt RH Fender Protector			
1109	991740	Frnt RH Fender Inner Shield			
1110	991884	Frnt RH Mudflap			
1111	992087	Frnt RH Wheel Rim			
1112	994025	Frnt RH Rim Cover			
1113	995065	Frnt RH Tyre			
1114	992093	Frnt Windscreen Glass			
1115	992117	Frnt Windscreen Rubber			
1116	992108	Frnt Windscreen Moulding			
1117	992098	Frnt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frnt Wiper Arm			
1121	992142	Frnt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frnt Driver Seat			
1133	991922	Frnt RH Seat Belt Assy			
1134	991899	Frnt Passenger Seat			
1135	995182	Frnt LH Seat Belt Assy			
1136	990247	Sticker			

MOTORCAR (Rear)

Rear Portion

Vehicle No: **3DT 8659U**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper <i>488.00 CUT ✓</i>			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips <i>55.00 NEG ✓</i>			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector <i>DIS ✓ 1024.90</i>			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim <i>751.30 CUT ✓</i>			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender <i>DIS ✓ 1024.90</i>			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim <i>DIS ✓ 1024.90</i>			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 6

Assessor: T. Collins

MOTOR CAR (LH)

Left Portion

Vehicle No: **SDT 80594**

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

No of Items: 2

Assessor: TG Ginn

Condition (CON)

(0)None (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
 (07)Deformed (08)Shilled (09)Buckled (10)Broken (11)Necessary (12)Missing
 (13)Torn (14)Unconfirmed (15)Not Working

ACTION (AC)

(1)Replace (✓) (2)Repair (X) (3)Check (7)
 (4)Not Consistent (NC)

Aug 2015

MOTOR CAR (RH)

Vehicle No: SDT 8659U

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frnt RH Door	SCR	R	X
1317	991654	Frnt RH Door Protector			
1318	991601	Frnt RH Door Hinge			
1319	991685	Frnt RH Door Wing Mirror			
1320	991583	Frnt RH Door Garnish			
1321	991639	Frnt RH Door Glass Outer Moulding			
1322	991588	Frnt RH Door Glass Inner Moulding			
1323	991584	Frnt RH Door Glass			
1324	991595	Frnt RH Door Glass Regulator			
1325	991596	Frnt RH Door Glass Regulator Motor			
1326	991662	Frnt RH Door Rubber			
1327	991636	Frnt RH Door Outer Handle	298-00	CUT	✓
1328	991607	Frnt RH Door Inner Handle			
1329	991625	Frnt RH Door Lock w/Key			
1330	991624	Frnt RH Door Lock			
1331	991562	Frnt RH Door Central Lock			
1332	991675	Frnt RH Door Switch			
1333	991617	Frnt RH Door Inner Trim Board			
1334	991568	Frnt RH Door Checker			
1335	991575	Frnt RH Door Felt			
1336	991688	Frnt RH Door Wire Harness			
1337	991683	Frnt RH Door Window Glass Pillar			
1338	991640	Frnt RH Door Outer Pillar			
1339	991613	Frnt RH Door Inner Pillar			
1340	991646	Frnt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frnt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frnt Bumper			
1006	991325	Frnt Bumper Bracket			
1007	991462	Frnt Bumper Side Retainer			
1008	991433	Frnt Bumper Reinforcement			
1010	991468	Frnt Bumper Sponge			
1011	991427	Frnt Bumper Protector			
1014	991301	Frnt Bumper Moulding			
1015	991407	Frnt Bumper Lower Spoiler			
1030	991821	Frnt RH Headlamp Assy			
1032	995089	Frnt RH Side Lamp			
1105	995071	Frnt RH Fender			
1107	991744	Frnt RH Fender Lamp			
1108	991752	Frnt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	127-20	DD	✓
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1331	994070	Roof Top Panel			
1332	994098	Roof Top Moulding			
1333	994085	Roof Top Air-bag			
1334	994084	Roof Top Air-bag Sensor			
1335	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	109-40	BR	✓
1149	993045	Rear Bumper Reinforcement			
1150	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp	289.00	CUT	✓
1228	993456	Rear RH Fender		DD	✓
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items: 6

Assessor: TG Lim

Claim Handling

Task Transfer Exit

Accident MT/1005383 IDC SA SUB

Policy No.	5093622448	Vehicle No.	SOT8659U	GST Registration No.	
Certificate No.					
Policyholder Name	ZHENG MIANYONG			Policyholder NRIC	S82658131
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	94889112	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	
KPK	<input checked="" type="radio"/> No <input type="radio"/> Yes	TCA	<input checked="" type="radio"/> No <input type="radio"/> Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	31/07/2018 14:34	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Change / Cross lane
Date of Accident	31/07/2018	Time of Accident hh:mm	08:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	Yes	ICM No.	3593659
Accident Location	CTE (CITY) AFTER AMK AVE 1 EXIT				

Benefits

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes

Modification History

Policyholder Mailing Address

Address 1	BLK 862 #05-57	Address 2	YISHUN AVENUE 4	Address 3	SINGAPORE 760862
Address 4		Address Type	Singapore address	Post Code	760862
Unit No.	05-57	Related Policy Number	5093622448-01		

OT Driver Info

Driver Name	ZHENG MIANYONG	Driver Type	Main Driver	Driver DOB	17/03/1982
Unnamed driver Name		Driver NRIC	S82658131	Driving Experience	0
Register Date of Driver License	05/08/2017	Driver Age	36	Contact No.(Home)	0
Contact No.(Mobile)	94889112	Contact No.(Office)	0	Address 3	SINGAPORE 760862
Address 1	BLK 862	Address 2	YISHUN AVENUE 4	Post Code	760862
Address 4		Address Type	Singapore address		
Unit No.	05-57				
Does he own a Singapore Registered car?	<input type="radio"/> Yes <input checked="" type="radio"/> No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	<input type="radio"/> Yes <input checked="" type="radio"/> No
-------------------------------------	------	-------------	---

Modification History

Claim 001 OD-MD IDC SA SUB

Claim Case Officer Yap Chee Ling

Claim Type	OD-MD	Insured Name	ZHENG MIANYONG	Insured NRIC	S82658131
Contact No.(Mobile)	94889112	Contact No.(Home)		Contact No.(Office)	
Email Address		OT Vehicle Number	SOT8659U	TP Vehicle Number	XE3528P
Claimant Type		Type of Benefit		Name of Preferred Workshop	
Claimant Name		Claimant NRIC			
Claim Description	SOT8659U / XE3528P ON 31 Jul 2018	Insured Liability	Not at Fault	GIA report	Received
Preferred Workshop Contact No.		Preferred Repair Option	Preferred Workshop, Name unknown	Date Received	15/08/2018 11:58
Require Finalisation	Yes	Claim Close Date		Total Loss but Repaired	
Date Registered	31/07/2018 14:39	Workshop Repairer		OD Excess Collected by Workshop	
Report Taken By	Jackson				

Print AK letter

Modification History

Special Claim Creation Approval

Approval		Reason	
Remarks			

damage assessment Activity Handling Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	VIOS 3	Engine Capacity	
Date of Registration	14/07/2010	Classis No.	MR053HY9305183327	Parallel Import *	<input type="radio"/> Yes <input checked="" type="radio"/> No
Towing Required *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Vehicle in IDAC *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Survey Current Status	
Type of Tender *	Own Damage	Assessor Name *	TG LIM		

IDAC/Workshop Name: NATIONAL ASSESSMENT CENTR IDAC/Workshop Location: 51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost

Total Loss * Yes No

Market Value(\$)

Scrap Value(\$)

Economical Repair Value(\$)

REMARK:NO OF REPAIR DAY:12 DAYS, 1 X FRT RH DOOR OUTER HANDLE - REPLACE.

Remark

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	27700101	HEAD LAMP (LEFT)	<input type="text" value="1"/>	Replace	X
ABS	2	23300203	DOOR (REAR LEFT)	<input type="text" value="1"/>	Replace	X
ABSORBER	3	16000102	BUMPER (REAR)	<input type="text" value="1"/>	Replace	X
ACCELERATOR	4	16002402	BUMPER CLIPS (REAR)	<input type="text" value="1"/>	Replace	X
ACTUATOR	5	25400105	FENDER (REAR LEFT)	<input type="text" value="1"/>	Replace	X
ADVERTISEMENT STICKER	6	448014	WHEEL RIM	<input type="text" value="1"/>	Replace	X
AIR BAG	7	25400106	FENDER (REAR RIGHT)	<input type="text" value="1"/>	Replace	X
AIR BLOWER	8	25401002	FENDER INNER TRIM (REAR RIGHT)	<input type="text" value="1"/>	Replace	X
AIR BOX	9	23300202	DOOR (FRONT RIGHT)	<input type="text" value="1"/>	Repair	X
AIR CHAMBER BOX	10	23300204	DOOR (REAR RIGHT)	<input type="text" value="1"/>	Replace	X
AIR CLEANER	11	16005104	BUMPER RETAINER (REAR RIGHT)	<input type="text" value="1"/>	Replace	X
AIR COMPRESSOR	12	42000102	TAIL LAMP (RIGHT)	<input type="text" value="1"/>	Replace	X
AIR CON	13	16000101	BUMPER (FRONT)	<input type="text" value="1"/>	Replace	X
AIR CON (VAN)	14	16002401	BUMPER CLIPS (FRONT)	<input type="text" value="1"/>	Replace	X
AIR COOLER	15	25400102	FENDER (FRONT LEFT)	<input type="text" value="1"/>	Replace	X
AIR DISTRIBUTOR						
AIR FILTER						
AIR FLOW						
AIR GRILLE						
AIR HORN						
AIR INTAKE						
AIR RESONATOR BOX						

Save Submit



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SDT 8659 U Date In: 16/08/18 Time In: 12.35 with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: INDECO

Collection Date: 16/08/18 Time: 12.35 with Keys: Yes / No

Tow Truck No: YM6657B Tow Man: RAVEN NRIC: 6911971I

Signature: [Signature] 91811971

For office use

Attended by: ROSLINDA

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In
Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Yap Chee Ling <CheeLing.Yap@income.com.sg>
Sent: Thursday, 16 August 2018 10:52 AM
To: LKK Paya Ubi; IEPL DF12 Workshop; Tan Cheng Huat
Subject: SDT8659U | MT/1005383 (Awarding Letter to Indeco)

Importance: High

Hi IDAC and Indeco,

Vehicle is currently in IDAC.

Excess of \$600 is applicable.

Please liaise with the owner – Mr Zheng Mianyong at tel: 9488 9112 on the necessary.

Thank you.

Yap Chee Ling (Ms)
Claims Executive
Motor Insurance
T +65 6430 7893
www.income.com.sg



Our Ref: MT/CA/OD/051/1005383-001/YCL

16 Aug 2018

INDECO ENGINEERS (PTE) LTD
BLK 39 DEFU LANE 12
SINGAPORE 539139

Dear Sir

CLAIM NUMBER: MT/1005383-001
REPAIR OF VEHICLE NUMBER: SDT8659U

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 16 Aug 2018

Make: TOYOTA

Model: VIOS J

Estimated Repair Days: 8

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits: Not applicable

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Yap Chee Ling at 6430-7893 or email us at motor@income.com.sg.

Yours sincerely

Low Choo Mee
Senior Manager
Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.