



Our Ref :

CHARTIS Buliding 78 Shenton Way

Singapore 079120

T 0718 / SH 7117J /CL(st)

Your Ref: Date

#07-16

Dear Sir

21-Aug-18

Attn: Motor Claims Department

AIG ASIA PACIFIC INSURANCE PTE LTD

CDGE Taxi Claims Dept

59 Loyang Drive 4th Floor

Singapore 508969

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

Mainline +65 6383 6280

Workshops

205 Braddell Road Singapore 579701

59 Loyang Drive Singapore 508969

Singapore 408649

Singapore 758156

501 Yishun Industrial Park A Singapore 768732

Sungei Kadut Sungei Kadut Way Singapore 728791

Senoko 24 Senoko Loop

Sin Ming 383 Sin Ming Drive Singapore 575717

SH 7117J YOUR INSURED SGF 78L ACCIDENT INVOLVING OUR TAXI ON 29.07.18

AND OTHER

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor SH 7117J which was involved in the captioned accident with your insured vehicle 45 Pandan Road The vehicle owner and the taxi driver concerned have requested and authorized us to assist them 320 Ubi Road

WITHOUT PREJUDICE

in presenting their claims against the party responsible for all applicable matters arising from

the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SGF 78L we are submitting these claim for your consideration on behalf of the claimants.

TA

AX.	OWNER'S CLAIM	2	6.351.41
1	Cost of Repair	Ψ	
	4 days Loss of Rental @ \$ 117.00 per day	\$	468.00
2	4 days Loss of Rental & This IKK	\$	-
3	Survey Report Fees (Surveyed by M/s LKK)	-	7.49
1	GIA / LTA Search Fees	4	7.43
_	GIA / Police Report Fees	\$	-
5		\$	-
^	Taving / Medical / Transporation	4	

Towing / Medical / Transporation

Sub Total: 6,826.90

8

pcs.

HIRER'S CLAIM

7	1	days Loss of Income @	\$ 80.00 per days	\$	320.00
1		_days 2000 of mooning @_	Total Claims	: \$	7,146.90

We enclose herewith the following documents to support the claims: -

Original repair bill and photocopies of photographs: a) SGF 78L LTA search slip/s of :

b) SH 7117J GIA / Police report/s of: c)

Letter of authority from owner / hirer / operator

() Certificate of Insurance (X) Photograph/s of Accident Scene (x) Downtime/Mileage record () Witness statement/s

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Cecilia Lee

This is a computer generated letter. No signature is required.

A member of COMFORTDELGRO







Executive

d)

CDGE Claims Department

Tel: 6214 8354 Fax: 6214 1843 Email: cecilialee@sparkcarcare.com

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

i 40 SH7117J , SGF78L

ON 29-Jul-18 03:10

ALONG

PIE SLIP RD TOWARDS PAYA LEBAR RD

I / We

CHENG SOO MENG

(Hirer) NRIC No.:

S0018143I

and/or

LIM CHIN KAI

(Relief) NRIC No.: **\$1393513J**

Taxi Number

SH7117J

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

29-Jul-2018

Name of Hirer

CHENG SOO MENG

Hirer NRIC

S0018143I

Signature:



Address

325 SERANGOON AVENUE 3 #10-304

550325

Contact No.

98802733

Name of Relief

LIM CHIN KAI

Relief NRIC

S1393513J

Signature:

Address

256 SERANGOON CENTRAL DRIVE #07-34

550256

Contact No.

96792741



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

CONTACT NO: 64193000

Description: 3P 29.07.2018

04-01-0103-0739

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY.CHARTIS BUILDING #08 SINGAPORE SG 079120

3225094

8010004

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

VEHCLE NO SH 7117J

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W Page: 1

INV. NO/DATE 91389523 13.08.2018

JOB NO. 305193690 MAKE HYUNDAI

ODOMETER READING MODEL I - 40

DATE/TIME IN DATE OF REG 29.09.2016 29.07.2018 03:10

CHASSIS CODE KMHLB41UMGU093544

Qty Unit Price Net &Disc S/No Part No. PART REQUISITION 20.00 1,345.12 I40VC PANEL ASSY-TRUNK LI 1 1,681.40 0001 04-01-0103-0577 32.80 1 41.00 20.00 I40VC EMBLEM-CRDI 04-01-0103-0786 0002 32.80 1 41.00 20.00 04-01-0103-0787 0003 I40VC EMBLEM-I40 21.76 27.20 20.00 140VC SYMBOL MARK-TRUNK L 1 0004 04-01-0103-0800 20.00 20.00 0.00 1 28-01-0103-0005 (I40/SONATA) REAR BOOT LOG 0005 10.00 1 10.00 0.00 (I40/SONATA) REAR BOOT TEL 28-01-0103-0006 0006 1 603.60 20.00 482.88 140VC COVER ASSY-RR BUMPE 0007 04-01-0103-0579 20.00 403.48 1 504.35 0008 04-01-0103-0740 I40VC BEAM-RR BUMPER# 17.60 HYUNDAI BUMPER COVER CLIP 10 2.20 20.00 0009 04-01-0101-0111 20.00 180.00 140VC COVER-RR BUMPER LWR 1 225.00 0010 04-01-0103-0738

140VC ABSORBER-RR BUMPER

ComfortDelGro Engineering Pte Ltd A member of **COMFORT**DELGRO

0011

Head Office: 205 Braddell Road Singapore 579701

INVOICE No.	AMOUNT	BANK/CHQ No.
91389523	6,351.41	

1

143.40

20.00

114.72

Kindly note that no receipt shall be issued unless requested.



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

Page: 3

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY.CHARTIS BUILDING #08 SINGAPORE SG 079120

CONTACT NO: 64193000

3225094

VEHCLE NO SH 7117J

INV. NO/DATE 91389523 13.08.2018

JOB NO. 305193690

MODEL I - 40

ODOMETER READING

DATE OF REG 29.09.2016

DATE/TIME IN 29.07.2018 03:10

CHASSIS CODE KMHLB41UMGU093544

S/No	Part No.					Qty	Unit Price	%Disc	Net
0006	20-22	REMOVE/REFIX	REVERSE	SENSOR		30	0.00	30.00	
0007	20-06	REMOVE/REFIX	EXHAUST	PIPE TO	ASST	REP	50.00		50.00
					SUB-T	OTAL	:	1,3	80.00

Items total 5,935.90

7.000 % 415.51 Add GST @

6,351.41 Invoice amount

CHEWBEELENG 13.08.2018 15:32:16 CLSO/57/57

Issued by : CHEWBEELENG 13.0
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of COMFORIDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91389523	6,351.41	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18070827

Date: 02 August 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

29/07/2018 @ 03:10 hrs

ALONG

PIE SLIP RD TOWARDS PAYA LEBAR RD

INVOLVING

SGF78L

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SH7117J (the "Taxi"). The Taxi was hired to CHENG SOO MENG IC NO S0018143I a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$117.00 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	5471173		MILEAGE	HOURS OPERATED (TIME)	ATED (TIME)	DATE	NAME OF DRIVER
DATE	NAME OF DRIVER	MILEAGE READING	(KM)	FROM	TO		
27-7- Fr	7	188158	897	5181	0,500		
28-7-18	CX The	-		9081			
29/4/18	Seriolent ?	The state of the s	Loyang	0310			
81/8/10	Repair	Meng So Weal	1700 - 1700	. (1700		
7							
		7	41				
				411	,		
	y.						
							Contract of the Contract of th

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time

Search Status Insurance Company Code

Insurance Company Name

SGF78L

29 Jul 2018 / 03:10:00

Successful

A04

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

OK



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours: Monday to Friday, 09:00 – 17:00 UEN: S66SS0020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

ADDENIDLIM

	ADDE	INDUIVI	
PARTICULARS OF PER	RSON MAKING THE AMENDM	IENTS:	
Original Report No :	MCD618097687	Vehicle Registration No:SH7	117J
Name(as shownin NRIC):	LIM CHIN KAI	NRIC/FIN/Passport No:S139	3513J
(*Vehicle Driver) Vel	hicle Owner) (*) Please delete	as appropriate	
Address :	BLK 256 SERANGOON C	ENTRAL DRIVE #07-34 Si	ngapore(550256)
Contact (Tel) :		Mobile No. :	
Email Address :			
Date of Accident :	29/07/2018	Time of Accident :03:10	
Place of Accident :	PIE SLIP RD TOWARDS F	PAYA LEBAR RD	
Insurance Company:	MS First Capital Insuran	nce Ltd	
Upload Police Rep	port : T/20180729/2074		
_			
		Zijken.	
Policyholder / Driver'	s Signature	Reporting Centre Personnel's	s Signature

Date:

03.08.2018

GIARMC addendumform V3





1 of 3

Report No. T/20180729/2074

Police Station Of Origin: Tampines East NPP 263 Tampines Street 21 #01-138 SINGAPORE 520263 Tel No: 1800-7839999

REPORT OF A TRAFFIC ACCIDENT

Taxi driver

Date/Time 29/07/2018	Report Ma		Vide Report No.:	Station Diary No.: 18
Informant	's Particu	lars		Self-charge and the Act and act of the Act o
Name of Ir	formant:	¥	Address: APT BLK 256 SERANGOON (SINGAPORE 550256	CENTRAL DRIVE #07-34
ID Type / I	D No.: / S139351	3J	Contact No.: Home/Office:	Mobile: 96792741
Nationality SINGAPO	: RE CITIZI	EN .	Email:	
Sex:	Age: 58	Date of Birth: 21/10/1959	Type of Informant: Driver	L. Christian / Cahaal Name:
Race: Chinese	,		Language: English	Institution / School Name:
Occupation Taxi drive			Driving Licence Information: Class: 3,4,5	Date of Expiry:

Type of	Injury	Drink Drive:	Date/Time of Accident:	Type of Location Bend
Accident:	Others	No	29/07/2018 03:10	
Location:				
PAN ISLAND	EXPRESSWAY			
PIE(towards Weather:	Tuas) Paya Lebar E	Road Surface.		Road Speed Limit:
Clear Traffic Flow:		Dry Traffic Control:		Traffic Volume:
THE TOW.		Not Controlled		No Traffic Anyone conveyed by
One Way				ambulance:

Details of V	enicle invo			Color	Condition	No of Passenge
Vehicle No.	Type	Make	Model		Condition	
SGF78L	Car	NISSAN		Silver		0
SH7117J	Car	HYUNDAI	i40	Blue		0

Details of Person Involved	The Court See And Section 1997 And Secti
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20180729/2074

Police Station Of Origin: Tampines East NPP 263 Tampines Street 21 #01-138 SINGAPORE 520263 Tel No: 1800-7839999

CONTINUATION OF REPORT

Driver				ID No.		S1393513J	
Name	LIM CHIN KAI			וט ועט.		010000100	
Related Vehicle	SH7117J (Car)			Conta	ct No.	96792741	
THE PLANT OF THE P				Closs	of .	Class: 3,4,5	
Hospital/Clinic	NEPTUNE HEALTHCARE MEDICAL & SURGERY			Class of Driving Licence &		Date of Expiry: NIL	
1						Date of Enpiry	
				Expiry Date			
						7/0040	
Date Treatment	29/07/2018		Date Disc	110		7/2018	
No. of Days gran	ted Medical Leave	03	Degree of	Injury	Sligh	t	

Brief Details.

On 29/7/18 at about 0310hrs, I was driving vehicle A along PIE Exit Paya lebar Rd and stopped at the slip road to check for oncoming traffic. Suddenly, vehicle B hit onto the rear of my vehicle.

No Police or Ambulance were at scene. I have CCTV of the accident.

Vehicle A-SH7117J Vehicle B- SGF78L

































