



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18013905/Aps3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 16-09-2020



ATTN:WINNIE

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |              |                |            |
|--------------|--------------|----------------|------------|
| Insured Veh. | SLW 3348P    | Veh. Inspected | SLU 2877X  |
| Policy No.   | VPA/P2068977 | Coverage (\$)  | 0.00       |
| Claim No.    | S8M00QFH     | Excess (\$)    | 0.00       |
| Assign From  |              | Assign Date    | 31/07/2018 |

### 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | HONDA HRV         | c.c          | 1496       |
| Engine No.   | HIDDEN            | Year of Reg. | 2017       |
| Chassis No.  | JHMRU1830GX203402 | Colour       | WHITE      |
| Odometer     | 8055              | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

### 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm    |
| L/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 215/60 R16 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 215/60 R16 | DUNLOP | 6 mm    |

### 4. Description of Damages

|                                                                                          |
|------------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.<br>DAMAGES SEE DETAILS. |
|------------------------------------------------------------------------------------------|

### 5. General Information

|                |                                                                       |                 |            |
|----------------|-----------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 28/07/2018                                                            | Inspection Date | 31/07/2018 |
| Survey held at | SK AUTOMOBILE PTE LTD<br>23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933 |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|----------------|