

ASS. REC. BY:

REF: CS3/CT#18013413/TI 2403⁵²

Special Instruction:

Surveyor:

Tauyikoh

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of CTI

Date/Time:

31/7/18 @ 3:52pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SFS 333T

Insured:

WC 7004E

at Workshop m/s

Empire Image

Tel:

9742 5441

of

No. 4 Pandan Loop

Policy No:

DMCVSN/765851700

Claim No:

SNM18 D03717C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/07/2018

CA / REV / REP. / REV 24 HRS

up

01/08/2018

H.O.D. Endorsement:

Date/Time:

4:16pm @ 31/7/18

Person Contacted:

Mr. Kenny

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SFS 333T-X
	WC 7004 E-X
1/8/18	Dismantled.

Surveyor: Taylor

REF:

CT1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh.No: SFS333T Yr Regn: Jan / 12

Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz SLK 200 c.c. 1796

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 79629 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDDZF24482F020009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 1/8/18 @ 11:15

Survey held at Empire Image

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NO GIA.</u>
	<u>Estimated repair range \$7,000 - \$8,000 Range + No. of days</u>
	<u>[Signature]</u>
	<u>1/8/2018</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18013913/T1z4d3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 31-07-2018	
		Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	WC 7004E	Veh. Inspected	SFS 333T
Policy No.	DMCVSN1765851700	Coverage (\$)	0.00
Claim No.	SNM18D03717C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	31/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/07/2018	Inspection Date	01/08/2018
Survey held at	EMPIRE IMAGE NO.4 PANDAN LOOP (BLK K / BLK 1) SINGAPORE 128222		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jul 2018		31 Jul 2018 15:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YATSEN TECHNOLOGIES PTE LTD, Co. Reg. No.: -								
Main Claimant:	HO AMAOY, ID: S1626139D								
Vehicle Reg. No.:	SFS333T	Date of Loss:	23/07/2018 18:00 - :59						
Claim Type:	TP / SNM18D03717C02	Policy/Cover Note No.:	DMCV5N1765851700 (Comprehensive)						
Vehicle Reg. No. (Insured):	WC7004E	Policy No. (Claimant):	SI18V00054/VPC/R03						
		Excess:	S\$0.00						
Repairer:	Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/08/2018]								
Driver/Custodian (Insured):	KARUPPIAH KANNAN (44 / Male), NRIC: G7541672K, Tel: +6583868080								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Our Ref : CY(EI)SFS333T/hh
Please email to: helen@yoga-legal.com
Your Ref : Your insured vehicle WC7004E
SNM18D03693C02

31st July 2018

The Motor Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road, #16 – 00 Springleaf Tower
Singapore 079909

By Email: lucas.lee@sg.cntaiping.com

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SFS333T & WC7004E ON 23/07/2018 @ 18:30 HRS
ALONG KEPPEL ROAD TURNING OUT FROM TANJONG PAGAR**

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose Mr. Lawrence Ng of M/s. Priority Services to conduct a Pre-Repair inspection.


Please be informed that the said vehicle can be inspected at:

Name of workshop : M/s. Empire Image Pte Ltd
Address : 4 PandanLoop (Blk 1/Blk 1K)
Singapore 128222
Contact person : Mr. Kenny Lim
Telephone number : 97425441
Fax number : 67778126

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per Protocol, that you have no objections to our abovenamed motor surveyor you will be deemed to have agreed as a "single joint expert".

If you object to our motor surveyor, we will accordingly inform the claimant to instruct his choice of motor Surveyor to conduct the pre-repair survey.

Yours faithfully,


C. Yogarajah LLC

c.c. client, Ho Amaoy
c/o M/s. Empire Image Pte Ltd
(By Fax: 67778126)

For Surveyor

Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair inspection: /

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/07/2018 16:24
Date Of Accident	23/07/2018 18:30
Exact Location Of Accident	KEPPEL ROAD TURNING OUT FROM TANJONG PAGAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFS333T
Insured/Policyholder	
Name Of Registered Owner	HO AMAOY
NRIC No	S1626139D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97213926
Alternative Phone No	Office-97213926
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	SLK 200 KOMPRESSOR CONVERTIBLE-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S118V00054/VPC/R03
Cover Note Number	
Driver	
Name of Driver	TAN HUIPING, JOSEPHINE
NRIC No	S8137111C
Date Of Birth	23/11/1981
Occupation	INDOOR
Date Of Driving Pass	10/05/2004
Driving Experience	14 YEARS AND 2 MONTHS

Gender	FEMALE
Mobile Number	(LOCAL) +65-97703281
Fax Number	
Contact Number	
E-Mail Address	DENG.JOSEPHINE@GMAIL.COM
Address	124 TAMPINES STREET 11 #12-404
Postcode	521124
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


24/07/18

Driver's Signature
(if driver is not the policyholder)
Date & Time



24/07/18

MERITDELGRU ENGINEERING PTE LTD
45 PANDAN ROAD
SINGAPORE 609286
TEL: 6338 8778 FAX: 6262 6950

Reporting Centre Personnel's Signature

Name: Vo Yung Kheng
NRIC / Fin No.: G2638977T

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27th July 2018, I was driving out from Tanjong Pagar Road to turn into Keppel Road (to go to MCE.), when vehicle NO. WC 7004E hit me. We were both in yellow box.

We were both turning left to turn into Keppel Road. I was in my lane. Driver Karuppiakannan did not see my car & his vehicle is too long, so it went into my lane and as a result hit my bumper on the right hand side (driver side) of my car.

IMPORTANT NOTE

Under General Condition – Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 24/07/18

Driver's Signature
(if driver is not the policyholder)
Date & Time: 24/07/18

AFRITDELGRU ENGINEERING PTE L1
45 PANDAN ROAD
SINGAPORE 609286
TEL. 6338 8778 FAX: 6262 6950

Reporting Centre Personnel's Signature
Name: Voo Yung Kheng
NRIC / Fin No.: G2638977T

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SFS333T		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MERCEDES BENZ		
Vehicle Model :	SLK 200		
Chassis No. :	WDD1724482F020009		
Propellant :	Petrol		
Engine No. :	27186130314377		
Engine Capacity :	1796 cc		
Maximum Power Output :	135.0 kW (181 bhp)		
Maximum Laden Weight :	1785 kg		
Unladen Weight :	1470 kg		
Year Of Manufacture :	2011		
Original Registration Date :	13 Jan 2012		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$73,600.00		
COE Expiry Date :	12 Jan 2022		
Road Tax Expiry Date :	12 Jan 2019		
PARF Eligibility Expiry Date :	12 Jan 2022		
Inspection Due Date :	12 Jan 2019		
Intended Transfer Date :	06 Aug 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6139D
Vehicle Details	
Vehicle No.:	SFS333T
Vehicle to be Exported:	No
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	SLK 200
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186130314377
Chassis No.:	WDD1724482F020009
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$54,305.00
Original Registration Date:	13 Jan 2012
First Registration Date:	13 Jan 2012
Transfer Count:	1
Actual ARF Paid:	\$54,305.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2022
PARF Rebate Amount:	\$35,298.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$73,600.00
COE Rebate Amount:	\$25,265.00
Total Rebate Amount:	\$60,563.00

The information contained herein is correct as at 06 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jul 2018		31 Jul 2018 15:52 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	YATSEN TECHNOLOGIES PTE LTD , Co. Reg. No.: -								
Main Claimant:	HO AMAOY , ID: S1626139D								
Vehicle Reg. No.:	SFS333T	Date of Loss:	23/07/2018 18:00 - :59 [78 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03717C02	Policy/Cover Note No.:	DMCVSN1765851700 (Comprehensive)						
Vehicle Reg. No. (Insured):	WC7004E	Policy No. (Claimant):	SI18V00054/VPC/R03						
		Excess:	S\$0.00						
Repairer:	Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/08/2018]								
Driver/Custodian (Insured):	KARUPPIAH KANNAN (44 / Male), NRIC: G7541672K, Tel: +6583868080								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFS333T (SNM18D03717C02)
[WC7004E]
TP
HO AMAOY
Jul 23 2018 6:00PM
[YATSEN TECHNOLOGIES PTE LTD]
Empire Image

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail Print
1	24/07/18 18:04	Accident Statement	Load HTM
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail Print
1	24/07/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
2	24/07/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
3	24/07/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
4	24/07/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
5	24/07/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
6	24/07/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
7	24/07/18 17:10	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
8	24/07/18 17:10	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
9	24/07/18 17:10	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
10	24/07/18 17:10	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
11	24/07/18 18:01	THIRD PARTY DRIVER WORK PERMIT [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
12	24/07/18 18:01	THIRD PARTY DRIVER WORK PERMIT [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	31/07/18 15:51	PRS	Load PDF
2	31/07/18 15:52	OI GIA	Load PDF
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail Print
1	24/07/18 16:43	Sketch Plan [Linked Accident Report Documents]	Load TIF
2	24/07/18 18:03	AUTHORIZATION LETTER [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	03/08/18 11:22	LKKPhotosIn6-1.pdf	Load PDF
2	03/08/18 11:22	LKKPhotosIn6-2.pdf	Load PDF

Linked Accident Report Documents

			View View in Browser ▼
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail Print

Assessment Reports				✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	24/07/18 18:04	Accident Statement	Load HTM	

Photos/Images			3 per page	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	24/07/18 16:55	Accident Photo	Load JPG	✓
2	24/07/18 16:55	Accident Photo	Load JPG	✓
3	24/07/18 16:55	Accident Photo	Load JPG	✓
4	24/07/18 16:55	Accident Photo	Load JPG	✓
5	24/07/18 16:55	Accident Photo	Load JPG	✓
6	24/07/18 16:55	Accident Photo	Load JPG	✓
7	24/07/18 17:10	Accident Photo	Load JPG	✓
8	24/07/18 17:10	Accident Photo	Load JPG	✓
9	24/07/18 17:10	Accident Photo	Load JPG	✓
10	24/07/18 17:10	Accident Photo	Load JPG	✓
11	24/07/18 18:01	THIRD PARTY DRIVER WORK PERMIT	Load JPG	✓
12	24/07/18 18:01	THIRD PARTY DRIVER WORK PERMIT	Load JPG	✓

Documentation			1 per page	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	24/07/18 16:43	Sketch Plan	Load TIF	
2	24/07/18 18:03	AUTHORIZATION LETTER	Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18013913/T1Z4D3S2
Date: 10/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1765851700
Claimant Vehicle No :	SFS333T	Insured Vehicle No :	WC7004E
Date of Loss:	23/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03717C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFS333T	Engine No:	27186130314377
Make & Model:	MERCEDES-BENZ SLK 200 KOMPRESSOR CONVERTIBLE, 1.8 (A)	Chassis No:	WDD1724482F020009
Reg. Date:	13/01/2012 (Man. Year: 2011)	Odometer:	79629 km
Colour:	Silver		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40R17	Rear Tyre Size:	245/40R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	31/07/2018	Inspected At:	Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K) Singapore 128222
Date Inspected:	01/08/2018		
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Aug 2018)

Parts: M1-COUPE MERCEDES-BENZ SLK 200 KOMPRESSOR CONVERTIBLE 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFS333T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >