15/5/2010

INS. CASE OWNER: | CC3 /CTI1801 3923, K2WB3 | LKK: IDAC:

ASSIGNMENT

Surveyor: Kalvin. DOI: 20/7/18 Date / Time : 30/7/18

Registered in Merimen: —

Pre-assign / CCU / FTE

Insured Vehicle No. :	YN 7282L		Claim No. :	
Name of Insured :			Policy No. :	
Insured Tel No. :		HP:	Make / Model :	
Excess Sec II :S$		D.O.A : 27/7/18.	Place of Accident :	
Is driver the owner?	(YES / NO)	Nature of Accident :		

If **NO**, Driver Name / Age : OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

SHL 9684. → ____ → ____ → ____

INSRS: CDTE WSP: Tel : ly. Liability : RMKS:	INSRS: WSP: Tel : Liability : RMKS:	INSRS: WSP: Tel : Liability : RMKS:	INSRS: WSP: Tel : Liability : RMKS:

Date/ Time	
	SHL 9684 – C8/FC/18010486/0vd3 Dvr. 6/6/18
	YN7282L – Y

STAGE	**DATE / PIC**
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	

Documentation Check List:	**Handler**	**Typist**
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☐	☐
Release Voucher:	☐	☐
Final Repair Bill:	☐	☐
Car Rental Invoice:	☐	☐
Towing Invoice	☐	☐
LTA / GIA :	☐	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☐	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S$		
Loss of Rental (LOR):	S$	(days)	
Loss of Use (LOU):	S$	($ x days)	
Loss of Income (LOI):	S$	($ x days)	
LOR only ☐	LOU only ☐	LOR + LOU ☐ LOR + LO ☐ **[Tick only one]**	
GIA/LTA Search	S$		
Medical:	S$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S$		3) Survey fee:
Total:	**S$**	**Global Sum S$:**	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

(08/11/13)

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insped Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 9684Y Yr Regn: "Oct / 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Mercedes Benz Viano c.c 2143

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 481626 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDF63981323802651

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD W/Rim or _____

Tyre Size; F: 225 / 60R16C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	27/7/13	D.O.I.	30/7/13

Survey held at CDHE (Loyang)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S wing Mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	CTZ 4

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Prell. Report

☐ : Final Report

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:	
Transportation:	
$ + RS $	
Photos	
Others	
TOTAL	

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO.: 305193650

ISTOMER

R/MS
ISTOMER NO.
DRESS

CITYCAB PTE LTD
7010070
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188

L. (R) (O)
(P)

SCOUNT CARD NO.

VARS

(B)

REGN NO.: SHC 968Y	MILEAGE
MAKE : MERCEDES BENZ	FUEL E.....1/2.....F
MODEL VIANO CDI 2.2L	DATE/TIME IN 30.07.2018 09:45
YR OF MANU 11.10.2013	TARGET DATE
CHASSIS CODE WDF63981323802651	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 27.07.2018
NATURE: 3P 27.07.2018

S/NO	LABOR CODE	DESCRIPTION
✓		CHINA - Left Side Mirror



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

owledgement Slip

e:
o.:
le No.: SHC 968Y LARRY

Larry Ng

e of Service Advisor

Signature/Date

returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC 968Y

Name of Service Advisor

Date

To be kept by Security Guard