

108/11/13

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / RS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 968Y Yr Regn: Oct 12.5

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/O / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz Viano c.c. 2143Colour: White A/C: Insured / Std / NI / NASp. Reading: 481626 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDF 6398132382651Gen. Cond: Good / Fair / Poor / BurntSteering: Inor der / Jammed / Leaked / Burnt orBrake: Inor der / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rrim or

Tyre Size: F: 225 / 60R16C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KKK

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 2 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 27/2/8 D.O.I. 20/7/8Survey held at: (DHE (Loyang))

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S wing Mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/9/18 Confirm US \$ 1100.00 with 1 working day (TZ 4)

Date/Time, File Pass to? ☐ : Prel. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL

Date/Time, File Pass to? ☐ : Prel. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18013923/K1wb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 31-07-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7282L	Veh. Inspected	SHC 968Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	31/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/07/2018	Inspection Date	30/07/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18013923/K1wb3

Date: 31.07.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC968Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30.07.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	1,546.00
Revised Estimate Amount	: S\$	1,376.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 1 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Team: ARC Repair TP(CFSO)1	JOB CARD	Sales Order:	JO NO. 305193650
STOMER		REGN NO. SHC 968Y	MILEAGE
MS CITYCAB PTE LTD 7010070		MAKE: MERCEDES BENZ	FUEL E 1/2 F
STOMER NO. 383 SIN MING DRIVE Singapore SINGAPORE 575717		MODEL VIANO CDI 2.2L	DATE/TIME IN 30.07.2018 09:45
RESS 65551188		YR OF MANU 11.10.2013	TARGET DATE
(R) (P)		CHASSIS CODE WDF63981323802651	COMPLETION DATE/TIME
COUNT CARD NO.			

JOB DESCRIPTION

Accident Date: 27.07.2018


NATURE: 3P 27.07.2018

S/NO LABOR CODE

DESCRIPTION

FRONT

CHINA - Left Side Minor



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: SHC 968Y LARRY

Vehicle No.: SHC 968Y

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

Our Job Ref No : 305193650
Date : 2. Aug. 2018

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No : SHC 968Y

Date of Accident: 27. Jul. 2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: CHINA YN7282L
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$1,100.00


3. Estimated normal period for repairs: 1 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Larry Ng
Tel : 6214 8316
Fax : 6546 8156

Signature : 
Name : Kalvin
Date : 3/8/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Side Mirror – LH / CR			\$1,595.00
	SUB TOTAL			\$1,595.00
	LESS 20%			\$319.00
	DISCOUNTED TOTAL			\$1,276.00
	Labour Charge			
1	Panel Beating			\$100.00
1	Spray Painting Charge			\$128.00
1	Wiring Chrage			\$50.00
	TOTAL LABOUR CHARGE			\$270.00
	ESTIMATE TOTAL			\$1,546.00

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR ESTIMATE®

CHINA

[illegible]

Shu Pei (LKKAUTO)

From: Lucas Lee <luucas.lee@sg.cntaiping.com>
Sent: Wednesday, 1 August 2018 5:02 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving YN7282L (OI : CTI - SNM18D03754C02) and SHC968Y (TP : LKK REF - CC3/CTI18013923/K1wb3) on 27.07.2018
Attachments: leeSZ_SNM18D03754C01-YN7282L-LKKDirectSettlementAccidentLtr_CLCR95.130.pdf; MSAT18098957-YN7282L.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Hwang Shiang Yi

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: luucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 31 July, 2018 6:59 PM
To: Claims Dept of CTI
Cc: Angie Foo; Sharon Han; Vivian Lau (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving YN7282L (OI : CTI - TBA) and SHC968Y (TP : LKK REF - CC3/CTI18013923/K1wb3) on 27.07.2018

WITHOUT PREJUDICE

Dear Sharon,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 968Y at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP's GIA report

Our case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeei@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-02 Springleaf Tower Singapore 079909
Tel: 6389 8111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208394E

Our Reference: **SNM18D03754/C01/2**

Date : **01 AUGUST 2018**

via Ordinary & Registered Mail

**INTERINFO AGENCY PTE LTD
NO.48 TOH GUAN ROAD EAST
#07-123 ENTERPRISE HUB
SINGAPORE 608586**

Dear Sir / Madam

**ACCIDENT INVOLVING YN7282L AND SHC968Y ON 27 JULY 2018
ALONG TELOK BLANGAH ROAD BEFORE KAMPONG BAHRU ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC968Y**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : VIVIAN
Ref : CC3/CT118013923/K1WB3
Contact No : 68418625
via Email : VIVIAN@LKKAUTO.COM

CC : Agent - (AN0420A) - INXPRESS INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

Our Ref : CC18070797 / SHC 968Y /WT(st)

Your Ref :

Date : 16-Aug-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No. 19509549W

CHINA INSURANCE CO LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHC 968Y YOUR INSURED YN 7282L
AND OTHER _____ ON 27.07.18**

We are the authorised repair workshop for Citycab Pte Ltd, the owner of motor Vehicle No : SHC 968Y which was involved in the captioned accident with your insured vehicle.

The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : YN 7282L we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,177.00
2	<u>2</u> days Loss of Rental @ \$ 163.52 per day	\$ 327.04
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transportation Fees	\$ -
Sub Total :		\$ 1,511.53

HIRER'S CLAIM

7	<u>2</u> days Loss of Income @ \$ 80.00 per days	\$ 160.00
Total Claims :		\$ 1,671.53

We enclose herewith the following documents to support the claims :

- a) Original repair bill and photocopies of photographs : 7 pcs.
b) LTA search slip/s of : YN 7282L
c) GIA / Police report/s of : SHC 968Y
d) Letter of authority from owner / hirer / operator
(X) Photocopies of Accident Scene Photos () Certificate of Insurance
() Witness statement/s (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully
William Tan

Deputy Manager
CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 758732



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI18013923/K1wb3

21 August 2018

Interinfo Agency Pte Ltd

48 Toh Guan Road East

#07-123

Singapore 608586

Dear Sir/Madam,

ACCIDENT INVOLVING YN 7282L & SHC 968Y ON 27/07/2018

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 31/08/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd
(Motor Claims Dept)*

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****SONATA SHC968Y , YN7282L
TELOK BLANGAH RD TWDS KEPPEL RD.****ON 27-Jul-18 14:00**

I / We

KABEER KHAN BIN ALI K... (Hirer) NRIC No.: **S7242567G**

and/or

(Relief) NRIC No.:

Taxi Number

SHC968Y

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

27-Jul-2018

Name of Hirer

KABEER KHAN BIN ALI KHAN

Hirer NRIC


S7242567G

Signature :

Address

**836 TAMPINES STREET 82 #02-75
520836**

Contact No.

81116172

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMCVSN1443441703

Claim No : SNM18D03754C02/2

Claimant : CITYCAB PTE LTD

Amount : S\$ 1,500.00
Singapore Dollar One Thousand Five Hundred Only

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHC 968Y
Insured Vehicle No. : YN 7282L

Date of Loss : 27/07/2018
Place of Accident : TELOK BLANGAN RD BEF KAMPONG BAHRU RD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : INTERINFO AGENCY PTE LTD
Driver Name : JAMALLUDIN BIN MOHD AKIP

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Global Sum	S\$ 1,500.00
	=====
TOTAL	S\$ 1,500.00
	=====

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
35 LIAWANG DRIVE
SINGAPORE 349023

Claimant Name : _____ NRIC No : _____

Signature :  Date : 18-10-18

"The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

235 Braddell Road Singapore 579701
Mobile + 65 6283 6280 Facsimile + 65 6280 8755

Workshops

59 Luyang Drive Singapore 508959 24 Senoko Loop Singapore 758158
383 Serangoon Drive Singapore 575717 7 Sungei Kadut Way Singapore 7280
45 Pandan Road Singapore 608296 501 Yishun Industrial Park A Singapore
320 Ubi Road 3 Singapore 408648COMPANY REG. NO.: 199506048
Page: 1

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD
SPRINGLEAF TOWER3 ANSON ROAD #16-00
SINGAPORE 079909

CONTACT NO: 62222366

VEHICLE NO
SHC 968Y

NO/DATE

91388222 06.08.2018

MAKE
MERCEDES BENZ

JOB NO.

305193650

MODEL
VIANO CDI 2.2L

ODOMETER READING

DATE OF REG
11.10.2013CHASSIS CODE
WDF63981323802651

JOB TYPE

Description : 3P 27.07.2018

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	1,100.00
Add GST @ 7.000 %	77.00
Total Invoice amount	1,177.00

Issued by : CHEWBEELENG 06.08.2018 16:19:53
Repair Type : CFSO/57/57
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd
Member of COMFORTDELGROHead Office:
Braddell Road
Singapore 579701

Please note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CC18070797



Date: 06 August 2018

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	27/07/2018 @ 14:00 hrs
ALONG	TELOK BLANGAH RD TWDS KEPPEL RD
INVOLVING	YN7282L

We refer to the above-mentioned accident and wish to inform that **CityCab Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC0968Y** (the "Taxi"). The Taxi was hired to **KABEER KHAN BIN ALI KHAN IC NO S7242567G** a registered hirer-operator of **CityCab Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$163.52** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

ΣΗC 968 y

[illegible]

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

YN7282L 27 Jul 2018 / 14:00:00 Successful C01 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#)[OK](#)

SHC968V



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18013923/K1wb3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 23-10-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 7282L	Veh. Inspected	SHC 968Y
	Policy No.	DMCVSN1443441703	Coverage (\$)	0.00
	Claim No.	SNM18D03754C02/2	Excess (\$)	0.00
	Assign From		Assign Date	30/07/2018
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ VIANO	c.c	2143
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDF63981323802651	Colour	WHITE
	Odometer	481626	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60 R16C	HANKOOK	7 mm
	L/H Front Tyre	225/60 R16C	HANKOOK	7 mm
	R/H Rear Tyre	225/60 R16C	HANKOOK	7 mm
	L/H Rear Tyre	225/60 R16C	HANKOOK	7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S WING MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	27/07/2018	Inspection Date	30/07/2018
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 968Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE MIRROR -LH	CRACKED	1,595.00	1,595.00
	LESS 20% DISCOUNT		-319.00	-319.00
			1,276.00	1,276.00
	<u>LABOUR</u>			
	PANEL BEATING .	NOT NECESSARY	100.00	50.00
	SPRAY PAINTING CHARGE.		120.00	50.00
	WIRING CHARGE.		50.00	-
			270.00	100.00
	GRAND TOTAL		1,546.00	1,376.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CC3/CTI18013923/K1wb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.