

ASS. REC. BY:

REF: CS3/MSG18013927/Uzd3<sup>sr</sup> Special Instruction:

Surveyor:

From (Person):

Marull  
Chhia Nyuk

ASSIGNMENT (Office)

of MSIG

Date/Time: 31/7/18 @ 3:55pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 1655 U

Insured:

SKL 4575M

at Workshop m/s

Alpha Car Services

Tel:

6509 8268

of

BKC Teki Bkt Ave 6 # 01-59 Autobay

Policy No:

B29 040568Mcy

Claim No:

565970

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/07/2018

CA / REV / REP. / REV 24 HRS

Cup?

01/08/2018

H.O.D. Endorsement:

Date/Time:

5:26pm @ 31/7/18

Person Contacted:

Cui ling

Vehicle IN (OUT)

Date/Time	Action/Instruction ( X ) Estimate
	GX1655U-X
	SKL 4575M
3/8/18	After Repair

(08/11/13) wef

REF: MSIG

ASS. REC. BY:

## ASSIGNMENT

From: Date: 1/8/18

Estimated Cost:

On: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GX 16554  
at Workshop m/s Alpha Car Services  
of Blkc, Kaki Bkt Ave 6 # 01-59 Autobay

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: Plc.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GX16554

V Regn: 2104

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna

C.C. 2986

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 360018

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFUF344X03002483

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14 LS

R: 155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5/5 mm

L/Bal. 5 mm

L/Bal. 5/5 mm

D.O.A. 30/7/18

D.O.I. 1/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No settlement. 09.45 am.
	Call until 25-2-2019 LTA 2938
	2-3/4.
8/7/18	submit the report

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18013927/Uz4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 31-07-2018	
		Code : MSG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SKL 4575M	Veh. Inspected	GX 1655U
Policy No.	B29040568MCY	Coverage (\$)	0.00
Claim No.	565970	Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK)	Assign Date	31/07/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	30/07/2018	Inspection Date	01/08/2018
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		31 Jul 2018 15:55 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIME DARBY SERVICES PTE LTD, Co. Reg. No.: 197501065W		
Main Claimant:	JACKSON RENOVATION WORKS PTE LTD, Co. Reg. No.: 201021918G		
Vehicle Reg. No.:	GX1655U	Date of Loss:	30/07/2018 12:00 - :59 [173 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 565970	Policy/Cover Note No.:	B29040568MCY (Comprehensive) Coverage: 01/10/2017 - 30/09/2018
Vehicle Reg. No. (Insured):	SKL4575M	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/08/2018]		
Driver/Custodian (Insured):	WOON CHUEY LIAN (), NRIC: S1671757F, Tel: +6599999999		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY:0%-10% CONTACT: MS CAILING 6509 8258		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/07/2018 12:08
Date Of Accident	30/07/2018 12:15
Exact Location Of Accident	301 JALAN BUKIT HO SWEE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX1655U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	JACKSON RENOVATION WORKS PTE LTD
Co Reg No	0
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97943608

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCPHQ17-004983
Cover Note Number	

### Driver

Name of Driver	CHEOW WEE KHEONG
NRIC No	S7303822G
Date Of Birth	22/01/1973
Occupation	OUTDOOR
Date Of Driving Pass	23/04/1997
Driving Experience	21 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97943608
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 202B SENGKANG EAST ROAD #12-66
Postcode	542202
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL4575M
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WOON CHUEY LIAN
NRIC/Passport Number	S1671757F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*Chuan*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NIC/IRIS No.:

# Sketch Plan #2

## SKETCH PLAN



Vehicle A : GX 1655 L

Vehicle B : SKL 4575 M

301 Jalan Bukit Hu Swee.

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above mentioned Date & Time 20/2/18 @ 12:15hrs, I was station along 301 Jalan Bukit Hu Swee (Middle Road) waiting to park. Out of sudden, Vehicle B hit onto my vehicle.  
A Picture of Google map is enclosed.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:  
Date & Time:

Driver's Signature:  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre/Policyholder's Signature:  
Name:  
NRIC/ID No.:



## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1918G

## Vehicle Details

Vehicle No.:	GX1655U
Vehicle to be Exported:	No
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	White
Manufacturing Year:	2004
Engine No.:	5L5417004
Chassis No.:	JTFUF34YX03002183
Maximum Power Output:	-
Open Market Value:	\$23,715.00
Original Registration Date:	26 Feb 2004
First Registration Date:	26 Feb 2004
Transfer Count:	3
Actual ARF Paid:	\$1,186.00

## Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

## Intended COE Rebate Details

COE Expiry Date:	25 Feb 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$25,709.00
COE Rebate Amount:	\$2,938.00
<b>Total Rebate Amount:</b>	<b>\$2,938.00</b>

## Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 01 Aug 2018

OK



## CONNECTING CAR BUYERS &amp; SELLERS.

We'll handle your loans, insurance &amp; other paperwork for FREE.

Find out more



toyota dyna

Price Range

Depreciation

&gt; 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Direct Owners » Toyota Dyna 150 (COE till 02/2019)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Tyres



Shangri-La's Rasa Sentosa Resort &...



\$343

sg.hotels.com

## Toyota Dyna 150 (COE till 02/2019)

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

Price \$16,000

Depreciation \$31,230 /yr

Reg Date 05-Feb-2004  
(6mths 3days COE left)

Lifespan 04-Feb-2024

Manufactured 2003

Mileage -

Transmission Manual

Engine Cap 2,986 cc

Curb Weight 1,620 kg

Fuel type Diesel

Features -

Accessories -

Description Full Canopy With Checked Plate. Well Maintained And Good Condition.

COE \$25,709

OMV \$23,715

ARF \$1,186

Dereg Value \$2,634 as of today (change)

No. of Owners 5

Type of Veh Truck

Category COE Car, Direct Owner Sale

Availability Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 04-Jun-2018 | Last Updated on: 26-Jul-2018

Tags: Toyota Dyna, 2004 Toyota Dyna, Toyota, Dyna, Used Toyota

## Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$1,600 (change) Maximum 90% Loan

1st Instalment \$2,454

Total Upfront Payment \$4,079 (excluding insurance)

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.

Items for Toyota Dyna

» View All



NO IMAGE AVAILABLE

100% FREE  
PAPERWORK  
SUPPORT FOR  
BOTH BUYER  
& SELLER

## Seller Information

Contact Person(s) Cathie

Contact No. 81823333

Enquiry Contact Seller

## USEFUL FORMS

» Indemnity form » Sales agreement

» Receipt » Hand-over form

» M01

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans &amp; insurance for FREE.



## Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

### Sketch Plan #3



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		31 Jul 2018 15:55 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIME DARBY SERVICES PTE LTD, Co. Reg. No.: 197501065W		
Main Claimant:	JACKSON RENOVATION WORKS PTE LTD, Co. Reg. No.: 201021918G		
Vehicle Reg. No.:	GX1655U	Date of Loss:	30/07/2018 12:00 - :59 [173 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 565970	Policy/Cover Note No.:	B29040568MCY (Comprehensive) Coverage: 01/10/2017 - 30/09/2018
Vehicle Reg. No. (Insured):	SKL4575M	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 01/08/2018]		
Driver/Custodian (Insured):	WOON CHUEY LIAN (), NRIC: S1671757F, Tel: +6599999999		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY:0%-10% CONTACT: MS CAILING 6509 8258		

### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*GX1655U (565970)**  
**[SKL4575M]**  
**TP**  
**JACKSON RENOVATION WORKS PTE LTD**  
**Jul 30 2018 12:00PM**  
**[SIME DARBY SERVICES PTE LTD]**  
**Alpha Car Services Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

### Assessment Reports
































1 per page ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/07/18 14:10	<b>Accident Statement</b> From: SC - Reg. No: SKL4575M, Claimant: SIME DARBY SERVICES PTE LTD	Load HTM	<input checked="" type="checkbox"/>

### Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
31	02/08/18 13:46	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/08/18 13:46	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	07/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/07/18 14:10	<b>GX1655U TP E-FILE REPORT</b> From: SC - Reg. No: SKL4575M, Claimant: SIME DARBY SERVICES PTE LTD	 Load PDF	
2	31/07/18 14:11	<b>PRI - R.S. SOLOMON LLC</b>	 Load PDF	
3	31/07/18 14:11	<b>SURVEY DISAGREE ON SJE - ASSIGN LKK</b>	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.





# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18013927/UZ4D3S2

Date: 08/08/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29040568MCY
Claimant Vehicle No :	GX1655U	Insured Vehicle No :	SKL4575M
Date of Loss:	30/07/2018	Nature of Claim:	TP
		Claim No:	565970

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GX1655U</b>	Engine No:	5L5417004
Make & Model:	TOYOTA DYNA 150 D, 3.0 D (M)	Chassis No:	JTFUF34YX03002183
Reg. Date:	26/02/2004 (Man. Year: 2004)	Odometer:	360018 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	185 R14	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Firestone 5 mm	Rear Left Side:	West Lake 5/5 mm
Front Right Side:	Firestone 5 mm	Rear Right Side:	West Lake 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	31/07/2018	
Date Inspected:	01/08/2018	Inspected At: Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay Singapore 417883
Estimated Period of Repair:	0.0 days	

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 07 Aug 2018)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GX1655U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >