

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7550Y

DATE 31/7/2018 15:49

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>x hyundai</i>			\$ 1,349.50	
	Boot Lid Rubber <i>x</i>			\$ 110.90	
	Boot Lid Lock Upper <i>x</i>			\$ 132.10	
	Boot Lid Lock Lower <i>x</i>			\$ 30.30	
	Boot Lid Sonata Plate <i>-</i>			\$ 43.60	
	Boot Lid Hyundai Plate <i>-</i>			\$ 24.20	
	Boot Lid 'H' Emblem <i>-</i>			\$ 26.10	
	Boot Lid CRDI Plate <i>-</i>			\$ 22.70	
	Rear Bumper <i>-</i>			\$ 578.40	
	Rear Bumper Reinforcement <i>?</i>			\$ 483.30	
	Rear Bumper Clip <i>-</i>			\$ 22.00	
	Rear Bumper Sponge <i>?</i>			\$ 137.40	
	Rear Bumper Under Cover <i>x</i>			\$ 185.80	
	Rear Panel <i>x</i>			\$ 391.80	
	Rear Panel Garnish <i>x</i>			\$ 95.80	
	SUB TOTAL			\$ 3,633.90	
	LESS 20%			\$ 726.78	
	DISCOUNTED TOTAL			\$ 2,907.12	
	Boot Lid City Cab Logo & Tel No. Sticker <i>-</i>			\$ 30.00	Nett
	Rear No. Plate <i>x</i>			\$ 25.00	Nett
	Rear Bumper Reverse Sensor <i>-</i>			\$ 135.70	Nett
				\$ 190.70	
	Labour Charge				
	Panel Beating			\$ 850.00 ⁴⁰⁰	
	Spray Painting Charge			\$ 750.00 ⁴⁰⁰	
	Wiring Charge			\$ 50.00 ^x	
	Tuff Kote			\$ 50.00 ^x	
	Remove/Refix Reverse Sensor			\$ 120.00 ³⁰	
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 4,917.82	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TOTAL LABOUR
Date:

ESTIMATE TOTAL

Ka hui (11/11/18)
31/7/18 16:00
2 Rg
43
Athur Regal p 11